



VIC

Beng Hai Motor Service

Bedok North Ave 4, Blk 3012 Bedok Ind. Park E # 01-2058
Singapore 489978 Tel: 6444 1544 H/P: 9663 1569

Invoice No : **7214**Vehicle No : **SJX 2209H**Date : **5/8/19**

Terms :

No.	Description	Qty	Unit Price	Amount
1.	Rear Bumper assy. <i>oa</i>	1pc.		\$859.20 ^{\$574}
2.	Rear Right Bracket. <i>na</i>			\$323.00
3.	Rear Right re-former <i>na</i>			\$48.60
4.				\$940.10 ^{\$654.9}
	Loss 25%			\$235.00 ^{\$163.2}
				\$705.10 ^{\$491.18}
1.	Rear Bumper cl.ips. <i>na</i>	10/pz		\$50.00 ^{\$30}
2.	Rear Bumper Reverse Sensor <i>sw</i>	2pc		\$150.00 ^{\$200}
3.	Spray painting Rear Right portion			\$250.00 ^{\$180}
4.	Labour For Panel Beating, remove → Install, Rear Right damaged Parts and Rear Bumper Reverse Sensor			\$250.00
5.	Car Rental	2day	\$140.00	\$280.00
Total				81685.00 \$1051.18 2/5 20% = \$840.95

E. & O. E.

RAM (LKIC)
88628718
3 days

OK

Customer's Signature

Beng Hai Motor Service