

22/03/2002

ASS. REC. BY:

REF: CS / SMO / 9013627 / Evf307

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi of SMO

Date/Time: 5.8.19 10.50a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 1729U

Insured: SCE 444R

at Workshop m/s SMRT

Tel: 68662671

of 60 Woodland Industrial Park E4

Policy No: D18mTPV01015957

Claim No: CMTD 1903719

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5.8.19 10.57a.m

Person Contacted: Shann


Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 1729U - NBA / 1700749817 DOA - 07/04/2017
	SCE 444R - CCB / A441023223 / Aha 352 DOA - 13/12/2016
6/8/19	Send preli. revised via merimen

REF: *Sampo*

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
 To Inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SHB 1729U* Yt Regn: *20/8/14*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /
 Truck / Trailer or
 Make: *Toyota Pirus* C.C. *1798*
 Colour: *Mercury* A/C Insured / Std / NI / NA
 Sp. Reading: *607/12* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *JTAKN 36U 90S 747735*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rlm / STD A/Rlm or
 Tyre Size: F: *195/50R15*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Falken*
 Front _____ Rear _____
 R/Bal. *5* mm R/Bal. *5* mm
 L/Bal. _____ mm L/Bal. *5* mm
 D.O.A. *2/8/19* D.O.I. *5/8/19*
 Survey held at *SMRT*
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
19/8/19 Finalize Confirm \$1500, 3 app. Regs. (At JVA)
(Red 6723, 8090) *08/19/2019*
SCE 444 R

RECEIVED 19 AUG 2019

Date/Time, File Pass to? ☐ : Proll. Report
☐ : Final Report
 Date/Time, File Return to?

Days Of Repair: *3*
 Resurvey No. of Trip: *1*

Survey Fee: *250*
 Transportation
) \$ + R.N. 01
) Photos
) Other
)
11
261

19/8 - typist

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech Invs (\$
☐ : Weekend (\$

Report Format : *merimen*
 Lump Sum / I.B.L: (\$ *1500/-*

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2019		05 Aug 2019 10:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM HWEE LENG, ID: S1780577J		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB1729U	Date of Loss:	02/08/2019 20:00 - :59
Claim Type:	TP / CMTD1903719	Policy/Cover Note No.:	D18MTPV01015957 (Comprehensive)
Vehicle Reg. No. (Insured):	SCE444R	Policy No. (Claimant):	
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/08/2019]		
Driver/Custodian (Insured):	WONG SEIN MUN, VENESSA (), NRIC: S9235006A, Tel: +6590114847 Email:		
Adj Asg. Remarks:	WS: SHANTI 68662671/2		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

There are no mail for this case.

☐
ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn: Hwang Shiang Yi Date: 06 Aug 2019

Preliminary Advice

Insured Vehicle No	: SCE444R	Accident Date	: 02/08/2019
TP Vehicle No	: SHB1729U	Assignment Date	: 05/08/2019
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 3
Date of Inspection	: 5/8/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,355.30
Revised Amount	:S\$	1,667.15
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,667.15
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(X)	Other comments :The above survey was conducted on a 'Without Prejudice' basis.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 369K

Vehicle Details

Vehicle No.: SHB1729U

Vehicle to be Exported: No

Intended Deregistration Date: 05 Aug 2019

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2014

Engine No.: 2ZR6110423

Chassis No.: JTDKN36U905747735

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$32,920.00

Original Registration Date: 20 Aug 2014

First Registration Date: 20 Aug 2014

Transfer Count: 0

Actual ARF Paid: \$8,088.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Aug 2022

PARF Rebate Amount: \$6,066.00

Intended COE Rebate Details

COE Expiry Date: 19 Aug 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$50,088.00

COE Rebate Amount: \$19,018.00

Total Rebate Amount: \$25,084.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2019 10:20
Date Of Accident	02/08/2019 20:00
Exact Location Of Accident	BALESTIER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1729U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	CHOO KWEE HENG
NRIC No	S1802405E
Date Of Birth	11/02/1967
Occupation	OUTDOOR
Date Of Driving Pass	15/05/1989
Driving Experience	30 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	145
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG BALESTIER ROAD AT THE CENTRE LANE AND HAD STOPPED DUE TO THE FRONT VEHICLE STOPPED. AFTER WHICH, I FELT AN IMPACT FROM BEHIND. THE VEHICLE SCE444R FROM BEHIND HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCE444R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG SEIN MUN, VANESSA
NRIC/Passport Number	S9235006A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

3/8/18

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

du 3/8/19

Case Details

Case Reference Number : TAX/08/19/2009

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : Sompoo Insurance
Singapore Pte. Ltd

Type of Repair : Accident Repair

Estimation ID : EST-7932-ID

Accident Date and Time : 02/08/2019 12:01
PM

Vehicle Registration Number : SHB1729U

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 60

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	Re
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓ DD
Standard	Main		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ BR
Standard	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✓ BR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ MC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace	✓ MC
One Time Key In	Main		6505547	BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✓ X N/A
One Time Key In	Main		6505546	ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main		6505545	ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	25.00	118.05	Replace	0	0	Check	✓ X N/A
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace	✓ BR
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main		6505551	BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ BR
One Time Key In	Main		6505617	BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main		6505618	BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	✓ X N/A

Total Spare Part Cost 4,367.74

Surveyor Total 837.15

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace R
One Time Key In	Main		6505619	BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main			UNDER COVER CENTER REAR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main		6505522	END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	0	Repair <input checked="" type="checkbox"/> X R
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main		6505636	TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair <input checked="" type="checkbox"/> X R
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main		6505497	TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main		6505500	TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
One Time Key In	Main		6505637	TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give <input checked="" type="checkbox"/> X N/A
Total Spare Part Cost									4,367.74	Surveyor Total 837.15			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									3,131.02	Final Sur Total 669.72			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	

			Recommendation(\$)	Adjustment(\$)
2	Main	TO RESPRAY BUMPER BEAM	180.00	0
3	Main	TO RESPRAY REAR PANEL	180.00	50
4	Main	TO RESPRAY TAIL GATE	378.00	200
Total:			1,116.00	450.00

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	JK
2	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	JK
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	JK
6	Main	TO REPLACE SUNDRY PARTS	100.00	20	JK
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			720.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,131.02	669.72
Total Labour Cost	845.00	300.00
Total Spray Painting	1,116.00	450.00
Other	720.00	80.00
Overall Total	5,812.02	1,499.72
Lump Sum Repair Option		✓
Lump Sum Total	5,800.00	1,500.00
Surveyor Approved Amount		1,500.00
No of Repair Days*	6	3
Remarks	-	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN

Signature

Survey Date

05/08/2019

Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14/8/19

Section A - Accident Details	
Registration Number	SHB1729U
Case Reference Number	TAX/08/19/2009
Registration Date	20/8/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHOO KWEE HENG
Type of Accident	Head to Rear
Accident Date and Time	2/8/2019 8:01 PM
Accident Reported Date and Time	3/8/2019 10:19 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102698
Special Instruction to ARC, if any	TP SOMPO
Prepared Date and Time	4/8/2019 6:55 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,116.00	\$450.00
Total Spare Part Cost	\$3,494.19	\$669.73
Total Other Cost	\$720.00	\$80.00
TOTAL COST	\$6,175.19	\$1,499.73
Lump Sum Total	\$6,200.00	\$1,500.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / Sompo
ARC / Surveyor Sign Off Date	05/08/2019 3:24 PM	05/08/2019 2:39 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 65662623
Accident Reporting Number : 98662672

Date Generated : 18/08/2019

User ID : PohBuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0204	Invoice Number	
Quotation Date	16.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$50.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,116.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$720.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
6505547		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
6505546		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
6505545		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
30 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665522
Estimator Telephone Number : 68662623
Accident Reporting Number : 58662672

Date Generated : 18/08/2019

User ID : PohSuan

			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	BR
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	NN
6505551		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	NN
6505550		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	BR
6505617		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	NN
6505618		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	NN
6505619		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	NN
		58308-47011	UNDER COVER CENTER REAR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	NN
6505522		58307-47060	END PANEL	1.00	\$602.10	100.00	\$0.00	Replace	Repair	NN
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	NN
		64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Not Given	NN
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	NN
6505636		67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair	NN
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	NN
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	NN
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	NN
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	NN
6505497		68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	NN
6505500		69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given	NN
6505637		67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given	NN
Total					\$5,467.51		\$837.16			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

837.16
- 202
669.73
+ 300.00
+ 530.00

1499.73
4/5 \$1500/-

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 19 August 2019 9:35 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHB1729U

Hi,

Amount confirmed as per your recommendation, thanks. As for the repair days confirm 3 days, sorry for the typo error.

Regards
Poh Suan

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Monday, 19 August 2019 8:53 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: SHB1729U

Dear Poh Suan,

We confirm the finalize \$1500 (L/S, before GST). 3 repair days. (Not 12 repair days)

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Sunday, August 18, 2019 10:39 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB1729U

Hi Steve,

Attached herewith the repair estimate of SHB 1729U having Case No: TAX/08/19/2009.

There is no change to the approved amount of \$1,500 @ 12 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Aug 2019		05 Aug 2019 10:50 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM HWEE LENG , ID: S1780577J								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB1729U	Date of Loss:	02/08/2019 20:00 - :59 [59 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1903719	Policy/Cover Note No.:	D18MTPV01015957 (Comprehensive)						
Vehicle Reg. No. (Insured):	SCE444R	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 16/08/2019]								
Driver/Custodian (Insured):	WONG SEIN MUN, VENESSA (), NRIC: S9235006A, Tel: +6590114847 Email:								
Adj Asg. Remarks:	WS: SHANTI 68662671/2								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB1729U (CMTD1903719)**
[SCE444R]



































TP

SMRT TAXIS PTE LTD

Aug 2 2019 8:00PM

[LIM HWEE LENG]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	05/08/19 10:41	Accident Statement From: SC - Reg. No: SCE444R, Claimant: LIM HWEE LENG	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/08/19 10:30	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/08/19 08:56	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
6	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
18	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/08/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
				<input checked="" type="checkbox"/>
33	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
34	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
35	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
36	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
37	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
38	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
39	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
40	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
41	19/08/19 08:56	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	05/08/19 10:51	TP - SAS		Load PDF
2	05/08/19 10:51	TP - ACK+ASSIGN LKK		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19013627/EVF3E2

Date: 20/08/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01015957

Claimant Vehicle No : SHB1729U

Insured Vehicle No : SCE444R

Date of Loss: 02/08/2019

Nature of Claim: TP

Claim No: CMTD1903719

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB1729U

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR6110423

Reg. Date: 20/08/2014 (Man. Year: 2014)

Chassis No: JTDKN36U905747735

Colour: Maroon

Odometer: 607112 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15

Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,542.00	837.16	4,704.84	84.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,681.00	830.00	1,851.00	69.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,223.00	1,667.16	6,555.84	79.73
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	8,223.00	1,500.00	6,723.00	81.76

INSPECTION

Date of Assignment: 05/08/2019

Date Inspected: 05/08/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Aug 2019)

Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB1729U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Dented	458.60 F	*343.95 F
2	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Broken	94.80 F	*71.10 F
3	1		*NAME PLATE (HYBRID) (DISC 25%)	Broken	51.90 F	*38.93 F
4	1		*BUMPER CLIPS (DISC 25%) (10PCS)	Necessary	16.10 F	*12.08 F
5	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
6	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
7	1		*SENSOR REVERSE (SN)	Broken	180.00 F	*180.00 F
8	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
9	1		*ARM SUB-ASSY, RR BUMPER LH	Not Necessary	139.60 F	*- F
10	1		*ARM SUB-ASSY, RR BUMPER RH	Not Necessary	139.60 F	*- F
11	1		*ANTENNA, ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
12	1		*BUMPER SEAL, RR LH	Not Necessary	88.90 F	*- F
13	1		*BUMPER SEAL, RR RH	Not Necessary	65.70 F	*- F
14	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
15	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
16	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
17	1		*UNDER COVER CENTER REAR	Not Necessary	514.50 F	*- F
18	1		*END PANEL COVER, DECK TRIM HOLE	Not Necessary	46.10 F	*- F
19	1		*END PANEL COVER, DECK TRIM, RR	Not Necessary	121.10 F	*- F
20	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
21	1		*TAIL GATE DOOR GLASS MOULDING, RH	Not Necessary	29.40 F	*- F
22	1		*TAIL GATE DOOR GLASS MOULDING, LH	Not Necessary	29.40 F	*- F
23	1		*MOULDING BACK WINDOW, LOWER NO.1	Not Necessary	29.40 F	*- F
24	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
25	1		*TAILGATE DOOR HINGE LH / RH	Not Necessary	58.30 F	*- F
26	1		*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
27	1		*TAILGATE DOOR WEATHER STRIP	Not Necessary	353.40 F	*- F
28	1		*END PANEL	Repair	602.10 F	*- F
29	1		*TAILGATE ASY	Repair	1,007.90 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	5,542.00 837.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	300.00
2	SPRAY PAINT	New	1,116.00	450.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
6	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	20.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
8	TO REPLACE SUNDRY PARTS	New	100.00	20.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			2,681.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >