

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

**Accident Sketch Plan**

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

i understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

 3.29pm 16/7/19.  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan

lorong  
SKETCH PLAN  
Alh 500



A: GBC 2219J  
B: SGW 479Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my company van GBC 2219J from defu lane to hagans ave 3. While I almost turn in to the middle lane. Suddenly the car SGW 479Z drive forward without give way to me & hit onto my van rear rh partition.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

PP, 3.29pm 16/7/19

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



driver's nric & license

**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. S25845431



Name



LUM CHEE FAI

林志輝

Race  
**CHINESE**

Date of Birth: 10-08-1964      Sex: M

Country of Birth  
**MALAYSIA**



**REPUBLIC OF SINGAPORE**      **DRIVING LICENCE**



Licence Number: S25845431

Name:  
**LUM CHEE FAI**

Birth Date: 10 Aug 1964  
Issue Date: 30 Jul 2003



000697871G

driver's nric & license

0121922



NRIC No. **S25845431**

Nationality  
**MALYSIAN**

Blood Group Date of Issue  
**O+ 14-06-1994**


ADJ. ALI SAZ BERNAN MISHIN STREET 3 210-1281  
SINGAPORE 446547  
NRIC No: **S25845431** Date: **14-06-1994** No: **8154339**

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class	Description	EXPIRE DATE
Class 2B	Motorcycles <= 200 CC	28 Feb 1984
Class 3	Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	12 Jan 2009
Class 4	Heavy motor cars and motor tractors > 2500 kg	19 May 2009
Class 5	Motor vehicles > 7250 kg not constructed to carry any load	06 Jul 2009

S25845431

S / No. 9000107924



Licence No: S25845431

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6653 Fax: 67471017 Registration No: 209723252D

Report Reference : TP / 19025-07/AY / 2019  
Date of Report : 31 Jul 2019

Danny Buay Eng Kit  
c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

**THIRD PARTY SURVEY  
ACCIDENT HAPPENED ON 16 Jul 2019**

Workshop Address : Bluwel Automotive Service Pte Ltd  
No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

As per your instruction dated **22 Jul 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SGW 479 Z**. We enclosed herewith our report and findings as follows:

**1. VEHICLE PARTICULARS**

Registration No	: SGW 479 Z	Engine No	: EJ25D125745
Model	: Subaru WRX	Mileage	: 258521
Year / Capacity	: 2007/2457	Colour	: Grey
Chassis No	: JF1GDGKD37G071558		

**2. TYRES CONDITION**

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 225/40 R18	Michelin	6.00	mm	Sport
REAR O/S	: 225/40 R18	Michelin	6.00	mm	Sport
FRONT N/S	: 225/40 R18	Michelin	6.00	mm	Sport
REAR N/S	: 225/40 R18	Michelin	6.00	mm	Sport

# MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417983  
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the n/s front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.
5. Enclosed number of photograph : 83 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SGW 479 Z  
 Report No: TP/ 19025-07/AY / 2019

**SPARE PARTS**

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front n/s headlamp	Damage	\$ 1981.00	\$ <sup>CU</sup> 1981.00 ✓
1	Front bumper	Damage	\$ 654.00	\$ <sup>Def/orn</sup> 654.00 ✓
1	Front bumper n/s side retainer	Necessary	\$ 49.80	\$ <sup>Set</sup> 49.80 ✓
1	Front bumper n/s side air vent	Damage	\$ 85.50	\$ <sup>CU</sup> 85.50 ✓
1	Front n/s fender	Damage	\$ 300.30	\$ <sup>Set</sup> 300.30 ✓
1	Front n/s fender inner shield	Damage	\$ 106.20	\$ <sup>Torn</sup> 106.20 ✓
1	Front washer tank	Damage	\$ 186.00	\$ <sup>Be</sup> 186.00 ✓
1	Front n/s wheel hub c/w bearing	Necessary	\$ 316.50	\$ <sup>Set</sup> 316.50 ✓
1	Front n/s lower arm	Damage	\$ 520.00	\$ <sup>Set</sup> 520.00 ✓
1	Front n/s knuckle arm	Damage	\$ 435.60	\$ <sup>Set</sup> 435.60 ✓
			<u>\$ 4634.90</u>	<u>\$ 4634.90</u>
	Discount	20.0%	\$ 926.98	\$ 926.98
			<u>\$ 3707.92</u>	<u>\$ 3707.92</u>
<u>Special Nett Items</u>				
1	Front n/s fender inner shield clip (1 set)	Necessary	\$ 35.00	\$ <sup>Set</sup> 35.00 ✓
1	Front n/s tyre (depreciation)	Damage	\$ 300.00	\$ <sup>Set</sup> 180.00 x
1	Front n/s sport rim	Damage	\$ 600.00	\$ <sup>Set</sup> 600.00 ✓
2	Front n/s shock absorber (1 set)	Damage	\$ 1800.00	\$ <sup>Set</sup> 1800.00 x
			<u>\$ 2735.00</u>	<u>\$ 2615.00</u>

**Spare Parts Total**      \$ 6442.92      \$ 6322.92

Vehicle No: **SGW 479 Z**  
 Report No: **TP/ 19025-07/AY / 2019**

**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 6442.92	\$ 6322.92
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 <i>20</i>
2	To remove and refit front undercarriage.	\$ 300.00	\$ 200.00 <i>150</i>
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 200.00	\$ 120.00 ✓
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1000.00	\$ 750.00 <i>600</i>
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ 750.00 ✓
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 30.00 ✓
<b>Total</b>		<u>\$ 9142.92</u>	<u>\$ 8212.92</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ **6600.00**

*6012.92*  
*4810*

SDLS: SIX THOUSAND SIX HUNDRED ONLY

  
 Qualified Appraiser



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO19012680/Uvd3s2-1	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 08-08-2019	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 2219J	Veh. Inspected	SGW 479Z
Policy No.	D18MTPCVE002758	Coverage (\$)	0.00
Claim No.	CMTD1903416	Excess (\$)	0.00
Assign From	GNOH PAU LOONG	Assign Date	02/08/2019
2. Vehicle Particulars & Condition			
Make & Model	SUBARU WRX (A)	c.c	2457
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JF1GDGKD37G071558	Colour	GREY
Odometer	258521	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40ZR18	MICHELIN	6 mm
L/H Front Tyre	225/40ZR18	MICHELIN	6 mm
R/H Rear Tyre	225/40ZR18	MICHELIN	6 mm
L/H Rear Tyre	225/40ZR18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/07/2019	Inspection Date	22/07/2019
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 479Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT N/S HEADLAMP	CRACKED	1,981.00	1,981.00
1	FRONT BUMPER	DEFORMED / TORN	654.00	654.00
1	FRONT BUMPER N/S SIDE REAINER	BENT	49.80	49.80
1	FRONT BUMPER N/S SIDE AIR VENT	CUT	85.50	85.50
1	FRONT N/S FENDER	BENT	300.30	300.30
1	FRONT N/S FENDER INNER SHIELD	TORN	106.20	106.20
1	FRONT WASHER TANK	DEFORMED	186.00	186.00
1	FRONT N/S WHEEL HUB C/W BEARING	BENT	316.50	316.50
1	FRONT N/S LOWER ARM	BENT	520.00	520.00
1	FRONT N/S KNUCKLE ARM	BENT	435.60	435.60
	LESS 20% DISCOUNT		-926.98	-926.98
			3,707.92	3,707.92
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT N/S FENDER INNER SHIELD CLIP (SN)	NECESSARY	35.00	35.00
1	FRONT N/S TYRE (SN)	SERVICEABLE	300.00	-
1	FRONT N/S SPORT RIM (SN)	DENTED / BENT	600.00	600.00
2	FRONT N/S SHOCK ABSORBER (1 SET) (SN)	SERVICEABLE	1,800.00	-
			2,735.00	635.00
<b>LABOUR</b>				
	TO REMOVE AND REFIT DAMAGE PARTS, TETS FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		50.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		300.00	150.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		200.00	120.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		1,000.00	600.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,000.00	750.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	30.00
			2,700.00	1,670.00
<b>GRAND TOTAL</b>			<b>9,142.92</b>	<b>6,012.92</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,800.00</b>

Report Ref No. CS3/SMO19012680/Uvd3s2-1

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.