

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
H/p 91082728

Fax : 64816131

Dong Jinmei  
90 Edgedale Plains  
#16-22  
Singapore 828685

*Not Notion*  
*11 Sep @ ?*  
*Resurvey After Paint*

Vehicle No : SMG 8242 A  
Make : Honda Fit  
Year : 2018

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
1 pc	Rear tail-gate assy		\$881.30 ✓
1 pc	Rear tail-gate glass moulding		\$105.10 ✓
2 pcs	Rear tail-gate lamp <i>L/H crack R/H ? photo NISum</i>	\$475.30	\$950.60
1 pc	Rear tail-gate emblem " FIT "		\$45.10 ✓
1 pc	Rear tail-gate emblem " Hybrid "		\$55.20 ✓
1 pc	Rear tail-gate chrome handle		\$219.70 ✓
1 pc	Rear tail-gate inner lock sensor ?		\$185.70 ?
1 pc	Rear tail-gate inner lock		\$195.10 ✓
1 pc	Rear tail-gate inner trim board ? photo		\$152.60 ✓
2 pcs	Rear no plate lamp ?	\$55.10	\$110.20 ?
1 pc	Rear tail-gate wiper motor ?		\$287.10 ?
2 pcs	Rear fender <i>L/H Bunt NIS Bu</i>	\$685.60	\$1,371.20 ✓
2 pcs	Rear fender inner trim board ? photo	\$205.10	\$410.20 ?
1 pc	Rear n/s fender air vent		\$57.10 ✓
1 pc	Rear end panel		\$384.60 ✓
1 pc	Rear end panel inner garnish		\$191.10 ✓
1 pc	Rear boot rubber		\$103.40 ✓
1 pc	Rear spare tyre panel		\$1,072.50 ✓
1 pc	Rear spare tyre panel top cover board		\$215.90 ✓
2 pcs	Rear tail-lamp assy <i>L/H crack R/H ? photo NISum</i>	\$483.80	\$967.70
1 pc	Rear n/s tail-lamp panel		\$108.10 ✓
1 pc	Rear bumper		\$791.30 ✓
1 pc	Rear bumper lower garnish ( centre portion )		\$95.10 ✓
2 pcs	Rear bumper reflector garnish	\$115.20	\$230.40 ✓
2 pcs	Rear bumper side retainer	\$45.10	\$90.20 ✓
2 pcs	Rear bumper sponge		\$75.10 ✓
1 pc	Rear antenna		\$95.60 ✓
1 pc	Rear buzzer		\$92.10 ✓
1 pc	Rear axle assy		\$1,100.80 ✓
2 pcs	Rear shock absorber	\$247.10	\$494.20 ✓
2 pcs	Rear hub assy	\$326.90	\$653.80 ✓
	balance c/f		\$11,788.10

## LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMG 8242 A

1 pc	Rear exhaust silencer
1 pc	Rear exhaust silencer heat shield
1 pc	Hybrid battery
1 pc	Hybrid battery top chrome cover
1 pc	Hybrid battery fan discharge motor assy
1 pc	Hybrid battery air discharge hose
1 pc	Hybrid battery control unit
1 pc	Hybrid battery tray
1 pc	Rear towing hook
2 pcs	Rear reverse sensor

} photo

balance b/f \$11,788.10

	\$495.30	✓
	\$45.10	✓
	\$12,985.60	✓
	\$299.70	✓
	\$599.40	✓
	\$449.20	✓
	\$1,912.30	✓
	\$256.10	✓
	\$115.20	✓
\$287.90	\$575.80	✓
	\$29,521.80	
Less 20 %	\$5,904.30	
	\$23,617.44	

S Nett

1 pc	Rear reverse camera	?
1 pc	Rear no plate	✓
1 pc	Rear no plate holder	✓
1 pc	Rear windscreen sealant	✓
20 pcs	Rear bumper clip	✓

	\$300.00	?
	\$45.00	✓
	\$45.00	✓
	\$55.00	✓
\$3.00	\$60.00	✓
	\$505.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$2,000.00 1800

To putty & spray paint rear accident affected portion.

\$1,600.00 1400

Check/reconnect wiring.

\$45.00 200

To spray anti rust on accident affected portion.

\$200.00 1200

Remove/refit rear tail-gate wiper motor and lock mechanism and rear boot upholstery.

\$150.00 1200

Remove/renew rear exhaust silencer

\$120.00 600

Remove/refit rear windscreen to facilitate repair.

\$120.00 ✓

Remove/renew rear hybrid battery including diagnostic check

\$550.00 300

Four wheel troller towing

(Bill) \$150.00 ?

Remove/renew rear axle and undercarriages

\$550.00 2200

Check and realign wheel alignment

\$80.00 600

Remove/renew hybrid battery including diagnostic check and programming

\$600.00 ?  
\$30,287.44