

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SME8745B

Date of Accident : 29 July 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Ng Tze Sim

Date : 31 July 2019

Estimate To Repair SLE9357T - Honda VEZEL 1.5X A

Chassis No : RU11113905

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>gund</i>	\$ 762.70
02	1 pc	rear fender inner trim LH <i>11</i>	\$ 144.20
03	1 pc	rear fender inner cowling LH <i>11</i>	\$ 90.40
04	1 pc	rear fender arc flare garnish LH <i>gund</i>	\$ 271.10
05	12 pc	rear fender arc flare garnish clips @ \$3.50 <i>11</i>	\$ 42.00
06	1 pc	front door LH <i>3-550</i>	\$ 950.00
07	1 pc	front door lower weatherstrip LH <i>rec</i>	\$ 60.00
08	1 pc	front door weatherstrip front LH <i>11</i>	\$ 30.00
09	1 pc	front door weatherstrip rear LH <i>Repair</i>	\$ 35.00
10	1 pc	front door outer weatherstrip moulding <i>11</i>	\$ 40.00
11	1 pc	rear door LH <i>100/24</i>	\$ 948.00
12	1 pc	rear door weatherstrip bottom LH <i>rec</i>	\$ 30.00
13	1 pc	rear door weatherstrip front LH <i>11</i>	\$ 30.00
14	1 pc	rear door weatherstrip rear LH <i>11</i>	\$ 30.00
15	1 pc	rear door outer weatherstrip moulding LH <i>11</i>	\$ 60.00
		Less 20 %	\$ 3,523.40
			\$ 704.68
			\$ 2,818.72
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of door fittings and perform water seepage test.	\$ 300.00
02		To rust-proofing of the affected areas.	\$ 150.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
04		Putty and spray painting of the affected portion.	\$ 800.00
05		To check electrical wiring concerned.	\$ 80.00
			\$ 1,830.00
		Total	\$ 4,648.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

352148
417.44
367.44

Acknowledged by Repairer
Signature:
Date: