



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105893

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/08/2021
Reference CC6/CTI19013653/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 9935M
Insured Veh. SKJ 2664M
Claim No. SNM19D203692C02
Policy No. DMPCSN3058571900
Accident Date 03/08/2019
Inspection Date 05/08/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI19013653/Upa3q2	
			Date: 20/08/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 2664M	Veh. Inspected	GBF 9935M	
Policy No.	DMPCSN3058571900	Coverage (\$)	0.00	
Claim No.	SNM19D203692C02	Excess (\$)	0.00	
Assign From		Assign Date	05/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZFA26300006E02928	Colour	GREY	
Odometer	89301 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	CONTINENTAL	6 mm	
L/H Front Tyre	195/60 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	195/60 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	195/60 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/08/2019	Inspection Date	05/08/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9935M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BACK DOOR N/S	TO REPAIR SEE LABOUR	1,850.00	-
1	REAR BACK DOOR INNER LOCK N/S	NOT NECESSARY	395.00	-
1	REAR BACK DOOR O/S	TO REPAIR SEE LABOUR	1,650.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,050.00	765.20
1	REAR BUMPER REINFORCEMENT	BENT	755.00	681.00
2	REAR BUMPER SIDE RETAINERS @\$65.00	NOT NECESSARY	130.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
1	REAR BUMPER REFLECTOR N/S	NOT NECESSARY	95.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	820.00	-
1	REAR DOOR 'MAXI' EMBLEM	NECESSARY	105.00	105.00
1	REAR 'DOBLO' EMBLEM	NECESSARY	102.00	102.00
1	REAR 'MULTIJET' EMBLEM	NECESSARY	85.00	85.00
	LESS 10% DISCOUNT		-	-179.82
			7,097.00	1,618.38
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BACK DOOR CORPORATE STICKER N/S (SN)	NECESSARY	680.00	360.00
1	SET REAR BACK DOOR CORPORATE STICKER O/S (SN)	NECESSARY	680.00	200.00
1	REAR 70KM/H STICKER & 6 PAX (SN)	NECESSARY	20.00	20.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			1,660.00	780.00
<u>LABOUR</u>				
	TO CHECK WIRING .		50.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX SEAT CUSHION ,UPHOLSTERY .		120.00	60.00
	TO SPRAY RUST PROOFING .	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR BACK DOOR N/S ,REAR BACK DOOR O/S AND REAR END PANEL .		880.00	550.00

Report Ref No. CC6/CTI19013653/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING .		1,200.00	800.00
			2,430.00	1,490.00
GRAND TOTAL			11,187.00	3,888.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CC6/CTI19013653/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 9935M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 9935M

RE-INSPECTION

