

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48/50
SINGAPORE 417883 TEL:67452063

not Authorized
Hale
5/8/19
4/5 ~~3100~~
4dy.

VEHICLE No:GBF 9935M

1PC	REAR BACK DOOR N/S	
1PC	REAR BACK DOOR INNER LOCK N/S	
1PC	REAR BACK DOOR O/S	
1PC	REAR BUMPER	765.20
1PC	REAR BUMPER REINFORCEMENT	681.00
2PCS	REAR BUMPER SIDE RETAINERS @65.00	
1SET	REAR BUMPER CLIPS	
1PC	REAR BUMPER REFLECTOR N/S	
1PC	REAR END PANEL	
1PC	REAR DOOR ~MAXI~ EMBLEM	
1PC	REAR ~DOBLO~ EMBLEM	
1PC	REAR ~MULTIJET~ EMBLEM	

2	\$1,850.00	x
11	\$395.00	x
2	\$1,650.00	x
10/12	\$1,050.00	—
Bent	\$755.00	—
11	\$130.00	x
11	\$60.00	✓
11	\$95.00	x
2	\$820.00	x
11	\$105.00	✓
11	\$102.00	✓
11	\$85.00	✓
	\$7,097.00	

10%

S.NETT	
1SET	REAR BACK DOOR CORPORATE STICKER N/S
1SET	REAR BACK DOOR CORPORATE STICKER O/S
1PC	REAR 70km/h STICKER & 629x
1SET	REAR BUMPER REVERSE SENSOR

11	\$680.00	360	S.N
11	\$680.00	200	S.N
11	\$20.00	✓	S.N
11	\$280.00	200	S.N

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO DISMANTLE & REFIX SEAT CUSHION ,UPHOLSTERY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	30
	\$80.00	50
	\$120.00	60
11	\$100.00	x
	\$880.00	550
	\$1,200.00	800
TOTAL	\$11,187.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1798.20
112
1618.38
3888.38