

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO.: SHA 279M

DATE 30/7/2019 10:18

MAKE :

MODEL : HYUNDAI i40

BRGD

Chiang

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender (LH) <i>X repair</i>			\$ 2,171.40	
	Rear Windscreen Moulding <i>X</i>			\$ 28.30	
	Front Door Glass (LH) <i>/</i>			\$ 228.20	
	Front Door Mirror Assy (LH) <i>/</i>			\$ 670.00	
	Front Door Trim Board (LH/RH) <i>X</i>			\$ 973.50	
	Front Fender (LH) <i>X repair</i>			\$ 663.00	
	Front Fender Shield (LH) <i>X</i>			\$ 174.90	
	Front Bumper Cover <i>X repair</i>			\$ 1,052.20	
	Front Bumper Bracket (LH) <i>X</i>			\$ 24.60	
	<i>Rear Door (LH) X repair</i>				
	SUB TOTAL			\$ 5,986.10	
	LESS 20%			\$ 1,197.22	
	DISCOUNTED TOTAL			\$ 4,788.88	
	Rear Fender Advertisement Logo (LH) <i>/</i>			\$ 100.00	Nett
	Rear Windscreen Sealant <i>X</i>			\$ 46.00	Nett
	Rear Door Advertisement Logo (LH) <i>/</i>			\$ 100.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>/</i>			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (LH) <i>/</i>			\$ 75.00	Nett
	Front Door Advertisement Logo (LH) <i>/</i>			\$ 100.00	Nett
	Front Fender Advertisement Logo(LH) <i>/</i>			\$ 100.00	Nett
				\$ 601.00	
	Labour Charge			<i>400</i>	
	Panel Beating			\$ 1,000.00	
	Spray Painting Charge			\$ 1,300.00	890
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	X
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X
	Remove/Refix Reverse Sensor			\$ 80.00	X
	TOTAL LABOUR			\$ 2,750.00	
	ESTIMATE TOTAL			\$ 8,139.88	
<i>Kahin (11/11/19)</i> <i>2/8/19 1515h</i> <i>3 Dps</i> <i>4/5</i> <i>Atk Repair p.hi</i> This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

