

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9464U****AAD1908-005***Not Whair**Reservy B4paint***P/P = \$6,608.45**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

02 AUG 2019

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 9464U**

JTDKB3FU303081198

TOYOTA

PRIUS

1.8.19

**AXA**

18/6/2019

**PART****LIST**

1	1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	B <sub>1</sub>	1,264.00	✓
2	1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, LH	\$	S <sub>1</sub>	316.90	X
3	1	RUN, FRONT DOOR GLASS, LH	\$	S <sub>1</sub>	151.20	X
4	1	WEATHERSTRIP, FRONT DOOR, LH	\$	S <sub>1</sub>	228.10	X
5	1	LOCK ASSY, FRONT DOOR W/MOTOR, LH	\$	N	592.70	X
6	1	HANDLE ASSY, FRONT DOOR, OUTSIDE LH	\$	CM	383.40	✓
7	1	FRONT DOOR OUTER MOULDING LH	\$	N <sub>1</sub>	188.60	✓
8	1	MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	S <sub>1</sub>	791.50	X
9	1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	S <sub>1</sub>	235.10	X
10	1	TAPE, BLACK OUT, NO.1 FRT LH	\$	N <sub>1</sub>	13.10	—
11	1	TAPE, BLACK OUT, NO.2 FRT LH	\$	N <sub>1</sub>	42.90	—
12	1	TAPE, BLACK OUT, NO.3 FRT LH	\$	N <sub>1</sub>	25.90	—
13	1	BOARD SUB-ASSY, FRONT DOOR TRIM, LH	\$	S <sub>1</sub>	737.90	} X
14	1	MOULDING ASSY, FRONT DOOR BELT, LH	\$	S <sub>1</sub>	90.50	
15	1	COVER, FRONT DOOR OUTSIDE HANDLE, LH	\$	S <sub>1</sub>	17.60	
16	1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	N	191.10	
17	1	WEATHERSTRIP, FRONT DOOR GLASS, INNER LH	\$	S <sub>1</sub>	136.30	
18	1	GLASS SUB-ASSY, FRONT DOOR, LH	\$	S <sub>1</sub>	514.80	} X
19	1	MOULDING, FRONT DOOR WINDOW FRAME, REAR LH	\$	S <sub>1</sub>	55.80	
20	1	LEFT SIDE VIEW MIRROR	\$	S <sub>1</sub>	1,275.52	
21	1	PANEL SUB-ASSY, REAR DOOR, LH	\$	B <sub>1</sub>	1,264.00	✓
22	1	WEATHERSTRIP, REAR DOOR, LH	\$	S <sub>1</sub>	177.60	} X
23	1	LOCK ASSY, REAR DOOR W/MOTOR, LH	\$	N	554.60	
24	1	MOULDING ASSY, REAR DOOR BELT, LH	\$	S <sub>1</sub>	111.90	
25	1	WEATHERSTRIP, REAR DOOR, NO.3 LH	\$	S <sub>1</sub>	35.70	
26	1	HINGE ASSY, REAR DOOR, LOWER LH	\$	N	74.50	
27	1	HINGE ASSY, REAR DOOR, UPPER LH	\$	N	84.60	} X
28	1	MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	S <sub>1</sub>	791.50	
29	1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	S <sub>1</sub>	204.20	

**Trans-cab Auto Services Pte Ltd****AAD1908-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9464U**

30	1	CHECK ASSY, REAR DOOR, LH	\$	Su	156.60	X
31	1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	Su	288.90	X
32	1	RUN, REAR DOOR GLASS, LH	\$	Su	120.90	X
33	1	TAPE, BLACK OUT, NO.1 REAR LH	\$	su	21.50	✓
34	1	TAPE, BLACK OUT, NO.2 REAR LH	\$	su	34.40	—
35	1	TAPE, BLACK OUT, NO.3 REAR LH	\$	su	15.10	✓
36	1	BOARD SUB-ASSY, REAR DOOR TRIM, LH	\$	Su	549.30	X
37	1	WIRE, FRONT DOOR, LH	\$	Su	454.10	X
38	1	WEATHERSTRIP, REAR DOOR GLASS, INNER LH	\$	Su	101.60	X
39	1	MOULDING, REAR DOOR WINDOW FRAME, FRONT LH	\$	Su	55.80	X
40	1	BAR SUB-ASSY, REAR DOOR WINDOW DIVISION, LH	\$	Su	110.70	X
41	1	GLASS, REAR DOOR QUARTER WINDOW, LH	\$	Su	106.60	X
42	1	GLASS SUB-ASSY, REAR DOOR, LH	\$	Su	405.30	X
43	1	PANEL SUB-ASSY, QUARTER, LH	\$	Bu Su	841.70	✓
44	1	LID ASSY, FUEL FILLER OPENING	\$	Su	167.30	X
45	1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	Bu Su	557.90	X
46	1	COVER, REAR COMBINATION LAMP, LH	\$	Su	55.00	X
47	1	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, LH	\$	Su	54.00	X
48	1	REAR TAILGATE	\$	su	1,547.27	X
49	1	REAR TAILGATE OUTER GARNISH	\$	EM	910.40	—
50	1	BOARD ASSY, BACK DOOR TRIM	\$	Su	254.40	}
51	1	BOARD, BACK DOOR TRIM	\$	Su	222.00	
52	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	Su	351.10	
53	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	Su	351.10	
54	1	COVER, DECK TRIM, REAR	\$	Su	125.00	
55	1	BOARD, REAR FLOOR, NO.1	\$	Su	511.80	
56	1	SPOILER SUB-ASSY, REAR	\$	Su	1,345.00	
57	1	GLASS, BACK WINDOW FIX	\$	Su	737.90	}
58	1	LENS AND BODY, REAR LAMP, LH	\$	Bu Su	548.40	
59	1	REAR BUMPER	\$	Su	458.60	X
60	1	REAR BUMPER UNDER COVER (BLACK)	\$	Su	552.60	X
61	1	REAR BUMPER SIDE LH	\$	Su	232.00	X
62	1	REAR BUMPER SIDE RETAINER LH	\$	Su	112.70	X
<b>TOTAL</b>			\$		<b>22,908.49</b>	
<b>25%</b>			\$		<b>5,727.12</b>	
			\$		<b>17,181.37</b>	

**Special Nett**

1	1	FRONT DOOR STICKER 'TRANS-CAB'	\$	su	80.00	60su
2	1	REAR DOOR STICKER "6555-3333"	\$	su	80.00	60su
3	1	REAR TAILGATE TOYOTA LOGO	\$	su	47.00	✓

**Trans-cab Auto Services Pte Ltd****AAD1908-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9464U**

4	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i>	52.90	<i>—</i>
5	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i>	53.50	<i>—</i>
6	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i>	80.00	<i>30mm</i>
7	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i>	80.00	<i>30mm</i>
8	1	REAR BUMPER PROTECTOR	\$	<i>SL</i>	100.00	<i>✓</i>
9	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	<i>✓</i>
10	1SET	CLIP (FOR DECK TRIM SIDE BOARD)	\$	<i>SL</i>	20.00	<i>✓</i>
11	1SET	PROTECTOR, BACK DOOR OUTSIDE GARNISH	\$	<i>SL</i>	14.30	<i>✓</i>
12	1SET	PROTECTOR, BACK DOOR OUTSIDE GARNISH, NO.2	\$	<i>SL</i>	14.30	<i>✓</i>
<b>TOTAL</b>			\$		<b>688.00</b>	

**TOTAL PARTS \$ 17,869.37****LABOUR**

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 *8801*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *9001*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *60901*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

To apply paint protection system (PPS) maintain and enhancement

\$ *nn* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 *X*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *1001*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

**Trans-cab Auto Services Pte Ltd****AAD1908-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9464U**

To transfer of front door fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear door fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear bumper fittings, attachment to facilitate bodywork repair.	\$	4 170.00	X
To transfer of rear tailgate fittings, attachment and perform water seepage test.	\$	4 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>14,720.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>32,589.37</b>	

**(PART-BY-PART) Repair Days**~~20 days~~

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: