



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBH7887X190727

**Estimate**

<b>Customer</b>		<b>Date:</b> 02-08-19
<b>Name:</b> AXA Insurance Singapore Pte Ltd		<b>Vehicle No:</b> GBH7887X
<b>Address:</b> Motor Claims Department		<b>Model/Make:</b> Nissan NV350
8 Shenton Way #27-01		Panel Van 2.5 5MT
AXA Tower Singapore 068811		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear: Tailgate <i>Body 1742</i>	\$ 2,101.40	<i>✓</i>
2	Tailgate "70 KM/H" Emblem <i>neu</i>	\$ 12.00	SN 105.00
3	Tailgate "8 Pax" Emblem <i>neu</i>	\$ 12.00	SN 105.00
4	Tailgate Weatherstrip <i>11</i>	\$ 188.50	N X
5	Tailgate Windscreen Glass Weatherstrip <i>NS</i>	\$ 142.50	N X
6	Tailgate Windscreen Glass Sealant <i>neu</i>	\$ 50.00	SN 405.00
7	Tailgate "Corporate" Advertisement & Artwork <i>neu</i>	\$ 300.00	SN 2505.00
8	Tail Lamp <i>11</i>	\$ 217.80	N X
9	Bumper <i>neu 690.60</i>	\$ 993.10	N X
10	Bumper Clip 1 Set <i>neu</i>	\$ 45.00	SN 15.00
11	Bumper Reverse Sensor <i>should</i>	\$ 220.00	SN 2005.00
12	Bumper Side Retainer 02 pcs (@ \$178.60 N) <i>11</i>	\$ 357.20	N X
13	End Panel Outer <i>Body</i>	\$ 508.80	<i>✓</i>
14	End Panel Inner <i>neu 502</i>	\$ 383.50	X
	To check all wiring & electrical component for proper function	\$ 50.00	30
	Remove and refix rear bumper reverse sensor	\$ 80.00	50
	Remove & reinstall Tailgate Glass to facilitate repairs	\$ 150.00	120
	Remove and refix rear tailgate components & wiper mechanism	\$ 100.00	60
	Remove and refix Seat Cushion Upholstery & Etc's ...	\$ 100.00	70 X
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 100.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc's	\$ 880.00	800
	To putty & spray painting & including touch up paint on accident affected	\$ 900.00	680

Total Parts & Labour of estimate for damaged vehicle \$ 7,891.80

Total amount in Lump Sum Basis for repaired vehicle

SDLS: \_\_\_\_\_



M/s Liu's Brother Auto Engrg Wks

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*not allowed*  
*neu*  
*\$ 3800*  
*S.dry.*

*2941.40*  
*502*  
*P-1470.7*  
*S.N 555*  
*L-1800*  
*3825*

*P-2941.40*  
*102*  
*P-2647.26*  
*S.N 555*  
*1800*  
*5002.26*