

CHARN'S CUSTOMCRAFT
1010 Bukit Merah Lane 3,
159724

Claim Reference:
Assessment number: 012315
Version: 1810
Date calculated: 03/08/2019 10:30 AM

Full Report
Registration: SE200M
Printed: 03/08/2019 10:30 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Sharon Lee	Currency:	SGD
Claim Reference:		Date of Incident:	
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	X5 (E70)
Sub Model:	X5 X DRIVE 35I
Model Sheet Number:	01 46 05
Registration:	SE200M
VIN number:	WBAZV42050L491657
Odometer:	

Model Specs

FROM 03/2011	BACKUP CAMERA SYSTEM	AIR CON AUTO 4-ZONES	WINDSCREEN RAIN SENS
DIP REAR VIEW MIRROR	CD AUTO CHANGER	HI-FI SPEAKER SYSTEM	XENON HEADLAMPS
LIGHT PACKAGE-APRON	LEATHER TRIM	ELEC/SEAT ADJ MEMORY	AUTO TAILGATE CONTR
THIRD SEAT ROW	ANTI-THEFT ALARM	DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON
3.0 LTR 225 KW	SPORT S-WHEEL LEATH	6-SPEED AUTOMATIC	RR LEVELLING SYSTEM
TYRES 255/55 HR 18	WHEELS 8.5J X 18 ALU	ROOF RACK ALU	ELEC PANORAMIC ROOF
INT MOULDINGS ALUMIN	USB/AUX CONNECTION	STEP PLATES ALU	BASECOAT CLEAR

CHARN'S CUSTOMCRAFT
1010 Bukit Merah Lane 3,
159724

Claim Reference:

Assessment number: 012315

Version: 1810

Date calculated: 03/08/2019 10:30 AM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Full Report

Registration: SE200M

Acknowledged by Repairer:

Signature:

Date:

Printed: 03/08/2019 10:30 AM

Taufik 97495749
WP' 8/8/19 @ 1240

** Resurvey new parts*

& Resurvey after repair

Taufik 11/11/19 @ 1240

02-03 days

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐

Underbody ☐



Labour

Code	Description	Time Base 12 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.50 ✓
51 71 978	R + R L/R WHEELARCH TRIM	XNN	4.0	15.00
63 14 625	R + R REAR REFLECTOR		1.0	3.75 ✓
2583	REAR BUMPER REPAIR		30.0*	112.50 ✓
	<i>cupp</i> R+R left tailamp		2.0	7.50
	Labour Cost	Hrs	WU	131.25
	Panel / Mechanical Labour	3.10	37.0	138.75
	Total of Labour			138.75

Paint

Paint Work

SYSTEM AZT

Time Basis 10WU/h

Code	Description - BASECOAT CLEAR	WU	Price SGD
	REAR BUMPER REPAIR PAINT PLASTIC	15.0	

CHARN'S CUSTOMCRAFT
1010 Bukit Merah Lane 3,
159724

Claim Reference:
Assessment number: 012315
Version: 1810
Date calculated: 03/08/2019 10:30 AM

Full Report
Registration: SE200M
Printed: 03/08/2019 10:30 AM

Paint Work **SYSTEM AZT** Time Basis 10WU/h
Code Description - BASECOAT CLEAR WU Price SGD

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER REPAIR PAINT PLASTIC	42.12

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		15.0	
Preparation Comp. Work Plastic	2.10	21.0	94.50
Total	10 WU/h	36.0	162.00
Total	12 WU/h	3.60	43.2
			162.00

Material Cost - Paint

	Price SGD
Repair Painting Plastic	42.12
Material-constant Plastic	18.10
Total	60.22

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2018-09-10/02	Price SGD
2611	L/R REFLECTOR	63 14 7 240 997			32.00
3671	L/R WHEELARCH TRIM	51 77 7 158 425			155.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				187.00
u: Used parts	Addition(+15.00%)				28.05
	Total				215.05

Supplementary - H/AR billamp cna ✓

433.45

\$1029.47

CHARN'S CUSTOMCRAFT
1010 Bukit Merah Lane 3,
159724

Claim Reference:

Assessment number: 012315

Version: 1810

Date calculated: 03/08/2019 10:30 AM

Full Report

Registration: SE200M

Printed: 03/08/2019 10:30 AM

Final Calculation

	SGD	SGD
Parts	187.00	
Addition(+15.00%)	28.05	
Total Parts		215.05
Labour Time Base 12 WU/h		
Total 37.0 WU X 45.00 SGD/h	138.75	
Total of Labour		138.75
Paint Work Time Base 10 WU/h		
Labour Cost 36.0 WU X 45.00 SGD/h	162.00	
Material Cost	60.22	
Total Paint Including Material		222.22
Repair Cost Excludes GST		576.02
GST (+7.0%)		40.32
Repair Cost Included GST		616.34

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS