

100000

INS. CASE OWNER:

CC3 / AIG1901 2670, T2 kb3

LKK:  
IDAC:

Surveyor: Zm/klh

DOI: ASSIGNMENT  
26/8/19

Date / Time: 5/8/19

Registered in Merimen: 5/8/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SUP 584  
Name of Insured : SM BAOQUN  
Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A : 1/5/19  
Is driver the owner? ( YES / NO ) Nature of Accident :

Claim No. : 105274648459  
Policy No. : 200504520-02  
Make / Model : MERCEDES  
Place of Accident : STAMPOKO RO

If NO, Driver Name / Age :  
Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO  
Insured Liability : % Final ? Yes / No

S13 52259



INSRS:  
WSP: performance  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP:  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP:  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP:  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	STAGE	DATE / PIC
<u>13/11/19</u> <u>klh/klh</u>	Non-Reporting 1r (1st)	
	Non-Reporting 1r (2nd)	
	Non-Reporting 1r (Final)	
	Notification 1r (if non-pickup)	
	Call OI:	
	After call 1r to OI:	<u>-13/8/19 klh/klh</u>
	Documentation Check List:	Handler Typist
	Notification 1r (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call 1r to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Project Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: ¥ 11 \$5,309.90 ( 3 days) Reduction: 30 % Email  Call

FINAL SETTLEMENT Date/Time: 12/11/19 Confirm with Caroline Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia: CO / REAR END TP

Repair Cost: (W/ASS) \$5,651.59

Loss of Rental (LOR): \$5 - ( - days)

Loss of Use (LOU): \$5 360 (520 x 3 days)

Loss of Income (LOI): \$5 - (5 - x - days)

LOR only  LOU only  LOR + LOU  LOR + LO  (Tick only one)

GIA/LTA Search \$5 2.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 6,043.59 Global Sum \$5: \_\_\_\_\_

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$5 6,043.59 Name 1: PERFORMANCE MOTORS LTD

Payee 2: (Strike if N.A.) \$5 Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$5 Name 3: \_\_\_\_\_

DUPLICATE

1) Claim status: TP Normal/Reject/Private Settle  
2) Report Format: TP  
3) Survey fee: 5320



# Performance Motors Limited

8 Siew Ewey Road, Singapore  
 Tel: 674 12219 (10 Lines) Fax: 674 12212  
 Toll-Free Number: 1800-2252487

115, Alameda Road  
 Siew Ewey Road, Singapore 115644  
 Singapore 115644  
 Tel: 6747770

270, Selegie Road  
 Siew Ewey Road, Singapore 346440  
 Singapore 346440  
 Fax: 6744711

115, Alameda Road  
 Siew Ewey Road, Singapore 115644  
 Singapore 115644  
 Tel: 6747770 (10 Lines)  
 Fax: 6747770 (10 Lines)

*28/8/2019*  
*1 Aug*  
*19/8/2018*  
*13/8*  
*19/8/2018*  
*1 Aug*  
*19/8/2018*  


GST REG. NO : M2 - 0020081 - X

07 AUG 2019

## ESTIMATE

**PLEASE CONSULTANTS hence notify the Repairer of the following:**

- To display damaged parts on survey 1 of 4
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No third party involvement

Estimate No. : b1 52210  
 Date Estimated : 02/08/2019  
 Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -  
**Lim Oon Cheng**  
 Bukit Tunggal Road  
 Singapore 309715

- ACCOUNT -  
 Cash Sales - Service  
 Singapore  
 Signature:  
 Date:

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5225G	BE46166	10/04/2018	630i GT	0

DESCRIPTION	VALUE
Replace Rear bumper and remove attachment etc include knock on accident area	850 1,275.00 ✓
Spray painting rear bumper	134 1,038.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00 ✓
Sundries <i>N/A</i>	80.00 ✓
<b>Total Labour 1:</b>	<b>2,570.00</b>

DESCRIPTION	QTY	PRIC	VALUE
Abrasion gus	1	5.50	5.50 ✓
Abrasion gus	1	5.50	5.50 ✓
REAR BUMPER BOTTOM REINFORCEMENT	1	84.75	84.75 ✓
REAR BUMPER CENTRE GUIDE	1	73.80	73.80 ✓
REAR BUMPER TOWING EYE FLAP (M)	1	87.25	87.25 ✓
REAR BUMPER TRIM PANEL PAINTED (M)	1	455.35	455.35 ✓
CLAIMS (REAR BUMPER PANEL PRIMED) (M) Settlement	1	1,821.30	1,821.30 ✓
DECOUPLING RING PDC TORQUE CONVERTER	6	5.05	30.30 ✓
ULTRASONIC SENSOR MINERALWEISS(WA96)	4	368.80	1,475.20 ✓
<b>Total Parts :</b>			<b>4,038.95</b>

Authorised Date: *02/08/2019* Time: *11:14*

RESURVEY PARTS PHOTO BY SURVEYOR (Yes/No) PSL Yes/No

Surveyor's E-mail: *jeffrey@kkh.com*

No. of Working Days Recommend: *03 days*

Labour 1	:	2,570.00
Parts	:	4,038.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	462.63
<b>Grand Total</b>	:	<b>7,071.58</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
 \*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
 Co. Reg. No. 19740155MW GST Reg. No. M2-002081-X



## Final Report

Estimate No : **b1 52210**  
 Date Estimated : **02/08/2019**  
 Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Lim Oon Cheng**

**Bukit Tunggal Road**  
**Singapore 309715**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**30.00 78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5225G	WBAJV22000BE461	10/04/2018	630i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including remove attachments to facilitate repairs.	850.00		850.00
To respray rear bumper	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER	934.50	1.00		934.50
REAR BUMPER BOTTOM REINFORCEMENT	84.75	1.00		84.75
REAR BUMPER TRIM PANEL PAINTED (M)	455.35	1.00		455.35
REAR BUMPER PANEL PRIMED (M)	1,821.30	1.00		1,821.30

# SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	3,295.90
Total Labour & Parts :	5,309.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,309.90
GST @7%:	371.69
<b>Grand Total :</b>	<b>5,681.59</b>

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559A, GST Reg. No. M2-002001-4



## Final Report

Estimate No. : **b1 52210**  
Date Estimated : **02/08/2019**  
Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Lim Oon Cheng**

**Bukit Tunggal Road**  
**Singapore 309715**

30.00

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5225G	WBAJV22000BE461	10/04/2018	630i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including remove attachments to facilitate repairs.	850.00		850.00
To respray rear bumper.	1,038.00	934	1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER	934.50	1.00		934.50
REAR BUMPER BOTTOM REINFORCEMENT	84.75	1.00		84.75
REAR BUMPER TRIM PANEL PAINTED (M)	455.35	1.00		455.35
REAR BUMPER PANEL PRIMED (M)	1,821.30	1.00		1,821.30

### # SUPPLEMENTARY ITEMS

Total Labour :	2,118.00
Total Parts :	3,295.90
Total Labour & Parts :	5,413.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,413.90
GST @7%:	378.97
<b>Grand Total :</b>	<b>5,792.87</b>

5309.9

3 days

# Performance Motors Limited

A member of the Sime Darby Group  
Co-Reg No. 107401159M. GST Reg No. M2-0020091-X



## Supplementary

Estimate No. : b1 52210  
Date Estimated : 02/08/2019  
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -  
Lim Oon Cheng

Bukit Tunggul Road

Singapore 309715

30.00

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5225G	WBAJV22000BE461	10/04/2018	630i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER	934.50	1.00		934.50 <i>bt</i>

### # SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	934.50
Total Labour & Parts :	934.50

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Tuesday, 12 November 2019 5:15 PM  
**To:** PBSP  
**Cc:** Admin A  
**Subject:** RE: PAYMENT REMINDER - SLZ5225G & SLP58H ON 01/08/2019

WITHOUT PREJUDICE

Dear Sir/Madam,

The above matter refers.

We confirm settlement as per your LOD/Payment breakdown for **\$6,043.59(all in)**.

We will be proceeding to do the necessary.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,  
Khanchna | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Tuesday, 5 November 2019 2:47 PM  
**To:** CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Cc:** Khanchna (LKK Auto) <khanchna@lkkauto.com>  
**Subject:** PAYMENT REMINDER - SLZ5225G & SLP58H ON 01/08/2019

PAYMENT REMINDER

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607196R)

 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

 To : AIG Asia Pacific Insurance Pte. Ltd.  
 Attn : MdNoor, Norsiah

 Your Ref : 0052346984SG  
 Our Ref : CC3/AIG19013670/T1KB3  
 Date : 15 Oct 2019
**"WITHOUT PREJUDICE"**
**ACCIDENT INVOLVING SLP58H & SLZ5225G ON 01/08/2019**

Refer to the above accident.

The accident occurred when Insured rear ended third party. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

 On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SLP58H) and third party claimant (vehicle no. SLZ5225G).

Summary of offer made to workshop Performance Motors Limited is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 8,071.49	\$ 5,681.59
Loss of Use (\$120 x 3 days)	\$ 360.00	\$ 360.00 (\$120 x 3 days)
LTA Search Fee	\$ 2.00	\$ 2.00
<b>Total</b>	<b>\$ 8,433.49?</b>	<b>6,043.59?</b>

 Amount of claim at **Liability 100%**                      \$ 6,043.59?

\*\* 3 days recommendation for repair

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

 Regards,  
 Khanchna Pothuraj  
 LKK Auto Consultants Pte Ltd



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19013670/kb3

13 AUGUST 2019

**SU BAOGUI**  
18 LEONIE HILL ROAD  
#35-06  
SINGAPORE 239199

Dear Sir/Madam,

**ACCIDENT INVOLVING SLP58H & SLZ5225G ALONG/AT STAMFORD ROAD ON  
01/08/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLZ5225G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

**KHANCHNA**  
Case Handler  
DID: 6841-2360  
FAX: 6741 4108  
Email: [khanchna@lkkauto.com](mailto:khanchna@lkkauto.com)

*c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)*



## Courtesy Car Form SML 6240S

Courtesy Car Regn No: ~~SLZ 5225G~~

Extended by: Chuc Kee Sin

Date: 28.08.2019

Customer Name Lim con Cheng

NRIC / Passport /  
Driving License No. (if  
different) S1436066B



Car Regn No. / Model SLZ 5225G

Address Bukit Tinggi road

Contact No. 96399122

Delivered to Customer

Returned to Performance Motors Limited



Interior Check

Interior Check

Glove Compartment Centre Console  
In-Vehicle Unit (IU) Side Pockets (All Doors)  
Front Seats Rear Pockets Rear Boot  
Date and Time Out 28.08.19  
Mileage Out 1570km  
Fuel Level E L H I I I F  
Checked By [Signature]  
Customer Signature [Signature]

Glove Compartment Centre Console  
In-Vehicle Unit (IU) Side Pockets (All Doors)  
Front Seats Rear Pockets Rear Boot  
Date and Time Returned 31/9/2019 @ 12.05hr  
Mileage Returned 1740km  
Fuel Level E L H I I I F  
Checked By [Signature]  
Customer Signature [Signature]

Terms & Conditions

\* less of use claim will be under PML

I, the undersigned, confirm as follows:

- I hold a valid driving license, as declared herein, for the operation of the above loan car described above ("the Car").
- I understand that the Car is being provided to me, free of charge and on a goodwill basis, for a period not exceeding the duration that my own car remains in the workshop for repairing/repairing works or a period of not exceeding the duration that you agree to let me have possession of the car for testing, demonstration or promotional purposes, or any other purpose that you may decide ("the loan period"). I further acknowledge that you are fully entitled to request the return of the Car at any time without assigning any reason whatsoever, irrespective of whether the repairing/repairing works in respect of my own car are completed or not or whether the purpose for which the Car was provided to me has been accomplished or completed.
- I have checked and accepted the Car in the state and condition stated above and agree to return it to you in the same condition, failing which, I agree to pay you all costs and expenses necessary to restore the Car to its original state and condition.
- I agree that I shall, at all times, exercise reasonable care when using the Car and shall further ensure that all my authorized drivers observe this same duty and standard of care.
- I undertake not to:
  - Drive or operate or permit the Car to be driven or operated outside Singapore;
  - Permit the Car to be driven or operated by a person who does not possess a valid driving license;
  - Smoke or permit any smoking in the Car;
  - Do or permit to be done anything whereby the insurance policies over the Car may become void or voidable or whereby the rate of premium may be increased or whereby any insurance claim arising out of the use or operation of the Car during the loan period may be jeopardized or affected in any way;
  - Make any representation that the car is owned by any person other than Performance Motors Limited;
  - Hold you responsible for any indirect or special or economic loss that I may suffer from the use or possession of the car to the furthest extent permitted by law.
- I shall be responsible for and shall promptly pay for and fully indemnify you against:
  - All damage or loss howsoever caused to the Car during the loan period;
  - All traffic violations, fines and penalties imposed on the Car for whatsoever reason in respect of or in connection with the use or operation of the Car during the loan period; and
  - All claims, damages, losses, (increased insurance premiums, insurance claim excess amounts (if at least S\$ 2000), costs and expenses (including legal costs) on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the Car or the use or operation of the car during the loan period.
- I have read and fully understand the terms and conditions herein, and have been notified of the current daily charges applicable to the Car as follows:
 

Mileage	Charge per day
1/2 Series & X1	\$250
3/4 Series, 24 & X3/X4	\$300
5 Series & X5	\$400
6/7 Series & X6	\$500
- In the event that I shall fail to return the Car to you promptly upon your request, I agree to pay such daily rental charges for the Car that you may deem fit to impose for each day or part thereof that the Car remains in my possession, without prejudice to your other legal rights.

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-2688)  
www.pml.com.sg

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales  
6319 0527  
Fax 6479 8624

896 Dunearn Road  
#01-01  
Sime Darby Centre  
Singapore 589472  
Tel Sales 6319 0500  
Tel AfterSales  
6319 0555  
Fax 6469 1709

280  
Kemping Arang Rd  
East Coast Centre  
Singapore 436180  
Tel AfterSales  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No.

\* [Signature]

## Print Received Message

This mail is associated with :

**\*SLZ5225G (0052346984SG)**  
**[SLP58H]**  
TP  
LIM OON CHENG  
Aug 1 2019 4:00PM  
[SU BAOGUI]  
Performance Motors Limited

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 12/11/2019 10:18 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$6043.59) - SLZ5225G - Claim Handler: MdNoor, Norsiah

Approved:6043.59.

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Aug 2019 <a href="#">Edit Reg</a>		28 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,309.90</b> <a href="#">Edit Estimates</a>	<b>S\$5,309.90</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float:right">[Created by adjuster]</span>									
Insured:	<b>SU BAOGUI</b> , ID: G1607885P, Tel: +6599999999								
Main Claimant:	<b>LIM OON CHENG</b> , ID: S1436066B								
Vehicle Reg. No.:	<b>SLZ5225G</b>	Date of Loss:	01/08/2019 16:00 - :59 [15 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 0052346984SG</b>	Policy/Cover Note No.:	2100509283 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLP58H</b>	Policy No. (Claimant):	B29078923SMP						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 16/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float:right"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG_EXPRESS (12/11/2019): Alert - Adj Mandate Approved (S\$6043.59) - SLZ5225G - Claim Handler: MdNoor, Nor...									
<b>ALL ASSOCIATED TASKS</b> <span style="float:right"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLZ5225G (0052346984SG)  
 [SLP58H]  
 TP  
 LIM OON CHENG  
 Aug 1 2019 4:00PM  
 [SU BAOGUI]  
 Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>	
<b>Letters/Correspondences</b>														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	{Draft}	Third Party Express Settlement - Payment Breakdown											Edit			
<b>Assessment Reports</b>														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	15/10/19 15:25	Adjuster Immediate Advice											Load HTM			
No	Finalized On	ATG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	07/08/19 14:13	Accident Statement From: SC - Reg. No: SLP58H, Claimant: SU BAOGUI											Load HTM			
<b>Photos/Images</b>														3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	15/10/19 15:01	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>		
2	15/10/19 15:01	Chassis Number											Load JPG	<input checked="" type="checkbox"/>		
3	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
4	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
5	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
6	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
7	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
8	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
9	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
10	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
11	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
12	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
13	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
14	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
15	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
16	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
17	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
18	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
19	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
20	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
21	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
22	15/10/19 15:01	General View											Load JPG	<input checked="" type="checkbox"/>		
23	15/10/19 15:01	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
24	15/10/19 15:01	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
25	15/10/19 15:01	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
26	15/10/19 15:01	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
27	15/10/19 15:01	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>														1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	05/08/19 17:56	TP GIA REPORT											Load PDF			
2	05/08/19 17:56	TP ESTIMATE.											Load PDF			
3	29/08/19 17:29	TP ESTIMATE- MARKED											Load PDF			
4	15/10/19 15:08	TP LOD, FINAL INVOICE, ATA, LTA SEARCH											Load PDF			
5	13/11/19 17:17	LETTER TO OI											Load PDF			
6	15/11/19 08:44	WORKSHOP INVOICE											Load PDF			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
7	15/11/19 08:44	<b>AUTHORISATION TO ACT FORM</b>	 Load PDF	
8	15/11/19 08:44	<b>Release Voucher</b>	 Load PDF	
9	15/11/19 08:44	<b>GIA SEARCH</b>	 Load PDF	
10	15/11/19 08:44	<b>LOD</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLP58H (Insd veh)	Model:	BMW 630I 2.0 GT LED NAV (A)
	SLZ5225G (TP veh)		
Date of Accident:	01/08/2019		

Global Sum Settlement	: [ ] Yes	[ X ] No	
Repair Estimate	: \$	8,071.49	
Final Repair Cost	: \$	5,681.59	
Loss of Use	: \$	360.00	3.00 days at \$120.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	6,043.59	
Is Third Party Workshop GIA Registered? [ X ] YES [ ] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No- BOLA Scenario No: _27_	
BOLA Liability: ____100____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	6,043.59
2)		: \$	
3)		: \$	

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

15 Nov  
2019

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19013670/T1KB3Q2

Date: 15/11/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100509283  
 Claimant  
 Vehicle No : SLZ5225G Insured Vehicle No : SLP58H  
 Date of Loss: 01/08/2019 Nature of Claim: TP Claim No: 0052346984SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLZ5225G**  
 Make & Model: BMW 630I, 2.0 GT LED NAV (A) Engine No: 18285247B48B20B  
 Reg. Date: 10/04/2018 (Man. Year: 2018) Chassis No: WBAJV22000BE46166  
 Colour: White Odometer: 11933 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 275/40 R19 Rear Tyre Size: 275/40 R19  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,053.45	3,375.90	1,677.55	33.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,543.45</b>	<b>5,309.90</b>	<b>2,233.55</b>	<b>29.61</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>528.04</b>	<b>371.69</b>	<b>156.35</b>	<b>29.61</b>
<b>Nett Amount (S\$)</b>	<b>8,071.49</b>	<b>5,681.59</b>	<b>2,389.90</b>	<b>29.61</b>
<b>+ Loss of Use (3.0 x S\$120.00/day) (S\$)</b>		<b>360.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>6,043.59</b>		

## INSPECTION

Date of Assignment: 28/08/2019  
 Date Inspected: 28/08/2019 Inspected At: Performance Motors Limited  
 (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS	
2	1		*ABRASION GUA	Not Necessary	5.50 FS	*- FS	
3	1		*ABRASION GUA	Not Necessary	5.50 FS	*- FS	
4	1		*REAR BUMPER BOTTOM REINFORCEMENT	Deformed	84.75 FS	*84.75 FS	
5	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	73.80 FS	*- FS	
6	1		*REAR BUMPER TOWING EYE FLAP (M)	Not Necessary	87.25 FS	*- FS	
7	1		*REAR BUMPER TRIM PAEL PAINTED (M)	Deformed	455.35 FS	*455.35 FS	
8	1		*REAR BUMPER PANEL PRIMED (M)	Deformed	1,821.30 FS	*1,821.30 FS	
9	6		*DECOUPLING RING PDC TORQUE CONVERTER	Not Necessary	30.30 FS	*- FS	
10	4		*ULTRASONIC SENSOR MINERAL WEISS (WA96)	Not Necessary	1,475.20 FS	*- FS	
11	1		*REAR BUMPER CARRIER	Bent	934.50 FS	*934.50 FS	
					<b>Total Parts (\$\$)</b>	<b>5,053.45</b>	<b>3,375.90</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT AREA	New	1,275.00	850.00
2	SPRAY PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,490.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >