

BMW Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



*28/8/2019  
minorly any  
& repair*

*Due Date  
13/8*

*19/8/2019 working  
any  
& repair*

GST REG. NO : M2 - 0020081 - X

02 AUG 2019

## ESTIMATE

**Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed

Supplementary item(s) surveyed and is subject to final approval from Insurance Company

**40000**

Cash Sales - Service

Singapore

Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Estimate No. : **b1 52210**  
Date Estimated : **02/08/2019**  
Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Lim Oon Cheng**  
**Bukit Tunggul Road**  
**Singapore 309715**

**- ACCOUNT**  
**Cash Sales - Service**  
**Singapore**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5225G	BE46166	10/04/2018	630i GT	0

DESCRIPTION	VALUE
Replace Rear bumper and remove attachment etc include knock on accident area	850 1,275.00
Spray painting rear bumper	1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
<b>Total Labour 1:</b>	<b>2,570.00</b>

DESCRIPTION	QTY	PRIC	VALUE
Abrasion gua	1	5.50	? 5.50
Abrasion gua	1	5.50	? 5.50
REAR BUMPER BOTTOM REINFORCEMENT	1	84.75	? 84.75
REAR BUMPER CENTRE GUIDE	1	73.80	? 73.80
REAR BUMPER TOWING EYE FLAP (M)	1	87.25	? 87.25
REAR BUMPER TRIM PANEL PAINTED (M)	1	455.35	455.35
REAR BUMPER PANEL PRIME (M)	1	1,821.30	1,821.30
DECOUPLING RING PDC TORQUE CONVERTER	6	5.05	30.30
ULTRASONIC SENSOR MINERALWEISS(WA96)	4	368.80	? 1,475.20
<b>Total Parts :</b>			<b>4,038.95</b>

Claims On Rear Bumper Panel (PML) - Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 2 Excess S\$ \_\_\_\_\_

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 67445114 Authorised Yes/No \_\_\_\_\_

Authorised Date WP Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PML Yes/No

Surveyor's E-mail TanJiah@kkauto.com

No. of Working Days Recommend 03 days

Labour 1	:	2,570.00
Parts	:	4,038.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	462.63
<b>Grand Total</b>	<b>:</b>	<b>7,071.58</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***