

Surveyor:

Steve

DOI:

ASSIGNMENT

2/8/19

Date / Time:

Registered in Merimen:

5/8/2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMN 701H

Claim No.:

Name of Insured:

Sme Auto Care Works

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

25/7/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

E2 134T



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

E2 134T - 03/08/2019 10:00 AM - 7/11/19

SMN 701H - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : N1L

If NO or B 28, Ass. Lia:

Repair Cost: W/194

SS

21224.49

Loss of Rental (LOR):

SS

days)

Loss of Use (LOU):

SS

960 - W (580) x 2 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2-00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 600.00

Total:

SS

22236.09

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

22236.09

Name 1:

Performance Motors Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

ASS. PED. BY:

Steve

REF:

36721EW

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % - 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

EQ 234T

Yr Regn:

25/2/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X1

c.c

1499

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

4560

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WBAJG123503677210.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

925/55 R17

R:

A

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/7/19

D.O.I.

7/8/19

Survey held at

Performance Mot

Des. of Damages: (Frt) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-14SK
	PIP \$ 19882.70 (Red \$ 9033.49 31%).
	12 F.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

C/W/2

-

TOTAL

Report Format: _____

Lump Sum / L.B. / F

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

302, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

189, Tampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



Steve (LKK)

W/L P/P 7/8/19, 4.15pm
Ray Gek Sky
10 days

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52154
Date Estimated : 30/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chong Joon Meng Edwin (Zhong JunMin)
50 Telok Blangah Drive
#08-104

Singapore 100050

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

India

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EQ234T	3G77210	25/02/2019	X1 sDrive18i	0

DESCRIPTION

VALUE

To replace front bumper, fender right, support right and attachments. 850

3400.2125 4,250.00

Painting front bumper, fender right and bonnet.

2898 3,221.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To replace right headlight.

408 481.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (2x)

451 1,062.00

To remove and install front suspension for inspection and replace damaged parts. 750

2256 2,655.00

To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function. 750

750 885.00

To carry out body cavity preservation. (Per panel).

100 118.00

Sundries. Nil

✓ 150.00

Total Labour 1: 13,093.00

DESCRIPTION

QTY PRIC

VALUE

Threaded plu

1 6.60

6.60

ASA BOLT M12X45

3 8.15

24

EXPANDING RIVET

8 0.75

ASA SCREW SELF TAPPING 10X40

2 6.45

ASA SCREW SELF TAPPING M12X1.5X60

1 7.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63448772

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52154
Date Estimated : 30/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EQ234T	3G77210	25/02/2019	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
FRT AXLE SUPPORT	1	1,452.65	1,452.65
RH WISHBONE WITH RUBBER MOUNTING	1	290.85	290.85
RH WISHBONE BRACKET W/RUBBER MOUNT	1	191.05	191.05
SPHERICAL COLLAR SCREW M12X1.25X45	4	7.70	30.80
SPHERICAL COLLAR SCREW M12X1.25X45	4	7.70	30.80
WHEEL HUB WITH BEARING	1	465.75	465.75
RH SWIVEL BEARING CAMBER CORRECTION	1	545.95	545.95
FRT SWING SUPPORT	1	99.70	99.70
HEX BOLT WITH WASHER M8X30	4	5.40	21.60
FRT RH SPRING STRUT	1	511.55	511.55
FRT SUPPORT BEARING	1	222.65	222.65
Exch. steeri	1	3,811.95	3,811.95
RH TIE ROD	1	273.50	273.50
ASA SCREW SELF TAPPING M12X1.5X30	12	5.75	69.00
HEX NUT WITH FLANGE	1	2.35	2.35
HEXAGON NUT WITH COLLAR	2	2.25	4.50
COLLAR BOLT WITH COMPRESSION SPRING	12	18.15	217.80
ALLOY RIM 7.5X17 V SPK 560	1	814.00	814.00
RH BRACKET FOR GAS SPRING	1	37.80	37.80
RH WHEEL HOUSING STRUT EXTENSION	1	147.10	147.10
FRT RH SIDE PANEL	1	664.00	664.00
IMPACT ABSORBER TOP	1	43.70	43.70
FRT BUMPER TOP CARRIER	1	373.95	373.95
FRT RH TOP MOUNTING SIDE PANEL	1	19.20	19.20
FRT BUMPER RH INSERT	1	18.25	18.25
FRT BUMPER PANEL PRIMED (PDC/PMA)	1	734.70	734.70
FRT BUMPER PANEL LOWER SECTION (PDC)	1	281.80	281.80
BMW PLAQUE WITH ADHESIVE FILM	1	71.25	71.25
RH HEADLIGHT SUPPORT ARM	1	133.05	133.05
FRT RH WHEEL ARCH COVER	1	142.55	142.55
CLIP	8	1.15	9.20
FRT RH WHEEL ARCH TRIM	1	151.00	151.00
RH HEADLIGHT LED TECHNOLOGY	1	2,670.85	2,670.85

Total Parts : 14,342.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Labour 1	:	13,093.00
Parts	:	14,342.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,920.49
Grand Total	:	29,355.99

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 191401559W, GST Reg. No. M2-0020081-K



Supplementary

Estimate No. : b1 52154
Date Estimated : 30/07/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Chong Joon Meng Edwin (Zhong JunMing Edw
50 Telok Blangah Drive
#08-104

Singapore 100050

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EQ234T	3G77210	25/02/2019	X1 sDrive18i	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

# To tow accident vehicle to PML workshop.	195.00	0	195.00
--	--------	---	--------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SQUARE NUT M12X1.5 / ncc	6.40	1	0	6.40
# ASA BOLT M12X1.5 / ncc	9.15	1	0	9.15
# ASA BOLT M10X55 / ncc	9.05	1	0	9.05
# FRT RH CARRIER / DD	481.90	1	0	481.90
# PIPE CLAMP / ncc	12.65	1	0	12.65
# HEX NUT WITH FLANGE M10 / ncc	2.10	1	0	2.10
# COMBINATION NUT M14X1.5 / ncc	5.55	2	0	11.10
# RH CROSS SUPPORT SIDE PANEL / DD	67.60	1	0	67.60
# RH OPEN GRID (BASIC PDC) / DD	111.45	1	0	111.45
# RH SUPPORT / DD	138.75	1	0	138.75
# EXPANDING RIVET BLACK / ncc	1.35	20	0	27.00
# WINDSHIELD CLEANING CONTAINER / CR4	129.60	1	0	129.60
# RH FOGLAMP / DR	276.25	1	0	276.25
# (S/L) WASHER ADDITIVES (250ML) / ncc	3.60	2	0	7.20

SUPPLEMENTARY ITEMS

Total Labour :	195.00
Total Parts :	1,290.20
Total Labour & Parts :	1,485.20

25920.70

Performance Motors Limited

A member of the Time Darryl Group
Co. Reg No. 197491559W, GST Reg No. M2-0020081-X



Final Report

Estimate No. : **b1 52154**
Date Estimated : **30/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Chong Joon Meng Edwin (Zhong JunMing Edw
50 Telok Blangah Drive
#08-104

Singapore 100050

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EQ234T	3G77210	25/02/2019	X1 sDrive18i	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front right fender, front right wheel housing strut extension, right open grid, right support, front right wheel arch trim and cover etc including to remove and install body parts in order to carry out painting job.	3,400.00	0	3,400.00 /
To respray front bumper, front bonnet and front right fender.	2,898.00	0	2,898.00 /
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00 /
To replace right Technology LED headlight and right fog lamp	408.00	0	408.00 /
To replace front right wheel rim including balancing.	80.00	0	80.00 /
To check steering geometry and conduct wheel alignment according to BMW Specification	451.00	0	451.00 /
To remove and install front suspension for inspection and replace damaged parts.	2,256.00	0	2,256.00 /
To carry out body cavity preservation.	100.00	0	100.00 /
Sundries.	150.00	0	150.00 /
# To tow accident vehicle to PML workshop.	195.00	0	195.00 /

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ASA SCREW SELF TAPPING 10X40	6.45	2	0	12.90 /
# SQUARE NUT M12X1.5	6.40	1	0	6.40 /
# ASA BOLT M12X1.5	9.15	1	0	9.15 /
# ASA BOLT M10X55	9.05	1	0	9.05 /
RH WISHBONE WITH RUBBER MOUNTING	290.85	1	0	290.85 /
RH WISHBONE BRACKET W/RUBBER MOUNT	191.05	1	0	191.05 /
SPHERICAL COLLAR SCREW M12X1.25X45	7.70	4	0	30.80 /
WHEEL HUB WITH BEARING	508.80	1	0	508.80 /
# FRT RH CARRIER	481.90	1	0	481.90 /

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-K



Final Report

HEX BOLT WITH WASHER M8X30	5.40	5	0	27.00 ✓	
FRT RH SPRING STRUT	511.55	1	0	511.55 ✓	
FRT SUPPORT BEARING	222.65	1	0	222.65 ✓	
# PIPE CLAMP	12.65	1	0	12.65 ✓	Supp
RH TIE ROD	273.50	1	0	273.50 ✓	
# HEX NUT WITH FLANGE M10	2.10	1	0	2.10 ✓	Supp
# COMBINATION NUT M14X1.5	5.55	2	0	11.10 ✓	Supp
ASA SCREW SELF TAPPING M12X1.5X30	5.75	2	0	11.50 ✓	
HEX NUT WITH FLANGE	2.35	1	0	2.35 ✓	
COLLAR BOLT WITH COMPRESSION SPRING	18.15	2	0	36.30 ✓	
ALLOY RIM 7.5X17 V SPK 560	814.00	1	0	814.00 ✓	
# RH CROSS SUPPORT SIDE PANEL	67.60	1	0	67.60 ✓	Supp
RH WHEEL HOUSING STRUT EXTENSION	147.10	1	0	147.10 ✓	
FRT RH SIDE PANEL	664.00	1	0	664.00 ✓	
IMPACT ABSORBER TOP	43.70	1	0	43.70 ✓	
FRT BUMPER TOP CARRIER	373.95	1	0	373.95 ✓	
FRT RH TOP MOUNTING SIDE PANEL	19.20	1	0	19.20 ✓	
FRT BUMPER RH INSERT	18.25	1	0	18.25 ✓	
FRT BUMPER PANEL PRIMED (PDC/PMA)	854.55	1	0	854.55 ✓	
# RH OPEN GRID (BASIC PDC)	111.45	1	0	111.45 ✓	Supp
FRT BUMPER PANEL LOWER SECTION (PDC)	281.80	1	0	281.80 ✓	
BMW PLAQUE WITH ADHESIVE FILM	71.25	1	0	71.25 ✓	
RH HEADLIGHT SUPPORT ARM	133.05	1	0	133.05 ✓	
# RH SUPPORT	138.75	1	0	138.75 ✓	Supp
FRT RH WHEEL ARCH COVER	142.55	1	0	142.55 ✓	
# EXPANDING RIVET BLACK	1.35	20	0	27.00 ✓	Supp
FRT RH WHEEL ARCH TRIM	151.00	1	0	151.00 ✓	
# WINDSHIELD CLEANING CONTAINER	129.60	1	0	129.60 ✓	Supp
RH HEADLIGHT LED TECHNOLOGY	2,670.85	1	0	2,670.85 ✓	
# RH FOGLAMP	276.25	1	0	276.25 ✓	Supp
# (S/L) WASHER ADDITIVES (250ML)	3.60	2	0	7.20 ✓	Supp
#					
#					

SUPPLEMENTARY ITEMS

Total Labour :	10,088.00
Total Parts :	9,794.70
Total Repair Costs less Excess:	19,882.70 ✓
GST @7%:	1,391.79
Grand Total :	21,274.49

CO.	MO. PART	DATE	TIME
TAX TO PAYING	Steve	13/5/19	10
PAY TO TAXING	LFR		
TOTAL			
CONFIRMED			
DATE			
SIGNATURE			

LOSS OF USE = \$80 X 12 DAYS
LTA SEARCH FEE - \$2.00

Hsiao Tong

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Vehicle No : _____
 Chassis No : _____
 CSA Name : _____
 Model Year : _____

Quotation No : 0000529990
 Date : 16/08/2019
 Time : 11:17:00
 Page : 1
 Partsman : p13tansb
 Del Doc : 003786905

S/N	PART NUMBER	DESCRIPTION	CT	STK	POC	ISS.	SELLING	DIS	NET
***	*****	*****	**	***	***	***	*****	*****	*****
		5g77210							
1	51117453980	RH OPEN GRID (BASI	—	P	—	1	111.45	ant	111.45
2	51777171004	EXPANDING RIVET BL	—	P	—	20	1.35	all	27.00
3	61667403903	WINDSHIELD CLEANIN	—	P	—	1	129.60	all	129.60
4	41007427128	RH CROSS SUPPORT S	—	P	—	1	67.60	bt	67.60
5	51647342502	RH HEADLIGHT SUPPO	—	P	—	1	133.05	bt	133.05
6	51647426634	RH SUPPORT	—	P	—	1	138.75	bt	138.75
7	63177238788	RH FOGLAMP	—	P	—	1	276.25	ant	276.25

Signature
 16/8

CSA Signature : _____
 Date : _____
 Time : _____

Parts Total : 883.70
 Labour Charges : _____

Sub Total : _____
 Add 7% GST : _____

Customer's Name : _____
 or Contact Person : _____

TOTAL AMOUNT : _____

- Note: (1) The above quotation is based on visual inspection only and may change based on further checks.
 (2) The validity of this quotation is 14 days from the above date.
 (3) Parts are subject to availability.
 (4) Any prices change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for us to proceed with the job on the understanding that prior approval will be obtained from you before we carry out any further repair or replacement of parts that will extend the total charges beyond the sum stated.

Ion No : 52154
 Ion Date : 30/07/2019
 I No : EQ234T
 I No : 3677210

Page No : 1
Customer No : Z38
Customer Name: AXA Insurance Pte Ltd
Model Ref. : X1 sDrive18i

MBER	DESCRIPTION	QTY	UNIT PRICE	DISC%	NET PRICE	SCH
9338	Threaded plu	1	6.60	0.00	6.60	0
8411	ASA BOLT M12X45	3	8.15	0.00	24.45	0
6172	EXPANDING RIVET	8	0.75	0.00	6.00	6
2545	ASA SCREW SELF TAPPING 10X40	1	6.45	0.00	6.45	14
3182	ASA SCREW SELF TAPPING M12X1.5	1	7.05	0.00	7.05	74
2729	FRT AXLE SUPPORT	1	1,452.65	0.00	1,452.65	1
9844 ✓	RH WISHBONE WITH RUBBER MOUNTI	1	290.85	0.00	290.85	42
2844 ✓	RH WISHBONE BRACKET W/RUBBER M	1	191.05	0.00	191.05	9
2920	SPHERICAL COLLAR SCREW M12X1.2	4	7.70	0.00	30.80	59
2920	SPHERICAL COLLAR SCREW M12X1.2	4	7.70	0.00	30.80	59
4445 ✓	WHEEL HUB WITH BEARING	1	465.75	0.00	465.75	2
5857 ✓ 21 216 576 146	RH SWIVEL BEARING CAMBER CORRE	1	545.95	0.00	545.95	0
2864	FRT SWING SUPPORT	1	99.70	0.00	99.70	2
3531	HEX BOLT WITH WASHER M8X30	4	5.40	0.00	21.60	77
5752 ✓	FRT RH SPRING STRUT	1	511.55	0.00	511.55	0
3617	FRT SUPPORT BEARING	1	222.65	0.00	222.65	8
1922	Exch. steering	1	3,811.95	0.00	3,811.95	0
1485 ✓	RH TIE ROD	1	273.50	0.00	273.50	1
1482	ASA SCREW SELF TAPPING M12X1.5	1	5.75	0.00	5.75	80
1668	HEX NUT WITH FLANGE	1	2.35	0.00	2.35	37
1864	HEXAGON NUT WITH COLLAR	2	2.25	0.00	4.50	51
1534	COLLAR BOLT WITH COMPRESSION S	1	16.15	0.00	16.15	6
061 ✓	ALLOY RIM 7.5X17 V SPK 600	1	814.00	0.00	814.00	8
992	RH BRACKET FOR GAS SPRING	1	37.80	0.00	37.80	0
130 ✓	RH WHEEL HOUSING STRUT EXTENSI	1	147.10	0.00	147.10	1

62154
 10/07/2019
 EQ234T
 3677210

Page No : 2
 Customer No : 238
 Customer Name: AXA Insurance Pte Ltd
 Model Ref. : X1 sDrive18i

REF	DESCRIPTION	QTY	UNIT PRICE	DISC%	NET PRICE	SOH
300	FRT RH SIDE PANEL	1	664.00	0.00	664.00	2
437 ✓	IMPACT ABSORBER TOP <i>W</i>	1	43.70	0.00	43.70	3
439 ✓	FRT BUMPER TOP CARRIER <i>W</i>	1	375.95	0.00	375.95	3
768 ✓	FRT RH TOP MOUNTING SIDE PANEL <i>W</i>	1	19.20	0.00	19.20	2
770 ✓	FRT BUMPER RH INSERT <i>W</i>	1	15.25	0.00	15.25	2
566	FRT BUMPER PANEL PRIMED (POC/P)	1	734.70	0.00	734.70	3
599	FRT BUMPER PANEL LOWER SECTION	1	281.80	0.00	281.80	2
539	RH PLAQUE WITH ADHESIVE FILM	1	71.25	0.00	71.25	7
582	RH HEADLIGHT SUPPORT ARM	1	133.05	0.00	133.05	2
1176 ✓	FRT RH WHEEL ARCH COVER <i>A</i>	1	142.55	0.00	142.55	1
002	CLIP	5	1.15	0.00	9.20	57
2338 ✓	FRT RH WHEEL ARCH TRIM <i>A</i>	1	151.00	0.00	151.00	1
5464	RH HEADLIGHT LED TECHNOLOGY	1	2,670.85	0.00	2,670.85	2

 END OF REPORT

AMOUNT : \$ 14,342.50

33 406 858 534 x 2
 31 206 872 920 x 4
 31 306 869 931 x 5
 33 324 760 668 x 1
 33 306 760 587 x 2
 31 106 876 027 x 1
 31 106 867 397 x 1
 31 106 868 038 x 1
 33 306 857 402 x 2
 31 106 862 545 x 2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	115C
Vehicle Details	
Vehicle No.:	EQ234T
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Aug 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I LED NAV
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	38885542B38B15A
Chassis No.:	WBAJG120503G77210
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$34,636.00
Original Registration Date:	25 Feb 2019
First Registration Date:	25 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$40,491.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2029
PARF Rebate Amount:	\$30,368.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$32,958.00
Total Rebate Amount:	\$63,326.00

The information contained herein is correct as at 07 Aug 2019

OK

View Received Message

This mail is associated with :

***EQ234T**
[SMN701H]
TP
CHONG JOON MENG EDWIN
Jul 25 2019 8:00PM
[SMC AUTO ENGINEERING WORKS]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **08/08/2019 11:19 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - EQ234T - Claim Handler: Lalitha Krishnan

Approved:0.00:please revert on quantum

DOCUMENTS SUMMARY

There are no documents.

Hsiao Tong (LKKAUTO)

From: Steve Chen (LKK Auto)
Sent: Tuesday, 17 September 2019 7:16 PM
To: Sharon Heng L K
Cc: Vivian Lau (LKKAUTO)
Subject: DIRECT SETTLEMENT FINAL REPORT - EQ234T

Dear Sharon,

We confirm the finalize \$19,882.70 (P/P, before GST). 12 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K [<mailto:sharon.heng.leekun@simedarby.com.sg>]
Sent: Friday, September 13, 2019 7:23 PM
To: Steve Chen (LKK Auto)
Cc: Vivian Lau (LKKAUTO)
Subject: DIRECT SETTLEMENT FINAL REPORT - EQ234T

Dear Steve

For your perusal :

Labour\$10088.00
Parts\$ 9794.70
Total\$19882.70

Owner is claiming LOSS OF USE = \$80 X 12 DAYS GIA SEARCH FEE - \$2.00

Note : 10 working days.

Please reply me directly.

Best Regards

Sharon Heng
PML – Body and Paint

DID : 63190123
Fax : 64743229

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]
Sent: Friday, 13 September, 2019 5:18 PM
To: Sharon Heng L K
Subject: Message from KM_C458

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Aug 2019 18:19	Clim Dtl Modified	Claimant's Name: -> CHONG JOON MENG EDWIN. Claimant's ID: -> S7528115C.	[A] HOW MEI KWAN
2	05 Aug 2019 18:19	Clim Veh Model Changed	(206197) BMW X1 SDRIVE18I 1.5 LED NAV (A).	[A] HOW MEI KWAN
3	05 Aug 2019 18:19	Clim Created	Reg No: EQ234T. Acct Date: 2019/07/25. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: Liberty Insurance Pte Ltd (HQ). Workshop: Performance Motors Limited (Alexandra)	[A] HOW MEI KWAN
4	05 Aug 2019 18:19	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	05 Aug 2019 18:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/16	[A] HOW MEI KWAN
6	05 Aug 2019 18:19	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	05 Aug 2019 18:19	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
8	05 Aug 2019 18:20	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
9	06 Aug 2019 11:34	TP Ins Updated	TPPoNo:SD19V02623/VPC/R00/E00 -> D18MTS0000309.	[I] Gabriel Wee
10	08 Aug 2019 09:45	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: OID moving out from stop line. cannot stop in time collided TP	[A] VIVIAN LAU PEI FENG
11	08 Aug 2019 11:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/16. Mandate Remarks: please revert on quantum	[I] Lalitha Krishnan
12	08 Aug 2019 11:19	Adj Mandate Set	Approved:0.00:please revert on quantum	[I] Lalitha Krishnan
13	08 Aug 2019 13:39	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> CHEN TSUE YEE	[A] HOW MEI KWAN
14	08 Aug 2019 13:39	Clim Dtl Modified	Insured Name: -> SMC AUTO ENGINEERING WORKS. Insured ID: -> 52889066B.	[A] HOW MEI KWAN
15	03 Oct 2019 17:22	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
16	03 Oct 2019 17:22	Clim Dtl Modified	JPJ Reg. Date: -> 2019/02/25.	[A] JOANNE LEE KHANG MIN
17	03 Oct 2019 17:22	Clim Details Notified		[A] JOANNE LEE KHANG MIN
18	05 Oct 2019 09:13	Adj Mandate Request	Cur.Req:22236.49:PODS Liability: 100% *Quantum: (a)CORw/GST: \$21,274.49 + (b)L OU(12days x \$80.00): \$960.00 + (c)LTA/GIA search fee: \$2.00 = Total: \$22,236.49 *Vehicle Model: BMW X1 (1499cc) *12 recommendation repair days *For your approval please	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

ACTIVITY

[08/08/2019 09:45] VIVIAN LAU PEI FENG:
seek liability via merimen

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2237272	06 Aug 2019 08:47:02	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	EQ234T	SMN701H	11.77
2301820	03 Oct 2019	OD/TP Case	Motor	LKK Auto	LKK Auto	EQ234T	SMN701H	11.77

Print Received Message

This mail is associated with :

***EQ234T (MTS2019D0000826)**
[SMN701H]

TP

CHONG JOON MENG EDWIN

Jul 25 2019 8:00PM

[SMC AUTO ENGINEERING WORKS]

Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/11/2019 17:05 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$22236.49) - EQ234T - Claim Handler: Lalitha Krishnan

Approved:22236.49:please revert on quantum

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 13 November 2019 5:54 PM
To: PBSP
Cc: Admin A; Su Li (LKK Auto)
Subject: RE: LOD REMINDER - EQ234T & SFL4000P ON 25/07/2019 //LKK REF: CC3/III19013672/Epa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement at \$22,236.49(all-in).

We will proceed to close file.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 23 October 2019 7:37 AM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Su Li (LKK Auto) <suli@lkkauto.com>
Subject: RE: LOD REMINDER - EQ234T & SFL4000P ON 25/07/2019 //LKK REF: CC3/III19013672/Epa3

Without Prejudice

Hi,

We are pending mandate from III.

We will expedite the matter.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Su Li (LKK Auto) <suli@lkkauto.com>

Sent: Tuesday, 22 October 2019 9:07 AM

To: PBSP <pml-pbsp@simedarby.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: FW: LOD REMINDER - EQ234T & SFL4000P ON 25/07/2019

Without Prejudice

Dear Sir / Madam,

Thank you for your email.

Please be informed that this matter is now handled by my colleague, Ms Hsiao Tong.

Hi Hsiao Tong,

FYNA, our ref CC3/III19013672/Epa3

Thank you.

Best Regards,

Su Li | Admin Support

LKK Auto Consultants Pte Ltd

Phone: 6841 2157 (Ext:119) Email: SuLi@lkkauto.com Fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Tuesday, 22 October 2019 9:00 AM

To: Vivian Lau (LKKAuto)

Cc: Admin A

Subject: LOD REMINDER - EQ234T & SFL4000P ON 25/07/2019

LOD REMINDER

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Name of Policyholder:	Certificate No.:
CHONG JOON MENG EDWIN (ZHONG JUNMING EDWIN)	SD19V02623/ VPC / R00
Date of Issue:	Effective Date of Commencement:
26 Feb 2019	25 Feb 2019 00:00
Registration No.:	Date of Expiry:
EQ234T	24 Feb 2020 23:59
Chassis No.:	Type of Certificate:
WBAJG120503G77210	MX1

Persons or Classes of Persons entitled to drive*:

- A) The Policyholder.
- B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers

For Information Only:

Coverage(s):	Comprehensive, Unlimited Windscreen, NCD Protection
Sum Insured:	MARKET VALUE AT THE TIME OF LOSS
Excess:	Section I S\$600, Additional Excess for Young & Inexperienced Drivers S\$2500, Windscreen Excess S\$0
Name of Finance Company:	DBS BANK LTD
Name of Producer:	SD CONTEGO SERVICES (A1429-5)

ROBIO18CIC/SD19V02623/27-Feb-2019/Motor CL v1.0

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2019 Edit Reg		07 Aug 2019 00:00 Edit Adj Rpt	\$19,882.70 Edit Estimates	\$19,882.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SMC AUTO ENGINEERING WORKS, Co. Reg. No.: 52889066B								
Main Claimant:	CHONG JOON MENG EDWIN, ID: S7528115C								
Vehicle Reg. No.:	EQ234T	Date of Loss:	25/07/2019 20:00 - :59 [5 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MTS2019D0000826	Policy/Cover Note No.:	D18MTS0000309_01						
Vehicle Reg. No. (Insured):	SMN701H	Policy No. (Claimant):	SD19V02623/VPC/R00/E00						
	Excess:								
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 16/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (05/11/2019): Alert - Adj Mandate Approved (\$22236.49) - EQ234T - Claim Handler: Lalitha Kris... - III_SG (06/08/2019): Alert - Adj Mandate Approved (\$0.00) - EQ234T - Claim Handler: Lalitha Krishnan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EQ234T (MTS2019D0000826)
[SMN701H]

TP

CHONG JOON MENG EDWIN

Jul 25 2019 8:00PM

[SMC AUTO ENGINEERING WORKS]
Performance Motors Limited

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/08/19 19:13	General View	 Load JPG	☒
2	07/08/19 19:13	General View	 Load JPG	☒
3	07/08/19 19:13	General View	 Load JPG	☒
4	07/08/19 19:13	Odometer Reading	 Load JPG	☒
5	07/08/19 19:13	Chassis Number	 Load JPG	☒
6	07/08/19 19:13	General View	 Load JPG	☒
7	07/08/19 19:13	General View	 Load JPG	☒
8	07/08/19 19:13	General View	 Load JPG	☒
9	07/08/19 19:13	General View	 Load JPG	☒
10	07/08/19 19:13	General View	 Load JPG	☒
11	07/08/19 19:13	General View	 Load JPG	☒
12	07/08/19 19:13	General View	 Load JPG	☒
13	07/08/19 19:13	General View	 Load JPG	☒
14	07/08/19 19:13	General View	 Load JPG	☒
15	07/08/19 19:13	General View	 Load JPG	☒
16	07/08/19 19:13	General View	 Load JPG	☒
17	07/08/19 19:13	General View	 Load JPG	☒
18	07/08/19 19:13	General View	 Load JPG	☒
19	07/08/19 19:13	General View	 Load JPG	☒
20	07/08/19 19:13	General View	 Load JPG	☒
21	07/08/19 19:13	General View	 Load JPG	☒
22	07/08/19 19:13	General View	 Load JPG	☒
23	07/08/19 19:13	General View	 Load JPG	☒
24	07/08/19 19:13	General View	 Load JPG	☒
25	07/08/19 19:13	General View	 Load JPG	☒
26	07/08/19 19:13	General View	 Load JPG	☒
27	07/08/19 19:13	General View	 Load JPG	☒
28	07/08/19 19:13	General View	 Load JPG	☒
29	07/08/19 19:13	General View	 Load JPG	☒
30	07/08/19 19:13	General View	 Load JPG	☒
31	07/08/19 19:13	General View	 Load JPG	☒
32	07/08/19 19:13	General View	 Load JPG	☒
33	07/08/19 19:13	General View	 Load JPG	☒
34	07/08/19 19:13	General View	 Load JPG	☒
35	07/08/19 19:13	General View	 Load JPG	☒
36	07/08/19 19:13	General View	 Load JPG	☒
37	07/08/19 19:13	General View	 Load JPG	☒
38	07/08/19 19:13	General View	 Load JPG	☒
39	07/08/19 19:13	General View	 Load JPG	☒
40	07/08/19 19:13	General View	 Load JPG	☒
41	07/08/19 19:13	General View	 Load JPG	☒
42	07/08/19 19:13	General View	 Load JPG	☒
43	07/08/19 19:13	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	07/08/19 19:13	General View	 Load JPG	☒
45	07/08/19 19:13	General View	 Load JPG	☒
46	07/08/19 19:13	General View	 Load JPG	☒
47	07/08/19 19:13	General View	 Load JPG	☒
48	07/08/19 19:13	General View	 Load JPG	☒
49	07/08/19 19:13	General View	 Load JPG	☒
50	07/08/19 19:13	General View	 Load JPG	☒
51	07/08/19 19:13	General View	 Load JPG	☒
52	07/08/19 19:13	General View	 Load JPG	☒
53	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
54	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
55	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
56	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
57	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
58	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
59	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
60	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
61	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
62	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
63	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
64	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
65	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
66	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
67	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
68	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
69	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
70	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
71	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
72	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
73	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
74	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
75	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
76	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
77	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
78	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
79	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
80	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
81	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
82	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
83	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
84	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
85	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
86	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
87	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
88	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
89	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
90	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
91	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
92	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
93	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
94	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
95	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
96	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
97	17/09/19 19:19	Photographs of Damaged Items	 Load JPG	☒
98	17/09/19 19:19	Photographs of Damaged Items	Load JPG	☒
99	17/09/19 19:19	Photographs of Damaged Items	Load JPG	☒

Photos/Images			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	17/09/19 19:19	Photographs of Damaged Items		☒
101	17/09/19 19:19	Photographs of Damaged Items		☒
102	17/09/19 19:19	Photographs of Damaged Items		☒
103	17/09/19 19:19	Photographs of Damaged Items		☒
104	17/09/19 19:19	Photographs of Damaged Items		☒
105	17/09/19 19:20	Before Repair Photo		☒
106	17/09/19 19:20	Before Repair Photo		☒
107	17/09/19 19:20	Before Repair Photo		☒
108	17/09/19 19:20	Before Repair Photo		☒
109	17/09/19 19:20	Before Repair Photo		☒
110	17/09/19 19:20	Before Repair Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/19 18:20	TP ESTIMATE + DOCS		☐
2	05/08/19 18:20	TP GIA REPORT		☐
3	08/08/19 17:54	TP ESTIMATE - MARKED		☐
4	05/10/19 09:11	TP LOD		☐
5	05/10/19 09:11	WORKSHOP INVOICE		☐
6	05/10/19 09:11	INSURANCE SEARCH FEE		☐
7	15/11/19 09:18	AUTHORISATION TO ACT FORM		☐
8	15/11/19 09:18	DISCHARGE VOUCHER		☐
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/08/19 08:30	Singapore Accident Statement - Motor Trade Plate policy		☐

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19013672/EPA3Q2

Date: 15/11/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MTS0000309_01
Claimant Vehicle No :	EQ234T	Insured Vehicle No :	SMN701H
Date of Loss:	25/07/2019	Nature of Claim:	TP
		Claim No:	MTS2019D0000826

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EQ234T	Engine No:	38885542B38B15A
Make & Model:	BMW X1 SDRIVE18i, 1.5 LED NAV (A)	Chassis No:	WBAJG120503G77210
Reg. Date:	25/02/2019 (Man. Year: 2018)	Odometer:	4560 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,981.35	9,944.70	6,036.65	37.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,138.00	9,938.00	3,200.00	24.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,119.35	19,882.70	9,236.65	31.72
+ GST 7.00/7.00% (S\$)	2,038.35	1,391.79	646.56	31.72
Nett Amount (S\$)	31,157.70	21,274.49	9,883.21	31.72
+ Loss of Use (12.0 x S\$80.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		22,236.49		

INSPECTION

Date of Assignment: 07/08/2019

Date Inspected: 07/08/2019 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2019)
Parts:	M1-SUV	BMW X1 SDRIVE18i 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EQ234T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*THREADED PLU	Not Necessary	6.60 FS	*- FS
3	3		*ASA BOLT M12X45	Not Necessary	24.45 FS	*- FS
4	8		*EXPANDING RIVET	Not Necessary	6.00 FS	*- FS
5	2		*ASA SCREW SELF TAPPING 10X40	Necessary	12.90 FS	*12.90 FS
6	1		*ASA SCREW SELF TAPPING M12X1.5X60	Not Necessary	7.05 FS	*- FS
7	1		*FRT AXLE SUPPORT	Not Necessary	1,452.65 FS	*- FS
8	1		*RH WISHBONE WITH RUBBER MOUNTING	Bent	290.85 FS	*290.85 FS
9	1		*RH WISHBONE BRACKET W/RUBBER MOUNTI	Bent	191.05 FS	*191.05 FS
10	4		*SPHERICAL COLLAR SCREW M12X1.25X45	Necessary	30.80 FS	*30.80 FS
11	4		*SPHERICAL COLLAR SCREW M12X1.25X45	Not Necessary	30.80 FS	*- FS
12	1		*WHEEL HUB WITH BEARING	Necessary	508.80 FS	*508.80 FS
13	1		*RH SWIVEL BEARING CAMBER CORRECTION	Not Necessary	545.95 FS	*- FS
14	1		*FRT SWING SUPPORT	Not Necessary	99.70 FS	*- FS
15	5		*HEX BOLT WITH WASHER M8X30	Necessary	27.00 FS	*27.00 FS
16	1		*FRT RH SPRING STRUT	Bent	511.55 FS	*511.55 FS
17	1		*FRT SUPPORT BEARING	Necessary	222.65 FS	*222.65 FS
18	1		*EXCH ,STEERI	Not Necessary	3,811.95 FS	*- FS
19	1		*RH TIE ROD	Bent	273.50 FS	*273.50 FS
20	2		*ASA SCREW SELF TAPPING M12X1.5X30	Dislodged	11.50 FS	*11.50 FS
21	1		*HEX NUT WITH FLANGE	Necessary	2.35 FS	*2.35 FS
22	2		*HEXAGON NUT WITH COLLAR	Not Necessary	4.50 FS	*- FS
23	2		*COLLAR BOLT WITH COMPRESSION SPRING	Necessary	36.30 FS	*36.30 FS
24	1		*ALLOY RIM 7.5X17 V SPK 560	Cut	814.00 FS	*814.00 FS
25	1		*RH BRACKET FOR GAS SPRING	Not Necessary	37.80 FS	*- FS
26	1		*RH WHEEL HOUSING STRUT EXTENSION	Crushed	147.10 FS	*147.10 FS
27	1		*FRT RH SIDE PANEL	Dented	664.00 FS	*664.00 FS
28	1		*IMPACT ABSORBER TOP	Missing	43.70 FS	*43.70 FS
29	1		*FRT BUMPER TOP CARRIER	Bent	373.95 FS	*373.95 FS
30	1		*FRT RH TOP MOUNTING SIDE PANEL	Bent	19.20 FS	*19.20 FS
31	1		*FRT BUMPER RH INSERT	Missing	18.25 FS	*18.25 FS
32	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Dented	854.55 FS	*854.55 FS
33	1		*FRT BUMPER PANEL LOWER SECTION (PDC)	Cut	281.80 FS	*281.80 FS
34	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	71.25 FS	*71.25 FS
35	1		*RH HEADLIGHT SUPPORT ARM	Bent	133.05 FS	*133.05 FS
36	1		*FRT RH WHEEL ARCH COVER	Cut	142.55 FS	*142.55 FS
37	8		*CLIP	Not Necessary	9.20 FS	*- FS
38	1		*FRT RH WHEEL ARCH TRIM	Crushed	151.00 FS	*151.00 FS
39	1		*RH HEADLIGHT LED TECHNOLOGY	Broken	2,670.85 FS	*2,670.85 FS
40	1		*SQUARE NUT M12X1.5	Necessary	6.40 FS	*6.40 FS
41	1		*ASA BOLT M12X1.5	Necessary	9.15 FS	*9.15 FS
42	1		*ASA BOLT M10X55	Necessary	9.05 FS	*9.05 FS
43	1		*FRT RH CARRIER	Dented	481.90 FS	*481.90 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*PIPE CLAMP	Necessary	12.65 FS	*12.65 FS
45	1		*HEX NUT WITH FLANGE M10	Necessary	2.10 FS	*2.10 FS
46	2		*COMBINATION NUT M14X1.5	Necessary	11.10 FS	*11.10 FS
47	1		*RH CROSS SUPPORT SIDE PANEL	Dented	67.60 FS	*67.60 FS
48	1		*RH OPEN GRID (BASIC PDC)	Dented	111.45 FS	*111.45 FS
49	1		*RH SUPPORT	Dented	138.75 FS	*138.75 FS
50	20		*EXPANDING RIVET BLACK	Necessary	27.00 FS	*27.00 FS
51	1		*WINDSHIELD CLEANING CONTAINER	Crushed	129.60 FS	*129.60 FS
52	1		*RH FOGLAMP	Broken	276.25 FS	*276.25 FS
53	2		*(S/L) WASHER ADDITIVES (250ML)	Necessary	7.20 FS	*7.20 FS
Total Parts (S\$)					15,981.35	9,944.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
2	TO REPLACE FRONT BUMPER ,FENDER RIGHT ,SUPPORT RIGHT AND ATTACHMENTS	New	4,250.00	3,400.00
3	PAINTING FRONT BUMPER ,FENDER RIGHT AND BONNET	New	3,221.00	2,898.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
5	TO REPLACE RIGHT HEADLIGHT	New	481.00	408.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	1,062.00	451.00
8	TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND REPLACE DAMAGED PARTS	New	2,655.00	2,256.00
9	TO REPLACE ELECTROMECHANICAL POWER STEERING INCLUDING PROGRAM ,INITIALIZE STEERING COLUMN ADJUSTMENT AND CONDUCT CHECKS FOR PROPER FUNCTION	New	885.00	0.00
10	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			13,138.00	9,938.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >