

12/03/2002

REF: CS/MSG 19013715 / ug f 3m2

Special Instructions:

ASS. REC. BY:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Zheng Han Yangof MS19Date/Time: 14.19 9.33a.m

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SBY 112EInsured: SLT 2683Tat Workshop m/s Hock Wah MotorTel: 6441 5655of Blk 3011 Bedok Industrial Park E #01-2008Policy No: 29114756Claim No: 600242

Sum Insured:

Excess:

D.O.A. 17.7.19

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 6.8.19 10.05a.m

Person Contacted:

Anysia

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SBY 112E -x

SLT 2683T -x

07/8/19 @ 10.31am revised to Zheng Han Yang via Merimen.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GR / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/9/19

Conf. with final by 3035.20 with Ays.s.
(Red 63506.80, 54/1)

RECEIVED 05 SEP 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 05/9/19 Trust

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

MER-TP

3035.20

150
11

161

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Zheng Hanyang

Date: 07 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLT2683T	Accident Date	: 17/07/2019
TP Vehicle No	: SBY112E	Assignment Date	: 06/08/2019
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 4.00
Date of Inspection	: 06/08/2019		
Inspection At	: HOCK WAH MOTOR WORKSHOP PTE LTD (BEDOK) BLK 3011, BEDOK INDUSTRIAL PARK E., #01-2008/2010/2012 SINGAPORE 489977		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,542.00
Revised Amount	:S\$	3,124.08
Check Items (Estimated)	:S\$	16.00
Total	:S\$	3,140.08
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2019 11:02		06 Aug 2019 09:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	YAP KOK HAI, ID: S6841651E								
Vehicle Reg. No.:	SBY112E	Date of Loss:	17/07/2019 15:00 - :59 [27 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600242	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLT2683T	Policy No. (Claimant):							
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Zheng Hanyang - 6594 2547]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/08/2019]								
Driver/Custodian (Insured):	LEONG CHEE WOH (/ Male) , NRIC: S1542771Z Email:								
Adj Asg. Remarks:	Car in survey ASAP. on WP. Please contact us ASAP if you cannot attend this assignment. OI: Grab. Liab: 100%. Assign: IHS. Contact: Anysia @ 6441 5655.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Fit 1.3A



3.08% p.a. 5ta Grade B No Major
Damage, 2 Year Warranty \$0
Down, Monthly Fm \$438
GV Credit Pte Ltd StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted 20 results/page

10 vehicles

Odyssey

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Odyssey		Any	Any	2017	Any	Any	Any	Available
	Honda	Odyssey 2.4A EXV-S Sunroof	\$120,800	\$12,680 /yr	21-Sep-2017	2,356 cc	44,690 km	MPV	Available
Kah Motor Unit. Fully Agent Maintained. Beautiful Premium Spice Purple Pearl Colour. Five Years Warranty. Interest Rate From 1.99%. M... Inchcape Pre-Owned Posted: 05-Aug-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EXV-S Sunroof	\$110,888	\$12,250 /yr	03-Feb-2017	2,356 cc	26,571 km	MPV	Available
Cheapest, Priced To Sell! Genuine Low Mileage Done! Under 5-Yrs Warranty & 3-Yrs Service Package By Agent Kah Motors. Pristine And... Posted: 05-Aug-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EXV-S Sunroof	\$114,800	\$12,850 /yr	18-Jan-2017	2,356 cc	23,595 km	MPV	Available
1 Owner With Low Mileage 23,595km Done. Well Maintained 7 Seater Spacious MPV. Kah Motor Unit. Comes With 5 Years Warranty And... Posted: 03-Aug-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EXV-S Sunroof	\$114,888	\$12,890 /yr	01-Feb-2017	2,356 cc	-	MPV	Available
One Under Utilized Single Owner Sunroof Unit, Most Demanding 7-Seater With Twin Powered Door Making Access In/Out Of Car Effortle... Creative Auto Posted: 01-Aug-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Volkswagen	Touareg							
Volkswagen's Touareg is a tech-laden beast Volkswagen's third generation Touareg is a massive improvement over its predecessor and is well-armed to take on the big boys. Find out more!									
	Honda	Odyssey 2.4A EXV-S Sunroof	\$112,000	\$11,620 /yr	25-Sep-2017	2,356 cc	58,000 km	MPV	Available
Very Nice Spacious Family Car. Servicing Not Yet Due. 1 Free Servicing Will Be Given Once Due. Original Japan Oil Will Be Used As Per H... Posted: 27-Jul-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									
	Honda	Odyssey 2.4A EX-S (OPC)	\$109,800	\$12,360 /yr	29-Mar-2017	2,356 cc	11,000 km	MPV	Available
1 Owner, OPC Unit. Fully Agent Maintained And 5 Year Warranty. Option To Convert To Normal Plate For Additional \$14k. Excellent Con... Hui Hua Credit Pte Ltd Posted: 22-Jul-2019 Tags: 2017 Honda Odyssey, 2017 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda									

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	651E

Vehicle Details

Vehicle No.:	SBY112E
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	K24W72013671
Chassis No.:	JHMRC1890GC208916
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,901.00
Original Registration Date:	06 Apr 2017
First Registration Date:	06 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$36,662.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Apr 2027
PARF Rebate Amount:	\$27,496.00

Intended COE Rebate Details

COE Expiry Date:	05 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,229.00
COE Rebate Amount:	\$35,431.00
Total Rebate Amount:	\$62,927.00

The information contained herein is correct as at 06 Aug 2019

OK

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10, SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: SXXX1651E

YAP KOK HAI
BLK 798 WOODLANDS DRIVE 72
13-75
SINGAPORE 730798
TEL: FAX:
PH: 96799461
ATTN:

ESTIMATE BILL

Number: EB00005220
Date: 18/07/2019
Case No: AD00010559
Vehicle No: SBY112E
Chassis: JHMRC1890GC208916
Year of Mfr: 2016
Policy No:
Model: HONDA ODYSSEY
2.4 EXV-S CVT SR

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BUMPER	1.0	557.20	20	445.76
2	REAR BUMPER RETAINER RH	1.0	20.00	20	16.00
3	REAR BUMPER RETAINER LH	1.0	20.00	20	16.00
4	TAIL LAMP RH	1.0	821.50	20	657.20
5	TAIL LAMP CLIP LH	4.0	4.20	20	13.44
6	END PANEL	1.0	451.80	20	361.44
7	REAR FENDER AIR DUST LH	1.0	28.80	20	23.04
8	TAIL GATE	1.0	1,193.70	20	954.96
9	TAIL GATE LAMP LH	1.0	378.50	20	302.80
10	TAIL GATE EMBLEM	1.0	27.40	20	21.92
11	TAIL GATE WINDSCREEN GLASS MOULDING	1.0	151.80	20	121.44
12	REAR BUMPER BRACKET LH	1.0			
List Price - Parts Sub Total					2,934.00
13	REVERSE CAMERA	1.0	580.00	0	580.00
14	REVERSE SENSOR	2.0	280.00	0	560.00
15	SPARE TYRE PANEL - REPAIR	1.0			
16	REAR FENDER LH - REPAIR	1.0			
17	WINDSCREEN SEALANT	2.0	24.00	0	48.00
Special Nett Price - Parts Sub Total					1,188.00
Parts Total					4,122.00
18	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
19	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
20	ANTI-RUST COATING	1.0	250.00	0	250.00
21	WIRING	1.0	40.00	0	40.00
22	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
23	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
Labour 1 Sub Total					2,420.00
SINGAPORE DOLLARS: SIX THOUSAND NINE HUNDRED NINETY-NINE AND CENTS NINETY-FOUR ONLY			Less Excess	6603.44	0.00
			SUBTOTAL		6,542.00
			GST 7.00%		457.94
			TOTAL		6,999.94

Date of accident: 17/07/2019 03:20 PM. Place: WOODLANDS AVE 7

E. & O. E.

CUSTOMER SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
AUTHORISED SIGNATURE

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19013715/UQF3N2

Date: 06/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SBY112E	Insured Vehicle No :	SLT2683T
Date of Loss:	17/07/2019	Nature of Claim:	TP
		Claim No:	600242

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBY112E	Engine No:	K24W72013671
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRC1890GC208916
Reg. Date:	06/04/2017 (Man. Year: 2016)	Odometer:	36128 km
Colour:	Grey		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,183.44	1,695.20	2,488.24	59.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,340.00	1,080.00	44.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,603.44	3,035.20	3,568.24	54.04
+ GST 7.00/7.00% (S\$)	462.24	212.46	249.78	54.04
Nett Amount (S\$)	7,065.68	3,247.66	3,818.02	54.04

INSPECTION

Date of Assignment:	06/08/2019	
Date Inspected:	06/08/2019	Inspected At:
		Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01- 2008/2010/2012 Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2019)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBY112E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	557.20 FL	*557.20 FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	20.00 FL	*- FL
3	1		*REAR BUMPER RETAINER LH	Not Necessary	20.00 FL	*- FL
4	1		*TAIL LAMP RH	Not Necessary	821.50 FL	*- FL
5	4		*TAIL LAMP CLIP LH	Not Necessary	16.80 FL	*- FL
6	1		*END PANEL	Repair	451.80 FL	*- FL
7	1		*REAR FENDER AIR DUST LH	Not Necessary	28.80 FL	*- FL
8	1		*TAIL GATE	Badly Dented	1,193.70 FL	*1,070.80 FL
9	1		*TAIL GATE LAMP LH	Not Necessary	378.50 FL	*- FL
10	1		*TAIL GATE EMBLEM	Necessary	27.40 FL	*27.40 FL
11	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	151.80 FL	*86.80 FL
12	1		*REAR BUMPER BRACKET LH (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REVERSE CAMERA	Not Necessary	580.00 FS	*- FS
14	2		*REVERSE SENSOR	Shorted	560.00 FS	*200.00 FS
15	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS
16	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
17	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
18	1		*REAR BUMPER SIDE LH	Deformed	76.80 FL	*76.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,932.30	2,059.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	748.86	363.80
Total Parts (\$\$)	4,183.44	1,695.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	520.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	600.00
3	ANTI-RUST COATING	New	250.00	30.00
4	WIRING	New	40.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
6	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
Gross Labour Cost (\$\$)			2,420.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >