

ASS. REC. BY:

REF: CSI FWD 49013716/TH4322

Special Instruction:

SURVEYOR: Tan Fik

ASSIGNMENT (Office)

From (Person): Lionel Tan

of FWD

Date/Time: 5.8.19 18.35pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLE 9721A

Insured:

at Workshop m/s Ethos Protect

Tel: 96248656

of 30 Bukit Batok Crescent

Policy No: PNPV2017-00006274-01

Claim No: 1201900022676

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 1.8.19

(Client's Record)

CA / REV REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 6.8.19 10.19am

Person Contacted: shah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLE 9721A - ✓

6/8@17:04 - mandate request. not exceeding \$15,500/-

7/8@9:23 - mandate approved by Lionel Tan

7/8@11:50am - email to wfs authorise repair not exceeding \$15,500/-

Taufik

FWD

CS/FWD19013716/Tiff3

SLE 9721A

2016 Aug 10

Honda Jazz.

1498

Red

40993.

JHM67K5850HX200360.

Ex: \$500.

185/65R15

Maxima

462K

6

6

6

6

6/5/1921/1am

Ethuz Blk Blk

Part by part B36271 (Red: 4127! 23%) confirm ^{Refute \$46,086}
with Shahh.

RECEIVED 09 SEP 2019

9/9 Typist

OD

136271

Item of Report

9

Resource No. of trip

250

90

90+90

11

411

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019 Sendback Est	05 Aug 2019 17:30 S\$17,071.00	05 Aug 2019 18:35 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	MAK CHAN KEET, ID: S89171051		
Vehicle Reg. No.:	SLE9721A	Date of Loss:	01/08/2019 09:00 - :59 [35 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900022676	Policy/Cover Note No.:	PNPV2017-00006274-01 (Comprehensive)
		Excess:	S\$500.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/08/2019]		
Driver/Custodian:	YAO YUEQI (29 / Female) . NRIC: S8935342D, Tel: +6597773928 Email: NOEMAIL		
		Vehicle Source:	Tow-in/Call-man
Repair Tracker:	Body Repair - 20%		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Selamatshahh Zainal <Selamatshahh.Zainal@ethozgroup.com>
Sent: Monday, 9 September 2019 9:43 AM
To: Denise Tay (LKKAUTO); Taufikh (LKKAUTO)
Subject: RE: Finalization for SLE9721A

Hi Denise,

Already submitted in Merimen previously.

COR confirmed at part by part \$13,627.00. Please submit offer in Merimen soonest.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 7 August 2019 11:55 AM
To: Selamatshahh Zainal
Cc: Lee Chen Sin
Subject: RE: SLE9721A FWD OD Ethoz Bukit Batok

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLE 9721A (Excess \$200/-). All in not exceeding \$15,500/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: Selamatshahh Zainal <Selamatshahh.Zainal@ethozgroup.com>
Sent: Tuesday, 6 August 2019 6:03 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Cc: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Subject: RE: SLE9721A FWD OD Ethoz Bukit Batok

Dear Denise,

Noted, Ethoz will be able to proceed with the repair at part by part limit at \$15,500.00.

Warmest regards,

Selamatshahh Zainal
Senior Executive
Motor Claims Operations

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

HP: 9624 8656 | DID: 6654 7519 | Fax: 6654 7542

Website: www.ethozgroup.com



Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 9 September 2019 9:32 AM
To: Selamatshahh Zainal; Taufikh (LKKAUTO)
Subject: RE: Finalization for SLE9721A
Attachments: SLE 9721A SUPP.pdf

Dear Shahh,

Please see marking adjusted for supplementary. (Unable to see this in merimen, please submit.)

Therefore part by part \$13,627/-. Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Selamatshahh Zainal <Selamatshahh.Zainal@ethozgroup.com>
Sent: Thursday, 29 August 2019 10:03 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: Finalization for SLE9721A
Importance: High

Hi Taufik,

Please assist to confirm final amount at \$13,727.00 9 days Excess \$500.00

**take note that there are some parts price amended.*

Warmest regards,

Selamatshahh Zainal
Senior Executive
Motor Claims Operations

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

HP: 9624 8656 | DID: 6654 7519 | Fax: 6654 7542

Website: www.ethozgroup.com



From: Denise Tay (LKKAUTO) [<mailto:denisetay@lkkauto.com>]
Sent: Wednesday, August 7, 2019 11:55 AM
To: Selamatshahh Zainal <Selamatshahh.Zainal@ethozgroup.com>

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1051
Vehicle Details	
Vehicle No.:	SLE9721A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B31190243
Chassis No.:	JHMGK5850HX200360
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$17,579.00
Original Registration Date:	10 Aug 2016
First Registration Date:	10 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$12,579.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Aug 2026
PARF Rebate Amount:	\$9,434.00
Intended COE Rebate Details	
COE Expiry Date:	09 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$36,652.00
Total Rebate Amount:	\$46,086.00

The information contained herein is correct as at 06 Aug 2019

OK

View Received Message

This mail is associated with :

SLE9721A (1201900022676)

OD

Aug 1 2019 9:00AM

[MAK CHAN KEET]

ETHOZ Protect Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 07/08/2019 09:23 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15500.00) - SLE9721A - Claim Handler: Lionel Tan

Approved:15500.00.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/08/2019 16:20
Date Of Accident	01/08/2019 09:20
Exact Location Of Accident	ALONG PORTSDOWN AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE9721A
Insured/Policyholder	
Name Of Registered Owner	MAK CHAN KEET
NRIC No	S8917105I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98391628
Alternative Phone No	OFFICE-98391628

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00006274-01
Cover Note Number	10/08/2018-09/08/2019

Driver

Name of Driver	YAO YUEQI
NRIC No	S8935342D
Date Of Birth	28/09/1989
Occupation	INDOOR
Date Of Driving Pass	02/11/2018
Driving Experience	0 YEAR AND 8 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97773928
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	35 ROBIN ROAD 02-04
Postcode	258210
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH TP
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	YAO YUEQI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLE9721A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 02/08/2019

1614

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Not familiar with the roads at Potsdam and made a wrong call to go onto the flyover.

Refer to the Police Report.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

✓

- Reporting Only
- Claim OD
- Claim TP
- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.



**SINGAPORE
POLICE FORCE**



T/20190801/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190801/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/08/2019 11:51		Vide Report No.: D/20190801/0061		Station Diary No.:	
Informant's Particulars					
Name of Informant: YAO YUEQI			Address: 35 ROBIN ROAD #02-04 SINGAPORE 258210		
ID Type / ID No.: NRIC NO / S8935342D			Contact No.: Home/Office: Mobile: 97773928		
Nationality: SINGAPORE CITIZEN			Email: chloeyieeee@gmail.com		
Sex: Female	Age: 29	Date of Birth: 28/09/1989	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Product Manager			Driving Licence Information: Class: 3A		Date of Expiry: 01/08/2019

General Information of the Accident					
Type of Accident:	Injury Government Property	Drink Drive: No	Date/Time of Accident: 01/08/2019 11:37	Type of Location: Flyover	
Location: PORTSDOWN AVENUE					
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Moderate	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SLE9721A	Car	HONDA	Jazz	Red	Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLE9721A	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.			



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190801/7009

2 of 3

Report No. T/20190801/7009

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YAO YUEQI	ID No.	S8935342D
Related Vehicle	SLE9721A (Car)	Contact No.	97773928
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: 01/08/2019
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

I was not familiar with the roads at Portsdown and made a wrong judgement to go onto the flyover.



**SINGAPORE
POLICE FORCE**



T/20190801/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190801/7009

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 01/08/2019 11:51
Officer In Charge Of Case: TP / TPHQ / WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S89171051**

Name: **MAK CHAN KEET (MAI ZHENJIE)**

Birth Date: **29 Apr 1989**

Issue Date: **30 Apr 2011**

0019400662



REPUBLIC OF SINGAPORE

IDENTITY CARD NO: **S89171051**

3118021

Portrait of Mak Chan Keet

Name: **MAK CHAN KEET (MAI ZHENJIE)**

麥 鎮 傑

Race: **CHINESE**

Date of Birth: **29-04-1989** Sex: **M**

Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE 30 Apr 2011

Class 3 Motor Cars < 3500kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 3500kg

NP 42BA



3118021


Barcode

NRIC No: **S89171051**

Date of Issue: **09-05-2004**

38 JALAN KIRONG KECHIL #05-14
SINGAPORE 568180

NRIC No: **S89171051** Date: **28/12/2017**





REPUBLIC OF SINGAPORE
IDENTITY CARD No: S8935342D



YAO YUEQI

姚悦倩

Race: CHINESE
Date of birth: 28-09-1989 Sex: F
Country of birth: SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 02 Nov 2018

NP 428A



Licence No: S8935342D



3449460

NRIC No: S8935342D



Date of issue: 15-12-2004

Address:

35 ROBIN ROAD
#02-04
SINGAPORE 258210



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00006274-01 (Comprehensive - Classic Plan)

Car plate number: SLE9721A

Your name (As the policyholder): Mak Chan Keet

Coverage start date: 10/08/2018

Coverage end date: 09/08/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: DBS Bank Ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 09/06/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00006274-01	Date of Loss:	01/08/2019
Vehicle Reg. No.:	SLE9721A	Driveable?	
Driver Age/Info:	29 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	MAK CHAN KEET		
Driver:	YAO YUEQI		
Make/Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Vehicle Reg. Date:	10/08/2016
Vehicle Colour:	RED	Chassis No:	JHMGK5850HX200360
Engine No:	L15B31190243		
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO THE POLICE REPORT		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

Taught 27495749 4/8/19 1/42
Ex: \$500
Not Authorise, Revert.
9 days
survivor to 100%
Resurvey before print.

COST OF CLAIMS	Amount
Parts	13,911.00
Miscellaneous Items	120.00
Labour	3,040.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	17,071.00
+ GST 7.00% (S\$)	1,194.97
Nett Amount (S\$)	18,265.97

This claim is handled by: KENNETH CORNELIUS / SHAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LOOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Aug 2019)

Parts: 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SLE9721A/05/08/2019 17:30

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	del ✓ *450.00 F ✓
2	2		*FRONT BUMPER RETAINER	0.00	0.00	? *48.00 F X nn
3	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	bt ✓ *190.00 F ✓
4	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	con ✓ *45.00 F ✓
5	10		*FRONT BUMPER CLIPS	0.00	0.00	wt ✓ *30.00 F ✓
6	1		*FRONT NUMBER PLATE BASE HOLDER	0.00	0.00	del ✓ *40.00 F ✓
7	1		*FRONT AIRGUIDE RH	0.00	0.00	? *26.00 F X nn
8	1		*FRONT AIRGUIDE LH	0.00	0.00	del ✓ *26.00 F ✓
9	1		*FOGLAMP LH	0.00	0.00	? *220.00 F X nn
10	1		*FOGLAMP GARNISH LH	0.00	0.00	wt ✓ *28.00 F ✓
11	1		*FRONT BUMPER SIDE LAMP LH	0.00	0.00	wt ✓ *160.00 F X nn
12	1		*FRONT GRILLE	0.00	0.00	con ✓ *240.00 F ✓
13	1		*FRONT GRILLE TOP COVER	0.00	0.00	del ✓ *15.00 F ✓
14	10		*FRONT GRILLE TOP COVER CLIPS	0.00	0.00	wt ✓ *30.00 F 15
15	1		*HEADLAMP RH	0.00	0.00	? *850.00 F X nn
16	1		*HEADLAMP LH	0.00	0.00	con ✓ *850.00 F 220
17	2		*HEADLAMP LOWER BRACKET	0.00	0.00	? *56.00 F 22 de
18	1		*BONNET	0.00	0.00	bt ✓ *600.00 F 580
19	1		*BONNET INSULATOR	0.00	0.00	del ✓ *85.00 F ✓
20	2		*BONNET HINGE	0.00	0.00	bt ✓ *72.00 F X nn
21	1		*BONNET LOCK	0.00	0.00	bt ✓ *75.00 F ✓
22	1		*SUPPORT PANEL ASSY	0.00	0.00	bt ✓ *380.00 F ✓
23	1		*AIRCON CONDENSER	0.00	0.00	bt ✓ *520.00 F ✓
24	1		*AIRCON FAN COWLING	0.00	0.00	? *60.00 F 04
25	1		*AIRCON FAN MOTOR	0.00	0.00	? *200.00 F X nn
26	1		*AIRCON FAN BLADE	0.00	0.00	? *55.00 F X nn
27	1		*AIRCON SUCTION PIPE	0.00	0.00	? *95.00 F X nn
28	1		*AIRCON DISCHARGE PIPE	0.00	0.00	? *120.00 F X nn
29	1		*RADIATOR → photo	0.00	0.00	bt ✓ *750.00 F ✓
30	1		*RADIATOR FAN COWLING	0.00	0.00	? *80.00 F 04
31	1		*RADIATOR FAN MOTOR	0.00	0.00	? *200.00 F X nn
32	1		*RADIATOR FAN BLADE	0.00	0.00	? *65.00 F X nn
33	1		*RADIATOR TOP HOSE	0.00	0.00	del ✓ *16.00 F X nn
34	1		*FRONT TOP AIRDUCT	0.00	0.00	? *14.00 F X nn
35	1		*INTAKE MANIFOLD	0.00	0.00	wt ✓ *380.00 F ✓
36	1		*STEERING AIRBAG	0.00	0.00	act ✓ *1,350.00 F 1300
37	1		*STEERING AIRBAG CLOCK SPRING	0.00	0.00	wt ✓ *240.00 F ✓
38	1		*PASSENGER AIRBAG UNIT	0.00	0.00	wt ✓ *980.00 F ✓
39	1		*AIRBAG CONTROL UNIT	0.00	0.00	wt ✓ *750.00 F ✓
40	2		*AIRBAG IMPACT SENSOR	0.00	0.00	wt ✓ *320.00 F 280
41	1		*DASHBOARD ASSY	0.00	0.00	del ✓ *850.00 F ✓
42	1		*FRONT SEAT BELT RH	0.00	0.00	wt ✓ *420.00 F X nn

ETHOZ Protect Pte Ltd/SLE9721A/05/08/2019 17:30. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*FRONT SEAT BELT LH	0.00	0.00	*420.00 F X n7
44	1		*FRONT WINDSCREEN GLASS	0.00	0.00	*1,480.00 F ✓
45	1		*FRONT WINDSCREEN MOUDLING	0.00	0.00	*30.00 F ✓
46	1		*FRONT FENDER RH/LH	0.00	0.00	- X
			RESTORE			

F=Franchise part.

Total Parts (S\$)	13,911.00
-------------------	-----------

ETHOZ Protect Pte Ltd/SLE9721A/05/08/2019 17:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	30.00 ✓
2	1	FRONT NUMBER PLATE	35.00 ✓
3	1	FRONT WINDSCREEN SEALANT	40.00 ✓
4	1	IU BRACKET	15.00 ✓
Sub Total (S\$)			120.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New	1,200.00 ✓
2	TO RESPRAY AFFECTED AREAS	New	1,000.00 ✓
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00 ✓
4	TO TOP UP AIRCON GAS	New	120.00 ✓
5	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	120.00 ✓
6	TO REMOVE AND REFIT DASHBOARD ASSY	New	250.00 ✓
7	TO RESET AND REPROGRAMME AIRBAG SYSTEM	New	300.00 ✓
Gross Labour Cost (S\$)			3,040.00

ETHOZ Protect Pte Ltd/SLE9721A/05/08/2019 17:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>



(SUPPLEMENTARY)

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00006274-01	Date of Loss:	01/08/2019
Vehicle Reg. No.:	SLE9721A	Driveable?	
Driver Age/Info:	29 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	MAK CHAN KEET		
Driver:	YAO YUEQI		

Make/Model:	HONDA JAZZ, 1.5 VTIR CVT (A) Vehicle Reg. Date: 10/08/2016		
Vehicle Colour:	RED		
Engine No:	L15B31190243	Chassis No:	JHMGK5850HX200360
Odometer:	1 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss	REFER TO THE POLICE REPORT
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)

COST OF CLAIMS

	Amount
Parts	280.00
Miscellaneous Items	0.00
Labour	400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	680.00
+ GST 7.00% (S\$)	47.60
Nett Amount (S\$)	727.60
+ Previous Estimates (S\$)	18,265.97
Claim Total (S\$)	18,993.57

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Aug 2019)**Parts:** 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ETHOZ Protect Pte Ltd/SLE9721A/13/08/2019 11:42**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CLEANER BOX	0.00	0.00	de *150.00 F ✓
2	1		*ENGINE MOUNTING RH	0.00	0.00	dis *130.00 F ✓
Total Parts (S\$)						280.00

F=Franchise part.

ETHOZ Protect Pte Ltd/SLE9721A/13/08/2019 11:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PULL AND REALIGN FRONT CHASSIS PANEL RH/LH	New	700 300.00
2	TO RENEW ENGINE MOUNTING RH	New	✓ 100.00
Gross Labour Cost (S\$)			400.00

ETHOZ Protect Pte Ltd/SLE9721A/13/08/2019 11:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Date : 28/08/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : MAK CHAN KEET
Insured By : FWD SINGAPORE PTE. LTD.
Certificate No : PNPV2017-00006274-01 Accident Date : 01/08/2019
Vehicle No : SLE-9721-A Make & Model : HONDA JAZZ 1.5L AT ABS D/AB HID 2WD 5D

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	AIR CLEANER BOX	150.00	150.00
1	ENGINE MOUNTING RH	130.00	130.00
1	FRONT BUMPER	450.00	450.00
2	FRONT BUMPER RETAINER	48.00	0.00
1	FRONT BUMPER REINFORCEMENT	190.00	190.00
1	FRONT BUMPER LOWER GRILLE	45.00	45.00
10	FRONT BUMPER CLIPS	30.00	30.00
1	FRONT NUMBER PLATE BASE HOLDER	40.00	40.00
1	FRONT AIRGUIDE RH	26.00	0.00
1	FRONT AIRGUIDE LH	26.00	26.00
1	FOGLAMP LH	220.00	0.00
1	FOGLAMP GARNISH LH	28.00	28.00
1	FRONT BUMPER SIDE LAMP LH	160.00	0.00
1	FRONT GRILLE	240.00	240.00

PAGE: 1

Date : 28/08/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : MAK CHAN KEET
Insured By : FWD SINGAPORE PTE. LTD.
Certificate No : PNPV2017-00006274-01 Accident Date : 01/08/2019
Vehicle No : SLE-9721-A Make & Model : HONDA JAZZ 1.5L AT ABS D/AB HID 2WD 5D

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT GRILLE BASE	0.00	0.00
1	FRONT GRILLE CHROME MOULDING	0.00	0.00
1	FRONT GRILLE LOGO	0.00	0.00
1	FRONT GRILLE TOP COVER	15.00	15.00
10	FRONT GRILLE TOP COVER CLIPS	30.00	15.00
1	HEADLAMP RH	820.00	0.00
1	HEADLAMP LH	820.00	820.00
2	HEADLAMP LOWER BRACKET	56.00	28.00
1	BONNET	580.00	580.00
1	BONNET INSULATOR (awaiting for parts)	85.00	85.00
10	BONNET INSULATOR CLIPS	0.00	0.00
2	BONNET HINGE	72.00	0.00
1	BONNET LOCK	75.00	75.00
1	SUPPORT PANEL ASSY	380.00	380.00
1	BRACE PANEL	0.00	0.00

Date : 28/08/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : MAK CHAN KEET
Insured By : FWD SINGAPORE PTE. LTD.
Certificate No : PNPV2017-00006274-01 Accident Date : 01/08/2019
Vehicle No : SLE-9721-A Make & Model : HONDA JAZZ 1.5L AT ABS D/AB HID 2WD 5D

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	AIRCON CONDENSER	520.00	520.00
1	AIRCON FAN COWLING	60.00	60.00
1	AIRCON FAN MOTOR	200.00	0.00
1	AIRCON FAN BLADE	55.00	0.00
1	AIRCON SUCTION PIPE	95.00	0.00
1	AIRCON DISCHARGE PIPE	120.00	0.00
1	RADIATOR	750.00	750.00
1	RADIATOR FAN COWLING	80.00	80.00
1	RADIATOR FAN MOTOR	200.00	0.00
1	RADIATOR FAN BLADE	65.00	0.00
1	RADIATOR TOP HOSE	16.00	0.00
1	FRONT TOP AIRDUCT	14.00	0.00
1	INTAKE MANIFOLD	380.00	380.00
1	STEERING AIRBAG	1300.00	1300.00
1	STEERING AIRBAG CLOCK SPRING	240.00	240.00

Date : 28/08/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : MAK CHAN KEET

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00006274-01 Accident Date : 01/08/2019

Vehicle No : SLE-9721-A Make & Model : HONDA JAZZ 1.5L AT ABS D/AB HID 2WD 5D

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	PASSENGER AIRBAG UNIT	980.00	980.00
1	AIRBAG CONTROL UNIT	750.00	750.00
2	AIRBAG IMPACT SENSOR	280.00	280.00
1	DASHBOARD TOP ASSY	850.00	850.00
1	FRONT SEAT BELT RH	420.00	0.00
1	FRONT SEAT BELT LH	420.00	0.00
1	FRONT WINDSCREEN GLASS	1480.00	1480.00
1	FRONT WINDSCREEN MOULDING	30.00	30.00
1	FRONT FENDER RH/LH	0.00	0.00
Sub Total		14021.00	11027.00
Add 0% On Parts		0.00	0.00
Special Nett Item			
1	FRONT NUMBER PLATE	35.00	35.00
1	COOLANT	30.00	30.00

Date : 28/08/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : MAK CHAN KEET

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2017-00006274-01 Accident Date : 01/08/2019

Vehicle No : SLE-9721-A Make & Model : HONDA JAZZ 1.5L AT ABS D/AB HID 2WD 5D

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT WINDSCREEN SEALANT	40.00	40.00
1	IU BRACKET	15.00	15.00
	Sub Total	120.00	120.00
Labour & Misc			
	REPAIR AND REALIGN FRONT CHASSIS PANEL RH/LH	300.00	300.00 (P)
	RENEW ENGINE MOUNTING RH	100.00	100.00 (P)
	LABOUR TO FACILITATE REPAIR TO RESPRAY AFFECTED AREAS	1200.00	800.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	1000.00	800.00
	TO TOP UP AIRCON GAS	50.00	30.00
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	120.00	100.00
		120.00	120.00

Date : 28/08/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : MAK CHAN KEET
Insured By : FWD SINGAPORE PTE. LTD.
Certificate No : PNPV2017-00006274-01 Accident Date : 01/08/2019
Vehicle No : SLE-9721-A Make & Model : HONDA JAZZ 1.5L AT ABS D/AB HID 2WD 5D

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO REMOVE AND REFIT DASHBOARD ASSY	250.00	180.00
	TO RESET AND REPROGRAMME AIRBAG SYSTEM	300.00	150.00
	Sub Total	3440.00	2580.00
			2480
			\$13627 #
	Sub Total	17,581.00	13,727.00
	GST 7.0 %	1,230.67	960.89
	Total	18,811.	14,687.

Surveyor Name : TAUFIK - LKK
Date & Time : 06/08/2019 11:00:00 AM

Selamatshahh

CLAIM DEPARTMENT

DID : 66547519

FAX :

PAGE: 6



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00006274-01	Date of Loss:	01/08/2019
Vehicle Reg. No.:	SLE9721A	Driveable?	
Driver Age/Info:	29 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	MAK CHAN KEET		
Driver:	YAO YUEQI		
Make/Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Vehicle Reg. Date:	10/08/2016
Vehicle Colour:	RED		
Engine No:	L15B31190243	Chassis No:	JHMGK5850HX200360
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO THE POLICE REPORT		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

Taujiah 97495749 c/b/te/ha
Ex: \$500
Not Authorise, Report
9 days
survivor auto insurance
Resurvey before paint

COST OF CLAIMS

	Amount
Parts	13,911.00
Miscellaneous Items	120.00
Labour	3,040.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	17,071.00
+ GST 7.00% (S\$)	1,194.97
Nett Amount (S\$)	18,265.97

This claim is handled by: KENNETH CORNELIUS / SHAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Aug 2019)
 Parts: 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ETHOZ Protect Pte Ltd/SLE9721A/05/08/2019 17:30
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00✓	0.00	450.00F
2	2		*FRONT BUMPER RETAINER	0.00	0.00	48.00F
3	1		*FRONT BUMPER REINFORCEMENT	0.00✓	0.00	190.00F
4	1		*FRONT BUMPER LOWER GRILLE	0.00✓	0.00	45.00F
5	10		*FRONT BUMPER CLIPS	0.00✓	0.00	30.00F
6	1		*FRONT NUMBER PLATE BASE HOLDER	0.00✓	0.00	40.00F
7	1		*FRONT AIRGUIDE RH	0.00	0.00	26.00F
8	1		*FRONT AIRGUIDE LH	0.00✓	0.00	26.00F
9	1		*FOGLAMP LH	0.00	0.00	220.00F
10	1		*FOGLAMP GARNISH LH	0.00✓	0.00	28.00F
11	1		*FRONT BUMPER SIDE LAMP LH	0.00	0.00	160.00F
12	1		*FRONT GRILLE	0.00✓	0.00	240.00F
13	1		*FRONT GRILLE TOP COVER	0.00✓	0.00	15.00F
14	10		*FRONT GRILLE TOP COVER CLIPS	0.00✓	0.00	30.00F
15	1		*HEADLAMP RH	0.00	0.00	850.00F
16	1		*HEADLAMP LH	0.00✓	0.00	850.00F
17	2		*HEADLAMP LOWER BRACKET ✓ LH - cracked	0.00✓	0.00	56.00F
18	1		*BONNET	0.00✓	0.00	600.00F
19	1		*BONNET INSULATOR	0.00✓	0.00	85.00F
20	2		*BONNET HINGE	0.00	0.00	72.00F
21	1		*BONNET LOCK	0.00✓	0.00	75.00F
22	1		*SUPPORT PANEL ASSY	0.00✓	0.00	380.00F
23	1		*AIRCON CONDENSER	0.00✓	0.00	520.00F
24	1		*AIRCON FAN COWLING	0.00✓	0.00	60.00F
25	1		*AIRCON FAN MOTOR	0.00	0.00	200.00F
26	1		*AIRCON FAN BLADE	0.00	0.00	55.00F
27	1		*AIRCON SUCTION PIPE	0.00	0.00	95.00F
28	1		*AIRCON DISCHARGE PIPE	0.00	0.00	120.00F
29	1		*RADIATOR → photo	0.00✓	0.00	750.00F
30	1		*RADIATOR FAN COWLING ✓ cracked	0.00✓	0.00	80.00F
31	1		*RADIATOR FAN MOTOR	0.00	0.00	200.00F
32	1		*RADIATOR FAN BLADE	0.00	0.00	65.00F
33	1		*RADIATOR TOP HOSE	0.00	0.00	16.00F
34	1		*FRONT TOP AIRDUCT	0.00	0.00	14.00F
35	1		*INTAKE MANIFOLD	0.00✓	0.00	380.00F
36	1		*STEERING AIRBAG	0.00✓	0.00	1,350.00F
37	1		*STEERING AIRBAG CLOCK SPRING	0.00✓	0.00	240.00F
38	1		*PASSENGER AIRBAG UNIT	0.00✓	0.00	980.00F
39	1		*AIRBAG CONTROL UNIT	0.00✓	0.00	750.00F
40	2		*AIRBAG IMPACT SENSOR	0.00✓	0.00	320.00F
41	1		*DASHBOARD ASSY	0.00✓	0.00	850.00F
42	1		*FRONT SEAT BELT RH	0.00	0.00	420.00F

ETHOZ Protect Pte Ltd/SLE9721A/05/08/2019 17:30. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS


No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*FRONT SEAT BELT LH	0.00	0.00	420.00 FX Repair
44	1		*FRONT WINDSCREEN GLASS	0.00	0.00	1,480.00 F
45	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	30.00 F
46	1		*FRONT FENDER RH/LH RESTORE	0.00	0.00	-
F=Franchise part.						
Total Parts (S\$)						13,911.00

ETHOZ Protect Pte Ltd/SLE9721A/05/08/2019 17:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Air Cleaner Box lower 150
 Engine out RH 130
 Labour
 Repair chassis flexel x2

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493586/67496950 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6399 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M



Io.: M2-00252314

10Z PROTECT PTE LTD
GUL CRESENT
9721 A(P/O:176622)
XER BY: SHAH

TAX INVOICE NO.: TL129242
INVOICE DATE : 08/08/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 1

AX INVOICE

TS NO	DESCRIPTION	LOC	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
11-T5A-000ZZ	FACE, FR BUMPER		1 PCS	450.000	450.00
130-T5A-000ZZ	BEAM ASSY, FR BUMPER		1 PCS	190.000	190.00
102-T5A-000	GRILLE, FR BUMPER LOWER		1 PCS	45.000	45.00
300300	CLIP, FR BUMPER		10	3.000	30.00
145-T5A-000	BASE, FR LICENSE PLATE		1 PCS	40.000	40.00
107-T5A-000	DUCT, FR BUMPER SIDE, LH		1	26.000	26.00
108-T5A-N00	GARNISH, FR BUMPER, LH		1	28.000	28.00
120-TAS-003	GRILLE ASSY, RADIATOR		1 PCS	240.000	240.00
105-T5A-000	COVER, FR GRILLE, UPPER		1 PCS	15.000	15.00
300300	CLIP, FR BUMPER		5	3.000	15.00
150-T5A-J21	HEADLAMP ASSY, LH		1	820.000	820.00

DUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED


TOTAL

SIGNATURE

SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493586/67496950 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6399 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M



Io.: M2-00252314

10Z PROTECT PTE LTD
GUL CRESENT
9721 A(P/O:176622)
XER BY: SHAH

TAX INVOICE NO.: TL129242
INVOICE DATE : 08/08/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 2

AX INVOICE

TS NO	DESCRIPTION	LOC	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
100-T5L-T00ZZ	HOOD		1 PCS	580.000	580.00
120-T5A-003	LOCK ASSY, HOOD		1	75.000	75.00
100-T5B-300ZZ	PANEL ASSY, FR SUPPORT		1 PCS	380.000	380.00
100-T5B-003	CONDENSER ASSY, A/C		1	520.000	520.00
110-5R1-901	RADIATOR ASSY		1 PCS	750.000	750.00
100-5R1-004	MANIFOLD ASSY, INTAKE		1 PCS	380.000	380.00
110-T5A-N80ZA	MODULE, AIR BAG, STEERING		1 PCS	1300.000	1300.00
100-T5A-J21	REEL ASSY, CABLE		1 PCS	240.000	240.00
120-T5A-J80	MODULE, PASSENGER AIR BAG		1 PCS	980.000	980.00
160-T5A-J41	CONTROL UNIT, AIR BAG		1 PCS	750.000	750.00
130-T5A-J01	SENSOR ASSY, FR IMPACT		2 PCS	140.000	280.00

DUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

TOTAL

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495888/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800 Tel: 6396 6369 / 6384 2235 Fax: 6384 2245
Bik 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M

Jo.: M2-00252314

ECL1


10Z PROTECT PTE LTD

GUL CRESENT

9721 A(P/O:176622)

DER BY: SHAH

AX INVOICE



TAX INVOICE NO.: TL129242

INVOICE DATE : 08/08/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : TBS

PAGE(S) : 3

ITS NO.	DESCRIPTION	LOC	QUANTITY	UNIT PRICE	AMOUNT
100-T5A-J102A	DASHBOARD ASSY		1 PCS	(SIN) 850.000	(SIN) 850.00
111-TAR-J01	GLASS, FR WINDSHIELD		1 PCS	1480.000	1480.00
150-T5A-J01	MOLDING, FR WINDSHIELD, UPR		1 PCS	30.000	30.00
GST Excl Amount :					10494.00
Special Discount :					
GST @ 7 % :					734.58

DUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

PRINT BY :

TBS 08/08/2019 12:57:46

TOTAL

11228.58

SIGNATURE

SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495888/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800 Tel: 6396 6369 / 6384 2235 Fax: 6384 2245
Bik 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M

Jo.: M2-00252314

ECL1


10Z PROTECT PTE LTD

GUL CRESENT

9721 A(P/O:176622)

DER BY: SHAH

AX INVOICE



TAX INVOICE NO.: TL129243

INVOICE DATE : 08/08/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : TBS

PAGE(S) : 1

ITS NO.	DESCRIPTION	LOC	QUANTITY	UNIT PRICE	AMOUNT
100-T5A-000	BRACKET, FR BUMPER, LH		1 PCS	(SIN) 28.000	(SIN) 28.00
315-5R1-003	SHROUD, AIR CON FAN		1 PCS	60.000	60.00
315-5R1-003	SHROUD, RAD COOLING FAN		1 PCS	80.000	80.00
GST Excl Amount :					168.00
Special Discount :					
GST @ 7 % :					11.76

DUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

PRINT BY :

TBS 08/08/2019 13:01:05

TOTAL


179.76

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496058 Fax: 67495066/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800 Tel: 6396 6369 / 6394 2235 Fax: 6384 2245
Blk 885 #01-324 Race Course Road Singapore 210685 Tel: 62964551 Fax: 62970774
Co. Reg. No.: 197602013M



BMW



Jo.: M2-00252314

ECL1

402 PROTECT PTE LTD
GUL CRESENT
9721 A(P/O:176622)
XER BY: SHAH

TAX INVOICE NO.: TL129244
INVOICE DATE : 08/08/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 1

AX INVOICE

QTY NO	DESCRIPTION	LOC	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
322-T9A-013	RUBBER ASSY, ENGINE SIDE MTG		1	130.000	130.00
201-5R1-J01	BODY ASSY, AIR CLEANER		1	150.000	150.00
GST Excl Amount :					280.00
Special Discount :					
GST @ 7 % :					19.60

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

299.60

PRINT BY :

TBS 08/08/2019 14:26:47

SIGNATURE

3.00

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019 Sendback Est	05 Aug 2019 17:30 \$517,071.00	05 Aug 2019 18:35 Edit Adj Rpt	\$513,627.00 Edit Estimates	\$513,627.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	13 Aug 2019 11:37	13 Aug 2019 11:42 \$5680.00	13 Aug 2019 11:42			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	MAK CHAN KEET, ID: S89171051		
Vehicle Reg. No.:	SLE9721A	Date of Loss:	01/08/2019 09:00 - :59 [35 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900022676	Policy/Cover Note No.:	PNPV2017-00006274-01 (Comprehensive)
		Excess:	S\$500.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/08/2019]		
Driver/Custodian:	YAO YUEQI (29 / Female) , NRIC: S8935342D, Tel: +6597773928 Email: NOEMAIL		
	Vehicle Source:	Tow-in/Call-man	
Repair Tracker:	Completed/Ready for Collection - 100% (without offer)		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- FWD_SG (09/09/2019): Alert - Adj Mandate Approved (\$513627.00) - SLE9721A - Claim Handler: Lionel Tan
- FWD_SG (07/08/2019): Alert - Adj Mandate Approved (\$515500.00) - SLE9721A - Claim Handler: Lionel Tan

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLE9721A (1201900022676)

OD

Aug 1 2019 9:00AM

[MAK CHAN KEET]

ETHOZ Protect Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)
View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	05/08/19 17:30	Repairer Estimates	 Load HTM	
2	13/08/19 11:42	Repairer Estimates Suppl. #1	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/08/19 08:37	Adjuster Immediate Advice	 Load HTM	
2	09/09/19 11:47	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/09/19 11:36	General View	 Load JPG	☒
2	09/09/19 11:36	General View	 Load JPG	☒
3	09/09/19 11:36	General View	 Load JPG	☒
4	09/09/19 11:36	General View	 Load JPG	☒
5	09/09/19 11:36	General View	 Load JPG	☒
6	09/09/19 11:36	General View	 Load JPG	☒
7	09/09/19 11:36	General View	 Load JPG	☒
8	09/09/19 11:36	General View	 Load JPG	☒
9	09/09/19 11:36	General View	 Load JPG	☒
10	09/09/19 11:36	General View	 Load JPG	☒
11	09/09/19 11:36	General View	 Load JPG	☒
12	09/09/19 11:36	General View	 Load JPG	☒
13	09/09/19 11:36	General View	 Load JPG	☒
14	09/09/19 11:36	General View	 Load JPG	☒
15	09/09/19 11:36	General View	 Load JPG	☒
16	09/09/19 11:36	General View	 Load JPG	☒
17	09/09/19 11:36	General View	 Load JPG	☒
18	09/09/19 11:36	General View	 Load JPG	☒
19	09/09/19 11:36	General View	 Load JPG	☒
20	09/09/19 11:36	General View	 Load JPG	☒
21	09/09/19 11:36	General View	 Load JPG	☒
22	09/09/19 11:36	General View	 Load JPG	☒
23	09/09/19 11:36	General View	 Load JPG	☒
24	09/09/19 11:36	General View	 Load JPG	☒
25	09/09/19 11:36	General View	 Load JPG	☒
26	09/09/19 11:36	General View	 Load JPG	☒
27	09/09/19 11:36	General View	 Load JPG	☒
28	09/09/19 11:36	General View	 Load JPG	☒
29	09/09/19 11:36	General View	 Load JPG	☒
30	09/09/19 11:36	General View	 Load JPG	☒
31	09/09/19 11:36	General View	 Load JPG	☒
32	09/09/19 11:36	General View	 Load JPG	☒
33	09/09/19 11:36	General View	 Load JPG	☒
34	09/09/19 11:36	General View	 Load JPG	☒
35	09/09/19 11:36	General View	 Load JPG	☒
36	09/09/19 11:36	General View	 Load JPG	☒
37	09/09/19 11:36	General View	 Load JPG	☒
38	09/09/19 11:36	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
39	09/09/19 11:36	General View	 Load JPG	☒
40	09/09/19 11:36	General View	 Load JPG	☒
41	09/09/19 11:36	General View	 Load JPG	☒
42	09/09/19 11:36	General View	 Load JPG	☒
43	09/09/19 11:36	General View	 Load JPG	☒
44	09/09/19 11:36	General View	 Load JPG	☒
45	09/09/19 11:36	General View	 Load JPG	☒
46	09/09/19 11:36	General View	 Load JPG	☒
47	09/09/19 11:36	General View	 Load JPG	☒
48	09/09/19 11:36	General View	 Load JPG	☒
49	09/09/19 11:36	General View	 Load JPG	☒
50	09/09/19 11:36	General View	 Load JPG	☒
51	09/09/19 11:36	General View	 Load JPG	☒
52	09/09/19 11:36	General View	 Load JPG	☒
53	09/09/19 11:36	General View	 Load JPG	☒
54	09/09/19 11:36	General View	 Load JPG	☒
55	09/09/19 11:36	General View	 Load JPG	☒
56	09/09/19 11:36	General View	 Load JPG	☒
57	09/09/19 11:36	General View	 Load JPG	☒
58	09/09/19 11:36	General View	 Load JPG	☒
59	09/09/19 11:36	General View	 Load JPG	☒
60	09/09/19 11:36	General View	 Load JPG	☒
61	09/09/19 11:36	General View	 Load JPG	☒
62	09/09/19 11:36	General View	 Load JPG	☒
63	09/09/19 11:36	General View	 Load JPG	☒
64	09/09/19 11:36	General View	 Load JPG	☒
65	09/09/19 11:36	General View	 Load JPG	☒
66	09/09/19 11:36	General View	 Load JPG	☒
67	09/09/19 11:36	General View	 Load JPG	☒
68	09/09/19 11:36	General View	 Load JPG	☒
69	09/09/19 11:36	General View	 Load JPG	☒
70	09/09/19 11:36	General View	 Load JPG	☒
71	09/09/19 11:36	General View	 Load JPG	☒
72	09/09/19 11:36	General View	 Load JPG	☒
73	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
74	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
75	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
76	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
77	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
78	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
79	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
80	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
81	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
82	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
83	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
84	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
85	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
86	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
87	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
88	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
89	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
90	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
91	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
92	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
93	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
94	09/09/19 11:40	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
95	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
96	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
97	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
98	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
99	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
100	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
101	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
102	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
103	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
104	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
105	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
106	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
107	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
108	09/09/19 11:40	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/09/19 11:35	SUPPLEMENTARY	 Load PDF	
2	09/09/19 12:27	PARTS INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	02/08/19 16:56	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	02/08/19 16:56	Accident Photo	 Load JPG	☒
2	02/08/19 16:56	Accident Photo	 Load JPG	☒
3	02/08/19 16:56	Accident Photo	 Load JPG	☒
4	02/08/19 16:56	Accident Photo	 Load JPG	☒
5	02/08/19 16:56	Accident Photo	 Load JPG	☒
6	02/08/19 16:56	Accident Photo	 Load JPG	☒
7	02/08/19 16:56	Accident Photo	 Load JPG	☒
8	02/08/19 16:56	Accident Photo	 Load JPG	☒
9	02/08/19 16:56	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	02/08/19 16:42	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19013716/T1TF3E2

Date: 19/09/2019

REFERENCE

Insured/Claimant: MAK CHAN KEET Policy No: PNPV2017-00006274-01
Date of Loss: 01/08/2019 Nature of Claim: OD Claim No: 1201900022676

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE9721A**
Make & Model: HONDA JAZZ, 1.5 VTIR CVT (A) Engine No: L15B31190243
Reg. Date: 10/08/2016 (Man. Year: 2016) Chassis No: JHMGK5850HX200360
Colour: Red Odometer: 40993 km
Engine Capacity: 1498 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: MAXIMUS 6 mm Rear Left Side: MAXIMUS 6 mm
Front Right Side: MAXIMUS 6 mm Rear Right Side: MAXIMUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,191.00	11,027.00	3,164.00	22.30
Miscellaneous Items	120.00	120.00	0.00	0.00
Labour	3,440.00	2,480.00	960.00	27.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,751.00	13,627.00	4,124.00	23.23
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	17,751.00	13,127.00	4,624.00	26.05
+ GST 7.00/7.00% (S\$)	1,242.57	918.89	323.68	26.05
Nett Amount (S\$)	18,993.57	14,045.89	4,947.68	26.05

INSPECTION

Date of Assignment: 05/08/2019 Present Location: ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected: 06/08/2019 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075
Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2019)
Parts:	144	HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE9721A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	450.00 F	*450.00 F
2	2		*FRONT BUMPER RETAINER	Not Necessary	48.00 F	*- F
3	1		*FRONT BUMPER REINFORCEMENT	Bent	190.00 F	*190.00 F
4	1		*FRONT BUMPER LOWER GRILLE	Cracked	45.00 F	*45.00 F
5	10		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 F
6	1		*FRONT NUMBER PLATE BASE HOLDER	Deformed	40.00 F	*40.00 F
7	1		*FRONT AIRGUIDE RH	Not Necessary	26.00 F	*- F
8	1		*FRONT AIRGUIDE LH	Deformed	26.00 F	*26.00 F
9	1		*FOGLAMP LH	Not Necessary	220.00 F	*- F
10	1		*FOGLAMP GARNISH LH	Cut	28.00 F	*28.00 F
11	1		*FRONT BUMPER SIDE LAMP LH	Not Necessary	160.00 F	*- F
12	1		*FRONT GRILLE	Cracked	240.00 F	*240.00 F
13	1		*FRONT GRILLE TOP COVER	Cracked	15.00 F	*15.00 F
14	1		*FRONT GRILLE TOP COVER CLIPS (10PCS)	Necessary-5pcs only	30.00 F	*15.00 F
15	1		*HEADLAMP RH	Not Necessary	850.00 F	*- F
16	1		*HEADLAMP LH	Cracked	850.00 F	*820.00 F
17	1		*HEADLAMP LOWER BRACKET (2PCS)	Deformed-1pc only	56.00 F	*28.00 F
18	1		*BONNET	Bent	600.00 F	*580.00 F
19	1		*BONNET INSULATOR	Deformed	85.00 F	*85.00 F
20	2		*BONNET HINGE	Not Necessary	72.00 F	*- F
21	1		*BONNET LOCK	Bent	75.00 F	*75.00 F
22	1		*SUPPORT PANEL ASSY	Bent	380.00 F	*380.00 F
23	1		*AIRCON CONDENSER	Bent	520.00 F	*520.00 F
24	1		*AIRCON FAN COWLING	Cracked	60.00 F	*60.00 F
25	1		*AIRCON FAN MOTOR	Not Necessary	200.00 F	*- F
26	1		*AIRCON FAN BLADE	Not Necessary	55.00 F	*- F
27	1		*AIRCON SUCTION PIPE	Not Necessary	95.00 F	*- F
28	1		*AIRCON DISCHARGE PIPE	Not Necessary	120.00 F	*- F
29	1		*RADIATOR	Bent	750.00 F	*750.00 F
30	1		*RADIATOR FAN COWLING	Cracked	80.00 F	*80.00 F
31	1		*RADIATOR FAN MOTOR	Not Necessary	200.00 F	*- F
32	1		*RADIATOR FAN BLADE	Not Necessary	65.00 F	*- F
33	1		*RADIATOR TOP HOSE	Not Necessary	16.00 F	*- F
34	1		*FRONT TOP AIRDUCT	Not Necessary	14.00 F	*- F
35	1		*INTAKE MANIFOLD	Cut	380.00 F	*380.00 F
36	1		*STEERING AIRBAG	Activated	1,350.00 F	*1,300.00 F
37	1		*STEERING AIRBAG CLOCK SPRING	Activated	240.00 F	*240.00 F
38	1		*PASSENGER AIRBAG UNIT	Activated	980.00 F	*980.00 F
39	1		*AIRBAG CONTROL UNIT	Activated	750.00 F	*750.00 F
40	2		*AIRBAG IMPACT SENSOR	Activated	320.00 F	*280.00 F
41	1		*DASHBOARD ASSY	Deformed	850.00 F	*850.00 F
42	1		*FRONT SEAT BELT RH	Not Necessary	420.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT SEAT BELT LH	Not Necessary	420.00 F	*- F
44	1		*FRONT WINDSCREEN GLASS	Cracked	1,480.00 F	*1,480.00 F
45	1		*FRONT WINDSCREEN MOUDLING	Necessary	30.00 F	*30.00 F
46	2		*FRONT FENDER RH/LH (NPA)	Repair	-	*- F
Supplementary #1						
47	1		*AIR CLEANER BOX	Deformed	150.00 F	*150.00 F
48	1		*ENGINE MOUNTING RH	Distorted	130.00 F	*130.00 F
F=Franchise part.					Total Parts (S\$)	14,191.00 11,027.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	30.00	30.00
2	1	FRONT NUMBER PLATE (BENT)	35.00	35.00
3	1	FRONT WINDSCREEN SEALANT (NECESSARY)	40.00	40.00
4	1	IU BRACKET (NECESSARY)	15.00	15.00
Sub Total (S\$)			120.00	120.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	800.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	30.00
4	TO TOP UP AIRCON GAS	New	120.00	100.00
5	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	120.00	120.00
6	TO REMOVE AND REFIT DASHBOARD ASSY	New	250.00	180.00
7	TO RESET AND REPROGRAMME AIRBAG SYSTEM	New	300.00	150.00
Supplementary #1				
Labour Items				
8	TO PULL AND REALIGN FRONT CHASSIS PANEL RH/LH	New	300.00	200.00
9	TO RENEW ENGINE MOUNTING RH	New	100.00	100.00
Gross Labour Cost (S\$)			3,440.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >