

ASS. REC. BY:

REF: TMI / CC3/TMI 19613733/K9A3⁷²

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. M3000894

Claims No. M1905881

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 872,400

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S/HO 5606D Yr Regn: 11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.G. 1798

Colour M.P. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 14439.5 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU 80.3076806

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 2/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

SND 6606D - NA / TMI 19013560 / h4

SLS 8244K - NA / TMI 19013560 / h4

06/8/19 @ 2.01pm Email GIA report B estimate to TMI

Final Prg 65746.64, 6 days (Red 617850.11, 77%)

Data/Time, File Pass to?

11/29/18 TMI

Data/Time, File Return to?

21

Report Format:

Lump Sum / I.B.I. (\$)

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S - RS \$1

Fees

Others

TOTAL

250

11

261

Shiau Chan (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 28 August 2019 5:06 PM
To: Shiau Chan (LKKAuto)
Subject: FW: TP VEHICLE SHD 5606D (DOA: 02/08/2019) -- AAD1908-013
Attachments: image001.wmz; SHD5606 EST.pdf

Hi Shiau Chan

Amount confirmed \$ 5,246.64.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Friday, 16 August, 2019 12:09 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHD 5606D (DOA: 02/08/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation of repair cost will be at \$5,246.64 before GST and 6 repair days.

Kindly check.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 6 August 2019 2:01 PM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 02/08/2019, SHD 5606D (TP VEHICLE), SLS 8299K (OI VEHICLE)
Attachments: SHD5606 GIA.pdf; SHD5606 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5606D at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 05/08/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD5606D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B74846
Chassis No.:	JTDKB3FU803076806
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	15 Nov 2018
First Registration Date:	15 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Nov 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	14 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,736.00
COE Rebate Amount:	\$18,988.00
Total Rebate Amount:	\$29,673.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/08/2019 10:31
Date Of Accident	02/08/2019 09:20
Exact Location Of Accident	BEACH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5606D
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM KIAH HENG
NRIC No	S1056356I
Date Of Birth	22/11/1947
Occupation	OUTDOOR
Date Of Driving Pass	25/01/1978
Driving Experience	41 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96645895
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 4 BEACH ROAD #10-4953
Postcode	190004
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 02.08.2019 at about 0920 hours, I was travelling straight on the third lane along Beach Road. Suddenly, I felt an impact. Vehicle B (SLS8299K) which was travelling on my right, swerved into my lane and hit onto my taxi right side rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS8299K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2 Pg. 1

SKETCH PLAN

A: SHD 560 GD
B: SL5 8249 K
Beach Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE SEE THE ATTACH G/A REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5606D**AAD1908-013***Not Notified**Resumy B4 paint**85246.64*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5606D

JTDKB3FU803076806

TOYOTA

PRIUS

2.8.19

TOKIO MARINE

15/11/2018

		PART		LIST	
1	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>CM</i> 583.30	✓
2	1	PANEL SUB-ASSY, REAR DOOR, RH	\$	<i>B4</i> 1,258.30	✓
3	1	LOCK ASSY, REAR DOOR W/MOTOR, RH	\$	<i>ln</i> 554.60	X
4	1	REINFORCE SUB-ASSY, ROCKER, OUTER RH	\$	<i>n</i> 572.10	X
5	1	REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$	<i>n</i> 336.60	X
6	1	BOARD SUB-ASSY, REAR DOOR TRIM, RH	\$	<i>ln</i> 549.30	X
7	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	<i>n</i> 290.50	X
8	1	REAR FENDER RH	\$	<i>B4</i> 836.70	✓
9	1	REAR FENDER LINER	\$	<i>ln</i> 138.10	} X
10	1	REAR BUMPER	\$	<i>n</i> 458.60	
11	1	REAR BUMPER RE-INFORCEMENT	\$	<i>n</i> 318.80	
12	1	REAR BUMPER TOWING COVER	\$	<i>ln</i> 14.70	
13	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>ln</i> 552.60	
14	1	REAR BUMPER SIDE RETAINER RH	\$	<i>ln</i> 112.70	
15	1	TAILLAMP LOWER RH	\$	<i>ln</i> 548.40	
16	1	TAILLAMP UPPER RH	\$	<i>ln</i> 557.90	
17	1	REAR BUMPER SIDE RH	\$	<i>ln</i> 232.00	
18	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>ln</i> 54.70	
19	1	REAR TAILGATE	\$	<i>n</i> 1,547.27	
20	1	TAPE, BLACK OUT, NO.1 REAR RH	\$	<i>ln</i> 21.50	
21	1	TAPE, BLACK OUT, NO.2 REAR RH	\$	<i>ln</i> 34.40	
22	1	TAPE, BLACK OUT, NO.3 REAR RH	\$	<i>ln</i> 15.10	
23	1	WEATHERSTRIP, REAR DOOR, RH	\$	<i>ln</i> 177.60	
24	1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	<i>ln</i> 288.90	
TOTAL			\$	10,054.67	
25%			\$	2,513.67	
			\$	7,541.00	

Special Nett

Trans-cab Auto Services Pte Ltd**AAD1908-013**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5606D

1	1	REAR DOOR STICKER '6555-3333'	\$	nn 80.00	601
2	1	REAR RIGHT WHEEL RIM → 258	\$	nn 1,570.55	✓
3	1	REAR RIGHT WHEEL RIM COVER	\$	nn 175.80	} X
4	1	SET PARKING AID	\$	nn 700.00	
5	1	SET REAR BUMPER CLIP	\$	nn 66.00	
6	1	REAR BUMPER PROTECTOR	\$	nn 100.00	
7	2	REAR WINDSCREEN SEALANT	\$	nn 80.00	
8	1	WINDSCREEN MOULDING	\$	nn 100.00	
9	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	
10	1	REAR TAILGATE TOYOTA LOGO	\$	nn 47.00	
11	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn 52.90	
12	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn 53.50	
13	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn 80.00	
14	1	REAR TAILGATE STICKER '6555-3333'	\$	nn 80.00	
TOTAL			\$	3,285.75	

TOTAL PARTS \$ 10,826.75**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	8801
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Rear Door fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To reinstall rear bumper parking sensor.	\$	nn 170.00	X.

Trans-cab Auto Services Pte Ltd**AAD1908-013**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5606D

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	8001
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	170.00	1001
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
TOTAL	\$	12,270.00	
Over All Total	\$	23,096.75	

(PART-BY-PART) Repair Days**15 DAYS***6 days*

LHC Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary fee(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19013733/KQF3N2

Date: 04/09/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI000894
Claimant Vehicle No :	SHD5606D	Insured Vehicle No :	SLS8299K
Date of Loss:	02/08/2019	Nature of Claim:	TP
		Claim No:	M1905881

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5606D	Engine No:	2ZR2B74846
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU803076806
Reg. Date:	15/11/2018 (Man. Year: 2018)	Odometer:	144395 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,826.75	3,246.63	7,580.12	70.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,270.00	2,000.00	10,270.00	83.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,096.75	5,246.63	17,850.12	77.28
+ GST 7.00/7.00% (S\$)	1,616.77	367.26	1,249.51	77.28
Nett Amount (S\$)	24,713.52	5,613.89	19,099.63	77.28

INSPECTION

Date of Assignment:	06/08/2019	
Date Inspected:	05/08/2019	Inspected At: Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$5,246.64

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2019)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5606D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*MOULDING ASSY,BODY ROCKER PANEL,RH	Cracked	583.30 FL	*583.30 FL
2	1	*PANEL SUB-ASSY,REAR DOOR,RH	Bent	1,258.30 FL	*1,258.30 FL
3	1	*LOCK ASSY,REAR DOOR W/MOTOR,RH	Serviceable	554.60 FL	*- FL
4	1	*REINFORCE SUB-ASSY,ROCKER,OUTER RH	Repair	572.10 FL	*- FL
5	1	*REINFORCEMENT SUB-ASSY,ROCKER PANEL,RH	Repair	336.60 FL	*- FL
6	1	*BOARD SUB-ASSY,REAR DOOR TRIM,RH	Serviceable	549.30 FL	*- FL
7	1	*PANEL,QUARTER WHEEL HOUSE,OUTER RH	Repair	290.50 FL	*- FL
8	1	*REAR FENDER RH	Bent	836.70 FL	*836.70 FL
9	1	*REAR FENDER LINER	Serviceable	138.10 FL	*- FL
10	1	*REAR BUMPER	Repair	458.60 FL	*- FL
11	1	*REAR BUMPER RE-INFORCEMENT	Repair	318.80 FL	*- FL
12	1	*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*- FL
13	1	*REAR BUMPER UNDER COVER (BLACK)	Serviceable	552.60 FL	*- FL
14	1	*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
15	1	*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
16	1	*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
17	1	*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
18	1	*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
19	1	*REAR TAILGATE	Repair	1,547.27 FL	*- FL
20	1	*TAPE,BLACK OUT,NO 1 REAR RH	Serviceable	21.50 FL	*- FL
21	1	*TAPE,BLACK OUT,NO 2 REAR RH	Serviceable	34.40 FL	*- FL
22	1	*TAPE,BLACK OUT,NO 3 REAR RH	Serviceable	15.10 FL	*- FL
23	1	*WEATHERSTRIP,REAR DOOR,RH	Serviceable	177.60 FL	*- FL
24	1	*WEATHERSTRIP,REAR DOOR OPENING TRIM,RH	Serviceable	288.90 FL	*- FL
25	1	*REAR RIGHT WHEEL RIM	Dented	1,570.55 F	*1,570.55 FN
26	1	*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS
27	1	*REAR RIGHT WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
28	1	*SET PARKING AID	Serviceable	700.00 FS	*- FS
29	1	*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
30	1	*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS
31	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
32	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
33	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
34	1	*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
35	1	*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
36	1	*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
37	1	*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
38	1	*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	13,340.42	4,308.85
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,513.67	669.58
- Nett Item Discount on N Items 0.00/25.00% (\$\$)	0.00	392.64

Total Parts (\$\$) 10,826.75 3,246.63

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	880.00
2	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
4	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	20.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
6	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
9	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,500.00	800.00
10	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	100.00
11	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
13	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
14	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
15	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
16	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
Gross Labour Cost (S\$)			12,270.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >