

ASS. REC. BY:

REF:

CS/FCI 19 013758/Uvd3/n2

Special Instructions:

Surveyor: Marcus

ASSIGNMENT (Office)

CWS

From (Person):

8thman

of

FCI

Date/Time: 11.52am 6/8/19

Estimated Cost:

Bill to:

OD ☒ TP / WST / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN1004M

Insured:

SHB 4544R

at Workshop m/s

Chin Meng Motor

Tel:

91912829.

of

1 kaki Bukit Ave 6 #01-40

Policy No:

Claim No:

D19004845MPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/07/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

12.16pm 6/8/19

Person Contacted:

Mr. Quek

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Tohmm/1

YN1004M-X

SHB 4544R - CC.3 / CA15004937 / H193s2

D.O.A: 19/3/15

7/8/19

Email preli revised to FCI

(06/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A1063

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

1/N1004M

Yr Regn:

3, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

ISUZU NHR85

c.c

2999

Colour

Dark Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

286281

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JAANHR85E97100114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

0/6

mm

L/Bal.

0

mm

L/Bal.

0/6

mm

D.O.A.

24/7/19

D.O.I.

6/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/1/19

16/8/19 2/5 \$1000 confid with Kimseng (Red 2050, 6110)
MV: \$7K (EST) LTA: \$1063 NV: \$5937

RECEIVED-19 AUG 2019

Date/Time, File Pass to?



Preli. Report

1)

Date/Time, File Return to?



Final Report

2)

19/8 - typst

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

\$ + RS, \$)



Interview (\$

Photos



Tech. Invs (\$

Others



Weekend (\$

Report Format:

CWS

Lump Sum / I.B.I. (\$

1000/2

TOTAL

266



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004845MFSH

Our ref: CS/FCI19013758/Uvd3

DATE: 7/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO YN 1004M


We thank for your instruction on 6/8/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 6/8/2019 at the premises of M/s CHIN MENG MOTORS

Workshop Estimate Amount	: S\$3,050.00
Revised Estimate Amount	: S\$1,280.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-07-2019	Our Ref No. D19004845MFSH
Accident Date	24-07-2019	Claim Type. Third Party
Insured Vehicle	SHB4544R	Third Party Vehicle. YN1004M
Survey Location	1 KAKI BUKIT AVE 6 #01-40 AUTOBAY@KAKI BUKIT	
Contact Person.	QUEK KIM SENG	
Contact No.	67474810/ 91912829	Fax No. 67455018
Survey Type	WITHOUT PREJUDICE; WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHIN MENG MOTORS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 August 2019 10:09 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004845MFSH/2-YN 1004M
Attachments: YN 1004M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle YN 1004M
Date of survey: 6/8/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 6 August 2019 12:18 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004845MFSH/2

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 August 2019 11:52 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004845MFSH/2

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
----------------	---------

Owner ID:	882K
-----------	------

Vehicle Details

Vehicle No.:	YN1004M
--------------	---------

Vehicle to be Exported:	No
-------------------------	----

Intended Deregistration Date:	06 Aug 2019
-------------------------------	-------------

Vehicle Make:	ISUZU
---------------	-------

Vehicle Model:	NHR85AUE4A
----------------	------------

Primary Colour:	Blue
-----------------	------

Manufacturing Year:	2009
---------------------	------

Engine No.:	4JJ1821620
-------------	------------

Chassis No.:	JAANHR85E97100114
--------------	-------------------

Maximum Power Output:	-
-----------------------	---

Open Market Value:	\$30,451.00
--------------------	-------------

Original Registration Date:	11 Mar 2010
-----------------------------	-------------

First Registration Date:	11 Mar 2010
--------------------------	-------------

Transfer Count:	1
-----------------	---

Actual ARF Paid:	\$1,523.00
------------------	------------

Intended PARF Rebate Details

PARF Eligibility:	No
-------------------	----

PARF Eligibility Expiry Date:	-
-------------------------------	---

PARF Rebate Amount:	\$0.00
---------------------	--------

Intended COE Rebate Details

COE Expiry Date:	10 Mar 2020
------------------	-------------

COE Category:	C - Goods Vehicle & Bus
---------------	-------------------------

COE Period(Years):	10
--------------------	----

QP Paid:	\$17,900.00
----------	-------------

COE Rebate Amount:	\$1,063.00
--------------------	------------

Total Rebate Amount:	\$1,063.00
-----------------------------	-------------------

The information contained herein is correct as at 06 Aug 2019

OK

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST292/19/CIS
Your Ref: To be advised

5-Aug-19

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimate cost of repair to Isuzu NHR85 no: YN1004M

Date of accident: 24-07-2019

Parts supply:

- 1 pc Rear R/h compartment door (S/Nett)
- 1 pc Rear R/h compartment door sticker (S/Nett)
- 1 pc Rear R/h compartment door spring lock (S/Nett)
- 1 pc Rear R/h compartment door aluminium plate (S/Nett)
- 1 pc Rear R/h compartment door railing (S/Nett)
- 1 pc R/h crash bar (S/Nett)
- 1 pc Rear R/h mudguard (S/Nett)

S\$	2	650.00	X
	11	150.00	100
	17	120.00	X
	2	350.00	X
	2	200.00	X
	2	250.00	X
	2	250.00	X
		<u>1,970.00</u>	

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.

To respray affected part.

To apply underseal.

To remove & refit of wirings.

		500.00	480
		500.00	450
	17	50.00	X
	17	30.00	X
S\$		<u>3,050.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Ackd
2/5/19
3 Aug.
6/8/19
Wheeler

P-350 s.w
L-930
1280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013758/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4544R	Veh. Inspected	YN 1004M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004845MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	06/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NHR85 (M)	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JAANHR85E97100114	Colour	DARK BLUE	
Odometer	286281	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	FALKEN	6 mm	
L/H Front Tyre	185 R14	FALKEN	6 mm	
R/H Rear Tyre	185 R14 (D)	FALKEN	6/6 mm	
L/H Rear Tyre	185 R14 (D)	FALKEN	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2019	Inspection Date	06/08/2019	
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 1004M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR R/H COMPARTMENT DOOR (SN)	TO REPAIR SEE LABOUR	650.00	-
1	REAR R/H COMPARTMENT DOOR STICKER (SN)	NECESSARY	150.00	100.00
1	REAR R/H COMPARTMENT DOOR SPRING LOCK (SN)	NOT NECESSARY	120.00	-
1	REAR R/H COMPARTMENT DOOR ALUMINIUM PLATE (SN)	TO REPAIR SEE LABOUR	350.00	-
1	REAR R/H COMPARTMENT DOOR RAILING (SN)	TO REPAIR SEE LABOUR	200.00	-
1	R/H CRASH BAR (SN)	BENT	250.00	250.00
1	REAR R/H MUDGUARD (SN)	TO REPAIR SEE LABOUR	250.00	-
			1,970.00	350.00
LABOUR				
	TO PANEL BEATING, WELDING, REMOVING DAMAGED PARTS AND REPLACEMENT OF THE PARTS AS MENTIONED ABOVE ETC. INCLUSIVE OF THE REPAIR OF REAR R/H COMPARTMENT DOOR, REAR R/H COMPARTMENT DOOR ALUMINIUM PLATE, REAR R/H COMPARTMENT DOOR RAILING AND REAR R/H MUDGUARD.		500.00	480.00
	TO RESPRAY AFFECTED PART.		500.00	450.00
	TO APPLY UNDERSEAL.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT OF WIRINGS.	NOT NECESSARY	30.00	-
			1,080.00	930.00
GRAND TOTAL			3,050.00	1,280.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/FCI19013758/Uvd3n2

MARKET VALUE: \$7,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,063.00=NETT VALUE: \$5,937.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.