

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9848X**AAD1908-010**

Not Authored
1/1/2014

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9848X

VF1ABL15AUC277392

RENAULT

LATITUDE

1.8.19

AXA

25/4/2014

PART		LIST	
1	DOOR PANEL REAR LH	\$	2,844.66
1	ROCKER PANEL INNER GARNISH LH	\$	466.51
1	ROCKER PANEL INNER LH	\$	1,024.79
1	ROCKER PANEL OUTER LH	\$	1,184.99
1	ROCKER PANEL CENTER LH	\$	990.25
1	BOOT REFLECTOR LAMP LH	\$	493.35
1	FENDER PANEL REAR LH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR LH	\$	671.45
1	WHEELARCH REAR LH	\$	543.47
1	BUMPER COVER REAR	\$	1,108.46
1	BUMPER LOWER REAR	\$	768.84
1	BUMPER BRACKET CTR REAR	\$	113.47
1	BUMPER BRACKET SIDE LH REAR	\$	135.97
1	BUMPER RETAINER LH REAR	\$	44.99
1	BUMPER REFLECTOR LH	\$	43.61
1	BUMPER BEAM REAR	\$	777.52
1	BUMPER BEAM BRACKET LH REAR	\$	225.95
1	TAILLAMP LH	\$	552.55
1	TAILLAMP PANEL LH	\$	986.70
1	FUEL FLAP	\$	343.57
TOTAL		\$	16,620.23
10%		\$	1,662.02
		\$	14,958.21

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	80.00
1	FENDER INNER TRIM CLIP LH	\$	28.00

Trans-cab Auto Services Pte Ltd**AAD1908-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9848X

1	TAILLAMP CLIP LH	\$	nn	5.00	
1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
1	WINDSCREEN MOULDING	\$	nn	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	REAR LEFT TYRE	\$	ph	300.00	
1	REAR LEFT TYRE RIM	\$	sh	380.00	
1SET	PARKING AID	\$	sh	700.00	
1SET	REAR BUMPER CLIP	\$	nn	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	X
TOTAL		\$		2,025.00	
TOTAL PARTS		\$		16,983.21	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	500 4,500.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 60
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To rust-proofing of the affected areas.	\$	nn 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1908-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9848X

To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>8000</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>100</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	<i>X</i>
TOTAL	\$	12,350.00	
Over All Total	\$	29,333.21	

LUMP SUM (REPAIR DAY)~~**15 DAYS**~~**3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: