

15/5/2010

INS. CASE OWNER:

CC 3/AIG1901 3760, 5/8/19

LKK:

IDAC:

Surveyor:

Steve

DOI:

5/8/19

Date / Time:

5/8/19

Registered in Merimen:

6/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMA 6006E

Name of Insured:

MIS MOTORING PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

2/8/19

Is driver the owner?

( YES / NO )

Nature of Accident:

Claim No.:

888511144656

Policy No.:

99999999

Make / Model:

EIN

Place of Accident:

VICTORIA ST

If NO. Driver Name / Age:

YEO JUN KAO

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHB 1855M



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHB 1855M - X

SMA 6006E - N/A (AIG 1901 3760) / 24 Jun: 26/4/19

13/8/19

- Sent addendum form - for OI/OID to amend on TP VEH number

3/3/2020  
Khandre

File pass to MK to close

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

- 13/8/19 Khandre

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

LIS

S\$ 5,600

( 6 days)

Reduction:

59 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

S\$

100

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

S\$

5,600

Loss of Rental (LOR):

S\$

1200.54

( 11 days)

X \$109.14

Loss of Use (LOU):

S\$

(S x days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

7.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

6,807.54

Global Sum S\$:

6,807

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

S\$

6,807

Name 1:

SMRT TAXIS PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REQ. BY:

Steve

REP:

AIG

## ASSIGNMENT

1855M

From:

Date:

5/8/19

Veh No:

SHB 1855M

Yr Regn:

16/7/14

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SHB 1855M

Make:

Toyota Prius

C.C.

1798

at Workshop m/s

SMRT

Colour

Maroon

A/C:

Insured / Std / NI / NA

of

woodlands Depot

Sp. Reading

528835

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JTOKN364J05747035

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
| X   | X   |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallon

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

6

days

Res.: Yes or No

D.O.A.

2/8/19

D.O.I.

5/8/19

Lum Sum:

20

%

3 Val.: Yes or No

Survey held at

SMRT

CA / REV / REP. / 24 HRS

up

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                    |
|-------------|---------------------------------------------------------|
|             | CUIS \$5,600 (Red \$ 8,086.74/59%).                     |
|             | 6 days + 2 public Holiday + 1 Sunday + 2 PPS = 11 days. |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

1)



Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.L (\$

## Case Details

Case Reference Number : TAX/08/19/2006

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-7930-ID

Accident Date and Time : 02/08/2019 03:30 AM

Vehicle Registration Number : SHB1855M

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 61

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

| BOM Type        | Costing Type | Portion | Material Number | Part Name                     | SMRT Recommendation |                         |                |        |                 |                 | Surveyor Approval |                          |                      |
|-----------------|--------------|---------|-----------------|-------------------------------|---------------------|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------------|
|                 |              |         |                 |                               | Qty                 | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace       |
| One Time Key In | Main         |         |                 | BUMPER CLIPS                  | 10                  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace         | 10                | 12.08                    | Replace <i>APC</i>   |
| One Time Key In | Main         |         |                 | PIXEL STICKER                 | 2                   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace         | 2                 | 120.0                    | Replace <i>APC</i>   |
| One Time Key In | Main         |         |                 | BUMPER REINFORCEMENT REAR     | 1                   | 205.70                  | 205.70         | 25.00  | 154.27          | Replace         | 1                 | 154.27                   | Replace <i>DD</i>    |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY. RR BUMPER LH    | 1                   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace         | 1                 | 104.7                    | Replace <i>DD</i>    |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY. RR BUMPER RH    | 1                   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace         | 1                 | 104.7                    | Replace <i>DD</i>    |
| One Time Key In | Main         |         |                 | ANTENNA,ELECTRICAL LOWER REAR | 1                   | 157.40                  | 157.40         | 10.00  | 141.66          | Replace         | 0                 | 0                        | Check <i>X NM</i>    |
| One Time Key In | Main         |         |                 | SENSOR REVERSE                | 1                   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace         | 1                 | 180.0                    | Replace <i>BR</i>    |
| One Time Key In | Main         |         |                 | BUMPER SEAL, RR LH            | 1                   | 88.90                   | 88.90          | 25.00  | 66.68           | Replace         | 0                 | 0                        | Not Give <i>X NM</i> |
| One Time Key In | Main         |         |                 | BUMPER SEAL, RR RH            | 1                   | 65.70                   | 65.70          | 25.00  | 49.28           | Replace         | 0                 | 0                        | Not Give <i>X NM</i> |
| One Time Key In | Main         |         |                 | BUMPER SIDE RETAINER RR/RH    | 1                   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace         | 1                 | 71.10                    | Replace <i>BR</i>    |
| One Time Key In | Main         |         |                 | BUMPER SIDE RETAINER RR/LH    | 1                   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace         | 1                 | 71.10                    | Replace <i>BR</i>    |
| One Time Key In | Main         |         |                 | BUMPER LIP COVER RR/LH        | 1                   | 72.20                   | 72.20          | 25.00  | 54.15           | Replace         | 1                 | 54.15                    | Replace <i>CR4</i>   |
| One Time Key In | Main         |         |                 | BUMPER LIP COVER RR/RH        | 1                   | 118.10                  | 118.10         | 25.00  | 88.57           | Replace         | 1                 | 88.57                    | Replace <i>CR4</i>   |
| One Time Key In | Main         |         |                 | BUMPER LIP REAR               | 1                   | 228.90                  | 228.90         | 25.00  | 171.68          | Replace         | 1                 | 171.68                   | Replace <i>CR4</i>   |

Total Spare Part Cost 10,968.42

Surveyor Total 4,540.72

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

| BOM Type              | Costing Type | Portion | Material Number | Part Name                        | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace  | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Repla   |
|-----------------------|--------------|---------|-----------------|----------------------------------|-----|-------------------------|----------------|--------|-----------------|------------------|-------------------|--------------------------|----------------|
| One Time Key In       | Main         |         |                 | UNDER COVER SUB-ASSY, RR FLOOR   | 1   | 514.50                  | 514.50         | 25.00  | 385.88          | Replace          | 1                 | 385.88                   | Replace / CRU  |
| One Time Key In       | Main         |         |                 | END PANEL                        | 1   | 602.10                  | 602.10         | 25.00  | 451.58          | Replace          | 1                 | 451.58                   | Replace / DD   |
| One Time Key In       | Main         |         |                 | END PANEL COVER, DECK TRIM HOLE  | 1   | 46.10                   | 46.10          | 25.00  | 34.58           | Replace          | 0                 | 0                        | Check X NAI    |
| One Time Key In       | Main         |         |                 | END PANEL COVER, DECK TRIM, RR   | 1   | 121.10                  | 121.10         | 25.00  | 90.82           | Replace          | 1                 | 90.82                    | Replace / CRU  |
| One Time Key In       | Main         |         |                 | SEALANT SIKAFLEX                 | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace          | 1                 | 37.00                    | Replace / MC   |
| One Time Key In       | Main         |         |                 | BOX, DECK FLOOR, RR              | 1   | 649.70                  | 649.70         | 25.00  | 487.28          | Replace          | 0                 | 0                        | Check X NAI    |
| One Time Key In       | Main         |         |                 | BOX, RR FLOOR, BOARD             | 1   | 679.60                  | 679.60         | 25.00  | 509.70          | Replace          | 0                 | 0                        | Check X NAI    |
| One Time Key In       | Main         |         |                 | SPARE TYRE PANEL                 | 1   | 667.70                  | 667.70         | 25.00  | 500.78          | Replace          | 1                 | 0                        | Repair X R     |
| One Time Key In       | Main         |         |                 | CUSHION, SPARE WHEEL             | 1   | 230.80                  | 230.80         | 25.00  | 173.10          | Replace          | 0                 | 0                        | Check X NAI    |
| One Time Key In       | Main         |         |                 | CARRIER, SPARE                   | 1   | 19.70                   | 19.70          | 25.00  | 14.77           | Replace          | 0                 | 0                        | Check X NAI    |
| One Time Key In       | Main         |         |                 | PROTECTOR, SPARE                 | 1   | 143.70                  | 143.70         | 25.00  | 107.77          | Replace          | 0                 | 0                        | Check X NAI    |
| One Time Key In       | Main         |         |                 | MEMBER SUB-ASSY, RR LH           | 1   | 174.10                  | 174.10         | 25.00  | 130.57          | Replace          | 1                 | 0                        | Repair X R     |
| One Time Key In       | Main         |         |                 | TAILGATE ASY                     | 1   | 1,007.90                | 1,007.90       | 25.00  | 755.92          | Replace          | 1                 | 755.92                   | Replace / DD   |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR GLASS MOULDING, RH | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace          | 1                 | 22.05                    | Replace / MC   |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR GLASS MOULDING, LH | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace          | 1                 | 22.05                    | Replace / MC   |
| One Time Key In       | Main         |         |                 | MOULDING BACK WINDOW, LOWER NO.1 | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace          | 1                 | 22.05                    | Replace / MC   |
| One Time Key In       | Main         |         |                 | SEALANT W/SCREEN                 | 3   | 37.00                   | 111.00         | 0.00   | 111.00          | Replace          | 3                 | 111.0                    | Replace / MC   |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR HINGE LH/RH        | 2   | 58.30                   | 116.60         | 25.00  | 87.45           | Replace          | 0                 | 0                        | Not Give X NAI |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR STAY LH            | 1   | 241.50                  | 241.50         | 25.00  | 181.13          | Replace          | 0                 | 0                        | Not Give X NAI |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR STAY RH            | 1   | 241.50                  | 241.50         | 25.00  | 181.13          | Replace          | 0                 | 0                        | Not Give X NAI |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR LOCK               | 1   | 444.10                  | 444.10         | 25.00  | 333.08          | Replace          | 1                 | 333.08                   | Replace / BT   |
| One Time Key In       | Main         |         |                 | TAILGATE LOCK, COVER             | 1   | 15.70                   | 15.70          | 25.00  | 11.77           | Replace          | 0                 | 0                        | Not Give X NAI |
| Total Spare Part Cost |              |         |                 |                                  |     |                         |                |        | 10,968.42       | Surveyor Total   |                   | 4,540.72                 |                |
| Lump Sum Discount (%) |              |         |                 |                                  |     |                         |                |        | 20.00           | Lump Sum Dis (%) |                   | 20                       |                |

| BOM Type              | Costing Type | Portion | Material Number | Part Name                   | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace         | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Repla          |
|-----------------------|--------------|---------|-----------------|-----------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------------|-------------------|--------------------------|-----------------------|
| One Time Key In       | Main         |         |                 | STRIKER, BACK DOOR          | 1   | 48.90                   | 48.90          | 25.00  | 36.67           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR WEATHER STRIP | 1   | 353.40                  | 353.40         | 25.00  | 265.05          | Replace                 | 1                 | 265.05                   | Replace <i>/ TM</i>   |
| One Time Key In       | Main         |         |                 | TAILGATE, BAORD ASSY        | 1   | 246.90                  | 246.90         | 25.00  | 185.18          | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | TAILGATE OUTSIDE GARNISH    | 1   | 504.90                  | 504.90         | 25.00  | 378.67          | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | EMBLEM REAR                 | 1   | 60.30                   | 60.30          | 25.00  | 45.22           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | LICENSE PLATE LAMP          | 2   | 35.70                   | 71.40          | 25.00  | 53.55           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | CAMERA ASSY, TELEVISION, RR | 1   | 1,436.60                | 1,436.60       | 25.00  | 1,077.45        | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | NAME PLATE (HYBRID)         | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace                 | 1                 | 38.92                    | Replace <i>/ AK</i>   |
| One Time Key In       | Main         |         |                 | NAME PLATE (PRUIS)          | 1   | 60.80                   | 60.80          | 25.00  | 45.60           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | NAME PLATE (TOYOTA)         | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | NUMBER PLATE                | 1   | 15.00                   | 15.00          | 0.00   | 15.00           | Replace                 | 1                 | 15.00                    | Replace <i>/ CUT</i>  |
| One Time Key In       | Main         |         |                 | NUMBER PLATE FRAME          | 1   | 12.00                   | 12.00          | 0.00   | 12.00           | Replace                 | 1                 | 12.00                    | Replace <i>/ CUT</i>  |
| One Time Key In       | Main         |         |                 | STICKER DECAL SMRT          | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | STICKER DECAL 6555 8888     | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | SPOILER REAR                | 1   | 953.70                  | 953.70         | 25.00  | 715.28          | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | FENDER RR/RH                | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | STICKER DECAL SMRT          | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | STICKER DECAL 6555 8888     | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         |                 | TAIL LAMP BRACKET, RH       | 1   | 30.70                   | 30.70          | 25.00  | 23.03           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| One Time Key In       | Main         |         | 10/1            | TAIL LAMP RH                | 1   | 557.80                  | 557.80         | 10.00  | 502.02          | Replace                 | 1                 | 502.02                   | Replace <i>/ CUT</i>  |
| One Time Key In       | Main         |         |                 | TAIL LAMP LH                | 1   | 548.40                  | 548.40         | 10.00  | 493.56          | Replace                 | 0                 | 0                        | Check <i>X N/A</i>    |
| One Time Key In       | Main         |         |                 | TAIL LAMP BRACKET, LH       | 1   | 30.70                   | 30.70          | 25.00  | 23.02           | Replace                 | 0                 | 0                        | Not Give <i>X N/A</i> |
| Total Spare Part Cost |              |         |                 |                             |     |                         |                |        | 10,968.42       | Surveyor Total 4,540.72 |                   |                          |                       |
| Lump Sum Discount (%) |              |         |                 |                             |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20     |                   |                          |                       |

| BOM Type              | Costing Type | Portion | Material Number | Part Name   | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Repla |
|-----------------------|--------------|---------|-----------------|-------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|--------------|
| Standard              | Main         |         | 6505548         | BUMPER REAR | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace                  | 1                 | 343.95                   | Replace      |
| Total Spare Part Cost |              |         |                 |             |     |                         |                |        | 10,968.42       | Surveyor Total 4,540.72  |                   |                          |              |
| Lump Sum Discount (%) |              |         |                 |             |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |              |
| Final Spare Part Cost |              |         |                 |             |     |                         |                |        | 8,774.74        | Final Sur Total 3,632.58 |                   |                          |              |

#### Labour's Cost Detail

| S.No.  | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR REAR PORTION | 1,352.00                | 850                     |         |
| Total: |              |                        | 1,352.00                | 850.00                  |         |

#### Spray Cost Detail

| S.No.  | Costing Type | Job Scope                           | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER              | 378.00                  | 200                     |         |
| 2      | Main         | TO RESPRAY BUMPER BEAM              | 180.00                  | 50                      |         |
| 3      | Main         | TO RESPRAY REAR PANEL               | 180.00                  | 100                     |         |
| 4      | Main         | TO RESPRAY REAR SPARE TYRE PANEL    | 180.00                  | 100                     |         |
| 5      | Main         | TO RESPRAY REAR MEMBER,LH           | 180.00                  | 0                       |         |
| 6      | Main         | TO RESPRAY TAIL GATE                | 378.00                  | 200                     |         |
| 7      | Main         | TO RESPRAY TAILGATE OUTSIDE GARNISH | 180.00                  | 0                       |         |
| 8      | Main         | TO RESPRAY REAR SPOILER             | 180.00                  | 0                       |         |
| 9      | Main         | TO RESPRAY REAR FENDER RH           | 378.00                  | 200                     |         |
| Total: |              |                                     | 2,214.00                | 850.00                  |         |

#### Other Cost Detail

| S.No. | Costing Type | Job Scope                           | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|-------|--------------|-------------------------------------|-------------------------|-------------------------|---------|
| 1     | Main         | TO REMOVE AND REFIX REAR WINDSCREEN | 240.00                  | 100                     | 11K     |
| 2     | Main         | TO CHECK WIRING AND SYSTEM FUNCTION | 80.00                   | 20                      | 11K     |
| 3     | Main         | TO ALIGN CHASSIS                    | 350.00                  | 0                       |         |
| 4     | Main         | TO TRANSFER REAR TAILGATE MECHANISM | 120.00                  | 30                      | 11K     |

|        |      |                                                                         | Recommendation(\$) | Adjustment(\$) |     |
|--------|------|-------------------------------------------------------------------------|--------------------|----------------|-----|
| 5      | Main | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.    | 120.00             | 30             | 110 |
| 6      | Main | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | 120.00             | 20             | 110 |
| 7      | Main | TO APPLY RUST-PROOFING ON AFFECTED AREA                                 | 100.00             | 20             | 110 |
| 8      | Main | TO REPLACE SUNDRY PARTS                                                 | 100.00             | 20             | 110 |
| 9      | Main | TO WASH AND VACUUM                                                      | 60.00              | 0              |     |
| 10     | Main | TOWING CHARGE                                                           | 56.00              | 0              | 40  |
| Total: |      |                                                                         | 1,346.00           | 240.00         | 280 |

## Summary

|                          | Estimator Assesment(\$)                                                              | Surveyor Assesment(\$) |
|--------------------------|--------------------------------------------------------------------------------------|------------------------|
| Total Spare Part Detail  | 8,774.74                                                                             | 3,632.58               |
| Total Labour Cost        | 1,352.00                                                                             | 850.00                 |
| Total Spray Painting     | 2,214.00                                                                             | 850.00                 |
| Other                    | 1,346.00                                                                             | 240.00                 |
| Overall Total            | 13,686.74                                                                            | 5,572.58               |
| Lump Sum Repair Option   |                                                                                      |                        |
| Lump Sum Total           | 13,700.00                                                                            | 5,550.00               |
| Surveyor Approved Amount |                                                                                      | 5,550.00               |
| No of Repair Days*       | 9                                                                                    | 6                      |
| Remarks                  | L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.                |                        |
| Surveyor Name            | STEVE CHEN                                                                           |                        |
| Signature                |  |                        |
| Survey Date              | 05/08/2019                                                                           |                        |

Save

Clear

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date:



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
80 Woodlands Industrial Park E4, Singapore 757105  
Fax Number: 63645502  
Estimator Telephone Number: 68626223  
Accident Reporting Number: 6862472

Date Generated: 03/08/2019  
User ID: PehBun

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1908-0517 | Invoice Number |  |
| Quotation Date   | 29.08.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope              | Quotation from AR | Adjusted by Surveyor, if applicable |
|------------------------|-------------------|-------------------------------------|
| TO REPAIR REAR PORTION | \$1,352.00        | \$850.00                            |
| Total Labour           | \$1,352.00        | \$850.00                            |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR BUMPER               | \$378.00           | \$200.00                            |
| TO RESPRAY BUMPER BEAM               | \$180.00           | \$50.00                             |
| TO RESPRAY REAR PANEL                | \$180.00           | \$100.00                            |
| TO RESPRAY REAR SPARE TYRE PANEL     | \$180.00           | \$100.00                            |
| TO RESPRAY REAR MEMBER, LH           | \$180.00           | \$0.00                              |
| TO RESPRAY TAIL GATE                 | \$378.00           | \$200.00                            |
| TO RESPRAY TAILGATE OUTSIDE GARNISH  | \$180.00           | \$0.00                              |
| TO RESPRAY REAR SPOILER              | \$180.00           | \$0.00                              |
| TO RESPRAY REAR FENDER RH            | \$378.00           | \$200.00                            |
| Total Spray Painting & Panel Beating | \$2,214.00         | \$850.00                            |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------------------------------|--------------------|-------------------------------------|
| TO REMOVE AND REFIX REAR WINDSCREEN                                     | \$240.00           | \$100.00                            |
| TO CHECK WIRING AND SYSTEM FUNCTION                                     | \$80.00            | \$20.00                             |
| TO ALIGN CHASSIS                                                        | \$350.00           | \$0.00                              |
| TO TRANSFER REAR TAILGATE MECHANISM                                     | \$120.00           | \$30.00                             |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR     | \$120.00           | \$30.00                             |
| TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | \$120.00           | \$20.00                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                                 | \$100.00           | \$20.00                             |
| TO REPLACE SUNDRY PARTS                                                 | \$100.00           | \$20.00                             |
| TO WASH AND VACUUM                                                      | \$60.00            | \$0.00                              |
| TOWING CHARGE                                                           | \$56.00            | \$40.00                             |
| Total Other Costs                                                       | \$1,346.00         | \$280.00                            |

## Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                 | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|---------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52161-16010  | BUMPER CLIPS              | 10.00    | \$1.61          | 25.00        | \$12.08          | Replace            | Replace           |
|             |         |              | PIXEL STICKER             | 2.00     | \$60.00         | 0.00         | \$120.00         | Replace            | Replace           |
|             |         | 52023-12240  | BUMPER REINFORCEMENT REAR | 1.00     | \$205.70        | 25.00        | \$154.28         | Replace            | Replace           |



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
50 Woodlands Industrial Park E4, Singapore 757705  
Fax Number: 63685582  
Estimator Telephone Number: 68653823  
Accident Reporting Number: 68652672

Date Generated: 03/08/2018  
User ID: PehSuan

|                |                                  |      |            |        |          |         |           |   |
|----------------|----------------------------------|------|------------|--------|----------|---------|-----------|---|
| 52016-47030    | ARM SUB-ASSY, RR BUMPER LH       | 1.00 | \$139.60   | 25.00  | \$104.70 | Replace | Replace   | ✓ |
| 52015-47050    | ARM SUB-ASSY, RR BUMPER RH       | 1.00 | \$139.60   | 25.00  | \$104.70 | Replace | Replace   | ✓ |
| 89997-30070    | ANTENNA, ELECTRICAL LOWER REAR   | 0.00 | \$157.40   | 0.00   | \$0.00   | Replace | Check     | X |
|                | SENSOR REVERSE                   | 1.00 | \$180.00   | 0.00   | \$180.00 | Replace | Replace   | ✓ |
| 52592-47021    | BUMPER SEAL, RR LH               | 0.00 | \$88.90    | 0.00   | \$0.00   | Replace | Not Given | X |
| 52591-47021    | BUMPER SEAL, RR RH               | 0.00 | \$65.70    | 0.00   | \$0.00   | Replace | Not Given | X |
| 52575-47020    | BUMPER SIDE RETAINER RR/RH       | 1.00 | \$94.80    | 25.00  | \$71.10  | Replace | Replace   | ✓ |
| 52576-47020    | BUMPER SIDE RETAINER RR/LH       | 1.00 | \$94.80    | 25.00  | \$71.10  | Replace | Replace   | ✓ |
| 76088-47020    | BUMPER LIP COVER RR/LH           | 1.00 | \$72.20    | 25.00  | \$54.15  | Replace | Replace   | ✓ |
| 76087-47020    | BUMPER LIP COVER RR/RH           | 1.00 | \$118.10   | 25.00  | \$88.58  | Replace | Replace   | ✓ |
| 76891-47020    | BUMPER LIP REAR                  | 1.00 | \$228.90   | 25.00  | \$171.68 | Replace | Replace   | ✓ |
| 58308-47011    | UNDER COVER SUB-ASSY, RR FLOOR   | 1.00 | \$514.50   | 25.00  | \$385.88 | Replace | Replace   | ✓ |
| 58307-47060    | END PANEL                        | 1.00 | \$602.10   | 25.00  | \$451.58 | Replace | Replace   | ✓ |
| 64718-47031B0  | END PANEL COVER, DECK TRIM HOLE  | 0.00 | \$46.10    | 0.00   | \$0.00   | Replace | Check     | X |
| 64716-47031B0  | END PANEL COVER, DECK TRIM, RR   | 1.00 | \$121.10   | 25.00  | \$90.83  | Replace | Replace   | ✓ |
|                | SEALANT SIKAFLEX                 | 1.00 | \$37.00    | 0.00   | \$37.00  | Replace | Replace   | ✓ |
| 64993-47020    | BOX, DECK FLOOR, RR              | 0.00 | \$649.70   | 0.00   | \$0.00   | Replace | Check     | X |
| 58416-47030B3  | BOX, RR FLOOR, BOARD             | 0.00 | \$679.60   | 0.00   | \$0.00   | Replace | Check     | X |
| 58311-47071    | SPARE TYRE PANEL                 | 1.00 | \$867.70   | 100.00 | \$0.00   | Replace | Repair    | ✓ |
| 64777-47090    | CUSHION, SPARE WHEEL             | 0.00 | \$230.80   | 0.00   | \$0.00   | Replace | Check     | X |
| 51931-47020    | CARRIER, SPARE                   | 0.00 | \$19.70    | 0.00   | \$0.00   | Replace | Check     | X |
| 64778-47050    | PROTECTOR, SPARE                 | 0.00 | \$143.70   | 0.00   | \$0.00   | Replace | Check     | X |
| 57604-47030    | MEMBER SUB-ASSY, RR LH           | 1.00 | \$174.10   | 100.00 | \$0.00   | Replace | Repair    | ✓ |
| 67005-47241    | TAILGATE ASY                     | 1.00 | \$1,007.90 | 25.00  | \$755.93 | Replace | Replace   | ✓ |
| 75573-47080    | TAILGATE DOOR GLASS MOULDING, RH | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
| 75574-47020    | TAILGATE DOOR GLASS MOULDING, LH | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
| 75575-47030    | MOULDING BACK WINDOW, LOWER NO.1 | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
|                | SEALANT W/SCREEN                 | 3.00 | \$37.00    | 0.00   | \$111.00 | Replace | Replace   | ✓ |
| 68810-47010    | TAILGATE DOOR HINGE LH/RH        | 0.00 | \$58.30    | 0.00   | \$0.00   | Replace | Not Given | X |
| 68960-0W532    | TAILGATE DOOR STAY LH            | 0.00 | \$241.50   | 0.00   | \$0.00   | Replace | Not Given | X |
| 68950-0W542    | TAILGATE DOOR STAY RH            | 0.00 | \$241.50   | 0.00   | \$0.00   | Replace | Not Given | X |
| 69350-47030    | TAILGATE DOOR LOCK               | 1.00 | \$444.10   | 25.00  | \$333.08 | Replace | Replace   | ✓ |
| 68415-47020    | TAILGATE LOCK, COVER             | 0.00 | \$15.70    | 0.00   | \$0.00   | Replace | Not Given | X |
| 69431-47010    | STRIKER, BACK DOOR               | 0.00 | \$48.90    | 0.00   | \$0.00   | Replace | Not Given | X |
| 67881-47022    | TAILGATE DOOR WEATHER STRIP      | 1.00 | \$353.40   | 25.00  | \$265.05 | Replace | Replace   | ✓ |
| 67750-47071C0  | TAILGATE, BAORD ASSY             | 0.00 | \$246.90   | 0.00   | \$0.00   | Replace | Not Given | X |
| 76801-47070-B0 | TAILGATE OUTSIDE GARNISH         | 0.00 | \$504.90   | 0.00   | \$0.00   | Replace | Not Given | X |
| 75310-47020    | EMBLEM REAR                      | 0.00 | \$60.30    | 0.00   | \$0.00   | Replace | Not Given | X |
| 81271-53011    | LICENSE PLATE LAMP               | 0.00 | \$35.70    | 0.00   | \$0.00   | Replace | Not Given | X |
| 86790-47040    | CAMERA ASSY, TELEVISION, RR      | 0.00 | \$1,438.60 | 0.00   | \$0.00   | Replace | Not Given | X |
| 75374-47051    | NAME PLATE (HYBRID)              | 1.00 | \$51.90    | 25.00  | \$38.93  | Replace | Replace   | ✓ |



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
80 Woodlands Industrial Park E4, Singapore 757708  
Fax Number: 63655582  
Estimator Telephone Number: 68882623  
Accident Reporting Number: 96662672

Date Generated: 8/30/2019  
User ID: PehBun

|       |             |                         |      |             |       |            |         |           |   |
|-------|-------------|-------------------------|------|-------------|-------|------------|---------|-----------|---|
|       | 75442-47030 | NAME PLATE (PRUIS)      | 0.00 | \$60.80     | 0.00  | \$0.00     | Replace | Not Given | X |
|       | 75443-47030 | NAME PLATE (TOYOTA)     | 0.00 | \$51.90     | 0.00  | \$0.00     | Replace | Not Given | X |
|       |             | NUMBER PLATE            | 1.00 | \$15.00     | 0.00  | \$15.00    | Replace | Replace   | ✓ |
|       |             | NUMBER PLATE FRAME      | 1.00 | \$12.00     | 0.00  | \$12.00    | Replace | Replace   | ✓ |
|       |             | STICKER DECAL SMRT      | 0.00 | \$7.80      | 0.00  | \$0.00     | Replace | Not Given | X |
|       |             | STICKER DECAL 6555 8888 | 0.00 | \$21.60     | 0.00  | \$0.00     | Replace | Not Given | X |
|       | 76085-47910 | SPOILER REAR            | 0.00 | \$953.70    | 0.00  | \$0.00     | Replace | Not Given | X |
|       | 61604-47090 | FENDER RR/RH            | 0.00 | \$766.80    | 0.00  | \$0.00     | Replace | Not Given | X |
|       |             | STICKER DECAL SMRT      | 0.00 | \$7.80      | 0.00  | \$0.00     | Replace | Not Given | X |
|       |             | STICKER DECAL 6555 8888 | 0.00 | \$21.60     | 0.00  | \$0.00     | Replace | Not Given | X |
|       | 52562-47010 | TAIL LAMP BRACKET, RH   | 0.00 | \$30.70     | 0.00  | \$0.00     | Replace | Not Given | X |
|       | 81551-47180 | TAIL LAMP RH            | 1.00 | \$557.80    | 10.00 | \$502.02   | Replace | Replace   | ✓ |
|       | 81561-47170 | TAIL LAMP LH            | 0.00 | \$548.40    | 0.00  | \$0.00     | Replace | Check     | X |
|       | 52563-47010 | TAIL LAMP BRACKET, LH   | 0.00 | \$30.70     | 0.00  | \$0.00     | Replace | Not Given | X |
|       | 52159-47905 | BUMPER REAR             | 1.00 | \$458.60    | 25.00 | \$343.95   | Replace | Replace   | ✓ |
| Total |             |                         |      | \$13,951.41 |       | \$4,540.77 |         |           |   |

|                                                              |         |              |           |          |               |              |                  |           |                |
|--------------------------------------------------------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Added Spare Parts / Material Usage After Surveyor Signed off |         |              |           |          |               |              |                  |           |                |
| Part Number                                                  | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
| Total                                                        |         |              |           |          |               |              |                  |           |                |

4540.77

- 202

3632.62

+ 850.00

+ 1130.00

5612.62

4/3 \$5600/-

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

|                                                                                                                                                                                                                         |                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                                      |
| Owner ID Type:                                                                                                                                                                                                          | Company                              |
| Owner ID:                                                                                                                                                                                                               | 369K                                 |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                                      |
| Vehicle No.:                                                                                                                                                                                                            | SHB1855M                             |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                                   |
| Intended Deregistration Date:                                                                                                                                                                                           | 05 Aug 2019                          |
| Vehicle Make:                                                                                                                                                                                                           | TOYOTA                               |
| Vehicle Model:                                                                                                                                                                                                          | PRIUS TAXI (SMRT)                    |
| Primary Colour:                                                                                                                                                                                                         | Maroon                               |
| Manufacturing Year:                                                                                                                                                                                                     | 2014                                 |
| Engine No.:                                                                                                                                                                                                             | 2ZR6096086                           |
| Chassis No.:                                                                                                                                                                                                            | JTDKN36U305747035                    |
| Maximum Power Output:                                                                                                                                                                                                   | 100.0 kW (134 bhp)                   |
| Open Market Value:                                                                                                                                                                                                      | \$32,920.00                          |
| Original Registration Date:                                                                                                                                                                                             | 16 Jul 2014                          |
| First Registration Date:                                                                                                                                                                                                | 16 Jul 2014                          |
| Transfer Count:                                                                                                                                                                                                         | 0                                    |
| Actual ARF Paid:                                                                                                                                                                                                        | \$8,088.00                           |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                                      |
| PARF Eligibility:                                                                                                                                                                                                       | Yes                                  |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | 15 Jul 2022                          |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$5,661.00                           |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                                      |
| COE Expiry Date:                                                                                                                                                                                                        | 15 Jul 2022                          |
| COE Category:                                                                                                                                                                                                           | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                                                                                                                                                                                                      | 8                                    |
| PQP Paid:                                                                                                                                                                                                               | \$53,269.00                          |
| COE Rebate Amount:                                                                                                                                                                                                      | \$19,599.00                          |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$25,260.00</b>                   |
| <b>Message</b>                                                                                                                                                                                                          |                                      |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                                      |

The information contained herein is correct as at 05 Aug 2019

OK

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.  
 Attn : Foo, Chit Yan

Your Ref : 8885111446SG  
 Our Ref : CC3/AIG19013760/EKB3  
 Date : 02 Jan 2020

**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SMA6006K & SHB1855M ON 02/08/2019**

Refer to the above accident.

The accident occurred when 4 vehicle chain collision, Insured vehicle last (BOLA 28). We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SMA6006K) and third party claimant (vehicle no. SHB1855M).

Summary of offer made to workshop SMRT Automotive Services Pte Ltd is as follows :

|                                     | Claimed             | Revised                          |
|-------------------------------------|---------------------|----------------------------------|
| Cost of Repairs                     | \$ 13,686.74        | \$ 5,600.00                      |
| Loss of Rental (12 days x \$109.14) | \$ 1,309.68         | \$ 1,200.54 (11 days x \$109.14) |
| Loss of Income (12 days x \$60)     | \$ 720.00           | \$ 660.00 (11 days x \$60)       |
| LTA Search                          | \$ 7.00             | \$ 7.00                          |
| <b>TOTAL</b>                        | <b>\$ 15,723.42</b> | <b>\$ 7,467.54</b>               |

Amount of claim at **Liability 100%**      \$ 7,467.54

Enclose herewith the relevant supporting documents for your perusal.

\*\* 6 days recommendation for repair + 2 Public Holidays + 1 Sunday + 2 PRS = 11 days

For your approval please.

Regards,  
 Khanchna Pothuraj  
 LKK Auto Consultants Pte Ltd

## Print Received Message

This mail is associated with :

**\*SHB1855M (8885111446SG)**

**[SMA6006K]**

TP

SMRT TAXIS PTE LTD

Aug 2 2019 11:00AM

[BIS MOTORING PTE LTD]

SMRT Automotive Services Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 17/02/2020 15:48 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$7357.54) - SHB1855M - Claim Handler: Foo, Chit Yan

Approved:7357.54;Cost of Repair: \$5,600.00 Loss of rental: \$1,200.54 (\$109.14 x 11 days) Loss of income: \$550.00 (\$50.00 x 11 days) LTA: \$7.00 Total: \$7,357.54 Subject to final repair bill, LTA receipts and other supporting documents

## **Khanchna (LKK Auto)**

---

**From:** Khanchna (LKK Auto)  
**Sent:** Monday, 24 February 2020 9:46 AM  
**To:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)  
**Cc:** Admin A  
**Subject:** RE: URGENT / FINAL REMINDER Re: ACCIDENT INVOLVING SHB 1855M, SMA 6006K (AIG'S INSURED) & SLM 2951G (Our Ref: TAX/08/19/2006/lg)

### **Without Prejudice**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement on a global sum for **\$7,357.00(all in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: **6841 2360** | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Suwanna (LKK Auto) [<mailto:Suwanna@lkkauto.com>]

**Sent:** 18/09/2019 15:08

**To:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)

**Cc:** Khanchna (LKK Auto); Admin A; CS A Team

**Subject:** FW: LOD RE: ACCIDENT INVOLVING SHB 1855M, SMA 6006K (AIG'S INSURED) & SLM 2951G (Our Ref: TAX/08/19/2006/lg)

### **Without Prejudice**

Dear Sir / Madam,

Thank you for your email.

Please be informed that this matter is now handled by my colleague, Miss Khanchna.

Hi Khanchna,

FYNA, our ref CC3/AIG19013760/Ekb3

## **Khanchna (LKK Auto)**

---

**From:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>  
**Sent:** Friday, 28 February 2020 5:34 PM  
**To:** Khanchna (LKK Auto)  
**Subject:** Important Re: ACCIDENT INVOLVING SHB 1855M, SMA 6006K (AIG'S INSURED) & SLM 2951G (Our Ref: TAX/08/19/2006/lg)  
**Attachments:** img-228165622-0001.pdf

Dear Khanchna,

Sorry for the error as we have just realised that our hirer has claimed his loss of income under his injury claim as he has 13 days of medical leave. Hence we now withdraw his claim for loss of income. Please let us have your fresh offer excluding the loss of income. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)  
Claims Department  
SMRT Automotive Services Pte Ltd



---

**From:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)  
**Sent:** Friday, February 28, 2020 5:20 PM  
**To:** Khanchna (LKK Auto)  
**Cc:** Admin A  
**Subject:** Returned of DV Re: ACCIDENT INVOLVING SHB 1855M, SMA 6006K (AIG'S INSURED) & SLM 2951G (Our Ref: TAX/08/19/2006/lg)

Dear Khanchna,

We attach the duly signed DV and ATA for your necessary action. Please let us have AIG's cheque for \$7,357.00 in respect of our own losses payable to **SMRT TAXIS PTE LTD**. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)  
Claims Department  
SMRT Automotive Services Pte Ltd



---

**From:** Khanchna (LKK Auto) [<mailto:khanchna@lkkauto.com>]  
**Sent:** Friday, February 28, 2020 1:37 PM  
**To:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)  
**Cc:** Admin A

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Monday, 2 March 2020 9:09 AM  
**To:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)  
**Cc:** Admin A  
**Subject:** RE: Important Re: ACCIDENT INVOLVING SHB 1855M, SMA 6006K (AIG'S INSURED) & SLM 2951G (Our Ref: TAX/08/19/2006/lg)

| Tracking: | Recipient                                             | Delivery                    |
|-----------|-------------------------------------------------------|-----------------------------|
|           | Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) |                             |
|           | Admin A                                               |                             |
|           | olivialau@lkkauto.com                                 | Delivered: 2/3/2020 9:09 AM |
|           | Meikwan@lkkauto.com                                   | Delivered: 2/3/2020 9:09 AM |

### Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement on a global sum for **\$6,807.00(all in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <[LeeGek@smrt.com.sg](mailto:LeeGek@smrt.com.sg)>  
**Sent:** Friday, 28 February 2020 5:34 PM  
**To:** Khanchna (LKK Auto) <[khanchna@lkkauto.com](mailto:khanchna@lkkauto.com)>  
**Subject:** Important Re: ACCIDENT INVOLVING SHB 1855M, SMA 6006K (AIG'S INSURED) & SLM 2951G (Our Ref: TAX/08/19/2006/lg)

Dear Khanchna,