

Case Details

Case Reference Number : TAX/08/19/2008

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-7930-ID

Accident Date and Time : 02/08/2019 03:30 AM

Vehicle Registration Number : SHB1855M

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 61

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	Part Name	SMRT Recommendation					Repair/ Replace	Surveyor Approval		
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace / AC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace / AC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.28	Replace / DO
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace / DO
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace / DO
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check X MI
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace / BR
One Time Key In	Main			BUMPER SEAL, RR LH	1	66.90	66.90	25.00	50.18	Replace	0	0	Not Give X MI
One Time Key In	Main			BUMPER SEAL, RR RH	1	66.70	66.70	25.00	50.03	Replace	0	0	Not Give X MI
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace / BR
One Time Key In	Main			BUMPER SIDE RETAINER RRLH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace / BR
One Time Key In	Main			BUMPER LIP COVER RRLH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace / BR
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace / BR
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace / BR

Total Spare Part Cost 10,968.42

Surveyor Total 4,540.72

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Repla
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	1	385.88	Replace / CR
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.58	Replace / ON
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check X NW
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	1	90.82	Replace / CR
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace / NC
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Check X NW
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Check X NW
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	1	0	Repair X R
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check X NW
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Check X NW
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check X NW
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	1	0	Repair X R
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace / ON
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace / NC
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace / NC
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace / NC
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.0	Replace / NC
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give X NW
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give X NW
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give X NW
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.08	Replace / BT
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give X NW
					Total Spare Part Cost		10,966.42		Surveyor Total		4,540.72		
					Lump Sum Discount (%)		20.00		Lump Sum Dis (%)		20		

BOM Type	Coasting Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	1	285.05	Replace / <i>TN</i>
One Time Key In	Main			TAILGATE, BAORD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			TAILGATE OUTSIDE GARMISH	1	504.90	504.90	25.00	379.67	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	25.00	53.55	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			CAMERA ASSY, TELEVISION, RH	1	1,436.60	1,436.60	25.00	1,077.45	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace / <i>AK</i>
One Time Key In	Main			NAME PLATE (PRUIS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace / <i>CM</i>
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace / <i>CM</i>
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			STICKER DECAL 6555 6555	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			FENDER RR/RH	1	766.90	766.90	25.00	575.10	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			STICKER DECAL 6555 6555	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.03	Replace	0	0	Not Givt X <i>MM</i>
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.02	Replace / <i>CM</i>
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Check X <i>MM</i>
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Givt X <i>MM</i>
					Total Spare Part Cost		10,968.42		Surveyor Total		4,540.72		
					Lump Sum Discount (%)		20.00		Lump Sum Dis (%)		20		

SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main		6506548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace
Total Spare Part Cost									10,968.42	Surveyor Total		4,540.72	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20	
Final Spare Part Cost									8,774.74	Final Sur Total		3,832.58	

OR

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,352.00	850	
Total:			1,352.00	850.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	50	
3	Main	TO RESPRAY REAR PANEL	180.00	100	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	100	
5	Main	TO RESPRAY REAR MEMBER, LH	180.00	0	
6	Main	TO RESPRAY TAIL GATE	378.00	200	
7	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
8	Main	TO RESPRAY REAR SPOILER	180.00	0	
9	Main	TO RESPRAY REAR FENDER RH	378.00	200	
Total:			2,214.00	850.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100	MC
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	MC
3	Main	TO ALIGN CHASSIS	350.00	0	
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	30	MC

			Recommendation(\$)	Adjustment(\$)	
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30	11K
6	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	11K
7	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	11K
8	Main	TO REPLACE SUNDRY PARTS	100.00	20	11K
9	Main	TO WASH AND VACUUM	60.00	0	
10	Main	TOWING CHARGE	56.00	8	40
Total:			1,346.00	240.00	280

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	8,774.74	3,632.58
Total Labour Cost	1,352.00	850.00
Total Spray Painting	2,214.00	850.00
Other	1,346.00	240.00
Overall Total	13,686.74	5,572.58
Lump Sum Repair Option		
Lump Sum Total	13,700.00	5,550.00
Surveyor Approved Amount		5,550.00
No of Repair Days*	9	6
Remarks		
Surveyor Name		STEVE CHEN
Signature		

L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.

Survey Date 05/08/2019

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHB1855M
Case Reference Number	TAX/08/19/2006
Registration Date	16/7/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	M PANDEYAN
Type of Accident	Head to Rear
Accident Date and Time	2/8/2019 11:30 AM
Accident Reported Date and Time	2/8/2019 3:16 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	2/8/2019 11:45 AM
Replacement Vehicle issued?	No
Job Card Number	24102687
Special Instruction to ARC, if any	REAR PORTION/AIG-LKK
Prepared Date and Time	4/8/2019 5:43 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$850.00
Total Spray Cost	\$2,214.00	\$850.00
Total Spare Part Cost	\$8,774.74	\$3,632.62
Total Other Cost	\$1,346.00	\$280.00
TOTAL COST	\$13,686.74	\$5,612.62
Lump Sum Total	\$13,700.00	\$5,600.00 (L/S)
Number of Repair Days	9.0	6.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	05/08/2019 3:18 PM	05/08/2019 2:32 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0517	Invoice Number	
Quotation Date	29.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,352.00	\$850.00
Total Labour	\$1,352.00	\$850.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$50.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00
TO RESPRAY REAR MEMBER, LH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,214.00	\$850.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$100.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$1,348.00	\$280.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
65 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 69682823
Accident Reporting Number : 69682672

Date Generated : 03/08/2018

User ID : PohSuan

52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	✓
52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	✓
89997-30070	ANTENNA, ELECTRICAL LOWER REAR SENSOR REVERSE	0.00	\$157.40	0.00	\$0.00	Replace	Check	X
		1.00	\$180.00	0.00	\$180.00	Replace	Replace	✓
52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X
52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace	✓
76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace	✓
76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	✓
58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace	✓
58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace	✓
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
64718-47031B0	END PANEL COVER, DECK TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace	✓
	SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	✓
64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Check	X
58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Check	X
58311-47071	SPARE TYRE PANEL	1.00	\$667.70	100.00	\$0.00	Replace	Repair	✓
64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Check	X
51931-47020	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	Check	X
64778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Check	X
57604-47030	MEMBER SUB-ASSY, RR LH	1.00	\$174.10	100.00	\$0.00	Replace	Repair	✓
67005-47241	TAILGATE ASSY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	✓
75573-47080	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75574-47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓
68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	X
68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X
68950-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X
69350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace	✓
69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	X
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given	X
67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	✓
67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Not Given	X
76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X
75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
81271-53011	LICENSE PLATE LAMP	0.00	\$35.70	0.00	\$0.00	Replace	Not Given	X
86790-47040	CAMERA ASSY, TELEVISION, RR	0.00	\$1,436.80	0.00	\$0.00	Replace	Not Given	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757708
FAX Number : 63685592
Estimate Telephone Number : 68602623
Accident Reporting Number : 6662672

Date Generated : 03/09/2019

User ID : PohSuan

	75442-47030	NAME PLATE (PRUIS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X
	75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	✓
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	✓
		STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	X
	61604-47080	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X
	81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	✓
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Check	X
	52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X
	52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	✓
Total				\$13,951.41		\$4,540.77			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

4540.77

- 202

3632.62

+ 850.00

+ 1130.00

5612.62

4/3 \$5600/-