

ASS. REC. BY:

REF: es/FCI/9013761/R/d3

n2

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person):

Sikhara

of

FCI

Date/Time: 11:32am @ 6/8/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBT 433E

Insured:

SHB 3364A

at Workshop m/s

Mova Automotive

Tel:

6272 3842

of

Blk 1008, Blk memb Jene 3 #01-04

Policy No:

Claim No:

D19005066MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02/08/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 11:43am @ 6/8/19

Person Contacted:

Nidher

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Tohmy!!

SBT 433E-X

SHB 3364A-X.

7/8/19

Email preli revised to FCI

ASS. REC. BY:

REF:

FCT

857F

ASSIGNMENT

From:

Date:

6/6/19

Veh No:

SBT 433E

Yr Regn:

2017 / may

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SBT 433E

Make:

HYUNDAI ELANTRA 1.6

c.c. 1591

at Workshop m/s

MOVA

Colour:

Red

A/C:

Insured / Std / NI / NA

of

Blk 1008 Bkt manih lane 3 #01-04

Sp. Reading

60944

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

KM4D841CM4 U4 62637

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

car In Ready

Modi: Nil / SRim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

225/45R17

R:

Remark: The veh had commenced its repair at the time of inspection.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs: days Res.: Yes or No

D.O.A.

02/08/19

D.O.I.

06/08/19

Lum Sum: % 3 Val.: Yes or No

Survey held at

MOVA

CA / REV / REP. / 24 HRS

(DS)


Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
05/09/19	Confirmed P/P \$ 2,526.00 @ 4 days with Resul (\$ 295.20 red - 11%)
	RECEIVED 05 SEP 2019
	

Date/Time, File Pass to?

05/09/19
Type

Date/Time, File Return to?

3)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Survey Fee:

110

Transportation:

50

S + PS, St

50

Photos

40

Other:

TOTAL

250

Report Format:

Lump Sum / L.B.F/S \$ 2,526.00 P/P



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005066MFSH

Our Ref: CS/FCI19013761/R1sd3

Date : 7/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO: SBT 433E


We thank you for your instruction on 6/8/2019

Please be informed that we had conducted the inspection of the above mentioned
6/8/2019 at the premises of M/s MOVA AUTOMOTIVE PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$2,821.20
Revised Estimate Amount	: S\$2,480.40
"Check" Items Amount	: S\$60.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-08-2019	Our Ref No. D19005066MFSH
Accident Date	02-08-2019	Claim Type. Third Party
Insured Vehicle	SHB3364A	Third Party Vehicle. SBT433E
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 August 2019 10:51 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005066MFSH/1-SBT 433E
Attachments: SBT 433E PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SBT 433E
Date of survey: 6/8/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 6 August 2019 12:14 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005066MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 August 2019 11:32 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005066MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

RE: FINALIZATION: SBT433E - TP/FCI - HYUNDAI ELANTRA 1.6 (DOA 02.08.2019)

Rasul (LKKAuto)

Thu 5/9/2019 11:26 AM

To: Jacelyn <jacelyn@nova.com.sg>

Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Hi Jacelyn,

Finalised amount confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Jacelyn [mailto:jacelyn@nova.com.sg]

Sent: Monday, 2 September, 2019 7:44 PM

To: Rasul (LKKAuto)

Cc: SUR

Subject: FINALIZATION: SBT433E - TP/FCI - HYUNDAI ELANTRA 1.6 (DOA 02.08.2019)

Dear Rasul,

Please find the attached 'Marking Estimate' & After-Paint' photographs for your reference.

We propose the finalize amount at Part-By-Part \$ 2,526.00 with 4 working days. Kindly revert.

Best Regards,

Jacelyn Ooi

Estimator

Nova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system.

Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1006,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

02/08/2019

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Page # :- 1

Veh # :- SBT433E

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK419493

Claim # :- TP/CK135735

ACC. Date :- 02/08/19

Terms :- C.O.D Days

Remarks :- MFG 23 MAY 2017 (2017)

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID LOGO <i>new</i>	1	PC 38.00	38.00
2.	BOOT LID EMBLEM - ELANTRA <i>new</i>	1	PC 48.00	48.00
3.	BOOT LID EMBLEM - S <i>new</i>	1	PC 28.00	28.00
4.	REAR BUMPER <i>de</i>	1	PC 469.00	469.00
5.	REAR BUMPER REFLECTOR LH <i>200</i>	1	PC 49.00	49.00
6.	REAR BUMPER REFLECTOR RH <i>200</i>	1	PC 49.00	49.00
7.	REAR BUMPER LOWER GARNISH <i>cr</i>	1	PC 268.00	268.00
8.	REAR BUMPER UNDER COVER LH <i>200</i>	1	PC 57.00	57.00
9.	REAR BUMPER SIDE RETAINER LH <i>X 80</i>	1	PC 44.00	44.00
10.	REAR BUMPER SIDE RETAINER RH <i>new</i>	1	PC 44.00	44.00
11.	REAR BUMPER REINFORCEMENT <i>bt</i>	1	PC 480.00	480.00
12.	REAR BUMPER INNER BRACKET TOP LH <i>? x 80</i>	1	PC 15.00	15.00
13.	REAR BUMPER INNER BRACKET TOP RH <i>? x 80</i>	1	PC 15.00	15.00
14.	REAR BUMPER INNER BRACKET BOTTOM LH <i>? x 80</i>	1	PC 15.00	15.00
15.	REAR BUMPER INNER BRACKET BOTTOM RH <i>? x 80</i>	1	PC 15.00	15.00
16.	REAR BUMPER INNER BRACKET BOTTOM CTR <i>? x 80</i>	1	PC 15.00	15.00
17.	REAR BUMPER CLIPS <i>new</i>	10	PC 4.00	40.00
18.	END PANEL - REPAIR	1	PC	
19.	BOOT LID - REPAIR	1	PC	
LIST TOTAL S\$				1,689.00
20% DISCOUNT S\$				-337.80
				1,351.20
SPECIAL NET ITEMS :				
1.	REVERSE SENSOR <i>new</i>	1	PC 220.00	220.00
SPECIAL NET TOTAL S\$				220.00
LABOUR :				
TO INSTALL REVERSE SENSOR & CHECK WIRING				50.00
TO REPAIR ON END PANEL & BOOT LID, TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION				500 600.00
TO SPRAY PAINT ON REPAIRED AREAS				500 600.00
LABOUR TOTAL S\$				1,250.00

Estimate

02/08/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- **XA026**

Page # :- 1 135735
Veh # :- SBT433E
Veh Model :- HYUNDAI ELANTRA
Estimate# :- CK419493
Claim # :-
ACC. Date :- 02/08/19
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : **(65) 6272 3892**
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	2,821.20
GST @ 7 %	197.48

AMOUNT DUE S\$	3,018.68
----------------	----------

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Jaclyn

Rasue
13/8/19
Hp 90010068
4 days
P/P
06/08/19 @ 1540
Reevy before part



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

02/08/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention:- XA026

Page # :- 1

Veh # :- SBT433E

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK419493

Claim # :- TP/CK135735

ACC. Date :- 02/08/19

Terms :- C.O.D Days

Remarks :- MFG 23 MAY 2017 (2017)

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID LOGO <i>see</i>	1 PC	38.00	38.00
2.	BOOT LID EMBLEM - ELANTRA <i>see</i>	1 PC	48.00	48.00
3.	BOOT LID EMBLEM - S <i>see</i>	1 PC	28.00	28.00
4.	REAR BUMPER <i>see</i>	1 PC	469.00	469.00
5.	REAR BUMPER REFLECTOR LH <i>see</i>	1 PC	49.00	49.00
6.	REAR BUMPER REFLECTOR RH <i>see</i>	1 PC	49.00	49.00
7.	REAR BUMPER LOWER GARNISH <i>see</i>	1 PC	268.00	268.00
8.	REAR BUMPER UNDER COVER LH <i>Cracked</i>	1 PC	57.00	57.00
9.	REAR BUMPER SIDE RETAINER LH <i>X</i>	1 PC	44.00	44.00
10.	REAR BUMPER SIDE RETAINER RH <i>see</i>	1 PC	44.00	44.00
11.	REAR BUMPER REINFORCEMENT <i>see</i>	1 PC	480.00	480.00
12.	REAR BUMPER INNER BRACKET TOP LH <i>?</i>	1 PC	15.00	15.00
13.	REAR BUMPER INNER BRACKET TOP RH <i>?</i>	1 PC	15.00	15.00
14.	REAR BUMPER INNER BRACKET BOTTOM LH <i>?</i>	1 PC	15.00	15.00
15.	REAR BUMPER INNER BRACKET BOTTOM RH <i>?</i>	1 PC	15.00	15.00
16.	REAR BUMPER INNER BRACKET BOTTOM CTR <i>?</i>	1 PC	15.00	15.00
17.	REAR BUMPER CLIPS <i>see</i>	10 PC	4.00	40.00
18.	END PANEL - REPAIR	1 PC		
19.	BOOT LID - REPAIR	1 PC		
LIST TOTAL S\$			1570.00	1,689.00
20% DISCOUNT S\$			- 20%	-337.80
			1256.00	1,351.20

SPECIAL NET ITEMS :				
1.	REVERSE SENSOR <i>see</i>	1 PC	220.00	220.00
SPECIAL NET TOTAL S\$			220.00	220.00

LABOUR :
TO INSTALL REVERSE SENSOR & CHECK WIRING

TO REPAIR ON END PANEL & BOOT LID, TO REMOVE
& REPLACE DAMAGED ITEMS, REALIGN CONNECTION

TO SPRAY PAINT ON REPAIRED AREAS

LABOUR TOTAL S\$

50.00
500
~~500~~ 600.00
500 600.00
1050.00 1,250.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Page # :- 1 135735

Veh # :- SBT433E

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK419493

Claim # :-

ACC. Date :- 02/08/19

Terms :- C.O.D Days

Remarks :-

Estimate

02/08/2019

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

2,821.20

GST @ 7 %

197.48

AMOUNT DUE S\$

3,018.68

Jaclyn

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Part : \$ 1256.00

SN : \$ 220.00

Lab : \$ 1050.00

\$ 2526.00
Issue
HP 90010068
4 days
P/P
06/08/19 @ 1540
Recovery before part



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013761/R1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3364A	Veh. Inspected	SBT 433E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005066MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	06/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA 1.6	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMHU462637	Colour	RED	
Odometer	60944	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2019	Inspection Date	06/08/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBT 433E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID LOGO	NECESSARY	38.00	38.00
1	BOOT LID EMBLEM-ELANTRA	NECESSARY	48.00	48.00
1	BOOT LID EMBLEM-S	NECESSARY	28.00	28.00
1	REAR BUMPER	DEFORMED	469.00	469.00
1	REAR BUMPER REFLECTOR LH	CRACKED	49.00	49.00
1	REAR BUMPER REFLECTOR RH	CRACKED	49.00	49.00
1	REAR BUMPER LOWER GARNISH	CRACKED	268.00	268.00
1	REAR BUMPER UNDER COVER LH	CRACKED	57.00	57.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	44.00	-
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	44.00	44.00
1	REAR BUMPER REINFORCEMENT	BENT	480.00	480.00
1	REAR BUMPER INNER BRACKET TOP LH	SERVICEABLE	15.00	-
1	REAR BUMPER INNER BRACKET TOP RH	SERVICEABLE	15.00	-
1	REAR BUMPER INNER BRACKET BOTTOM LH	SERVICEABLE	15.00	-
1	REAR BUMPER INNER BRACKET BOTTOM RH	SERVICEABLE	15.00	-
1	REAR BUMPER INNER BRACKET BOTTOM CTR	SERVICEABLE	15.00	-
10	REAR BUMPER CLIPS @\$4.00	NECESSARY	40.00	40.00
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	BOOT LID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-337.80	-314.00
			1,351.20	1,256.00
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	NOT WORKING	220.00	220.00
			220.00	220.00
LABOUR				
	TO INSTALL REVERSE SENSOR & CHECK WIRING.		50.00	50.00
	TO REPAIR ON END PANEL & BOOT LID.TO REMOVE & REPLACE DAMAGED ITEMS.REALIGN CONNECTION.		600.00	500.00

Report Ref No. CS/FCI19013761/R1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON REPAIRED AREAS.		600.00	500.00
			1,250.00	1,050.00
GRAND TOTAL			2,821.20	2,526.00
RECOMMENDED COST OF REPAIRS				2,526.00

Report Ref No. CS/FCI19013761/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.