

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

LKK Auto Consult
 the Repairer of the
 To resurvey before/after
 • To display damaged parts
 • Parts prices are subject to final approval
 • Third party survey is on a "best estimate" basis
 • No illegal modification(s)
 • Supplementary item(s) is subject to final approval
 Acknowledged by Repairer
 Signature:
 Date:

6/8/2019

Your ref :

M/S INDIA INT'L INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR: 5JX8070A

List Items

- | | | |
|----|-------|------------------------------|
| 1 | 1 PC | FRONT RH DOOR |
| 2 | 1 PC | FRONT RH FENDER |
| 3 | 1 PC | FRONT HEADLAMP RH |
| 4 | 1 PC | FRONT BUMPER |
| 5 | 1 SET | FRONT BUMPER CLIPS |
| 6 | 1 PC | FRONT BUMPER RH RETAINER |
| 7 | 1 PC | FRONT RH FENDER SHIELD |
| 8 | 1 SET | FRONT RH FENDER SHIELD CLIPS |
| 9 | 1 PC | FRONT RH KNUCKLE ARM |
| 10 | 1 PC | FRONT RH SHOCK ABSORBER |
| 11 | 1 PC | FRONT RH KNUCKLE ARM BEARING |
| 12 | 1 PC | FRONT RH LOWER ARM |

door	\$	1,600.97	α
body	\$	600.99	—
	\$	633.96	?
car/de	\$	1,433.60	—
nr	\$	70.00	—
3.4	\$	130.71	—
7.1.1	\$	160.97	—
nr	\$	35.00	—
	\$	800.99	?
	\$	533.70	?
	\$	488.96	?
	\$	533.75	?
	\$	7,023.60	
LESS 10%	\$	(702.36)	
	\$	6,321.24	
car/de	\$	1,399.60	4805.w
	\$	880.00	600
	\$	50.00	20
	\$	680.00	400
	\$	400.00	120
	\$	80.00	30
	\$	80.00	60
	\$	9,290.84	

- | | | |
|----|------|---|
| 13 | 1 PC | TYRE RIM (FRONT RH) |
| 14 | | SPRAY PAINTING |
| 15 | | CHECK WIRING |
| 16 | | LABOUR CHARGE TO REMOVE AND RENEW PARTS |
| 17 | | TO REMOVE AND REFIX UNDERCARRIAGE PART |
| 18 | | TUFF KOTE |
| 19 | | WHEEL ALIGNMENT |

Not Allowed
 2/5/5
 the pre. After 4 day.
 6/8/18