

INS. CASE OWNER:

cc 4, ALG 190 13772, Uda352

LKK:

IDAC:

LIFE 2019

Surveyor:

CKS

DOI:

ASSIGNMENT

21/8/19

Date / Time:

6/8/2019

Registered in Merimen:

6/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

GW8707M

Name of Insured:

KST Auto Rental Pte Ltd

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

3/8/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLE 8018 D



INSRS:

WSP:

Tel:

Liability:

RMKS:

Jazz
pml

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLE 8018 D
GW8707M
NAPAC 120130431 v3 : 009: 3/8/19
CAMEL 700 546164302 : 00A: 11/11/19

16-10-19 WE ARE LIKELY TO BE BLAMED FOR CAUSING THE ACCDT
(SEE COMMENTS)

11/11/19 - FILED PM) TO HMIL TO CLOSE

11/11 Final bill different in settlement amount.
(including. LOR).

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : NIL

If NO or B 28, Ass. Lia :

Repair Cost: (w/45)

S\$ 10486.00

Loss of Rental (LOR):

S\$ 900.00

(9 days) x \$100

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 11386.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 11386.00

Name 1:

Jazz Performance Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

COPY SENT
11/11/19

(08/11/13) wef

ASS. REC. BY: *MORUS*

REF:

ALU

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SL E8018D*at Workshop m/s *Jus 03-51*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *63*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *7* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: *net 16964*Date / Time Action / Instruction *net 16964**11A 46036 by 11/11/13
Direct author.**45 - \$9800 (Red \$27872.56 / 742)*Veh No: *SL E8018D* Yr Regn: *1/8, 10*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*Make: *Horde veez* C.C. *1496*Colour: *s.hen* A/C: Insured / Std / NI / NASp. Reading: *5-2039* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *RU 1116572*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt or *del*Brake: *In order* / Jammed / Leaked / Burnt orModi: Nil / *S/Rim* / STD A/Rim orTyre Size: F: *215/55ZR17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *2umHO*Front: *6* Rear: *6*

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. *6* mm L/Bal. *6* mmD.O.A. *3/8/19* D.O.I. *7/8/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*0/5 RL - 0/5 Body &*The *U/C* / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	070G
Vehicle Details	
Vehicle No.:	SLE8018D
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B4036577
Chassis No.:	RU11116572
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,015.00
Original Registration Date:	01 Aug 2016
First Registration Date:	01 Aug 2016
Transfer Count:	2
Actual ARF Paid:	\$10,021.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jul 2026
PARF Rebate Amount:	\$7,515.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$38,521.00
Total Rebate Amount:	\$46,036.00

The information contained herein is correct as at 08 Aug 2019

OK

Pixel 3a

Google Pixel 3a. Get the latest phone today.

vezel

Price Range ▼

Depreciation ▼

2016 ▼

Vehicle Type ▼



Home » Used Cars » YS Auto Pte Ltd » Honda Vezel 1.5A X

Honda Vezel 1.5A X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$63,800**Depreciation** ?

\$9,200 /yr

View models with similar depre

Reg Date

14-Jan-2016

(6yrs 5mths 5days COE left)

Mileage

43,000 km (12.1k /yr)

Manufactured ?

2015

Road Tax ?

\$682 /yr

Transmission

Auto

Dereg Value ?

\$43,559 as of today (change)

OMV ?

\$19,157

COE ?

\$56,989

ARF ?

\$9,157

Engine Cap

1,496 cc

Power

96.0 kW (128 bhp)

Curb Weight ?

1,190 kg

No. of Owners ?

1

Type of Vehicle

SUV

Features

Powerful And Responsive 4 Cylinder Inline DOHC I-VTEC, SRS Airbags, ABS, Cruise Control, Traction Control, Keyless Engine Push Start Button, CMBS. View specs of the Honda Vezel

Accessories

Leather Seats, Sports Rims, Pioneer Audio System, Reserve Camera, Auto Retractable Side Mirrors, Fog Lamps, Solar Film, Reverse Sensors.

Description

1 Owner, 90% Loan Available. Well Maintained By Previous Owner, Not A Grab/Rental Car, Accident-Free. Powerful Yet Reliable And Practical. Well Known For It's Low Fuel Consumption. Have A Peace Of Mind To Own A Trouble Free Car For Your Family Usage. Very Neat Interior And Exterior. Don't Miss This Fabulous Unit Before It's Gone. Kindly Contact Us Today To View And Go For A Test Drive.

Category

PARF Car

Status


Avr ***

Compare



Location Map

Price Chart



Click on the point to view

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Das WeltAuto.
Used cars you can trust. Guaranteed.

Visit the sgCarMart Carnival @ Downtown East
for exclusive deals on our certified pre-owned cars!
From 31 Aug to 1 Sep 2019



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2017 Toyota C-HR Hybrid 1.8A S Full BodyKit At \$79K.



Elegant Sporty Silver SUV Totally
Like New Condition Low Mileage
Cheapest C-HR.
Direct Owner StarAd

Lake View Credit Pte Ltd

> Low p
> Specia
> Easy li
> All ter

Browse by Category ▼

« Back (1 2 3 4 5 6 7) Next »

Sort by Date Posted

129 vehicles

vezel

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	vezel		Any	Any	2016	Any	Any	
	Honda	Vezel 1.5A X	\$63,800	\$9,200 /yr	14-Jan-2016	1,496 cc	43,000 km	
1 Owner, 90% Loan Available. Well Maintained By Previous Owner, Not A Grab/Rental Car, Accident-Free. Powerful Yet Reliable And Practical. Well Known For It's Low Fuel Consumption. Have A Peace Of Mind To Own A Trouble Free Car For Your Family Usage. Very Ne								
Posted: 07-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda	Vezel 1.5A X Honda Sensing	\$68,800	\$9,610 /yr	29-Mar-2016	1,496 cc	62,000 km	
100% Full Loan, Offer Interest Rate From 2.28%, 1 Careful Owner Only And Low Mileage! Interior And Exterior Looks Like New! 100% Accident Free! High Loan Up To 100% Available, Trade In Are Most Welcome! Buy With A Peace Of Mind From An ISO Certified Compar								
Hua Yang Credit Pte Ltd								
Posted: 07-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda	Vezel 1.5A X	\$68,800	\$9,140 /yr	28-Jul-2016	1,496 cc	43,562 km	
1 Owner, Sporty Deep Ocean Pearl Colour, Reliable And Excellent Fuel Efficiency, Spacious Cabin/Boot, With Add On Accessories Bluetooth, HUD, Upgraded Sports Rims, Front And Back Cameras, Reverse Camera, Trade-In Welcome, Car Available In Showroom For..								
Posted: 07-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda	Vezel 1.5A X	\$67,800	\$9,070 /yr	22-Jul-2016	1,496 cc	16,630 km	
1 Careful Owner, Still Have 2 Warranty. All Come Wt Original Paintwork And Original Items For First Day Buy Till Now, Not Grab Car Before, Genuine Mileage, Well Maintained, Seldom Used. Accident Free, Undergone A 120 Points Safety Check By Our In House Mechan								
Posted: 07-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Toyota	Previa						
The Toyota Previa is the de facto MPV								
The Toyota Previa is an MPV that excels with its space, practicality and a level of luxury some may not reach.								
Find out more!								
	Honda	Vezel Hybrid 1.5A X	\$69,800	\$9,950 /yr	13-May-2016	1,496 cc	-	
Fuel Type: Petrol-Electric								
1 Private Owner Owned Honda Vezel Hybrid 1.5X In Stock Now! Low Mileage Clocked! Regularly Serviced And Maintained By Seller! xterior And Interior Condition! Flexible Loan And Tenures Available! Flexible Down Payment Available! Come View And We Disc								
ad: 07-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								

Compare

CC4/AIG/9013772/Uda3

Jike

JUZZPERFORMANCE

Co Reg No: 201534963C
 8 Kaki Bukit Avenue 4
 #03-51/52 Premier@Kaki Bukit
 Singapore 415875
 Email: admin@juzzperformance.com.sg /
 anwar@juzzperformance.com.sg

4/s \$9800
 1ly.

TO	: AIG ASIA PACIFIC INSURANCE	DATE	: 6-Aug-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
OWNER'S PARTICULAR		VEHICLE DETAILS	
NAME	: AMIRUDDIN BIN ZAINI	VEHICLE NO	: SLE8018D
ADDRESS	: BLK 523A #03-77 TAMPINES GREENLEAF S(521523)	MODEL	: HONDA VEZEL
TEL. NO.	: 90280057	CHASSIS NO	: RU1-1116572
OWNER'S INSURANCE :			
POLICY NO. :			
ACCIDENT DETAILS		DATE	: 3-Aug-19
		TIME	: 8:00
THIRD PARTY REQUESTOR / CONTACT :			

QUOTATION SUMMARY**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET	1	\$ 1,359.00	\$ 1,359.00
2	FRONT BUMPER	1	\$ 989.00	\$ 989.00
3	FRONT LOWER BUMPER	1	\$ 415.90	\$ 415.90
4	FRONT WHEEL ARCH PROTECTOR	2	\$ 298.20	\$ 596.40
5	FRONT FENDER RH	1	\$ 830.10	\$ 830.10
6	FRONT FENDER INNER SHIELD RH	1	\$ 228.60	\$ 228.60
7	HEADLAMP	2	\$ 1,556.00	\$ 3,112.00
8	SIDE MIRROR ASSY RH	1	\$ 589.60	\$ 589.60
10	FRONT DOOR RH	1	\$ 1,454.00	\$ 1,454.00
11	FRONT DOOR TAPE RH	1	\$ 30.10	\$ 30.10
12	FRONT DOOR OUTER MOULDING RH	1	\$ 175.60	\$ 175.60
13	FRONT DOOR LOWER SEAL RH	1	\$ 51.90	\$ 51.90
14	FRONT DOOR UPPER HINGE RH	1	\$ 131.90	\$ 131.90
15	FRONT DOOR LOWER HINGE RH	1	\$ 195.50	\$ 195.50
16	FRONT DOOR CHECKER RH	1	\$ 58.00	\$ 58.00
17	FRONT DOOR POWER WINDOW MOTOR RH	1	\$ 554.00	\$ 554.00
18	FRONT DOOR REGULATOR RH	1	\$ 510.80	\$ 510.80
19	FRONT DOOR SPEAKER RH	1	\$ 215.00	\$ 215.00

crossmember mounting +312 torn

X
 ✓
 ✓
 IPC
 ✓
 ✓
 1PC
 X
 ✓
 ✓
 X
 ✓
 2
 131.90
 X
 2
 X

2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 2,200.00	1400
3	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 80.00	30
4	REMOVE AND INSTALL FRONT PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY INPUT TESTING.	\$ 80.00	
5	REMOVE AND RENEW DASHBOARD PANEL, WIRING HARNESS, SIDE TRIMMING TO ENABLE REPAIRS.	\$ 200.00	11 X
6	TRANSFER FRONT LHS DOOR ATTACHMENT AND MECHANISM INTO NEW DOOR PANEL.	\$ 150.00	60
7	TRANSFER REAR LHS DOOR ATTACHMENT AND MECHANISM INTO NEW DOOR PANEL.	\$ 150.00	11 X
8	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	11 X
9	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM.	\$ 200.00	50
10	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 80.00	11 X
11	PERFORMED DIAGNOSTIC CHECK.	\$ 600.00	11 X
12	DISMENTLE AND REPLACE FRONT UNDER-CARRIAGE COMPONENTS.	\$ 180.00	✓
13	WHEEL ALIGNMENT.	\$ 150.00	80
14	APPLY TUFF COATING TREATMENT.	\$ 150.00	80

TOTAL \$ 7,120.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 30,552.56
TOTAL LABOUR COST : \$ 7,120.00
TOTAL REPAIR COST : \$ 37,672.56

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

PA Auto Consultants hence notify the Reparer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No structural modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Reparer

Signature

Date:

not Attach
renew
Zahid A. Khan rep -
2/5/9801
7 day.

P- 8262.80
S.W- 1376.00
idem 12680.00
12258.80
9807.04

TEO HIN TYRES
11 KAKI BUKIT ROAD 1
#01-01 EUNOS TECHNOLINK
SINGAPORE 415939
TEL: 67455711

Work Order: R000279
 Company: JUZZPERFORMANCE
 License: SLE8018D
 Odometer:
 Date: 19/08/2019 9:35

HONDA VEZEL

Front : Left			Camber Caster Toe SAI Included Angle Turning Angle Diff.	Front : Right		
Actual	Before	Specified Range		Actual	Before	Specified Range
-0°54'	-1°02'	-1°10' 0°10'	↔	-1°12'	-1°05'	-1°00' 1°10'
3°43'	3°01'	4°05' 6°35'		-3°21'	3°51'	4°00' 6°00'
-0°00'	-0°01'	-0°08' 0°08'		-0°03'	-0°03'	-0°08' 0°06'
12°54'	12°54'	11°30' 13°30'		12°54'	12°54'	11°30' 13°30'
11°53'	11°53'	10°30' 14°30'		11°53'	11°53'	10°30' 14°30'

Front			
	Actual	Before	Specified Range
Cross Camber	-0°07'	-0°12'	-1°20' 0°10'
Cross Caster	-0°04'	-0°04'	-1°20' 0°10'
Cross SAI	-0°24'	-0°28'	
Cross Toe	-0°01'	-0°24'	-1°20' 0°10'
Cross Turning Diff.			

Rear : Left

Actual	Before	Specified Range
-1°17'	-1°29'	-1°53' 0°26'
-0°04'	0°52'	0°06' 0°16'

Rear : Right

Actual	Before	Specified Range
-1°12'	-1°12'	-1°53' 0°26'
-0°08'	-0°08'	0°06' 0°16'

Camber Toe

Rear

Actual	Before	Specified Range
-0°17'	-0°22'	-0°45' 0°45'
-0°10'	-0°10'	-0°00' 0°33'
-0°11'	-0°09'	

Cross Camber

Total Toe

Thrust Angle

R000486
19.8.19 15:29
SLE 8018 D



Odometer:58044

LS TYRES & AUTOMOTIVE PTE LTD
53,UBI AVE1 #01-03/04/05
PAYA UBI INDUSTRIAL PARK
408934 SINGAPORE

HENG

Factory Japan 2019.0.1 : Honda : Vezel : RU1
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°54'	-0°43'	-1°00' 1°00'
3°43'	3°43'	4°00' 6°00'
0°00'	0°39'	-0°08' 0°08'
13°33'	13°22'	11°30' 13°30'
12°40'	12°40'	10°30' 14°30'
	0psi	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.
Tire Pressure

Front : Right

Actual	Before	Specified Range
-1°02'	-0°57'	-1°00' 1°00'
4°26'	4°26'	4°00' 6°00'
0°01'	0°18'	-0°08' 0°08'
12°27'	12°22'	11°30' 13°30'
11°25'	11°25'	10°30' 14°30'
	0psi	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°09'	0°14'	-0°45' 0°45'
-0°43'	-0°43'	
1°07'	1°01'	
0°00'	0°57'	-0°15' 0°15'

Rear : Left

Actual	Before	Specified Range
-1°45'	-1°48'	-2°30' -0°30'
-0°06'	-0°04'	0°00' 0°15'
	0psi	

Camber
Toe
Tire Pressure

Rear : Right

Actual	Before	Specified Range
-1°28'	-1°26'	-2°30' -0°30'
0°15'	0°15'	0°00' 0°15'
	0psi	

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-0°17'	-0°22'	-0°45' 0°45'
0°10'	0°10'	0°00' 0°31'
-0°11'	-0°09'	
0mm	0mm	

Guidance Note

This Guidance Note is intended to assist you with your policy details and accident reporting procedures.
If you require further assistance, please call our Customer Care Executive at 6841 9000.

Vehicle Number: SLE8018D
Policy Details: drivo CLASSIC
Policy No: S111056579
Policy Date: 01/08/2019 to 31/07/2020

Total Excess Payable (Subject to Prevailing GST):
(Payment in MSC via Cash, NETS or Cheque only)

Excess (Subject to Prevailing GST)

Standard Excess: \$300 / \$500 / \$600 / \$1500 / \$2000 / N.A.
Additional Excess: \$500 / \$1000 / \$1500 / N.A.
Unnamed Driver Excess: \$500 / \$1000 / \$2500 / N.A.
Third Party Excess: \$1500 / \$2000 / N.A.
No Claims Discount (NCD): 0 / 10 / 15 / 20 / 30 / 40 / 50
NCD Protector * ☐ Yes ☒ No
*First Claim During Policy Year

Own Damage (OD)

- ☐ Premium may be affected upon renewal (Claim Loading)
- ☐ NCD affected upon renewal (30% affected)
- ☐ Standard excess waiver
- ☐ Tendering process apply (NTUC Income to allocate workshop) (Min 2 working days, exclude Reporting Date, Sat, Sun and PH)
- ☐ SGD\$50 transport allowance. (Up to 7 days after repair commence in the workshop)
- ☐ For recovery of uninsured losses (UIL), you must sign the UIL form before Income proceed to do a claim recovery.
- (Outcome will not be guaranteed)**
- ☐ Damage to third party property
- ☐ Medical expenses (Up to \$1000 - Refer to policy details)
- ☐ Personal Accident benefits (Refer to policy details)

Third Party (TP)

- ☐ Able to revert to OD claim if repair is done at Income Quality Workshops (within a year)
- ☐ The preferred workshop will follow up with all claim matters and advice (To check with preferred workshop on claims outcome)

Self-Repair (SR) / Reporting Only (RO)

- ☐ Premium & NCD may not be affected if there is NO claim against your policy
- ☐ Premium may be affected upon renewal (Claim Loading)
- ☐ Third Party Excess Apply
- ☐ NCD affected upon renewal (30% affected)

Remarks

- ☐ Vehicle continue driving after accident reporting, any further damage e.g. overhear / further accident will not be covered.
- ☐ Usage of Refurbish & Repair / New parts (Subject to Surveyor Approval)
- ☐ Survey necessary as cost of repair above \$3000 (before repair / before paint / after repair). Repair period may extend
- ☐ Subject to parts availability, repair deadline may extend. Income will NOT pay for any transport expenses or any losses due to unavailability of parts or accessories.
- ☐ NCD (10%) will be affected due to late reporting. Please write in to motor@income.com.sg for NCD loss appeal

Signature of Authorised Person/Driver

Relationship

Date (dd/mm/yyyy) - Time
3/8/2019 9:18

Name / Contact Number

Note taken by

Staff Code

Date (dd/mm/yyyy) - Time

Eric Woo

S992753

3/8/2019 9:18

Andrudetin / 9028
Bin Zaini / 0057

PRE-REPAIR INSPECTION REQUEST – SLE8018D vs GW8707M (OI) on D.O.A.: 03/08/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
Sent: 8/6/2019 10:05:08 AM
Attachments: [SLE8018D REPORT.pdf](#), [SURVEYOR ARRANGEMENT SLE8018D.pdf](#), [SLE8018D REPORT.pdf](#), [SURVEYOR ARRANGEMENT SLE8018D.pdf](#)

Hi,

Please refer to the enclosed request from **Juzz Performance Pte Ltd**.

Claim no : 3522331059SG003
Case Owner : Lee Ming Yao

If you have any queries/concerns, please let us know.
Kindly assist to assign **Marcus Chua** as *Single Joint Expert* as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

10:23am @ 6/8/19
person @ firm
vehicle in

From: admin [mailto:admin@juzzperformance.com.sg]

Sent: Monday, August 05, 2019 5:44 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin; Anwar

Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GW8707M AND SLE8018D ON 03/08/2019

This message is from an external sender; be cautious with links and attachments.

Dear In Charge,

We would like to choose Mr Marcus Chua from LKK Auto Consultants Pte Ltd.

Warmest regards,

Fira

Juzz Performance Pte Ltd
8 Kaki Bukit Ave 4
#03-51/52 PREMIER @ Kaki Bukit
Singapore 415875
Tel: 6385 0303
www.juzzperformance.com.sg

From: Hor, Yinrul <Yinrul.Hor@aig.com>

Sent: Monday, August 05, 2019 3:12 PM

To: admin <admin@juzzperformance.com.sg>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Tong, Wahxin <Wahxin.Tong@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GW8707M AND SLE8018D ON 03/08/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-08-12 15:12 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinru.Hor@aig.com

To: admin@juzzperformance.com.sg

Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GW8707M AND SLE8018D ON 03/08/2019

Date: Mon, 5 Aug 2019 07:11:30 +0000

Without Prejudice

Your Reference : SLE8018D

Our Reference : 3522331059SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations - Auto

Yinru.Hor@aig.com | www.aig.sg

From: admin [mailto:admin@juzzperformance.com.sg]

Sent: Monday, August 05, 2019 12:17 PM

To: AIG SGP, Claims-Survey

Cc: Anwar

Subject: [EXTERNAL] Arrange surveyor for SLE8018D & Your Ref:GW8707M

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Mdm,

We the repairers of motor vehicle no.: SLE8018D.

Please provide a list of surveyor for further inspection.

Location : 8 Kaki Bukit Ave 4 #03-51/52

Premier @ Kaki Bukit

Singapore 415875

Contact No : 96408974 - Anwar

We appreciate your early reply.

Thank you.

Warmest regards,

Fira

Juzz Performance Pte Ltd

8 Kaki Bukit Ave 4

#03-51/52 PREMIER @ Kaki Bukit

Singapore 415875

Tel: 6385 0303

www.juzzperformance.com.sg

JUZZPERFORMANCE

Co. Reg. No: 201534963C
8 Kaki Bukit Avenue 4 #03-51/52
PREMIER @ Kaki Bukit
Singapore 415875
Tel: 6385 0303
Fax: 6385 7038
Email: admin@juzzperformance.com.sg
Email: anwar@juzzperformance.com.sg

Date:

(Insert Insurance
Company Name
& Details)

SATISFACTION/DISCHARGE VOUCHER

Dear Sir/Madam,

Insured Name: AMIRUDDIN BIN ZAINI
Vehicle Registration No: SLE8018D
Discharge Date: 20/08/19

This is reference to my Claim Number: _____, for my vehicle bearing registration number reflected above. I have taken the delivery of my vehicle duly repaired and the vehicle performance is found to my satisfaction.

Do note that I have assigned all compensation monies due to me in the above said claim to **Juzz Performance Pte Ltd.**

I, hereby authorize you to release all compensation monies pertaining to the above-mentioned claim to **Juzz Performance Pte Ltd.** Please forward your settlement cheque to **Juzz Performance Pte Ltd.**, whom I have authorized to collect the said compensation/monies.
Thank you.



Name: AMIRUDDIN BIN ZAINI
IC No.: S8412070G



Witness

Jia Le (LKK Auto)

From: Lee, Ming-Yao <MingYao.Lee@aig.com>
Sent: Monday, 21 October 2019 11:10 AM
To: Jia Le (LKK Auto)
Subject: RE: [MANDATE REQUEST] Your ref: 3522331059SG [ACCIDENT INVOLVING VEHICLES GW8707M AND SLE8018D ON 03/08/2019]

Hi Jia Le,

May we have surveyor's view on the case? In my opinion, both scenario also possible to have such damages.

Regards,
Lee Ming Yao, George
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1769

Ming-Yao.Lee@AIG.com | www.aig.sg

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: 17 October 2019 11:55
To: Lee, Ming-Yao <MingYao.Lee@aig.com>
Subject: [EXTERNAL] RE: [MANDATE REQUEST] Your ref: 3522331059SG [ACCIDENT INVOLVING VEHICLES GW8707M AND SLE8018D ON 03/08/2019]

This message is from an external sender; be cautious with links and attachments.

Dear Ming Yao,

We have offered 50% to TP due to conflicting version. However, they rejected and provide the scene photo. TP mention that OI's lorry swerved from the center lane and asked for further review their claim.

In view of damage profile to TP vehicle, the impact on TP's vehicle is quite great and impact on OI's vehicle is side panel sustained a dent. If both parties are cutting lane and side swipe, damage to TP would not have been so bad, especially right front tyre/rim & left tyres were affected too. Therefore, OI cut into left most lane causing the accident is possible.

We seek your approval to propose settlement as follows:-

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 40,309.64	\$ 10,486.00
2. Loss of Rental (17days x \$120.00)	\$ 2,040.00	\$ 900.00 (9days x \$100.00)
Total	\$ 18,415.25	\$ 11,386.00

Kindly let us have your approval/instruction.

View Received Message

This mail is associated with :

***SLE8018D (3522331059SG)**
[GW8707M]

TP
AMIRUDDIN BIN ZAINI
Aug 3 2019 8:00AM
[KST Auto Rental Pte Ltd]
Juzz Performance Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 08/10/2019 12:03 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5693.00) - SLE8018D - Claim Handler: Lee, Ming-Yao

Approved:5693.00;PLease settle at bst

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLE8018D (3522331059SG)**
[GW8707M]

TP

AMIRUDDIN BIN ZAINI

Aug 3 2019 8:00AM

[KST Auto Rental Pte Ltd]

Juzz Performance Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/11/2019 10:21 AM.
To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11386.00) - SLE8018D - Claim Handler: Lee, Ming-Yao

Approved:11386.00:Please settle at Best COR : S\$ 10,486.00 LOR : S\$ 900.00

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Aug 2019 Edit Reg		06 Aug 2019 00:00 Edit Adj Rpt	\$9,800.00 Edit Estimates	\$9,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: KST Auto Rental Pte Ltd , Co. Reg. No.: -		[Created by adjuster]							
Main Claimant: AMIRUDDIN BIN ZAINI , ID: S8412070G									
Vehicle Reg. No.: SLE8018D		Date of Loss: 03/08/2019 08:00 - :59 [36 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3522331059SG		Policy/Cover Note No.: (Third Party Only)							
Vehicle Reg. No. (Insured): GW8707M		Policy No. (Claimant): 5111056579							
		Excess:							
Repairer: Juzz Performance Pte Ltd (HQ) 8 Kaki Bukit Avenue 4 #03-51/52 PREMIER @Kaki Bukit, 415875 Kaki Bukit - Tel: 63850303									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/08/2019]									
ASSOCIATED MAIL RECEIVED									
				View All Compose Case Mail					
- AIG_SG_EXPRESS (06/11/2019): Alert - Adj Mandate Approved (\$11386.00) - SLE8018D - Claim Handler: Lee, Ming-... - AIG_SG_EXPRESS (04/11/2019): Alert - Adj Mandate Maintained - SLE8018D - Claim Handler: Lee, Ming-Yao - AIG_SG_EXPRESS (21/10/2019): Alert - Adj Mandate Maintained - SLE8018D - Claim Handler: Lee, Ming-Yao - AIG_SG_EXPRESS (08/10/2019): Alert - Adj Mandate Approved (\$5693.00) - SLE8018D - Claim Handler: Lee, Ming-Y... - AIG_SG_EXPRESS (03/10/2019): Alert - Adj Mandate Approved (\$5350.00) - SLE8018D - Claim Handler: Lee, Ming-Y...									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLE8018D (3522331059SG)**
[GW8707M]

TP

AMIRUDDIN BIN ZAINI

Aug 3 2019 8:00AM

[KST Auto Rental Pte Ltd]

Juzz Performance Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	☒
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Thumbnail	Print
			1	Edit
Assessment Reports				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	☒
1	26/09/19 09:00	Adjuster Immediate Advice	Thumbnail	Print
			1	Load HTM
Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	☒
1	07/08/19 17:26	Chassis Number	Thumbnail	Print
2	07/08/19 17:26	Odometer Reading	1	Load JPG
3	07/08/19 17:27	General View	1	Load JPG
4	07/08/19 17:27	General View	1	Load JPG
5	07/08/19 17:27	General View	1	Load JPG
6	07/08/19 17:27	General View	1	Load JPG
7	07/08/19 17:27	General View	1	Load JPG
8	07/08/19 17:27	General View	1	Load JPG
9	07/08/19 17:27	General View	1	Load JPG
10	07/08/19 17:27	General View	1	Load JPG
11	07/08/19 17:27	General View	1	Load JPG
12	07/08/19 17:27	General View	1	Load JPG
13	07/08/19 17:27	General View	1	Load JPG
14	07/08/19 17:27	General View	1	Load JPG
15	07/08/19 17:27	General View	1	Load JPG
16	07/08/19 17:27	General View	1	Load JPG
17	07/08/19 17:27	General View	1	Load JPG
18	07/08/19 17:27	General View	1	Load JPG
19	07/08/19 17:27	General View	1	Load JPG
20	07/08/19 17:27	General View	1	Load JPG
21	07/08/19 17:27	General View	1	Load JPG
22	07/08/19 17:27	General View	1	Load JPG
23	07/08/19 17:27	General View	1	Load JPG
24	07/08/19 17:27	General View	1	Load JPG
25	07/08/19 17:27	General View	1	Load JPG
26	07/08/19 17:27	General View	1	Load JPG
27	07/08/19 17:27	General View	1	Load JPG
28	07/08/19 17:27	General View	1	Load JPG
29	07/08/19 17:27	General View	1	Load JPG
30	07/08/19 17:27	General View	1	Load JPG
31	07/08/19 17:27	General View	1	Load JPG
32	07/08/19 17:27	General View	1	Load JPG
33	07/08/19 17:27	General View	1	Load JPG
34	07/08/19 17:27	General View	1	Load JPG

Letters/Correspondences

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	Thumbnail	Print
35	07/08/19 17:27	General View		Load JPG	☒
36	07/08/19 17:27	General View		Load JPG	☒
37	07/08/19 17:27	General View		Load JPG	☒
38	07/08/19 17:27	General View		Load JPG	☒
39	07/08/19 17:27	General View		Load JPG	☒
40	07/08/19 17:27	General View		Load JPG	☒
41	07/08/19 17:27	General View		Load JPG	☒
42	07/08/19 17:27	General View		Load JPG	☒
43	07/08/19 17:27	General View		Load JPG	☒
44	07/08/19 17:27	General View		Load JPG	☒
45	07/08/19 17:27	General View		Load JPG	☒
46	07/08/19 17:27	General View		Load JPG	☒
47	07/08/19 17:27	General View		Load JPG	☒
48	07/08/19 17:27	General View		Load JPG	☒
49	07/08/19 17:27	General View		Load JPG	☒
50	07/08/19 17:27	General View		Load JPG	☒
51	07/08/19 17:27	General View		Load JPG	☒
52	07/08/19 17:27	General View		Load JPG	☒
53	07/08/19 17:27	General View		Load JPG	☒
54	07/08/19 17:27	General View		Load JPG	☒
55	07/08/19 17:27	General View		Load JPG	☒
56	07/08/19 17:27	General View		Load JPG	☒
57	07/08/19 17:27	General View		Load JPG	☒
58	07/08/19 17:27	General View		Load JPG	☒
59	07/08/19 17:27	General View		Load JPG	☒
60	07/08/19 17:27	General View		Load JPG	☒
61	07/08/19 17:27	General View		Load JPG	☒
62	07/08/19 17:27	General View		Load JPG	☒
63	07/08/19 17:27	General View		Load JPG	☒
64	07/08/19 17:27	General View		Load JPG	☒
65	07/08/19 17:27	General View		Load JPG	☒
66	07/08/19 17:27	General View		Load JPG	☒
67	07/08/19 17:27	General View		Load JPG	☒
68	07/08/19 17:27	General View		Load JPG	☒
69	07/08/19 17:27	General View		Load JPG	☒
70	07/08/19 17:27	General View		Load JPG	☒
71	07/08/19 17:27	General View		Load JPG	☒
72	07/08/19 17:27	General View		Load JPG	☒
73	07/08/19 17:27	General View		Load JPG	☒
74	07/08/19 17:27	General View		Load JPG	☒
75	07/08/19 17:27	General View		Load JPG	☒
76	07/08/19 17:27	General View		Load JPG	☒
77	07/08/19 17:27	General View		Load JPG	☒
78	07/08/19 17:27	General View		Load JPG	☒
79	07/08/19 17:27	General View		Load JPG	☒
80	07/08/19 17:27	General View		Load JPG	☒
81	07/08/19 17:28	General View		Load JPG	☒
82	07/08/19 17:28	General View		Load JPG	☒
83	07/08/19 17:28	General View		Load JPG	☒
84	07/08/19 17:28	General View		Load JPG	☒
85	07/08/19 17:28	General View		Load JPG	☒
86	07/08/19 17:28	General View		Load JPG	☒
87	07/08/19 17:28	General View		Load JPG	☒

Letters/Correspondences

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	Thumbnail	Print
88	07/08/19 17:28	General View			
89	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
90	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
91	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
92	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
93	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
94	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
95	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
96	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
97	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
98	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
99	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
100	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
101	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
102	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
103	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
104	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
105	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
106	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
107	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
108	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
109	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
110	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
111	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
112	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
113	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
114	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
115	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
116	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
117	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
118	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
119	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
120	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
121	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
122	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
123	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
124	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
125	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
126	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
127	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
128	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
129	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
130	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
131	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
132	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
133	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
134	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
135	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
136	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
137	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
138	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
139	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓
140	10/08/19 15:19	Reinspection Photo	1	Load JPG	✓

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
141	10/08/19 15:19	Reinspection Photo	1 Load JPG	✓
142	10/08/19 15:19	Reinspection Photo	1 Load JPG	✓
143	28/08/19 08:39	After Repair Photo	1 Load JPG	✓
144	28/08/19 08:39	After Repair Photo	1 Load JPG	✓
145	28/08/19 08:39	After Repair Photo	1 Load JPG	✓
146	28/08/19 08:39	After Repair Photo	1 Load JPG	✓
147	28/08/19 08:39	After Repair Photo	1 Load JPG	✓
148	28/08/19 08:39	After Repair Photo	1 Load JPG	✓
149	28/08/19 08:39	After Repair Photo	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/08/19 16:27	EMAIL FROM AIG DD 06.08.2019	1 Load PDF	
2	06/08/19 16:27	SURVEYOR ARRANGMENT SLE8018D	1 Load PDF	
3	06/08/19 16:28	TP GIA REPORT	1 Load PDF	
4	06/08/19 19:01	ACKNOWLEDGEMENT EMAIL TO AIG DD 06.08.2019	1 Load PDF	
5	26/09/19 08:46	TP ESTIMATE - MARKED	1 Load PDF	
6	26/09/19 08:46	LOD	1 Load PDF	
7	26/09/19 08:46	RENTAL RECEIPT	1 Load PDF	
8	26/09/19 09:01	LETTER TO OI	1 Load PDF	
9	12/11/19 15:05	AUTHORISATION TO ACT	1 Load PDF	
10	12/11/19 15:05	RELEASE VOUCHER	1 Load PDF	
11	12/11/19 15:05	WORKSHOP INVOICE	1 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/08/19 14:52	OI GIA REPORT	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset Save Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GW8707M (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT ABS
	SLE8018D (TP veh)		D/AIRBAG 2WD 5DR (A)
Date of Accident:	03/08/2019		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		39,897.26
Final Repair Cost	: \$		10,486.00
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		900.00
LTA / GIA Search Fee	: \$		9 days
Others:	: \$		
	: \$		
Final Settlement Sum	: \$		11,386.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Juzz Performance Pte Ltd	: \$	11,386.00
2)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

12 Nov

2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19013772/UDA3S2
Date: 12/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No: SLE8018D Insured Vehicle No: GW8707M
Date of Loss: 03/08/2019 Nature of Claim: TP Claim No: 3522331059SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE8018D
Make & Model: HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: L15B4036577
Reg. Date: 01/08/2016 (Man. Year: 2016) Chassis No: RU11116572
Colour: Silver Odometer: 58039 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55ZR17 Rear Tyre Size: 215/55ZR17
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	30,167.16	9,578.80	20,588.36	68.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,120.00	2,680.00	4,440.00	62.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,287.16	12,258.80	25,028.36	67.12
Approved Total (Overridden) (S\$)		9,800.00		
(S\$)	37,287.16	9,800.00	27,487.16	73.72
+ GST 7.00/7.00% (S\$)	2,610.10	686.00	1,924.10	73.72
Nett Amount (S\$)	39,897.26	10,486.00	29,411.26	73.72
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		11,386.00		

INSPECTION

Date of Assignment: 06/08/2019
Date Inspected: 07/08/2019 Inspected At: Juzz Performance Pte Ltd (HQ)
8 Kaki Bukit Avenue 4 #03-51/52 PREMIER @Kaki Bukit
Singapore 415875
Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

11/12/2019

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,359.00 FL	*- FL
2	1		*FRONT BUMPER	Distorted	989.00 FL	*801.70 FL
3	1		*FRONT LOWER BUMPER	Grazed	415.90 FL	*391.10 FL
4	1		*FRONT WHEEL ARCH PROTECTOR	O/s Torn	596.40 FL	*298.20 FL
5	1		*FRONT FENDER RH	Badly Dented	830.10 FL	*580.00 FL
6	1		*FRONT FENDER INNER SHIELD RH	Torn	228.60 FL	*228.60 FL
7	1		*HEADLAMP	O/s Scratched	3,112.00 FL	*1,556.00 FL
8	1		*SIDE MIRROR ASSY RH	Repair	589.60 FL	*- FL
9	1		*FRONT DOOR RH	Badly Dented	1,454.00 FL	*1,102.00 FL
10	1		*FRONT DOOR TAPE RH	Necessary	30.10 FL	*30.10 FL
11	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	175.60 FL	*- FL
12	1		*FRONT DOOR LOWER SEAL RH	Necessary	51.90 FL	*51.90 FL
13	1		*FRONT DOOR UPPER HINGE RH	Twisted	131.90 FL	*131.90 FL
14	1		*FRONT DOOR LOWER HINGE RH	Twisted	195.50 FL	*131.90 FL
15	1		*FRONT DOOR CHECKER RH	Not Necessary	58.00 FL	*- FL
16	1		*FRONT DOOR POWER WINDOW MOTOR RH	Shorted	554.00 FL	*554.00 FL
17	1		*FRONT DOOR REGULATOR RH	Bent	510.80 FL	*262.50 FL
18	1		*FRONT DOOR SPEAKER RH	Not Necessary	215.00 FL	*- FL
19	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	367.60 FL	*- FL
20	1		*FRONT DOOR LOCK ASSY RH	Not Necessary	389.00 FL	*- FL
21	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	712.40 FL	*- FL
22	1		*FRONT DOOR FRAME WEATHERSTRIP RH	Necessary	285.00 FL	*133.90 FL
23	1		*FRONT DOOR PILLAR OUTER RH	Badly Dented	1,025.00 FL	*1,025.00 FL
24	1		*FRONT SKID PLATE RH	Grazed	228.10 FL	*228.10 FL
25	1		*REAR DOOR RH	Repair	1,458.00 FL	*- FL
26	1		*REAR DOOR TAPE RH	Not Necessary	30.10 FL	*- FL
27	1		*REAR DOOR MOULDING RH	Not Necessary	175.60 FL	*- FL
28	1		*REAR DOOR CHECKER RH	Not Necessary	38.90 FL	*- FL
29	1		*REAR DOOR FRAME WEATHERSTRIP RH	Not Necessary	285.00 FL	*- FL
30	1		*ROCKER PANEL RH	Repair	1,589.50 FL	*- FL
31	1		*CENTRE DOOR PILLAR OUTER RH	Repair	1,139.70 FL	*- FL
32	1		*CENTRE PANEL INNER GARNISH RH	Not Necessary	398.20 FL	*- FL
33	2		*FRONT KNUCKLE ARM	Bent	1,378.00 FL	*910.20 FL
34	1		*STEERING RACK AND PINION	Serviceable	2,598.00 FL	*- FL
35	2		*FRONT DRIVE SHAFT	Not Necessary	2,718.00 FL	*- FL
36	2		*FRONT KNUCKLE BEARING	Necessary	215.00 FL	*215.00 FL
37	2		*FRONT LOWER CONTROL ARM	Bent	577.60 FL	*577.60 FL
38	2		*FRONT SHOCK ABSORBER	Bent	769.00 FL	*769.00 FL
39	1		*FRONT STABILIZER LINK	N/s Twisted	75.60 FL	*37.80 FL
40	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
41	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	65.00 FS	*50.00 FS
42	1		*SET FRONT DOOR INNER TRIM BOARD CLIP	Not Necessary	65.00 FS	*- FS
43	1		*SET SIDE SILL GARNISH CLIP	Not Necessary	75.00 FS	*- FS
44	1		*SIDE SILL PANEL SEALANT	Not Necessary	90.00 FS	*- FS
45	1		*SIDE SILL STIFFENER SEALANT	Not Necessary	90.00 FS	*- FS
46	1		*SET CENTER PILLAR INNER TRIM CLIP	Not Necessary	35.00 FS	*- FS
47	1		*SET REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
48	1		*SET REAR DOOR INNER TRIM BOARD CLIP	Not Necessary	52.00 FS	*- FS
49	2		*SIDE SKIRT SIDE PANEL	Not Necessary	4,000.00 FS	*- FS
50	2		*FRONT TYRE (LOCAL PURCHASE) (@ \$360.00 DISC 60%)	Punctured / Cut	560.00 FS	*216.00 FS
51	2		*SPORT RIM	Dented / Bent / Cracked	2,400.00 FS	*1,000.00 FS
52	1		*CROSSMEMBER MOUNTING	Torn	312.00 FL	*312.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (\$\$)	35,819.70
					11,644.50	
					- List Item Discount on L Items 20.00/20.00% (\$\$)	5,652.54
					2,065.70	
					Total Parts (\$\$)	30,167.16
					9,578.80	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OFF AND REPLACE LHS SILL PANEL. STRAIGHTEN, REALIGN SIDE FLOOR CHASSIS AND RENEW OTHER DAMAGE PARTS.	New	2,800.00	800.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	New	2,200.00	1,400.00
3	ADJUST AND FOCUS FRONT LIGHTING SYSTEM, PERFORM HEADLAMP ADJUSTMENT TO POSITION. }	New	80.00	30.00
4	REMOVE AND INSTALL FRONT PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY INPUT TESTING. }	New	80.00	0.00
5	REMOVE AND RENEW DASHBOARD PANEL, WIRING HARNESS, SIDE TRIMMING TO ENABLE REPAIRS.	New	200.00	0.00
6	TRANSFER FRONT LHS DOOR ATTACHMENT AND MECHANISM INTO NEW DOOR PANEL.	New	150.00	60.00
7	TRANSFER REAR LHS DOOR ATTACHMENT AND MECHANISM INTO NEW DOOR PANEL.	New	150.00	0.00
8	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	New	100.00	0.00
9	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM.	New	200.00	50.00
10	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	New	80.00	0.00
11	PERFORMED DIAGNOSTIC CHECK.	New	600.00	0.00
12	DISMANTLE AND REPLACE FRONT UNDER-CARRIAGE COMPONENTS.	New	180.00	180.00
13	WHEEL ALIGNMENT.	New	150.00	80.00
14	APPLY TUFF COATING TREATMENT.	New	150.00	80.00
Gross Labour Cost (\$\$)			7,120.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >