



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

**QUOTATION**

Customer :

NO. : 34615

FIRST CAPITAL INSURANCE LTD  
06 RAFFLES QUAY #21-00  
SINGAPORE 048580

Supplementary 1 To QTN: 34539

DATE : 21/08/2019  
CLAIM NO. : 11400  
POLICY NO. : AVFMSB0000611902  
FROM : RAYMOND

VEHICLE NO. : FBG6178X  
MAKE/MODEL : YAM / YBR125ESD

S/N	Description	Action	Qty	Unit Price	Amount
<i>bracket</i>	BRACKET METER P/N: 63729	Replace	1.00	\$28.00	28.00
2	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	Replace	1.00	\$12.00	12.00

SUB TOTAL	\$40.00
GST @ 7 %	\$2.80
<b>GRAND TOTAL</b>	<b>\$42.80</b>

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of  
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



*bizSAFE<sub>3</sub>*



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0303  
ISS: 01/11/2015