

INS. REC. BY:

REF: CS/FCI/9013775/ Awd3ⁿ² Special Instructions:

Surveyor: Adrian

ASSIGNMENT (Office)

CWS

From (Person):

Maychan

of

FCI

Date/Time: 1155am @ 8/18/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 689L

Insured:

SHC 8780T

at Workshop m/s

Premium Automobiles

Tel: 6388 2323

of

55 ubi Road 1

Policy No:

Claim No: D19004984 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/07/2019

(Client's Record)

19/8/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time:

12:43pm @ 6/18/19

Person Contacted:

syuhq

Vehicle IN/OUT

Date/Time

Action/Instruction

13hmm ✓

SJK 689L-X

SHC 8780T-NS/INC/8006022/K1/m2

att: 20/03/18

15/8/19

Email preli revised to FCI

24/10/19

Final fig \$ 2178.50 (Reel 4468.50, 67% confirmed by email)

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From:

Date:

14/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJK 689 L

at Workshop m/s

Premium Automobiles

of

55 ubi Road 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2pm owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 hrs

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(DS)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJK 689 L

Yr Regn:

2018 / Sept

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4

C.C.

1984

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

9295

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU222F49JA177148

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/40 R18

R: 245/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

ob

mm

R/Bal.

ob

mm

L/Bal.

ob

mm

L/Bal.

ob

mm

D.O.A.

D.O.I.

14/08/19

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 24 OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

24/10 - typst

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend 10

Survey Fee:

Transportation:

S + RS \$

Phone

Others

TOTAL

145

50

13

208

Report Format:

CWS

Lump Sum / U.S.D.:

2178.50



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004984MFSH

Our ref: CS/FC119013775/Avd3

Date : 15/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJK 689L


We thank you for your instruction on 6/8/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/8/2019 at the premises of M/s PREMIUM AUTOMOBILES and have the following to report:-

Workshop Estimate Amount	: S\$6,647.00
Revised Estimate Amount	: S\$2,179.00
"Check" Items Amount	: S\$403.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	31-07-2019	Our Ref No. D19004984MFSH
Accident Date	29-07-2019	Claim Type. Third Party
Insured Vehicle	SHC8780T	Third Party Vehicle. SJK689L
Survey Location	55 UBI ROAD 1	
Contact Person.	SYAFIQ	
Contact No.	63882323/ 0	Fax No. 67689911
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 August 2019 8:45 AM
To: 'CWS Motor Claims'
Cc: 'May Chua'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004984MFSH/1-SJK 689L
Attachments: SJK 689L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJK 689L

Date of survey: 14/8/2019

Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 6 August 2019 4:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004984MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 14/08/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 August 2019 11:55 AM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004984MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

• **Veron Chen (LKKAUTO)**

From: Veron Chen (LKKAUTO)
Sent: Thursday, 24 October 2019 12:25 PM
To: 'jiayee.yap@premiumauto.com.sg'; SUR; Admin A; CS A Team; SUR
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SJK689L - TP FIRST - SURVEYED 14 AUG 19

Dear Jia Yee,

WITHOUT PREJUDICE

Confirm repair cost of \$2178.50 before GST @ 3 days of repairs

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiayee.yap@premiumauto.com.sg <jiayee.yap@premiumauto.com.sg>
Sent: Wednesday, 23 October 2019 1:41 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SJK689L - TP FIRST - SURVEYED 14 AUG 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$2178.50 @ 3 days of repairs

Your early closure is well appreciated.

Thanks & Best Regard

JiaYee Yap

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiayee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0949/2019/NS
Date : 7-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No: SHC 8780 T

First Capital Insurance Ltd

36 Robinson Road


16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : MR NG SWEE LEONG
Address : BLK 806 BEDOK RESERVOIR ROAD
#05-02
Singapore 479243
Telephone : HP 97333002
Type of Claim : Third party Claims
Policy No. : 1800109961
Vehicle No : **SJK 689 L**
Model Code : Audi A4 SEDAN 2.0 TFSI 8W
Model / Year : Sep-18
Engine No : CVK 062606
Chassis No : WAUZZZF49JA177148
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Jul-19
Place of Accident : ALONG FULLERTON ROAD



Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 689 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00 ✓	✓
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,050.00 700 ✓	✓
3	To respray rear bumper.		\$ 900.00 700 ✓	✓
4	To carry out diagnostics checks	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SJK 689 L

S/N	Parts Description	Damaged Parts & Prices		REMARKS
		S/Nett		
1	REAR BUMPER <i>Repair</i>	\$	2,015.00 ^x	
2	REAR BUMPER FIXING PARTS <i>Not Nec</i>	\$	66.00 ⁺	
3	REAR BUMPER SECURING STRIP <i>Not Nec</i>	NEC \$	203.00 [?]	X
4	REAR BUMPER SPOILER <i>cut</i>	\$	227.00	226.50
5	REAR LIGHT REFLECTOR - LH / RH <i>Not Nec</i>	2 \$	76.00 ⁺	
6	REAR BUMPER CARRIER <i>3 not</i>	\$	819.00 ⁺	
7	REAR BUMPER CARRIER SEAL <i>3 not</i>	2 \$	25.00 ⁺	
8	REAR BUMPER GUIDE SECTION - LH / RH <i>not nec</i>	2 \$	40.00 ⁺	
9	REAR PARKING AID SENSOR - INNER / OUTER <i>not nec</i>	2 \$	462.00 ⁺	
10	SEAL RING <i>Not nec</i>	4 \$	12.00 ⁺	
11	SUNDRIES <i>Not Nec.</i>	\$	200.00 [?]	X
TOTAL SPARE PARTS		:	\$ 4,145.00	
TOTAL LABOUR CHARGES		:	\$ 2,502.00	
GRAND TOTAL		:	\$ 6,647.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 14/08/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0949/2019/NS
Date : 7-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No: SHC 8780 T

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Hi Adrian,

3 days - ok - Jy - 23 Oct 2019

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : MR NG SWEE LEONG
Address : BLK 806 BEDOK RESERVOIR ROAD
#05-02
Singapore 479243
Telephone : HP 97333002
Type of Claim : Third party Claims
Policy No. : 1800109961
Vehicle No : **SJK 689 L**
Model Code : Audi A4 SEDAN 2.0 TFSI 8W
Model / Year : Sep-18
Engine No : CVK 062606
Chassis No : WAUZZZF49JA177148
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Jul-19
Place of Accident : ALONG FULLERTON ROAD

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 689 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	\$ 700.00
3	To respray rear bumper.	\$ 900.00	\$ 700.00
4	To carry out diagnostics checks	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,502.00	\$ 1,952.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SJK 689 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	REMARKS
1	REAR BUMPER	\$ 2,015.00	
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURING STRIP	NEC \$ 203.00	
4	REAR BUMPER SPOILER	\$ 227.00	\$ 226.50
5	REAR LIGHT REFLECTOR - LH / RH	2 \$ 76.00	
6	REAR BUMPER CARRIER	\$ 819.00	
7	REAR BUMPER CARRIER SEAL	2 \$ 25.00	
8	REAR BUMPER GUIDE SECTION - LH /RH	2 \$ 40.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	
10	SEAL RING	4 \$ 12.00	
11	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS		: \$ 4,145.00	\$ 226.50
TOTAL LABOUR CHARGES		: \$ 2,502.00	\$ 1,952.00
GRAND TOTAL		: \$ 6,647.00	\$ 2,178.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013775/Avd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-10-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8780T	Veh. Inspected	SJK 689L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004984MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	06/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZF49JA177148	Colour	GREY	
Odometer	9295	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	245/40 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	245/40 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	245/40 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2019	Inspection Date	14/08/2019	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 689L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	2,015.00	-
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	66.00	-
1	REAR BUMPER SECURING STRIP (SN)	NOT NECESSARY	203.00	-
1	REAR BUMPER SPOILER (SN)	CUT	227.00	226.50
2	REAR LIGHT REFLECTOR-LH/RH (SN)	NOT NECESSARY	76.00	-
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	819.00	-
2	REAR BUMPER CARRIER SEAL (SN)	NOT NECESSARY	25.00	-
2	REAR BUMPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	40.00	-
2	REAR PARKING AID SENSOR-INNER/OUTER (SN)	NOT NECESSARY	462.00	-
4	SEAL RING (SN)	NOT NECESSARY	12.00	-
1	SUNDRIES (SN)	NOT NECESSARY	200.00	-
			4,145.00	226.50
LABOUR				
	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.		360.00	360.00
	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,050.00	700.00
	TO RESPRAY REAR BUMPER.		900.00	700.00
	TO CARRY OUT DIAGNOSTICS CHECKS.		192.00	192.00
			2,502.00	1,952.00
GRAND TOTAL			6,647.00	2,178.50
RECOMMENDED COST OF REPAIRS				2,178.50

Report Ref No. CS/FCI19013775/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.