


OK - Labour \$400/- only



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724

BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723

TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg

Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

DA/III(SHD3565B)

DOA: 01/08/2019@1955

INDIA INTERNATIONAL INSURANCE PTE LTD

05/08/2019

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKR 1843 C - TOYOTA PICNIC AUTO W/O ROOF RACK

CHASSIS NO: JTEGH23B500022104 (08/2006)

1 pc

Rear
~~Front~~ bumper
LESS 25%

Rx
\$ 652.30
\$ 163.08
\$ 489.22

Labour to jacking, panel beating, repair and straighten
rear inner panel and installing rear bumper.

\$ 300.00 200

Putty and respray rear inner panel and rear bumper.

\$ 300.00 200
\$ 1,089.22
\$ 76.25
\$ 1,165.47

ADD 7% GST

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

[Signature]

OK \$400
2 days

Email to Steven 15/11

Taufik 97495749
WP
8/8/19 @ 1230
2 days
Resurvey after repair
taufik@kkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: