

INSURANCE

INS CASE OWNER

CC 6/CTI1901 3782, P1d63/

LRK

IDAC

Surveyor:

ENSWI

DOI:

ASSIGNMENT

6/8/19

Date / Time:

6/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

PL 12078

Name of Insured:

KFL MIET

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

6/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MUHAMMAD FAKHRI BIN SHAHIMAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SWM1902W688

Policy No.:

DMPB15W260891810

Make / Model:

GOLDEN DRAGON

Place of Accident:

Tx pickup point

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SHD 2087x



INSRS:

WSP:

Tel:

Liability:

RMKS:

prime auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHD 2087x - 8
7017077 - 15/01/2008/12/07/06/02
2017 - 10/01/19

6/11/19 - FILE PAS TO LIP TO LWS

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 18/10/19

Confirm with: Alice Leong

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 94

If NO or B 28, Ass. Lia :

Repair Cost: (w/631)

SS

2407.50

Loss of Rental (LOR):

SS

776.30

(7 days) x \$110.90

Loss of Use (LOU):

SS

-

(S

x

days)

Loss of Income (LOI):

SS

-

(S

x

days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

-

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

-

3) Survey fee: \$100

Total:

SS

3185.80

Global Sum SS: 3000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3000.00

Name 1:

Prime Auto Claims Service Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

2932

SHD 2087X

2015 APR

5HP 2087x

PRIME AUTO

6, Bkno1 PL

CTI

TOYOTA PRIUS HYBRID 1-83A 1757

1757

blown

54 boys

2vw400014328

DOI: 10.1002/for

8

All rights reserved.

205/60R16

1

GOORIG

N/S FRG

4/3 - \$2250 (Red \$ 1420.30 / 396)

Days Of Repair.

Resurvey No. of Traps



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTH19013782/R1db3

Date: 07.08.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD2087X

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.08.2019 at the premises of M/s Prime Auto Claims Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,670.30
Revised Estimate Amount	: S\$	2,807.03
"Check" Items Amount	: S\$	204.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

3/1/16



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 06.08.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2087X TOYOTA PRIUS ALPHA 1.8 (2014)

To Supply

1) 1pc	Front bumper <i>de</i>	\$ 585.00
2) 1pc	Front bumper left side retainer <i>new</i>	\$ 65.70
3) 1pc	Front bumper right side retainer <i>X old damage X new</i>	\$ 65.70 X
4) 1pc	Front bumper left fog lamp <i>scd</i>	\$ 152.00
5) 1pc	Left head lamp <i>scd</i>	\$ 1,060.00
6) 1pc	Left front fender <i>st</i>	\$ 435.00
7) 1pc	Left front fender cowling <i>? X new</i>	\$ 272.00 X
8) 1pc	Left front fender cowling "Hybrid" emblem <i>new</i>	\$ 65.00

Sub total parts	\$ 2,700.40	<i>2362.70</i>
Less: 25% discount	\$ 675.10	<i>-590.60</i>
	\$ 2,025.30	<i>1772.10</i>

To Supply S.Nett Parts

1) 1pc	Right front sport rim <i>repair</i>	\$ 220.00 X
2) 1set	Front bumper clip <i>new</i>	\$ 30.00
3) 1set	Left front fender cowling clip <i>new</i>	\$ 15.00

Sub total S.Nett Parts	\$ 265.00	<i>45.00</i>
------------------------	-----------	--------------

L/charge

1) To tuff kote	\$ 50.00	<i>30</i>
2) To remove & refit right front tyre rim, balance tyre	\$ 50.00	<i>30</i>
3) To focus left front headlamp, check wiring	\$ 30.00	<i>✓</i>
4) To remove left front fender, front bumper & left head lamp, knock left	\$ 600.00	<i>400</i>

wheel house panel. Replace the above parts. Align & adjust front bumper & fender

5) To putty, respray painting left front fender, front bumper & left front fender wheel house panel. To polish

\$ ~~650.00~~ 500

Sub total L/charges	\$ 1,380.00	990.00
	\$ 3,670.30	2807.10
		561.40
		2245.70

Prepared by: Pei Yee

Paul

Up 900/0068

LS 2250/-

4 days

4/8

06/08/19 @ 1630

Returning after repair



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 06.08.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2087X TOYOTA PRIUS ALPHA 1.8 (2014)

To Supply

1) 1pc	Front bumper <i>de-</i>	\$ 585.00
2) 1pc	Front bumper left side retainer <i>new</i>	\$ 65.70
3) 1pc	Front bumper right side retainer <i>X old damage</i>	\$ 65.70
4) 1pc	Front bumper left fog lamp <i>scd</i>	\$ 152.00
5) 1pc	Left head lamp <i>scd</i>	\$ 1,060.00
6) 1pc	Left front fender <i>st</i>	\$ 435.00
7) 1pc	Left front fender cowling ?	\$ 272.00
8) 1pc	Left front fender cowling "Hybrid" emblem <i>new</i>	\$ 65.00

Sub total parts	\$ 2,700.40
Less: 25% discount	\$ 675.10
	\$ 2,025.30

To Supply S.Nett Parts

1) 1pc	Right front sport rim <i>repair</i>	\$ 220.00
2) 1set	Front bumper clip <i>new</i>	\$ 30.00
3) 1set	Left front fender cowling clip <i>new</i>	\$ 15.00

Sub total S.Nett Parts	\$ 265.00
------------------------	-----------

L/charge

1) To tuff kote	\$ 50.00 30
2) To remove & refit right front tyre rim, balance tyre	\$ 50.00 30
3) To focus left front headlamp, check wiring	\$ 30.00
4) To remove left front fender, front bumper & left head lamp, knock left	\$ 600.00 400

wheel house panel. Replace the above parts. Align & adjust front bumper & fender

- 5) To putty, respray painting left front fender, front bumper & left front fender wheel house panel. To polish

\$ ~~650.00~~ 500

Sub total L/charges \$ 1,380.00
\$ 3,670.30

Prepared by: Pei Yee

Paul

Hp 900/0068

4 days

4/8

06/08/19 @ 1630

Returning after
repair

Nivitha (LKK Auto)

From: Pei Yee <peiyee@primeautoclaims.com>
Sent: Tuesday, 6 August 2019 12:10 PM
To: admin-d@lkkauto.com; admin-d@lkkauto.com
Cc: aliceleong@primeautoclaims.com
Subject: PRI REQUEST TO ACCIDENT ON 06.08.2019 INVOLVING SHD2087X & PC1207J
Attachments: CCF_000061.pdf

Importance: High
Expires: Sunday, 2 February 2020 12:00 AM

2.37pm 06/08/19
pei yee
vehicle in
sur @ Road

Hi Sir/Mdm,

The above referred

Our client's GIA report enclosed for your retention. Please arrange PRI on urgent basis.

Please inform surveyor to avoid 1230-1330pm lunch hour.

*We agree LKK Auto Consultants Pte. Ltd. to survey our vehicle ; Claims against China Taiping

*PRI sent directly to your side as per instruction from Alfred Toh

***Please arrange PRI soonest possible due to loss of income and loss of rental per day count.**

Thank you.

Thank you & Best regards,

Pei Yee

Prime Auto Claims Service Pte. Ltd.
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

A member of the Prime Group

Disclaimer: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Shu Pei (LKKAuto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Wednesday, 2 October 2019 10:26 AM
To: Admin A; Jia Le (LKK Auto)
Cc: Irene Tay; adrianquek@sgmotor.com.sg; Hsiao Tong (LKKAuto); Alfred Toh
Subject: RE: OUR REF: SNM19D203688-PC1207J-THP - Direct Settlement - Accident Involving PC1207J and SHD2087X (TP : LKK REF - CC6/CTI19013782/db3) on 06.08.2019 along Airport Terminal 2 Arrival Hall
Attachments: Video - Accident - PC1207J.MP4

LKK REF - CC6/CTI19013782/db3
CTPIS REF - SNM19D203688C02/7(thp)
Section II Excess: \$3,000.00

Dear Jia Le

We refer to our earlier email pertaining to the above matter.

Attach herewith Insured's video for your attention and further action.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, 2 October, 2019 10:25 AM
To: Admin A <admin-a@lkkauto.com>; 'Jia Le (LKK Auto)' <JiaLe@lkkauto.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>; adrianquek@sgmotor.com.sg; Chee So Chow <sochow.chee@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D203688-PC1207J-THP - Direct Settlement - Accident Involving PC1207J and SHD2087X (TP : LKK REF - CC6/CTI19013782/db3) on 06.08.2019 along Airport Terminal 2 Arrival Hall

LKK REF - CC6/CTI19013782/db3
CTPIS REF - SNM19D203688C02/7(thp)
Section II Excess: \$3,000.00

Dear Jia Le

Attach herewith Insured's SAS report for your attention and necessary action.

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Thursday, 29 August, 2019 10:20 AM

To: 'Shu Pei (LKKAuto)' <shupeil@lkkauto.com>; Admin A <admin-a@lkkauto.com>; 'rfl.mart2016@gmail.com' <rfl.mart2016@gmail.com>; adrianquek@sgmotor.com.sg

Cc: 'Irene Tay' <irene.tay@sg.cntaiping.com>; 'Alfred Toh' <alfred.toh@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; KKLau <kklau@lkkauto.com>

Subject: RE: OUR REF: SNM19D203688-PC1207J-THP - Direct Settlement - Accident Involving PC1207J and SHD2087X (TP : LKK REF - CC6/CTI19013782/db3) on 06.08.2019 along Airport Terminal 2 Arrival Hall

LKK REF - CC6/CTI19013782/db3

CTPIS REF - SNM19D203688C02/7(thp)

Section II Excess: \$3,000.00

M/s RFL MART

Attn: Officer-In-Charge

Dear Sirs

We are in receipt of a third party property damage claim against your Motor Insurance Policy through our appointed agent, M/s LKK Auto Consultants Pte Ltd.

It is noted that you have not and/or have yet to file Accident Report till date. (your last accident was reported at M/s UCB Engineering Pte Ltd)

Please instruct your driver to file the Accident Report IMMEDIATELY at M/s LKK Auto Consultants Pte Ltd or M/s China TaiPing Insurance (S) Pte Ltd's authorized workshop (reporting centre) to enable us to handle the claim on your behalf.

Aside to Irene, please assist to keep track and repudiate liability, if necessary/required.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Thursday, 29 August, 2019 9:21 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow

Subject: RE: OUR REF: SNM19D203688-PC1207J-THP - FW: Direct Settlement - Accident Involving PC1207J (OI : CTI - TBA) and SHD2087X (TP : LKK REF - CC6/CTI19013782/db3) on 06.08.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Wednesday, 7 August 2019 10:50 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Jia Le (LKK Auto) <jiale@lkkauto.com>

Subject: OUR REF: SNM19D203688-PC1207J-THP - FW: Direct Settlement - Accident Involving PC1207J (OI : CTI - TBA) and SHD2087X (TP : LKK REF - CC6/CTI19013782/db3) on 06.08.2019

Dear Irene,

Please revert LKk.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, August 06, 2019 4:59 PM

To: Claims Dept of CTI

Cc: Alfred Toh; Admin A; Jia Le (LKK Auto)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI19013782/R1db3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 14-11-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 1207J	Veh. Inspected	SHD 2087X	
Policy No.	DMB1SN3060891800	Coverage (\$)	0.00	
Claim No.	SNM19D203688C02/7	Excess (\$)	0.00	
Assign From		Assign Date	06/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID 1.8S A	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZVW400014325	Colour	BROWN	
Odometer	546085	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	GOODRIDE	6 mm	
L/H Front Tyre	205/60 R16	GOODRIDE	6 mm	
R/H Rear Tyre	205/60 R16	GOODRIDE	6 mm	
L/H Rear Tyre	205/60 R16	GOODRIDE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/08/2019	Inspection Date	06/08/2019	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2087X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	585.00	585.00
1	FRONT BUMPER LEFT SIDE RETAINER	NECESSARY	65.70	65.70
1	FRONT BUMPER RIGHT SIDE RETAINER	SERVICEABLE	65.70	-
1	FRONT BUMPER LEFT FOG LAMP	SCRATCHED	152.00	152.00
1	LEFT HEAD LAMP	SCRATCHED	1,060.00	1,060.00
1	LEFT FRONT FENDER	BENT	435.00	435.00
1	LEFT FRONT FENDER COWLING	SERVICEABLE	272.00	-
1	LEFT FRONT FENDER COWLING 'HYBID' EMBLEM	NECESSARY	65.00	65.00
	LESS 25% DISCOUNT		-675.10	-590.68
			2,025.30	1,772.02
SPECIAL NETT ITEMS				
1	RIGHT FRONT SPORT RIM (SN)	TO REPAIR SEE LABOUR	220.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET LEFT FRONT FENDER COWLING CLIP (SN)	NECESSARY	15.00	15.00
			265.00	45.00
LABOUR				
	TO TUFF KOTE.		50.00	30.00
	TO REMOVE & REFIT RIGHT FRONT TYRE RIM ,BALANCE TYRE .		50.00	30.00
	TO FOCUS LEFT FRONT HEADLAMP ,CHECK WIRING .		30.00	30.00
	TO REMOVE LEFT FRONT FENDER FRONT BUMPER & LEFT HEAD LAMP .KNOCK LEFT WHEEL HOUSE PANEL .REPLACE THE ABOVE PARTS .ALIGN & ADJUST FRONT BUMPER & FENDER.INCLUSIVE OF THE REPAIR OF RIGHT FRONT SPORT RIM.		600.00	400.00
	TO PUTTY,RESPRAY PAINTING LEFT FRONT FENDER ,FRONT BUMPER & LEFT FRONT FENDER WHEEL HOUSE PANEL.TO POLISH.		650.00	500.00
			1,380.00	990.00
GRAND TOTAL			3,670.30	2,807.02

Report Ref No. CC6/CTI19013782/R1db3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	----------

Report Ref No. CC6/CT119013782/R1db3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.