

SALE



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 06.08.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2087X TOYOTA PRIUS ALPHA 1.8 (2014)

To Supply

1) 1pc	Front bumper <i>de-</i>	\$	585.00
2) 1pc	Front bumper left side retainer <i>ne-</i>	\$	65.70
3) 1pc	Front bumper right side retainer <i>X old damage X ne</i>	\$	65.70X
4) 1pc	Front bumper left fog lamp <i>sc-</i>	\$	152.00
5) 1pc	Left head lamp <i>sc-</i>	\$	1,060.00
6) 1pc	Left front fender <i>bt -</i>	\$	435.00
7) 1pc	Left front fender cowling <i>? X ne</i>	\$	272.00X
8) 1pc	Left front fender cowling "Hybrid" emblem <i>ne /</i>	\$	65.00

Sub total parts	\$	2,700.40	<i>2362.70</i>
Less: 25% discount	\$	675.10	<i>-590.60</i>
	\$	2,025.30	<i>1772.10</i>

To Supply S.Nett Parts

1) 1pc	Right front sport rim <i>repair</i>	\$	220.00X
2) 1set	Front bumper clip <i>ne /</i>	\$	30.00
3) 1set	Left front fender cowling clip <i>ne /</i>	\$	15.00

Sub total S.Nett Parts	\$	265.00	<i>45.00</i>
------------------------	----	--------	--------------

L/charge

1) To tuff kote	\$	50.00 <i>30</i>
2) To remove & refit right front tyre rim, balance tyre	\$	50.00 <i>30</i>
3) To focus left front headlamp, check wiring	\$	30.00 <i>30</i>
4) To remove left front fender, front bumper & left head lamp, knock left	\$	600.00 <i>400</i>

wheel house panel. Replace the above parts. Align & adjust front bumper & fender

- 5) To putty, respray painting left front fender, front bumper & left front fender wheel house panel. To polish

\$ ~~650.00~~ 500

Sub total L/charges	\$ 1,380.00	990.00
	<u>\$ 3,670.30</u>	<u>2807.10</u>
		561.40
		<u>2245.70</u>

Prepared by: Pei Yee

Issue

Up 90010068

LS 2250/-

4 days

4/3

06/08/19 @ 1630

Resurvey after repair