



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 06.08.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2087X TOYOTA PRIUS ALPHA 1.8 (2014)

To Supply

1) 1pc	Front bumper <i>de-</i>	\$	585.00
2) 1pc	Front bumper left side retainer <i>new</i>	\$	65.70
3) 1pc	Front bumper right side retainer <i>X old damage</i>	\$	65.70
4) 1pc	Front bumper left fog lamp <i>scr -</i>	\$	152.00
5) 1pc	Left head lamp <i>scr -</i>	\$	1,060.00
6) 1pc	Left front fender <i>st -</i>	\$	435.00
7) 1pc	Left front fender cowling <i>?</i>	\$	272.00
8) 1pc	Left front fender cowling "Hybrid" emblem <i>new</i>	\$	65.00

Sub total parts	\$	2,700.40
Less: 25% discount	\$	675.10
	\$	2,025.30

To Supply S.Nett Parts

1) 1pc	Right front sport rim <i>repair</i>	\$	220.00
2) 1set	Front bumper clip <i>new</i>	\$	30.00
3) 1set	Left front fender cowling clip <i>new</i>	\$	15.00

Sub total S.Nett Parts	\$	265.00
------------------------	----	--------

L/charge

1) To tuff kote	\$	50.00 30
2) To remove & refit right front tyre rim, balance tyre	\$	50.00 30
3) To focus left front headlamp, check wiring	\$	30.00
4) To remove left front fender, front bumper & left head lamp, knock left	\$	600.00 400

wheel house panel. Replace the above parts. Align & adjust front bumper & fender

- 5) To putty, respray painting left front fender, front bumper & left front fender wheel house panel. To polish

\$ ~~650.00~~ 500

Sub total L/charges \$ 1,380.00
\$ 3,670.30

Prepared by: Pei Yee

Issue

Up 90010568

4 days

4/3

06/08/19 @ 1630

Returning after
repair