

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Ong chin Kiat of C72 Date/Time: 6.8.19 16.20p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FU 3398 B Insured: SKH 52757at Workshop m/s Hua Ho Tel: 62844487of Bik 6 Refu Lam 10 #01-540Policy No: DM PCSN30047019000 Claim No: SNM 19020365502

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 20.7.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 7.8.19 4.20p.m Person Contacted: Thng H.O.D. Endorsement: \_\_\_\_\_  
Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>FU 3398 B -X</u>
	<u>SKH 52757 -X</u>

Surveyor

## ASSIGNMENT

From: \_\_\_\_\_ Date: 7.8.2019

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FU 3398B

at Workshop m/s Hua HO

of Blk 6 Refu Lane 10 #01-540

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FU 3398B Yr Regn: 1, 02  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Phantom C.C. 197

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 31387 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 7A200 0005160

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 100/80-17  
R: 130/90-15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or IRC

Front

R/Bal. 6 mm

L/Bal. mm

D.O.A. 20/7/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/8/19 174460 1-1-2022  
1/5 & 200 confirmed with Repairer (Red 205, 539)

RECEIVED 13 AUG 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 13/8 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 200/-)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2019		06 Aug 2019 16:20 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:		KOH GUO WEI, ID: S9226723G							
Main Claimant:		SOON YOU LIANG, ID: S9346785Z							
Vehicle Reg. No.:		FU3398B	Date of Loss: 20/07/2019 11:00 - :59 [210 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:		TP / SNM19D203655C02	Policy/Cover Note No.: DMPCSN30047019000						
Vehicle Reg. No. (Insured):		SKH5275T	Policy No. (Claimant): S106636458 (TP)						
		Excess:	S\$0.00						
Repairer:		Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C, 539187 Defu Lane - Tel: 62844487							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/08/2019]							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 785Z

### Vehicle Details

Vehicle No.: FU3398B  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 07 Aug 2019  
Vehicle Make: HONDA  
Vehicle Model: PHANTOM200  
Primary Colour: Black  
Manufacturing Year: 2001  
Engine No.: TA200E0005160  
Chassis No.: TA2000005160  
Maximum Power Output: -  
Open Market Value: \$3,500.00  
Original Registration Date: 02 Jan 2002  
First Registration Date: 02 Jan 2002  
Transfer Count: 3  
Actual ARF Paid: \$525.00

### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 01 Jan 2022  
COE Category: D - Motorcycle  
COE Period(Years): 10  
PQP Paid: \$1,909.00  
COE Rebate Amount: \$460.00  
**Total Rebate Amount: \$460.00**

### Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

The information contained herein is correct as at 07 Aug 2019

OK

# 和 好 贸 易

## HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540  
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,  
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FU3398

Items	Price
Signal light left	\$48
Rear Plate Number	\$22
Number Plate light 1 Set	\$42
Rear Fender	\$105
Rear Fender Bracket	\$58
Labor Charge	\$150
Total	\$425

not fixed  
LKR

L/S \$200  
2 days

7/8/19

to be 26. After 119 -

MP: 9009 6608

P-148  
107  
133.20  
263.20  
202  
210.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013783/UVF3N2

Date: 13/08/2019

**REFERENCE**

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMPCSN30047019000		
<b>Claimant Vehicle No :</b>	FU3398B	<b>Insured Vehicle No :</b>	SKH5275T		
<b>Date of Loss:</b>	20/07/2019	<b>Nature of Claim:</b>	TP	<b>Claim No:</b>	SNM19D203655C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	FU3398B	<b>Engine No:</b>	TA200E0005160
<b>Make &amp; Model:</b>	HONDA PHANTOM 200M, 197cc (M)	<b>Chassis No:</b>	TA20000005160
<b>Reg. Date:</b>	02/01/2002 (Man. Year: 2001)	<b>Odometer:</b>	31387 km
<b>Colour:</b>	Black		
<b>Engine Capacity:</b>	197 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	100/80-17	<b>Rear Tyre Size:</b>	130/90-15
<b>Front Left Side:</b>	IRC 6 mm	<b>Rear Left Side:</b>	IRC 6 mm
<b>Front Right Side:</b>	0 mm	<b>Rear Right Side:</b>	0 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	275.00	143.20	131.80	47.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	150.00	120.00	30.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>425.00</b>	<b>263.20</b>	<b>161.80</b>	<b>38.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>200.00</b>		
<b>Nett Amount (S\$)</b>	<b>425.00</b>	<b>200.00</b>	<b>225.00</b>	<b>52.94</b>

**INSPECTION**

<b>Date of Assignment:</b>	06/08/2019	
<b>Date Inspected:</b>	07/08/2019	<b>Inspected At:</b>
		Hua Ho Trading (HQ)
		Blk 6 Defu Lane 10, #01-540 Defu
		Industrial Estate Park C
		Singapore 539187

**Estimated Period of Repair:** 2.0 days**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 Aug 2019)	
<b>Parts:</b>	N/A	HONDA PHANTOM 200M 197cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FU3398B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIGNAL LIGHT LEFT	Cracked	48.00 F	*48.00 FL
2	1		*SET NUMBER PLATE LIGHT	Cut	42.00 F	*42.00 FL
3	1		*REAR FENDER	Repair	105.00 F	*- FL
4	1		*REAR FENDER BRACKET	Bent	58.00 F	*58.00 FL
5	1		*REAR PLATE NUMBER	Bent	22.00 FS	*10.00 FS
					<b>Sub Total (\$\$)</b>	<b>275.00 158.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00 14.80</b>
					<b>Total Parts (\$\$)</b>	<b>275.00 143.20</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LOBOR CHARGE	New	150.00	120.00
Gross Labour Cost (\$\$)			150.00	120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >