

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Steve (LKK) WPL Repair 6/8/19, 7.30pm
 5 days
 L/S
 R → AC SM

Ms AXA Insurance Pte Ltd
 Date 2/8/2019
 Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLG 5281T
 Chassis No: NKE1657135384
 MAKE / MODEL : Toyota Corolla Axio Hybrid 1.5 Auto
 DATE OF ACCIDENT : 01/08/2019
 YOUR INSURED VEHICLE NUMBER SKK 6406R
 MILEAGE : 264758 km

PARTS DESCRIPTION		QTY	UNIT PRICE	LIST PRICE
1	Rear boot <i>X R</i>	1PC	\$1,632.00	\$1,632.00
2	Rear boot Toyota logo <i>✓ APC</i>	1PC	\$60.00	\$60.00 <i>✓</i>
3	Rear boot Hybrid emblem <i>✓ APC</i>	1PC	\$50.00	\$50.00 <i>✓</i>
4	Rear boot AXIO emblem <i>✓ APC</i>	1PC	\$45.00	\$45.00 <i>✓</i>
5	Rear boot COROLLA emblem <i>✓ APC</i>	1PC	\$50.00	\$50.00 <i>✓</i>
6	Rear boot weatherstrip <i>✓ CRV</i>	1PC	\$270.00	\$270.00 <i>✓</i>
7	Rear boot lock <i>✓ BT</i>	1PC	\$420.00	\$420.00 <i>✓</i>
8	Rear boot lock catch <i>X</i>	1PC	\$60.00	\$60.00 <i>✓</i>
9	Rear end panel top cover <i>✓ CRV</i>	1PC	\$342.00	\$342.00 <i>✓</i>
10	Rear end panel <i>✓ DA</i>	1PC	\$792.00	\$792.00 <i>✓</i>
11	Rear bumper <i>✓ DA</i>	1PC	\$912.00	\$912.00 <i>✓</i>
12	Rear bumper RH side retainer <i>✓ DR</i>	1PC	\$138.00	\$138.00 <i>✓</i>
13	Rear bumper LH side retainer <i>✓ DR</i>	1PC	\$138.00	\$138.00 <i>✓</i>
14	Rear bumper LH reflector <i>X</i>	1PC	\$100.00	\$100.00
15	Rear bumper RH reflector <i>✓</i>	1PC	\$165.00	\$165.00
16	Rear bumper LH reflector <i>X</i>	1PC	\$165.00	\$165.00
17	Rear bumper RH reflector <i>X</i>	1PC	\$165.00	\$165.00
18	R/R taillamp <i>?</i>	1PC	\$850.00	\$850.00 <i>?</i>
19	R/L taillamp <i>?</i>	1PC	\$850.00	\$850.00 <i>?</i>
			LIST TOTAL S\$:	\$4,633.00
			25.00% DISCOUNT S\$:	\$1,158.25
				\$3,474.75
<u>SPECIAL NETT</u>				
1	Bumper clips <i>✓ APC</i>	1 SET	\$80.00	\$80.00 <i>30</i>
2	Body sealant <i>✓ APC</i>	1SET	\$200.00	\$200.00 <i>30</i>
3	Reverse sensor <i>✓ DR</i>	1SET	\$260.00	\$260.00 <i>200</i>
4	Windscreen sealant <i>X</i>	1SET	\$120.00	\$120.00
			Special Nett Total S\$:	\$660.00

LABOUR CHARGES

- | | | | |
|---|--|------------|------------|
| 1 | To labour charge for removing rear bumper, rear boot , rend end panel inner and outer out to facilitate repairs and replacement of damaged parts. Also starighten R/L fender | \$1,500.00 | 750
740 |
| 2 | To remove and install rear windscreen | \$120.00 | × |
| 3 | To respray rear boot R/L fender, rear bumper, end panel inner and outer panel, spare tyre panel | \$1,000.00 | 600 |
| 4 | To deactivate and activate high voltage battery as a safety precautions | \$300.00 | × |
| 5 | To conduct standard of opearting procedures post repairs diagnostic scan test s a requirement for hybrid cars upon completion of collision repairs | \$300.00 | × |
| 6 | Transfer tailgate mechanism | \$100.00 | × |

LABOUR TOTAL S\$:	<u>\$3,320.00</u>
TOTAL S\$:	\$7,454.75
7% GST	\$521.83
GRAND TOTAL S\$:	<u><u>\$7,976.58</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: