

cecilia

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Steve (LKK) htl AM/UL 6/8/19, 3.00pm
5 days
L/S
R - AC SM

Ms AXA Insurance Pte Ltd
Date 2/8/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLG 5281T
Chassis No: NKE1657135384
MAKE / MODEL : Toyota Corolla Axio Hybrid 1.5 Auto
DATE OF ACCIDENT : 01/08/2019
YOUR INSURED VEHICLE NUMBER SKK 6406R
MILEAGE : 264758 km

PARTS DESCRIPTION		QTY	UNIT PRICE	LIST PRICE
1	Rear boot OR R	1PC	\$1,632.00	\$1,632.00 X
2	Rear boot Toyota logo / MC	1PC	\$60.00	\$60.00 ✓
3	Rear boot Hybrid emblem / PH	1PC	\$50.00	\$50.00 ✓
4	Rear boot AXIO emblem / MC	1PC	\$45.00	\$45.00 ✓
5	Rear boot COROLLA emblem / MC	1PC	\$50.00	\$50.00 ✓
6	Rear boot weatherstrip / CRV	1PC	\$270.00	\$270.00 187 ✓
7	Rear boot lock / BT	1PC	\$420.00	\$420.00 200 ✓
8	Rear boot lock catch X NN	1PC	\$60.00	\$60.00 X
9	Rear end panel top cover / CRV	1PC	\$342.00	\$342.00 193 ✓
10	Rear end panel / DD	1PC	\$792.00	\$792.00 663 ✓
11	Rear bumper / DD	1PC	\$912.00	\$912.00 780 ✓
12	Rear bumper RH side retainer X NR	1PC	\$138.00	\$138.00 ✓
13	Rear bumper LH side retainer X NR	1PC	\$138.00	\$138.00 ✓
14	Rear bumper LH reflector X NAI	1PC	\$100.00	\$100.00 X
15	Rear bumper RH reflector X NAI	1PC	\$165.00	\$165.00 X
16	Rear bumper LH reflector X NAI	1PC	\$165.00	\$165.00 X
17	Rear bumper RH reflector X NN	1PC	\$165.00	\$165.00 X
18	R/R taillamp ? X NAI	1PC	\$850.00	\$850.00 X
19	R/L taillamp ? X NN	1PC	\$850.00	\$850.00 X
LIST TOTAL S\$:				\$4,633.00
25.00% DISCOUNT S\$:				\$1,158.25
				\$3,474.75

2594
- 25%
1878

SPECIAL NETT

1	Bumper clips / MC	1 SET	\$80.00	30
2	Body sealant / MC	1SET	\$200.00	30
3	Reverse sensor / BR	1SET	\$260.00	200
4	Windscreen sealant X NN	1SET	\$120.00	

Special Nett Total S\$: \$660.00 260

LABOUR CHARGES

- | | | | |
|---|---|------------|------------|
| 1 | To labour charge for removing rear bumper, rear boot, rear end panel inner and outer out to facilitate repairs and replacement of damaged parts. Also straighten R/L fender | \$1,500.00 | 750
740 |
| 2 | To remove and install rear windscreen | \$120.00 | X |
| 3 | To respray rear boot R/L fender, rear bumper, end panel inner and outer panel, spare tyre panel | \$1,000.00 | 600 |
| 4 | To deactivate and activate high voltage battery as a safety precautions | \$300.00 | X |
| | To conduct standard of operating procedures post repairs diagnostic scan test as a requirement | | |
| 5 | for hybrid cars upon completion of collision repairs | \$300.00 | X |
| 6 | Transfer tailgate mechanism | \$100.00 | X |

LABOUR TOTAL \$:	\$3,320.00	1350
TOTAL \$:	\$7,454.75	
7% GST	\$521.83	
GRAND TOTAL \$:	<u>\$7,976.58</u>	

P- 1878
NI- 269
L- 1350
3488
LIS- 2790.40
= 2800

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: