

Case Details

Case Reference Number : TAX/08/19/2007

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-7931-ID

Accident Date and Time : 02/08/2019 06:15 AM

Vehicle Registration Number : SHC4484A

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 54

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ NK
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	✓ X R
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ NK
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ NK
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ NK
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ NK
One Time Key In	Main		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	✓ X NK
Standard	Main	BODY RH	6505528	DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	✓ X R

Standard	Main	BODY RH	6505486	DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	✓	X R
Standard	Main	BODY RH	6505606	MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair	✓	X R
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	✓	X R
Total Spare Part Cost									3,091.43	Surveyor Total			209.40		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20		
Final Spare Part Cost									2,473.14	Final Sur Total			167.52		

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
2	Main	TO RESPRAY RH REAR DOOR	378.00	200	
3	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	150	
4	Main	TO RESPRAY REAR FENDER RH	378.00	200	
5	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			1,692.00	950.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	NA
2	Main	TO TRANSFER DOOR MECHANISM	240.00	0	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	NA
4	Main	TO REPLACE SUNDRY PARTS	100.00	20	NA
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			580.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,473.14	167.52
Total Labour Cost	845.00	300.00
Total Spray Painting	1,692.00	950.00
Other	580.00	60.00
Overall Total	5,590.14	1,477.52
Lump Sum Repair Option	☒	☒
Lump Sum Total	5,600.00	1,500.00

Surveyor Approved Amount

1,500.00

No of Repair Days*

6

3


Remarks

L/S repair, take after spray. Finalize sent to
stevechen@lkkauto.com

Surveyor Name

STEVE CHEN

Signature



Save

Clear

Survey Date

05/08/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHC4484A
Case Reference Number	TAX/08/19/2007
Registration Date	11/2/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ROSLAN BIN AWE
Type of Accident	Side Swipe
Accident Date and Time	2/8/2019 2:15 PM
Accident Reported Date and Time	2/8/2019 4:37 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24102699
Special Instruction to ARC, if any	TSS
Prepared Date and Time	4/8/2019 6:30 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Rear View

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,692.00	\$950.00
Total Spare Part Cost	\$2,473.14	\$167.52
Total Other Cost	\$580.00	\$60.00
TOTAL COST	\$5,590.14	\$1,477.52
Lump Sum Total	\$5,600.00	\$1,500.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	05/08/2019 3:33 PM	05/08/2019 2:16 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0134	Invoice Number	
Quotation Date	10.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,692.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$580.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
6505549		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check
	BODY RH	67001-47070	DOOR FRT/RH	1.00	\$894.40	100.00	\$0.00	Replace	Repair
	BODY RH	67003-47080	DOOR RR/RH	1.00	\$954.50	100.00	\$0.00	Replace	Repair
	BODY RH	75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair
Total					\$4,052.10		\$209.40		

209.40

- 208

167.52

+ 300.00

+ 1010.00

1477.52

415 \$1500/-