

15/5/2019

INS. CASE OWNER:

FOO CHIEF YAN | CC 3 / AIG1901 3804, Tiebbsz

LKK:
IDAC:

Surveyor:

TAUMIKH

DOI:

ASSIGNMENT
06/08/19

Date / Time:

6/8/19

Registered in Merimen:

6/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

989 6271 J

Name of Insured:

PRIMER FIBRE MANAGEMENT (S) PVT

Insured Tel No.:

HP:

D.O.A:

3/8/19

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: PHANG SIE KONT

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

81233379766

Policy No.:

ANAAA 558V

Make / Model:

MBR160ES

Place of Accident:

UE TOWARDS LUY

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

989 8114

INSRS:
WSP:
Tel:
Liability:
RMKS:

performance

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
08/08/19	989 8114 - 8 989 6271 J	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	10/08/19 - vic
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS

26,167.15

(11 days)

Reduction:

26 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

19/11/19

Confirm with:

CAROLINE

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

COLD RATE-ENDED TP)

Repair Cost (w/govt)

SS

27,998.85

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

900.00

x 15 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

BIBB

SS

402.43

(2 PAX)

DENIAL 4 2 PAX

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

-

3) Survey fee:

4320.00

Total:

SS

29,308.73

Global Sum SS:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

29/08/19

Confirm with:

PERFORMANCE

MOTOR LIMITED

Payee 1:

SS

29,308.73

Name 1:

PERFORMANCE

MOTOR LIMITED

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

ASS. REC. BY:

REF:

A19

ASSIGNMENT

From:

Date:

6/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLQ8114

at Workshop n/s

of

performance
303 Alexander Road

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Car In.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

996K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

11

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Date:

Person Contacted:

Vehicle: IN / OUT

Han.

Veh No:

SLQ8114

Yr Regn:

2017 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216D

c.c.

1496

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

44242

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA2B32000V92531

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

C

L

6/8/19 4pm

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rebuck: \$52,279

Date / Time

Action / Instruction

Plp & 26.167.15
Cred: \$9,419.90 (26.15)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L&L (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + PS, SI

Photos

Others

TOTAL

110

SLQ811U

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: +65477770

260, Kampong Arang Road
East Coast Centre
Singapore 438187
Fax: +65449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: +65796401 (AfterSales)
+65796424 (Motorrad)

06 AUG 2019

GST REG. NO : M2 - 0020081 - X

ESTIMATE

#Car in #

Estimate No. : b1 52230	Page No. : 1 of 6
Date Estimated : 05/08/2019	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Oh Sze Ching (Hu SiQin) 132 Punggol Walk #12-17 Singapore 828777	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	V925931	28/06/2017	216d CAT	0

DESCRIPTION	VALUE
To tow accident vehicle to PML workshop.	for receipt ✓ 195.00
To replace rear bumper & attachments, boot lid, tail panel exterior & interior including to pull & straighten both rear chassis, to knock out trunk floor panel and dented area caused by the accident	#250 ✓ 5,950.00
To respray rear bumper, tail panel, rear left fender, rear right fender, boot lid and boot compartment	4470 ✓ 4,967.00
To carry out body cavity preservation. (Per panel)	100 ✓ 118.00
To carry out body cavity preservation (For cut panel)	45 ✓ 531.00
To replace front exhaust silencer including align exhaust system and conduct checks for leak.	photo? 45 ✓ 531.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	photo? 45 ✓ 531.00
To replace each diesel particulate filter including alignment and conduct checks for leak	photo? 564 ✓ 664.00
To replace engine mountings including re-alignment of engine block to body frame.	photo? 577X un 679.00
To replace gearbox mountings including re-alignment of gearbox to cross member and propeller shaft system.	photo? 577X un 679.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230 ✓ 271.00
To remove and install fuse box at the rear section to facilitate repairs.	photo? 45X un 531.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-4
Toll-Free Number (1800-2255269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438160
Fax: 63449773

115, Alexandra Road
Sime Darby Performance Centre
Singapore 159944
Fax: 64796602
64796620



GST REG. NO : M2 - 0020081-4

ESTIMATE

Link Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate No. : b1 52230
Date Estimated : 05/08/2019
Prepared By : Han Kwan Yong

Page No. : 3 of 6
Acknowledged By Repairer
Signature:
Date:

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	V925931	28/06/2017	216d CAT	0

DESCRIPTION

QTY PRIC VALUE

RR BUMPER LH INNER SIDE GUIDE	1	60.05	60.05	61.35
RR BUMPER RH INNER SIDE GUIDE	1	60.05	60.05	61.35
GROMMET	2	0.75	1.50	
PLAQUE 74MM	1	71.25	71.25	
STRIKER BOOT LID	1	58.25	58.25	
LOCK TRUNK LID	1	193.80	193.80	
REAR FLAP TOWING EYE PRIMED	1	42.85	42.85	
REAR WINDOW ESG	1	654.35	654.35	
# REAR BUMPER HEAT INSULATOR	1	60.60	60.60	
# LOWER TAIL LID TRIM PANEL	1	275.70	275.70	
# TRUNK LID SEALING	1	97.85	97.85	
SENSOR WIRE FOR SMART OPENER TOP	1	43.15	43.15	
SENSOR WIRE FOR SMART OPENER BOTTOM	1	41.50	41.50	
CONTROL UNIT SMART OPENER	1	494.60	494.60	
# LH GUTTER STRIP	1	51.95	51.95	
# RH GUTTER STRIP	1	51.95	51.95	
REAR LH LIGHT IN THE SIDE PANEL	1	270.50	270.50	
RR LH LIGHT IN THE TRUNK LID	1	255.65	255.65	
RR RH LIGHT IN THE TRUNK LID	1	255.65	255.65	
RR RH LIGHT IN THE SIDE PANEL	1	365.20	365.20	
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20	
ULTRASONIC SENSOR MINERALWEISS(WA96	1,4	368.80	1,475.20	
BLIND RIVET AVIBVLB	60.75	0.55	33.41	
SCREW (SF PLUS M5X15)	5.20	0.55	2.86	
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80	
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	112.70	
(DG) CLEANER R1 (100ML)	1	26.15	26.15	
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10	
PUNCH RIVET N4	40.30	0.55	22.17	
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85	
(S/L) SEAM SEAL 300ML	3.2	33.80	108.16	

+ overp

Total Parts : 16,800.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 6181142 Claim No.

Date & Time 6/8/19 Excess \$0

Surveyor's Name Tan Jue Sign

Surveyor's Tel 97495349 Authorised Yes / No

A. Authorised Date 10/8/19 Time

RE SURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjue@linkauto.com

No. of Working Days Recommend 9-11 days

Labour 1 : 18,523.00

Parts : 16,800.60

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 2,472.65

Grand Total : 37,796.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

35587.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52230**
Date Estimated : **05/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Oh Sze Ching (Hu SiQin)
132 Punggol Walk
#12-17

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 828777

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	WBA2B32000V9259	28/06/2017	216d CAT	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#	2.55	4.00	0	10.20 <i>hd ✓</i>
# BLIND RIVET NUT M6	42.85	1.00	0	42.85 <i>bt ✓</i>
# V BAND CLAMP	8.25	1.00	0	8.25 <i>nee ✓</i>
# GASKET	61.25	1.00	0	61.25 <i>bt ✓</i>
# STEERING BOX HEAT RESISTANT PLATE	1.00	2.00	0	2.00 <i>nee ✓</i>
# EXPANDING NUT	3.50	8.00	0	28.00 <i>nee ✓</i>
# BUMP STOP	2.85	8.00	0	22.80 <i>nee ✓</i>
# HOOK AND LOOP FASTENER	1.00	3.00	0	3.00 <i>per ✓</i>
# SNAP LOCKING COUPLING				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	178.35
Total Labour & Parts :	178.35

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz 

Worldwide Partners

Date: 3/8/19 Time: 15:50

Customer Name: Mr. [unclear]

Technician Name: W.E.I.

Customer Telephone: 06 7973

Reg. No: SL 3511V Job No: _____

Make/Model: BMW 216

Odometer Reading (Customer Vehicle): _____

Location: Bainbridge 112

KM Travelled by Assistance Vehicle: _____ (1 way)

Time on Scene: 16:40

Fault Reported: _____

Time Job Completed: _____

Fault Found: _____

Repaired at Breakdown Scene: Y/N

How was vehicle repaired? _____

VIN No: _____

Hubcaps Y/N

Spare Wheel Y/N

Tools Y/N

Audio System Y/N

Keys + Remote Y/N

Aerial Y/N

Cashcard Y/N

Fuel

E		F
---	--	---

Interior Condition: _____

Front Seats

Rear Seats

Floor Covering

Headlining




Day/Night

Wet/Dry

Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent



Delivery to Dealership / Date and Time: _____

Vehicle received in the above condition YES/NO

If not stated as above specify difference: _____

CUSTOMER DECLARATION

1. I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
2. I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
3. In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
4. I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customer Name & Signature (green copy)	<u>[Signature]</u>	Dealer/Workshop Signature, Name & Stamp (yellow copy)	<u>[Signature]</u>	Operators Signature (white & pink copy)	<u>W.E.I.</u>
--	--------------------	---	--------------------	---	---------------

Vic (LKKAUTO)

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Sent: Friday, 18 October, 2019 1:51 PM
To: Taufikh (LKKAUTO)
Cc: Vic (LKKAUTO); Toh Jing Xuan; Bernard Wan Chong Huat
Subject: DIRECT SETTLEMENT FINAL REPORT - SLQ811U
Attachments: SKM_C45819101811470.pdf

Dear Taufikh

For your perusal :

Labour	\$12912.00
Parts	\$13255.15
Total	\$26167.15

Owner is claiming LOSS OF USE = \$100 X 15 DAYS.
 MEDICAL FEE - \$402.43.
 LTA SERCH FEE - \$7.45.

Note : 11 working days.

Please reply me directly.

Best Regards

Sharon Heng
Performance Motors Ltd
Body & Paint
DID : 63190123
Fax : 64743229

*email Sharon 21/10.
\$26167.15, 11 days*

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]
Sent: Friday, 18 October, 2019 11:48 AM
To: Sharon Heng L K
Subject: Message from KM_C458

Performance Motors Limited

A member of the Sime Darby Group
Co Reg No. 197401559W GST Reg No. M2-0020081-X



Final Report

Estimate No. : **b1 52230**
Date Estimated : **05/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Oh Sze Ching (Hu SiQin)
132 Punggol Walk
#12-17

Singapore 828777

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	WBA2B32000V9259	28/06/2017	216d CAT	0
DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT	
To tow accident vehicle to PML workshop.	195.00	0	195.00	
To replace rear bumper and attachments, rear boot lid and attachments, both tail lamps, tail end panel exterior & interior etc including to pull and straighten both rear chassis, to make good trunk floor panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	4,250.00	0	4,250.00	
To respray rear bumper, tail end panel, rear left fender, rear right fender, boot lid, boot compartment and both roof frames etc	4,470.00	0	4,470.00	
To carry out body cavity preservation.	100.00	0	100.00	
To carry out body cavity preservation. (For cut panel).	451.00	0	451.00	
To replace front exhaust pipe catalyst silencer including align exhaust system and conduct checks for leak.	451.00	0	451.00	
To replace rear exhaust silencer, chrome pipe and clamping bush etc including to align system and check for leak.	451.00	0	451.00	
To replace each diesel particulate filter including alignment and conduct checks for leak.	564.00	0	564.00	
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00	0	230.00	
To conduct water leak tests.	75.00	0	75.00	
To remove and install rear windscreen glass to transfer from old to new boot lid	574.00	0	574.00	
To replace bootlid smart opener control unit including to conduct checks for proper function.	350.00	0	350.00	
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking	451.00	0	451.00	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

system for proper function.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

150.00	0	150.00
150.00	0	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# BLIND RIVET NUT M6	2.55	4.00	0	10.20
CLAMPING BUSH	✓ 54.30	1.00	0	54.30 ?
# V BAND CLAMP	42.85	1.00	0	42.85
# GASKET	8.25	1.00	0	8.25
EXCHANGE EXHAUST PIPE CATALYST	✓ 1,694.80	1.00	0	1,694.80
REAR SILENCER	✓ 1,167.45	1.00	0	1,167.45 ?
EXCH DIESEL PARTICULATE FILTER EU5	✓ 3,727.75	1.00	0	3,727.75
HOLDER EXHAUST SYSTEM	✓ 27.90	1.00	0	27.90 ?
HOLDER EXHAUST SYSTEM	✓ 27.90	1.00	0	27.90 ?
TAILPIPE TRIM BLACK CHROME	✓ 110.55	1.00	0	110.55 ?
# STEERING BOX HEAT RESISTANT PLATE	61.25	1.00	0	61.25
TRUNK LID	✓ 1,204.35	1.00	0	1,204.35 ?
INTERIOR TAIL TRIM	✓ 279.10	1.00	0	279.10 ?
TAIL PANEL	✓ 355.20	1.00	0	355.20 ?
REAR BUMPER PANEL PRIMED (PDC)	✓ 1,045.45	1.00	0	1,045.45
# EXPANDING NUT	1.00	2.00	0	2.00
RR BUMPER LH SIDE GUIDE	✓ 61.35	1.00	0	61.35 ?
REAR BUMPER CARRIER	✓ 458.10	1.00	0	458.10 ?
SUPPORT	✓ 45.30	1.00	0	45.30 ?
RR BUMPER LH INNER SIDE GUIDE	✓ 61.35	1.00	0	61.35 ?
RR BUMPER RH INNER SIDE GUIDE	✓ 61.35	1.00	0	61.35 ?
GROMMET	✓ 0.75	2.00	0	1.50 ?
PLAQUE 74MM	✓ 71.25	1.00	0	71.25 ?
# BUMP STOP	3.50	8.00	0	28.00
# HOOK AND LOOP FASTENER	2.85	8.00	0	22.80
CONTROL UNIT SMART OPENER	✓ 494.60	1.00	0	494.60 ?
# SNAP LOCKING COUPLING	1.00	3.00	0	3.00
RR LH LIGHT IN THE TRUNK LID	✓ 255.65	1.00	0	255.65 ?
RR RH LIGHT IN THE TRUNK LID	✓ 255.65	1.00	0	255.65 ?
RR LH LIGHT IN THE SIDE PANEL	✓ 365.20	1.00	0	365.20
ULTRASONIC SENSOR MINERALWEISS(WA96	✓ 368.80	1.00	0	368.80 ?
BLIND RIVET AVIBVLB	✓ 0.55	60.00	0	33.00 ?
SCREW (SF PLUS M5X15)	✓ 0.55	5.00	0	2.75 ?
(DG/SL) BODY ADHESIVE K5B (195ML)	✓ 326.80	1.00	0	326.80 ?
PUNCH RIVET N4	✓ 0.55	40.00	0	22.00 ?
(DG) BODYWORK ADHESIVE K5A (50ML)	✓ 112.70	1.00	0	112.70 ?
(DG) CLEANER R1 (100ML)	✓ 26.15	1.00	0	26.15 ?
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	✓ 131.55	2.00	0	263.10 ?
(DG/SL) GLASS PRIMER 30ML (VP206)	✓ 27.85	1.00	0	27.85 ?
(S/L) SEAM SEAL 300ML	33.80	2.00	0	67.60 ?
#				
#				

SUPPLEMENTARY ITEMS

A member of the Sims Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Total Labour :	12,912.00
Total Parts :	13,255.15
Total Labour & Parts :	26,167.15
GST @7%:	1,831.70
Grand Total :	27,998.85

[illegible]

LOSS OF USE = \$100 x 15 days
MEDICAL FARE - \$402.43
LTA SEARCH FEE - \$7.45

SLQ811U

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



06 AUG 2019

GST REG. NO : M2 - 0020081 - X

ESTIMATE

#Car in #

Estimate No. : b1 52230
Date Estimated : 05/08/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Oh Sze Ching (Hu SiQin)
132 Punggol Walk
#12-17

Singapore 828777

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	V925931	28/06/2017	216d CAT	0

DESCRIPTION

To tow accident vehicle to PML workshop.

for receipt? 195.00

To replace rear bumper & attachments, boot lid, tail panel exterior & interior including to pull & straighten both rear chassis, to knock out trunk floor panel and dented area caused by the accident

#250 5,950.00

To respray rear bumper, tail panel, rear left fender, rear right fender, boot lid and boot compartment

4470 4,967.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

photo? 451 531.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

photo? 451 531.00

To replace each diesel particulate filter including alignment and conduct checks for leak.

photo? 564 664.00

To replace engine mountings including re-alignment of engine block to body frame.

photo? 577 679.00

To replace gearbox mountings including re-alignment of gearbox to cross member and propeller shaft system.

photo? 577 679.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To remove and install fuse box at the rear section to facilitate repairs.

photo? 451 531.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52230
Date Estimated : 05/08/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	V925931	28/06/2017	216d CAT	0

DESCRIPTION

VALUE

To conduct water leak tests.

63 75.00

To remove and install rear windscreen glass to transfer from old to new boot lid

487 574.00

To supply and install rear windscreen solar film.

451 531.00

To replace bootlid smart opener control unit, top and bottom sensor lines including program and conduct checks for proper function.

photo? 561 661.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Customer Comment: After accident engine loss power when accelerate -

To check & rectify engine loss power when accelerate

photo? 150 177.00

Sundries.

150.00

Total Labour 1: 18,523.00

DESCRIPTION

QTY PRIC

VALUE

CLAMPING BUSH
RUBBER MOUNTING
EXCHANGE EXHAUST PIPE CATALY
REAR SILENCER
MUFFLER CLAMP D=63.2MM
EXCH DIESEL PARTICULATE FILT
TAILPIPE TRIM BLACK CHROME
HOLDER EXHAUST SYSTEM
STABILIZER LINK
ENGINE MOUNT
GEARBOX MOUNT
TRUNK LID
INTERIOR TAIL TRIM
TAIL PANEL
REAR BUMPER PANEL PRIMED (PD
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT

1 54.30
2 17.00
1 1,694.80
1 1,167.45
1 42.85
1 3,727.75
1 110.55
2 57.20
1 92.05
1 239.80
1 208.50
1 1,204.35
1 279.10
1 355.20
1 1,045.45
1 49.05
1 49.05
1 458.10
1 45.30

54.30
34.00
1,694.80
1,167.45
42.85
3,727.75
110.55
114.40
92.05
239.80
208.50
1,204.35
279.10
355.20
1,045.45
49.05
49.05
458.10
45.30

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. NO. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601
64796624



GST REG. NO : M2 - 0020081

ESTIMATE

Insurance Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate No. : b1 52230
Date Estimated : 05/08/2019
Prepared By : Han Kwan Yong

Page No. : 3 of 6
Acknowledged by Repairer
Signature:
Date:

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	V925931	28/06/2017	216d CAT	0

DESCRIPTION

QTY	PRIC	VALUE
1	60.05	60.05
1	60.05	60.05
2	0.75	1.50
1	71.25	71.25
1	58.25	58.25
1	193.80	193.80
1	42.85	42.85
1	654.35	654.35
1	60.60	60.60
1	275.70	275.70
1	97.85	97.85
1	43.15	43.15
1	41.50	41.50
1	494.60	494.60
1	51.95	51.95
1	51.95	51.95
1	270.50	270.50
1	255.65	255.65
1	255.65	255.65
1	365.20	365.20
4	5.05	20.20
4	368.80	1,475.20
75	0.55	41.25
20	0.55	11.00
1	326.80	326.80
1	112.70	112.70
1	26.15	26.15
2	131.55	263.10
30	0.55	16.50
1	27.85	27.85
3	33.80	101.40

Total Parts : 16,800.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 6/8/19 Excess \$

Surveyor's Name _____ Sign _____
Surveyor's Tel 97445494 Authorised Yes / No
Authorised Date WP Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanfume@pml.com.sg
No. of Working Days Recommend 9-11 days

Labour 1	:	18,523.00
Parts	:	16,800.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,472.65
Grand Total	:	37,796.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



POLICY INFORMATION		Policy No. : VPA/P1954623
Source	: (01) 11615 SD CONTEGO BMW 1 YR	
Insured	: OH SZE CHING (HU SIQIN)	
Address	: 132 PUNGGOL WALK #12-17 SINGAPORE 828777	
Business/Profession	: ENGINEER Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.	
Period of Insurance : From 28/06/2019 To 27/06/2020 (Both Dates Inclusive)		
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.		
PREMIUM		
Premium After 30.00% : SGD 1,654.82		
NCD		
Safe Driver Disc	: SGD 165.48	
10.00%		
GST 7.00%	: SGD 104.26	
Annual Premium	: SGD 1,593.60	
Total Payable	: SGD 1,593.60	
RISK DETAILS THE MOTOR VEHICLE		
Type Of Cover	: Comprehensive	
Regn No.	: SLQ811U	
Type Of Use	: Private Car	
Make/Model	: BMW 216D ACTIVE TOURER D/AB	
Year of Manufacture	: 2017	Seating Capacity (excl. Driver) : 04
Body Type	: MULTI - PURPOSE VEHICLE	Engine C.C. : 1496
Engine No.	: 38919980B37C15A	
Chassis No.	: WBA2B32000V925931	
Insured's Estimated Market Value	: Market Value At The Time Of Loss (including Accessories and Spare Parts)	
Limitations as to Use : As specified in Certificate of Insurance		
Hire Purchase	: DBS BANK LTD	
Basic Own Damage Excess	: SGD 600.00	
Named Drivers		
1	OH SZE CHING (HU SIQIN)	
2	TAY SOK LI	
MEMORANDA, CLAUSES, WARRANTIES & ENDORSEMENTS		
Subject to the Memoranda, Clauses, Warranties & Endorsements attached hereto:		
MEMORANDUM A		

Print Received Message

This mail is associated with :

***SLQ811U (8123333797SG)**
[GBG6271J]

TP

OH SZE CHING

Aug 3 2019 3:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 15/11/2019 15:50 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$29308.73) - SLQ811U - Claim Handler: Foo, Chit Yan

Approved:29308.73.

X

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, OH SZE CHING (the third party claimant) of 132 PUNGGOL
WALK #12-17 S(828777) (address), owner of SLQ 811U (vehicle no.)
hereby authorize PERFORMANCE MOTORS LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLQ 811U that was damaged pursuant to the accident which occurred on 03/08/2019
(date) along CTE TOWARDS CITY BEFORE EXIT¹¹ (location) involving vehicle no/s
GBG 6271J ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this _____ (day) of _____ (month) 20____ (year)



Signed by "the third party claimant"
(with chop if applicable)

PERFORMANCE MOTORS LIMITED
203 Alexandra Road
Sino City Performance Centre
Singapore 159941
Tel: 6315 0100 (Sales)
6319 0111 (AfterSales)

Signed by "the workshop"
(with chop)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Aug 2019 Edit Reg		06 Aug 2019 00:00 Edit Adj Rpt	\$26,167.15 Edit Estimates	\$26,167.15 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z									
Main Claimant: OH SZE CHING, ID: S77036968									
Vehicle Reg. No.: SLQ811U		Date of Loss: 03/08/2019 15:00 - :59 [25 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8123333797SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): GBG6271J		Policy No. (Claimant): P1954623							
Excess:									
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/08/2019]									
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
• AIG_SG_EXPRESS (15/11/2019): Alert - Adj Mandate Approved (\$29308.73) - SLQ811U - Claim Handler: Foo, Chit Y...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ811U (8123333797SG)
[GBG6271J]

TP

OH SZE CHING

Aug 3 2019 3:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▾

Letters/Correspondences

1 per page ▾ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	☒

Photos/Images

3 per page ▾ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/10/19 16:00	Odometer Reading	Load JPG ☒	☒
2	22/10/19 16:00	Chassis Number	Load JPG ☒	☒
3	22/10/19 16:01	General View	Load JPG ☒	☒
4	22/10/19 16:01	General View	Load JPG ☒	☒
5	22/10/19 16:01	General View	Load JPG ☒	☒
6	22/10/19 16:01	General View	Load JPG ☒	☒
7	22/10/19 16:01	General View	Load JPG ☒	☒
8	22/10/19 16:01	General View	Load JPG ☒	☒
9	22/10/19 16:01	General View	Load JPG ☒	☒
10	22/10/19 16:01	General View	Load JPG ☒	☒
11	22/10/19 16:01	General View	Load JPG ☒	☒
12	22/10/19 16:01	General View	Load JPG ☒	☒
13	22/10/19 16:01	General View	Load JPG ☒	☒
14	22/10/19 16:01	General View	Load JPG ☒	☒
15	22/10/19 16:01	General View	Load JPG ☒	☒
16	22/10/19 16:01	General View	Load JPG ☒	☒
17	22/10/19 16:01	General View	Load JPG ☒	☒
18	22/10/19 16:01	General View	Load JPG ☒	☒
19	22/10/19 16:01	General View	Load JPG ☒	☒
20	22/10/19 16:01	General View	Load JPG ☒	☒
21	22/10/19 16:01	General View	Load JPG ☒	☒
22	22/10/19 16:01	General View	Load JPG ☒	☒
23	22/10/19 16:01	General View	Load JPG ☒	☒
24	22/10/19 16:01	General View	Load JPG ☒	☒
25	22/10/19 16:01	General View	Load JPG ☒	☒
26	22/10/19 16:01	General View	Load JPG ☒	☒
27	22/10/19 16:01	General View	Load JPG ☒	☒
28	22/10/19 16:01	General View	Load JPG ☒	☒
29	22/10/19 16:01	General View	Load JPG ☒	☒
30	22/10/19 16:01	General View	Load JPG ☒	☒
31	22/10/19 16:01	General View	Load JPG ☒	☒
32	22/10/19 16:01	General View	Load JPG ☒	☒
33	22/10/19 16:01	General View	Load JPG ☒	☒
34	22/10/19 16:01	General View	Load JPG ☒	☒
35	22/10/19 16:01	General View	Load JPG ☒	☒
36	22/10/19 16:01	General View	Load JPG ☒	☒
37	22/10/19 16:01	General View	Load JPG ☒	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/10/19 16:01	General View	1 Load JPG	✓
39	22/10/19 16:01	General View	1 Load JPG	✓
40	22/10/19 16:01	General View	1 Load JPG	✓
41	22/10/19 16:01	General View	1 Load JPG	✓
42	22/10/19 16:01	General View	1 Load JPG	✓
43	22/10/19 16:01	General View	1 Load JPG	✓
44	22/10/19 16:01	General View	1 Load JPG	✓
45	22/10/19 16:01	General View	1 Load JPG	✓
46	22/10/19 16:01	General View	1 Load JPG	✓
47	22/10/19 16:01	General View	1 Load JPG	✓
48	22/10/19 16:01	General View	1 Load JPG	✓
49	22/10/19 16:01	General View	1 Load JPG	✓
50	22/10/19 16:01	General View	1 Load JPG	✓
51	22/10/19 16:01	General View	1 Load JPG	✓
52	22/10/19 16:01	General View	1 Load JPG	✓
53	22/10/19 16:01	General View	1 Load JPG	✓
54	22/10/19 16:01	General View	1 Load JPG	✓
55	22/10/19 16:01	General View	1 Load JPG	✓
56	22/10/19 16:01	General View	1 Load JPG	✓
57	22/10/19 16:01	General View	1 Load JPG	✓
58	22/10/19 16:01	General View	1 Load JPG	✓
59	22/10/19 16:01	General View	1 Load JPG	✓
60	22/10/19 16:01	General View	1 Load JPG	✓
61	22/10/19 16:01	General View	1 Load JPG	✓
62	22/10/19 16:01	General View	1 Load JPG	✓
63	22/10/19 16:01	General View	1 Load JPG	✓
64	22/10/19 16:01	General View	1 Load JPG	✓
65	22/10/19 16:01	General View	1 Load JPG	✓
66	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
67	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
68	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
69	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
70	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
71	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
72	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
73	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
74	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
75	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
76	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
77	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
78	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
79	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
80	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
81	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
82	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
83	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
84	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
85	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
86	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
87	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
88	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
89	22/10/19 16:01	Reinspection Photo	1 Load JPG	✓
90	22/10/19 16:02	Reinspection Photo	1 Load JPG	✓

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
92	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
93	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
94	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
95	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
96	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
97	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
98	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
99	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
100	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
101	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
102	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
103	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
104	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
105	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
106	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
107	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
108	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
109	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
110	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
111	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
112	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
113	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
114	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
115	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
116	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
117	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
118	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
119	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
120	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
121	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
122	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
123	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
124	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
125	22/10/19 16:02	Reinspection Photo	 Load JPG	☒
126	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
127	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
128	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
129	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
130	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
131	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
132	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
133	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
134	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
135	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
136	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
137	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
138	22/10/19 16:03	Reinspection Photo	 Load JPG	☒
139	22/10/19 16:03	Reinspection Photo	Load JPG	☒
140	22/10/19 16:03	Reinspection Photo	Load JPG	☒
141	22/10/19 16:03	Reinspection Photo	Load JPG	☒
142	22/10/19 16:03	Reinspection Photo	Load JPG	☒
143	22/10/19 16:03	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
144	22/10/19 16:03	Reinspection Photo	1 Load JPG	✓
145	22/10/19 16:03	Reinspection Photo	1 Load JPG	✓
146	22/10/19 16:03	Reinspection Photo	1 Load JPG	✓
147	22/10/19 16:03	Reinspection Photo	1 Load JPG	✓
148	22/10/19 16:03	Reinspection Photo	1 Load JPG	✓
149	22/10/19 16:03	Reinspection Photo	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/08/19 18:50	TP GIA REPORT	1 Load PDF	
2	10/08/19 14:33	EMAIL TO OI	1 Load PDF	
3	10/08/19 14:33	LETTER TO OI	1 Load PDF	
4	13/08/19 19:25	TP ESTIMATE- MARKED	1 Load PDF	
5	06/11/19 10:16	LOD	1 Load PDF	
6	06/11/19 10:16	LTA SEARCH	1 Load PDF	
7	06/11/19 10:16	MEDICAL FEE	1 Load PDF	
8	08/11/19 16:25	AUTHORIZATION LETTER FOR MEDICAL BILLS	1 Load PDF	
9	08/11/19 16:26	EMAIL FROM TP	1 Load PDF	
10	22/11/19 14:29	AUTHORISATION TO ACT	1 Load PDF	
11	22/11/19 14:29	RELEASE VOUCHER	1 Load PDF	
12	22/11/19 14:29	WORKSHOP INVOICE	1 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/08/19 12:59	OI GIA REPORT	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG6271J (Insd veh)	Model:	BMW 216D 1.5 D ACTIVE
	SLQ811U (TP veh)		TOURER (F45) (A)
Date of Accident:	03/08/2019		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		38,078.14
Final Repair Cost	:	\$		27,998.85
Loss of Use	:	\$		900.00
Rental (if any)	:	\$		15.00 days at \$60.00 per day
LTA / GIA Search Fee	:	\$		7.45
Medical Fee	:	\$		402.43
	:	\$		
Final Settlement Sum	:	\$		29,308.73
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u>		
BOLA Liability: <u>100</u> (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 29,308.73
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

22 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19013804/T1HB3S2
Date: 22/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SLQ811U **Insured Vehicle No :** GBG6271J
 Date of Loss: 03/08/2019 Nature of Claim: TP Claim No: 8123333797SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ811U** Engine No: 38919980B37C15A
 Make & Model: BMW 216D, 1.5 D Active Tourer (F45) (A) Chassis No: WBA2B32000V925931
 Reg. Date: 28/06/2017 (Man. Year: 2017) Odometer: 44242 km
 Colour: White
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,214.05	13,255.15	3,958.90	23.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,373.00	12,912.00	5,461.00	29.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,587.05	26,167.15	9,419.90	26.47
+ GST 7.00/7.00% (S\$)	2,491.09	1,831.70	659.39	26.47
Nett Amount (S\$)	38,078.14	27,998.85	10,079.29	26.47
+ Loss of Use (15.0 x S\$60.00/day) (S\$)		900.00		
+ Medical Costs (S\$)		402.43		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		29,308.73		

INSPECTION

Date of Assignment: 06/08/2019 Performance Motors Limited (Alexandra)
 Date Inspected: 06/08/2019 Inspected At: 303 Alexandra Road, Sime Darby Performance Centre
 Estimated Period of Repair: 11.0 days Singapore 159941

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	61.35 FS	*61.35 FS
2	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	61.35 FS	*61.35 FS
3	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
4	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
5	1		*STRIKER BOOT LID	Not Necessary	58.25 FS	*- FS
6	1		*LOCK TRUNK LID	Not Necessary	193.80 FS	*- FS
7	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	42.85 FS	*- FS
8	1		*REAR WINDOW ESG	Not Necessary	654.35 FS	*- FS
9	1		*REAR BUMPER HEAT INSULATOR	Not Necessary	60.60 FS	*- FS
10	1		*LOWER TAIL LID TRIM PANEL	Not Necessary	275.70 FS	*- FS
11	1		*TRUNK LID SEALING	Not Necessary	97.85 FS	*- FS
12	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	43.15 FS	*- FS
13	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	41.50 FS	*- FS
14	1		*CONTROL UNIT SMART OPENER	Cracked	494.60 FS	*494.60 FS
15	1		*LH GUTTER STRIP	Not Necessary	51.95 FS	*- FS
16	1		*RH GUTTER STRIP	Not Necessary	51.95 FS	*- FS
17	1		*REAR LH LIGHT IN THE SIDE PANEL	Cracked	365.20 FS	*365.20 FS
18	1		*RR LH LIGHT IN THE TRUNK LID	Cracked	255.65 FS	*255.65 FS
19	1		*RR RH LIGHT IN THE TRUNK LID	Cracked	225.65 FS	*255.65 FS
20	1		*RR RH LIGHT IN THE SIDE PANEL	Not Necessary	365.20 FS	*- FS
21	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
22	4		*ULTRASONIC SENSOR MINERALWEISS (WA96)	Not Working 1pc Only	1,475.20 FS	*368.80 FS
23	1		*BLIND RIVET AVIBVLB	Necessary 60pcs Only	41.25 FS	*33.00 FS
24	1		75pcs *SCREW (SF PLUS M5X15)	Necessary 5pcs Only	11.00 FS	*2.75 FS
25	1		20pcs *(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
26	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	112.70 FS	*112.70 FS
27	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
28	2		*(DG/SL) WINDSCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
29	1		*PUNCH RIVET N4	Necessary	22.00 FS	*22.00 FS
30	1		40pcs *(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
31	1		3pcs *(S/L) SEAM SEAL 300ML	Necessary 2pcs Only	101.40 FS	*67.60 FS
32	1		*CLAMPING BUSH	Bent	54.30 FS	*54.30 FS
33	2		*RUBBER MOUNTING	Not Necessary	34.00 FS	*- FS
34	1		*EXCHANGE EXHAUST PIPE CATALY	Bent	1,694.80 FS	*1,694.80 FS
35	1		*REAR SILENCER	Bent	1,167.45 FS	*1,167.45 FS
36	1		*MUFFLER CLAMP D=63.2MM	Not Necessary	42.85 FS	*- FS
37	1		*EXCH DIESEL PARTICULATE FAULT	Bent	3,727.75 FS	*3,727.75 FS
38	1		*TAILPIPE TRIM BLACK CHROME	Bent	110.55 FS	*110.55 FS
39	2		*HOLDER EXHAUST SYSTEM	Bent	114.40 FS	*55.80 FS
40	1		*STABILIZER LINK	Not Necessary	92.05 FS	*- FS
41	1		*ENGINE MOUNT	Not Necessary	239.80 FS	*- FS
42	1		*GEARBOX MOUNT	Not Necessary	208.50 FS	*- FS
43	1		*TRUNK LID	Bent	1,204.35 FS	*1,204.35 FS
44	1		*INTERIOR TAIL TRIM	Deformed	279.10 FS	*279.10 FS
45	1		*TAIL PANEL	Bent	355.20 FS	*355.20 FS
46	1		*REAR BUMPER PANEL PRIMED (PD)	Deformed	1,045.45 FS	*1,045.45 FS
47	1		*RR BUMPER LH SIDE GUIDE	Deformed	61.35 FS	*61.35 FS
48	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	49.05 FS	*- FS
49	1		*REAR BUMPER CARRIER	Bent	458.10 FS	*458.10 FS
50	1		*SUPPORT	Bent	45.30 FS	*45.30 FS
51	1		*SUNDRIES	Not Necessary	150.00 FS	*- FS
52	4		*BLIND RIVET NUT M6	Necessary	10.20 FS	*10.20 FS
53	1		*V BAND CLAMP	Bent	42.85 FS	*42.85 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*GASKET	Necessary	8.25 FS	*8.25 FS
55	1		*STEERING BOX HEAT RESISTANT PLATE	Bent	61.25 FS	*61.25 FS
56	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
57	8		*BUMP STOP	Necessary	28.00 FS	*28.00 FS
58	8		*HOOK AND LOOP FASTENER	Necessary	22.80 FS	*22.80 FS
59	3		*SNAP LOCKING COUPLING	Necessary	3.00 FS	*3.00 FS
Total Parts (S\$)					17,214.05	13,255.15

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.	New	195.00	195.00
2	TO REPLACE REAR BUMPER & ATTACHMENTS, BOOT LID, TAIL PANEL EXTERIOR & INTERIOR INCLUDING TO PULL & STRAIGHTEN BOTH REAR CHASSIS, TP KNOCK OUT TRUNK FLOOR PANEL AND DENTED AREA CAUSED BY THE ACCIDENT.	New	5,950.00	4,250.00
3	TO RESPRAY REAR BUMPER, TAIL PANEL, REAR LEFT FENDER, REAR RIGHT FENDER, BOOT LID AND BOOT COMPARTMENT.	New	4,967.00	4,470.00
4	TO CARRY OUT BODY PRESERVATION. (PER PANEL)	New	118.00	100.00
5	TO CARRY OUT BODY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
6	TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
7	TO REPLACE EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
8	TO REPLACE EACH DIESEL PARTICULATE FILTER INCLUDING ALIGNMENT AND CONDUCT CHECKS FOR LEAK.	New	664.00	564.00
9	TO REPLACE ENGINE MOUNTINGS INCLUDING RE-ALIGNMENT OF ENGINE BLOCK TO BODY FRAME.	New	679.00	0.00
10	TO REPLACE GEARBOX MOUNTINGS INCLUDING RE-ALIGNMENT OF GEARBOX TO CROSS MEMBER AND PROPELLER SHAFT SYSTEM.	New	679.00	0.00
11	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.	New	271.00	230.00
12	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS.	New	531.00	0.00
13	TO CONDUCT WATER LEAK TEST.	New	75.00	75.00
14	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO TRANSFER FROM OLD TO NEW BOOT LID.	New	574.00	574.00
15	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	New	531.00	0.00
16	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	661.00	350.00
17	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.	New	531.00	451.00
18	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
19	TO CHECK & RECTIFY ENGINE LOSS POWER WHEN ACCELERATE.	New	177.00	150.00
Gross Labour Cost (S\$)			18,373.00	12,912.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >