

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SH 7382J

DATE 6/8/2019

MAKE :

MODEL : HYUNDAI i40

LKK - Calvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Repair</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>X 10</i>			\$ 22.00
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
SUB TOTAL				\$ 575.00
LESS 20%				\$ 115.00
DISCOUNTED TOTAL				\$ 460.00
	Rear Bumper Rubber Mat <i>X 10</i>			\$ 50.00
TOTAL				\$ 50.00
Labour Charge				
	Panel Beating			\$ 400.00 ¹⁰⁰
	Spray Painting Charge			\$ 300.00 ²⁰⁰
	Wiring Charge			\$ 30.00 ^{X 10}
	Remove/Refix Reverse Sensor			\$ 80.00 ^{X 20}
<p><i>Kalvin (LKK)</i> <i>6/8/19 12 45h.</i> <i>2073</i></p>				\$ 810.00
TOTAL LABOUR				
<p><i>U/S</i></p>				\$ 1,320.00
ESTIMATE TOTAL				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.