

22/03/2019

ASS. REC. BY:

REF: CS/CT1/9013811/Gsf312

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CT1

Date/Time: 6.3.19 17.19p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 7263E

Insured:

PC 7686V

at Workshop m/s Lcrf Pte Ltd

Tel:

9742 2188

of 60 Jalan Lam Huat #04-01

Policy No: DMB1SN19326718000

Claim No:

SNM1911 203654 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5.8.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 7.8.19 9.31a.m

Person Contacted:

Mr SM

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (V) Estimate
	SLQ 7263E - NBA / CT1 1901375214 DCA - 05/08/2019
	PC 7686V - NBA / CT1 1901375214 DCA - 05/08/2019

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 7263E

yr Regn:

20/7/17

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel Hybrid

c.o

1496

Colour:

Silk

A/C:

Insured / Std / NI / NA

Sp. Reading

198318

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R4J227030

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

5/8/19

D.O.I.

7/8/19

Survey held at

Linn City (LCRF)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12/19 Findre \$4650, 5 days (Mr Sim)

(\$8888.72 Red - 66%)

16/12/2019

RECEIVED 16 DEC 2019

Date/Time, File Pass to?

16/12/19

Type

Date/Time, File Return to?

3)

Report Format:

Lump Sum / B.B. (\$4,650/- US)



: Prel. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

3 + PS. \$

Field:

(Site):

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2019		06 Aug 2019 17:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	LONGLIM PTE LTD, Co. Reg. No.: 201109995N																							
Main Claimant:	LIONCITY RENTALS PTE LTD, Co. Reg. No.: 20150621K																							
Vehicle Reg. No.:	SLQ7263E	Date of Loss:	05/08/2019 09:00 - :59 [24 Months and 16 Days From LTA Reg Date (Mon Yr)]																					
Claim Type:	TP / SNM19D203654C02	Policy/Cover Note No.:	DMB1SN18326718000																					
Vehicle Reg. No. (Insured):	PC7686U	Policy No. (Claimant):	19-MK000195-ROO																					
		Excess:	S\$1,500.00																					
Repairer:	Lcrf Pte Ltd (HQ) 60 JALAN LAM HUAT, #04-01 SINGAPORE 737869, 737869 Kranji - Tel:																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]																							
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/08/2019]																							
Driver/Custodian (Insured):	WONG MIE WAH @CHEE WOON YING (61 / Female), NRIC: S1338668D Email:																							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
There are no mail for this case.																								
ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Steve Chen (LKK Auto)

From: Siak Tong Sim <siaktong@lioncityrentals.com.sg>
Sent: Friday, December 13, 2019 4:20 PM
To: Steve Chen (LKK Auto)
Subject: Re: Finalisation of SLQ7263E

Steve
Ok confirmed lump sum \$4,650.00/5 days

Regards
S.T.Sim (65-97422188)
Manager
Accident Reporting Center
60 Jalan Lam Huat
#04-35/36 Carros Centre
Singapore 737869



On Tue, Dec 10, 2019 at 6:14 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Mr Sim,

Kindly refer our finalize \$4650 (L/S, before GST). 5 repair days.

Kindly confirm.

Thanks

Best Regards,

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	621K
Vehicle Details	
Vehicle No.:	SLQ7263E
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	LEB5927042
Chassis No.:	RU31227030
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$22,345.00
Original Registration Date:	20 Jul 2017
First Registration Date:	20 Jul 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$43,246.00
Total Rebate Amount:	\$46,996.00

The information contained herein is correct as at 07 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/08/2019 16:27
Date Of Accident 05/08/2019 09:45
Exact Location Of Accident BRADELL ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLQ7263E
Insured/Policyholder
Name Of Registered Owner LIONCITY RENTALS PTE LTD
Co Reg No 20150621K
Email Address RENTALS@LIONCITYRENTALS.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-31381884

Vehicle Particulars

Manufacturer HONDA
Model VEZEL-1.5 HYBRID (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage THIRD PARTY
Fleet Policy YES
Policy Number 19-MK000195-ROO
Cover Note Number

Driver

Name of Driver NEO ROBERT
NRIC No S1316652H
Date Of Birth 25/09/1958
Occupation OUTDOOR
Date Of Driving Pass 12/01/1981
Driving Experience 38 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-94372701
Fax Number
Contact Number
Email Address NOEMAIL

Address	BLK 101A PUNGGOL FIELD #15-490
Postcode	821101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC7686U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

^{EVERETT}
I ~~was~~ was driving along Broadal Road and I also drove because I
want to turn into Apple Inc building 81078 ~~and~~ ^{PC 763611} a vehicle back
on my back and the impact is by

DECLARATION

I hereby declare that the information provided herein is true and correct to the best of my knowledge.

Police Officer's Signature

Place To Print

Driver's Signature

Signature of non-driver involved party

Reporting Officer's Signature

Place

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

[Signature]
13/8/19

7/8/19, 12:30 pm

Ms China Taiping Insurance (Singapore) Pte Ltd
Date: 06/08/2019
Attn : MOTOR CLAIMS DEPT

Steve (LKIS)
83228813

Mr Ng Jial
5 chys

L/S

Ry AL Smy

ESTIMATE

VEHICLE NO: SLQ 7263E
CHASSIS NO : RU31227030
MAKE / MODEL : Honda Vezel Hybrid 1.5 Auto
DATE OF ACCIDENT : 05/08/2019
YOUR INSURED VEHICLE NUMBER : PC 7686U
MILEAGE :

PARTS DeSCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 Rear tailgate / <i>OD</i>	1PC	\$1,450.00	\$1,450.00 <i>1100/</i>
2 Rear tailgate glass / <i>OR</i>	1PC	\$1,800.00	\$1,800.00 <i>1000/</i>
3 Rear tailgate roof top garnish / <i>OR</i>	1PC	\$800.00	\$800.00 <i>594/</i>
4 Rear tailgate Vezel emblem / <i>OR</i>	1PC	\$86.80	\$86.80
5 Rear tailgate Honda emblem <i>X NM</i>	1PC	\$81.30	\$81.30 <i>X</i>
6 Rear tailgate Hybrid emblem / <i>OR</i>	1PC	\$86.80	\$86.80
7 Rear tailgate windscreen moulding / <i>OR</i>	1PC	\$195.00	\$195.00
8 Rear tailgate weatherstrip <i>? X NM</i>	1PC	\$155.00	\$155.00 <i>X</i>
9 Rear tailgate lock / <i>OT</i>	1PC	\$550.00	\$550.00 <i>210/</i>
10 Rear tailgate lock catch <i>X NM</i>	1PC	\$180.00	\$180.00 <i>X</i>
11 Rear RH tail lamp / <i>OR</i>	1PC	\$780.00	\$780.00 <i>474/</i>
12 Rear RH taillamp reflector / <i>OR</i>	1PC	\$480.00	\$480.00 <i>413/</i>
13 Rear end panel <i>X R</i>	1PC	\$830.00	\$830.00 <i>X</i>
14 Rear end panel top garnish <i>? X NM</i>	1PC	\$155.00	\$155.00 <i>X</i>
15 Rear bumper / <i>OD</i>	1PC	\$955.00	\$955.00 <i>762/</i>
16 R/R side bumper / <i>CRU</i>	1PC	\$258.00	\$258.00
17 R/R fender wheel arch moulding / <i>CRU</i>	1PC	\$218.00	\$218.00

LIST TOTAL S\$: \$9,060.90

20.00% DISCOUNT S\$: \$1,812.18

\$7,248.72

5397.60
-20%
4318.08

SPECIAL NETT

1	Rear bumper clips	/ MC	1 SET	\$80.00	30
2	End panel top garnish clips	/ MC	1 SET	\$80.00	15
3	Reverse sensor	X MM	1PC	\$490.00	
4	Body sealant	/ MC	1set	\$300.00	30
5	Windscreen sealant	/ MC	1PC	\$2,100.00	40
Special Nett Total S\$:				\$3,050.00	115

LABOUR CHARGES

1	To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts	\$1,200.00	600
2	To respray rear tailgate, end panel and spare tyre panel	\$1,000.00	700
3	To remove and install rear tailgate glass	\$160.00	50
4	To apply rustproofing on all damaged parts	\$180.00	30
5	To check wiring system To deactivate and activate the high voltage	\$100.00	30
6	hybrid battery as a standard for safety precautions To conduct a standard of operating procedures	\$300.00	X
7	post scan test as a requirement for hybrid cars upon collection of collision repairs	\$300.00	X

LABOUR TOTAL S\$:	\$3,240.00	1410
TOTAL S\$:	\$13,538.72	
7% GST	\$947.71	
GRAND TOTAL S\$:	\$14,486.43	

P- 4318.08
 NI- 115
 L- 1410
 5843.08
 L/S - 4674.46
 = 4650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed & is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013811/ESF3N2
Date: 26/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN18326718000
Claimant Vehicle No: SLQ7263E Insured Vehicle No: PC7686U
Date of Loss: 05/08/2019 Nature of Claim: TP Claim No: SNM19D203654C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ7263E
Make & Model: HONDA VEZEL, 1.5 HYBRID (A) Engine No: LEB5927042
Reg. Date: 20/07/2017 (Man. Year: 2016) Chassis No: RU31227030
Colour: Silver Odometer: 198318 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Giti 5 mm Rear Left Side: Giti 5 mm
Front Right Side: Giti 5 mm Rear Right Side: Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,298.72	4,433.08	5,865.64	56.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,410.00	1,830.00	56.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,538.72	5,843.08	7,695.64	56.84
Approved Total (Overridden) (S\$)		4,650.00		
(S\$)	13,538.72	4,650.00	8,888.72	65.65
+ GST 7.00/7.00% (S\$)	947.71	325.50	622.21	65.65
Nett Amount (S\$)	14,486.43	4,975.50	9,510.93	65.65

INSPECTION

Date of Assignment: 06/08/2019
Date Inspected: 07/08/2019 Inspected At: Lcrf Pte Ltd (HQ)
60 JALAN LAM HUAT, #04-01 SINGAPORE 737869
Singapore 737869
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2019)

Parts: M1-SUV HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ7263E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,450.00 FL	*1,100.00 FL
2	1		*REAR TAILGATE GLASS	Broken	1,800.00 FL	*1,000.00 FL
3	1		*REAR TAILGATE ROOF TOP GARNISH	Broken	800.00 FL	*594.00 FL
4	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*86.80 FL
5	1		*REAR TAILGATE HONDA EMBLEM	Not Necessary	81.30 FL	*- FL
6	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	86.80 FL	*86.80 FL
7	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
8	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	155.00 FL	*- FL
9	1		*REAR TAILGATE LOCK	Bent	550.00 FL	*210.00 FL
10	1		*REAR TAILGATE LOCK CATCH	Not Necessary	180.00 FL	*- FL
11	1		*REAR RH TAIL LAMP	Broken	780.00 FL	*474.00 FL
12	1		*REAR RH TAIL LAMP REFLECTOR	Broken	480.00 FL	*413.00 FL
13	1		*REAR END PANEL	Repair	830.00 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	155.00 FL	*- FL
15	1		*REAR BUMPER	Dented	955.00 FL	*762.00 FL
16	1		*R/R SIDE BUMPER	Crushed	258.00 FL	*258.00 FL
17	1		*R/R FENDER WHEEL ARCH MOULDING	Crushed	218.00 FL	*218.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
19	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*15.00 FS
20	1		*REVERSE SENSOR	Not Necessary	490.00 FS	*- FS
21	1		*SET BODY SEALANT	Necessary	300.00 FS	*30.00 FS
22	1		*WINDSCREEN SEALANT	Necessary	2,100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,110.90	5,512.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,812.18	1,079.52
Total Parts (\$\$)	10,298.72	4,433.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE,REAR END PANEL,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	600.00
2	TO RESPRAY REAR TAILGATE,END PANEL AND SPARE TYRE PANEL	New	1,000.00	700.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	50.00
4	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	180.00	30.00
5	TO CHECK WIRING SYSTEM	New	100.00	30.00
6	TO DEACTIVATE AND ACTIVATE THE HIGH VOLTAGE HYBRID BATTERY AS A STANDARD FOR SAFETY PRECAUTIONS	New	300.00	0.00
7	TO CONDUCT A STANDARD OF OPERATING PROCEDURES POST SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COLLECTION OF COLLISION REPAIRS	New	300.00	0.00
Gross Labour Cost (S\$)			3,240.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >