

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0940/2019/NS  
**Date** : 6-Aug-19

**Vehicle IN workshop. Kindly arrange for survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : MS. LIU YING  
**Address** : BLK 602 ELIAS ROAD  
#15-236  
Singapore 510602  
**Telephone** : HP +65 94560687  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1900093775  
**Vehicle No** : **SJF 345 E**  
**Model Code** : Audi Q5 SPORT 2.0 TFSI qu  
**Model / Year** : 30/4/2019  
**Engine No** : DAX 052445  
**Chassis No** : WAUZZZF7K2045178  
**Mileage** :  
**Date In** : 2-Aug-19  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 2-Aug-19  
**Place of Accident** : TPE TOWARD AIRPORT NEAR PIE ENTRANCE

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SJF 345 E

| S/n                         | Nature of Jobs                                                                                                                                                                                             | Estimated Charges     | Surveyor's Recommendation |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|---------------------------|
| 1                           | To tow and recover vehicle from scene of accident.                                                                                                                                                         | S/N \$ 280.00         | X NN                      |
| 2                           | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.                                                          | S/N \$ 480.00         | ✓                         |
| 3                           | To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.                                      | S/N \$ 1,400.00       | ✓                         |
| 4                           | To dismantle both front door panel trims. To remove and reinstall both wing mirror assy.                                                                                                                   | S/N \$ 600.00         | 300                       |
| 5                           | To dismantle and renew front bumper, both front fenders, bonnet and both headlights. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. | 5.5 \$ 7,200.00       | 2750                      |
| 6                           | To respray front bumper, front lower spoiler, both front fenders, bonnet, hinges, both front wheel arch trims, both upper A-pillar and both front doors.                                                   | 6.5 \$ 9,300.00       | 3575                      |
| 7                           | To carry out diagnostic checks.                                                                                                                                                                            | S/N \$ 384.00         | ✓                         |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                            | <b>: \$ 19,644.00</b> |                           |

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SJF 345 E

| S/N                   | Parts Description                                         | Damaged Parts & Prices |        |
|-----------------------|-----------------------------------------------------------|------------------------|--------|
|                       |                                                           | S/Nett                 | Remark |
| 1                     | FRONT BUMPER ASSY / CNA                                   | \$ 2,364.00            |        |
| 2                     | FRONT BUMPER FIXING PARTS ?                               | \$ 244.00              |        |
| 3                     | FRONT BUMPER SECURING STRIP - LH / RH ? 2                 | \$ 68.00               |        |
| 4                     | FRONT BUMPER CLOSING ELEMENT - LH / RH ? 2                | \$ 202.00              |        |
| 5                     | FRONT BUMPER GRILLE - CENTER / ee.                        | \$ 129.00              |        |
| 6                     | FRONT BUMPER SPOILER ?                                    | \$ 685.00              |        |
| 7                     | FRONT BUMPER UNDERRUN BAR - SILVER ?                      | \$ 431.00              |        |
| 8                     | FRONT BUMPER CLOSING ELEMENT / ee.                        | \$ 156.00              |        |
| 9                     | RADIATOR GRILLE / CNA                                     | \$ 3,258.00            |        |
| 10                    | "QUATTRO" EMBLEM / nec. NEC                               | \$ 87.00               |        |
| 11                    | STRIKER PLATE ?                                           | \$ 222.00              |        |
| 12                    | FRONT BUMPER AIR GUIDE GRILLE LH / RH / Cont <sub>2</sub> | \$ 1,038.00            |        |
| 13                    | FRONT BUMPER END CAP - LH / RH / nec 2                    | \$ 166.00              |        |
| 14                    | FRONT BUMPER LOCKING CLIP /                               | \$ 15.00               |        |
| 15                    | FOAM FILLER PIECE / ee                                    | \$ 259.00              |        |
| 16                    | FRONT BUMPER CARRIER / BT.                                | \$ 831.00              |        |
| 17                    | FRONT BUMPER TOP COVER / PR.                              | \$ 116.00              |        |
| 18                    | FRONT BUMPER GUIDE SECTION - LH / RH ? 2                  | \$ 68.00               |        |
| 19                    | "CAUTION" SIGN STICKER / nec- NEC                         | \$ 13.00               |        |
| 20                    | "AIR COND " STICKER / nec- NEC                            | \$ 18.00               |        |
| SUB TOTAL SPARE PARTS |                                                           | <u>\$ 10,370.00</u>    |        |

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SJF 345 E**

| S/N                          | Parts Description                           | <u>Damaged Parts &amp; Prices</u> |           | Remarks         |
|------------------------------|---------------------------------------------|-----------------------------------|-----------|-----------------|
|                              |                                             | S/Nett                            |           |                 |
| 22                           | PEDESTRIAN PROTECTION WARNING SIGN ?        | NEC                               | \$        | 13.00           |
| 23                           | HORN - LOW TONE LH ?                        |                                   | \$        | 178.00          |
| 24                           | HORN - HIGH TONE RH ?                       |                                   | \$        | 178.00          |
| 25                           | FRONT PARKING AID SENSOR - INNER 1 pc / DM  |                                   | \$        | 462.00          |
| 26                           | FRONT PARKING AID SENSOR - OUTER X NM 2     |                                   | \$        | 462.00          |
| 27                           | FRONT PARKING AID SENSOR SEAL RING - NB 4   |                                   | \$        | 12.00           |
| 28                           | FRONT BUMPER WIRING SET ?                   |                                   | \$        | 378.00          |
| 29                           | FRONT FENDER - LH / RH X Repair 2           |                                   | \$        | 2,602.00        |
| 30                           | FRONT FENDER FRONT BRACKET - LH / RH X      |                                   | \$        | 412.00          |
| 31                           | FRONT FENDER CENTRE BRACKET - LH / RH X     |                                   | \$        | 32.00           |
| 32                           | FENDER ATTACHMENT PARTS - FRONT X NM 2      |                                   | \$        | 119.00          |
| 33                           | FRONT FENDER INNER SHIELD - LH / RH OUTER X |                                   | \$        | 142.00          |
| 34                           | CLOSURE PANEL - LH / RH X                   |                                   | \$        | 56.00           |
| 35                           | COVER PANEL - LH / RH X                     |                                   | \$        | 72.00           |
| 36                           | WHEEL HOUSING LINER - LH / RH X             |                                   | \$        | 492.00          |
| 37                           | WHEEL SPOILER - LH X                        |                                   | \$        | 146.00          |
| 38                           | WHEEL SPOILER - RH X                        |                                   | \$        | 139.00          |
| 39                           | BONNET / Bnc.                               |                                   | \$        | 3,707.00        |
| <b>SUB TOTAL SPARE PARTS</b> |                                             |                                   | <b>\$</b> | <b>9,602.00</b> |

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SJF 345 E

| S/N                   | Parts Description                          | <u>Damaged Parts &amp; Prices</u> |    | Remarks          |
|-----------------------|--------------------------------------------|-----------------------------------|----|------------------|
|                       |                                            | S/Nett                            |    |                  |
| 40                    | LID HINGE - LH / RH ?                      | 2                                 | \$ | 292.00           |
| 41                    | BONNET ATTACHMENT PARTS ?                  |                                   | \$ | 127.00           |
| 42                    | GAS FILLED STRUT X                         |                                   | \$ | 217.00           |
| 43                    | SAFETY CATCH - LH / RH X { NN              | 2                                 | \$ | 218.00           |
| 44                    | INSULATOR PAD X                            |                                   | \$ | 289.00           |
| 45                    | IMPACT PROTECTION - LH / RH / CENTRE / NEC | NEC                               | \$ | 75.00            |
| 46                    | PLENUM CHAMBER COVER X NN                  |                                   | \$ | 131.00           |
| 47                    | LID LOCK - FRONT ?                         | 2                                 | \$ | 391.00           |
| 48                    | MICRO SWITCH - 2 PIN ?                     | 2                                 | \$ | 24.00            |
| 49                    | RELEASE CABLE RETAINER X                   | 2                                 | \$ | 18.00            |
| 50                    | BOWDEN CABLE - CENTRE X                    |                                   | \$ | 53.00            |
| 51                    | RELEASE ELEMENT X { NN                     |                                   | \$ | 53.00            |
| 52                    | RELEASE LEVER X                            |                                   | \$ | 13.00            |
| 53                    | LID LOCK CABLE X                           |                                   | \$ | 67.00            |
| 54                    | HEADLIGHT MOUNTING - LH / RH ?             | 2                                 | \$ | 214.00           |
| 55                    | LED HEADLIGHT - LH / RH < LH? RH - CMA     | 2                                 | \$ | 14,454.00        |
| 56                    | LIGHT CONTROL SYSTEM CONTROL UNIT X        |                                   | \$ | 692.00           |
| 57                    | MAIN LIGHT ELECTRONICS POWER MODULE X { NN |                                   | \$ | 693.00           |
| 58                    | LED WITH HEAT SINK - RH X                  |                                   | \$ | 990.00           |
| 59                    | HEADLIGHT HOSE - RH X                      |                                   | \$ | 35.00            |
| 60                    | LIFT CYLINDER - LH / RH ?                  | 2                                 | \$ | 256.00           |
| SUB TOTAL SPARE PARTS |                                            |                                   | \$ | <u>19,302.00</u> |

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SJF 345 E**

|                              |                                  | <b><u>Damaged Parts &amp; Prices</u></b> |                |
|------------------------------|----------------------------------|------------------------------------------|----------------|
| <b>S/N</b>                   | <b>Parts Description</b>         | <b>S/Nett</b>                            | <b>Remarks</b> |
| 61                           | LIFT CYLINDER HOSE X             | \$ 113.00                                |                |
| 62                           | WASHER PUMP X                    | \$ 147.00                                |                |
| 63                           | WASHER PUMP HOSE X               | \$ 61.00                                 |                |
| 64                           | WASHER PUMP INSULATOR X          | \$ 19.00                                 |                |
| 65                           | WINDSCREEN WASHER SYSTEM PUMP X  | \$ 118.00                                |                |
| 66                           | WASH WATER RESERVOIR X           | \$ 200.00                                |                |
| 67                           | WASH WATER RESERVOIR STRAINER X  | \$ 24.00                                 |                |
| 68                           | WASH WATER RESERVOIR END CAP X   | \$ 59.00                                 |                |
| 69                           | LOCK CARRIER ?                   | \$ 1,169.00                              |                |
| 70                           | A/C CONDENSOR ?                  | \$ 547.00                                |                |
| 71                           | REFRIGERANT LINE INLET ?         | \$ 263.00                                |                |
| 72                           | REFRIGERANT LINE OUTLET ?        | \$ 273.00                                |                |
| 73                           | RADIATOR ?                       | \$ 820.00                                |                |
| 74                           | RADIATOR RUBBER BUSH - LOWER ?   | \$ 24.00                                 |                |
| 75                           | RADIATOR RUBBER BUSH - LOWER ?   | \$ 17.00                                 |                |
| 76                           | COOLANT FROST PROTECTION / MC    | \$ 165.00                                |                |
| 77                           | INTERCOOLER / BT                 | \$ 724.00                                |                |
| 78                           | SEAL RING ?                      | \$ 82.00                                 |                |
| 79                           | INTERCOOLER PRESSURE HOSE - RH ? | \$ 283.00                                |                |
| 80                           | INTERCOOLER PRESSURE PIPE - LH ? | \$ 477.00                                |                |
| <b>SUB TOTAL SPARE PARTS</b> |                                  | <b>\$ 5,585.00</b>                       |                |

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SJF 345 E**

| S/N                         | Parts Description                                        | <u>Damaged Parts &amp; Prices</u> |                  |
|-----------------------------|----------------------------------------------------------|-----------------------------------|------------------|
|                             |                                                          | S/Nett                            | Remarks          |
| 81                          | O-RING ?                                                 | \$                                | 17.00            |
| 82                          | MAP SENSOR ?                                             | \$                                | 183.00           |
| 83                          | FAN RING ?                                               | \$                                | 373.00           |
| 84                          | RADIATOR FAN WITH CONTROL UNIT ?                         | \$                                | 2,159.00         |
| 85                          | RADIATOR LOUVRE ?                                        | \$                                | 483.00           |
| 86                          | AIR GUIDE - UPPER / LOWER ?                              | 2 \$                              | 86.00            |
| 87                          | AIR GUIDE - CENTRE ?                                     | \$                                | 37.00            |
| 88                          | AIR GUIDE - LH / RH ?                                    | 2 \$                              | 100.00           |
| 89                          | SERVOMOTOR ?                                             | \$                                | 166.00           |
| 90                          | ADJUST MOTOR CAP ?                                       | 2 \$                              | 14,454.00        |
| 91                          | AIR DUCT ?                                               | \$                                | 79.00            |
| 92                          | AIR FILTER X                                             | \$                                | 368.00           |
| 93                          | INTAKE HOSE X <i>5mm</i>                                 |                                   | TBC              |
| 94                          | FRONT WHEEL COVER - LH / RH <i>de</i>                    | 2 \$                              | 1,154.00         |
| 95                          | FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH / R <i>2</i> | <i>\$ out</i>                     | 1,074.00         |
| 96                          | WINDOW GUIDE TRIM STRIP - LH / RH ?                      | 2 \$                              | 622.00           |
| 97                          | NOISE INSULATION ?                                       | \$                                | 743.00           |
| 98                          | FRONT NO. PLATE <i>BT</i>                                | S/N \$                            | 40.00            |
| 100                         | SUNDRIES ?                                               | \$                                | 1,000.00         |
| <b>TOTAL SPARE PARTS</b>    |                                                          | <b>\$</b>                         | <b>67,997.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                                          | <b>\$</b>                         | <b>19,644.00</b> |
| <b>GRAND TOTAL</b>          |                                                          | <b>\$</b>                         | <b>87,641.00</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Luo Qing - 82880282  
Surveyed Date : 06/8/19.  
Authorised Date :  
Excess Cost :  
Liability : Not Authorised.  
Remarks : before paint photos.  
9 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant