

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0950/2019/NS
Date : 7-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no. : **SMJ 6814 Y**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn : Motor Claims Dept

Tel: 6328 0620 - Fax: 6224 1047

Owner's Name : MR LEE SOR HAR
Address : BLK 587 BUKIT TIMAH ROAD
#04-17
Singapore 269707
Telephone : (HP)+65 97348530
Type of Claim : Third Party
Policy No. : 1800038013
Vehicle No : **SLX 8192 H**
Model Code : Audi Sedan 2.0 TFSI 8W
Model / Year : Apr-18
Engine No : CVK 057091
Chassis No : WAUZZZF43JA130049
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 6-Aug-19
Place of Accident : DUNEARN ROAD TOWARDS CITY

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8192 H

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$	360.00	✓
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	✓
3	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	✓
5	To remove and reinstall rear back seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 4,040.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8192 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dismantle rear bumper, rear lid and rhs rear door. To cut out and reweld rhs rear fender. To renew rear bumper and rhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00	3500.
7	To respray rear bumper, rhs rear fender, rhs rear door, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,500.00	2750.
8	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
9	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 16,312.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 8192 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	\$ 2,015.00	✓
2	REAR BUMPER FIXING PARTS <i>Neu</i>	\$ 66.00	+
3	REAR BUMPER SECURING STRIP <i>?</i>	\$ 203.00	?
4	REAR BUMPER SPOILER <i>Neu</i>	\$ 227.00	+
5	REAR LIGHT REFLECTOR - LH <i>at</i>	\$ 38.00	✓
6	REAR BUMPER GUIDE SECTION - RH <i>?</i>	\$ 20.00	?
7	REAR BUMPER GUIDE SECTION - RH <i>?</i>	\$ 41.00	?
8	REAR FENDER - RH <i>Dented</i>	\$ 2,443.00	✓
9	RIVETTED CAP NUT <i>3 neu</i>	NEC \$ 2.00	✓
10	GROMMET	NEC \$ 2.00	✓
11	REAR WINDOW - LH <i>3 neu</i>	\$ 1,049.00	✓
12	SIDE WINDOW - RH	\$ 561.00	✓
13	PRIMER <i>Neu</i>	\$ 25.00	✓
14	WHEEL HOUSING LINER - RH	\$ 223.00	+
15	WHEEL HOUSING LINER - FRONT / REAR <i>3 neu</i>	\$ 82.00	+
16	DOOR - RH <i>Dented</i>	\$ 2,152.00	✓
17	OUTER DOOR SEAL <i>Neu</i>	NEC \$ 185.00	✓
18	BONDING AGENT <i>?</i>	NEC \$ 45.00	?
19	CLEANING SOLUTION <i>?</i>	NEC \$ 65.00	?
20	DOOR SEALING STRIP <i>Neu</i>	\$ 15.00	+
21	DOOR CATCH <i>XH2</i>	\$ 109.00	+
SUB-TOTAL SPARE PARTS		\$ 9,568.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 8192 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
22	ALUMINIUM RIM <i>at</i>	\$ 651.00	✓
23	RUBBER VALVE <i>new</i>	4 \$ 13.00	+
24	ACRYLIC SEALANT <i>2</i>	S/N \$ 180.00	✓
25	CAVITY WAX <i>1/2</i>	S/N \$ 140.00	✓
26	STONE CHIP <i>1/2</i>	S/N \$ 180.00	✓
27	METAL FILLER POWDER <i>2</i>	S/N \$ 280.00	✓
28	REAR WINDSCREEN SEALANT <i>1/2</i>	S/N \$ 200.00	✓
29	1/4 GLASS SEALANT	S/N \$ 100.00	✓
30	SUNDRIES <i>?</i>	S/N \$ 500.00	?
TOTAL SPARE PARTS		: \$ 11,812.00	
TOTAL LABOUR CHARGES		: \$ 16,312.00	
GRAND TOTAL		: \$ 28,124.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling.
Surveyed Date : 08/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant