

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0941/2019/NS
Date : 6-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR SANG HWAN HWANG
Address : 22 NASSIM HILL, THE LOFT
#04-14
Singapore 258468
Telephone : HP +65 96525082
Type of Claim : Own Damage Claims
Policy No. : 2100317887-06
Vehicle No : **SKF 528 H**
Model Code : Audi A6 C7 2.0 TFSI MU 4G
Model / Year : Oct-12
Engine No : CDN 242840
Chassis No : WAUZZZ4G2CN085646
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Aug-19
Place of Accident : 22 NASSIM HILL, THE LOFT

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKF 528 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function	S/N \$ 360.00	X
2	To renew lhs 1/4 glass to facilitate fender renewal.	S/N \$ 300.00	X
3	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00	/
4	To dilodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	X
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	X,
SUB TOTAL LABOUR CHARGES		: \$ 4,020.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKF 528 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dismantle rear bumper, rear lid, lhs sill panel trim, lhs front door and lhs rear door. Cut out and weld lhs rear fender and lhs inner C-pillar panel. Renew lhs front door, lhs rear door and lhs sill panel trim. Re-organise rear crash management components. reinstall all parts removed.	\$ 11,200.00	2000.
7	To respray lhs rear fender, lhs front door, lhs sill panel, lhs sill panel trim, door entrances, roof channel, drain panel, lhs inner C-pillar panel and end panelling. To carry out stone chip treatment and joint sealer works. <i>Rear Door ✓ Handle x 02</i>	\$ 7,800.00	$2200 = 4 \times 550$ $200 = \text{Handle} \times 02$ <u>2400</u>
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
9	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 23,492.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 528 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR - LH <i>Dented</i>	\$ 3,374.00	✓
2	FRONT DOOR STONE GUARD FILM - LH <i>new</i>	NEC \$ 110.00	✓
3	FRONT DOOR ATTACHMENT PARTS ?	\$ 173.00	?
4	OUTER DOOR SEAL <i>new</i>	NEC \$ 212.00	✓
5	BONDING AGENT ?	NEC \$ 45.00	?
6	CLEANING SOLUTION ?	NEC \$ 65.00	?
7	DOOR CATCH <i>new</i>	\$ 109.00	✗
8	FRONT DOOR HANDLE TRIM PLATE - LH <i>Regt</i>	\$ 410.00	✗
9	FRONT DOOR HANDLE CAP - LH <i>new</i>	\$ 79.00	✗
10	REAR DOOR - LH <i>Distorted</i>	\$ 3,374.00	✓
11	REAR DOOR ATTACHMENT PARTS ?	\$ 112.00	?
12	OUTER DOOR SEAL <i>new</i>	NEC \$ 212.00	✓
13	BONDING AGENT ?	NEC \$ 45.00	?
14	CLEANING SOLUTION ?	NEC \$ 65.00	?
15	DOOR CATCH <i>new</i>	\$ 109.00	✗
16	OUTER DOOR SEAL <i>2 new</i>	\$ 168.00	✗
17	INNER DOOR SEAL	\$ 229.00	✗
18	REAR DOOR HANDLE TRIM PLATE - LH <i>cut</i>	\$ 410.00	✓
19	REAR DOOR HANDLE CAP - LH <i>new</i>	\$ 79.00	✗
20	REAR DOOR HANDLE SENSOR <i>new</i>	1 \$ 237.00	✗
SUB TOTAL SPARE PARTS		\$ 9,617.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 528 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	HANDLE BASE - LH <i>not a</i>	\$ 124.00	+
22	WINDOW REGULATOR - LH ?	\$ 320.00	?
23	WINDOW REGULATOR MOTOR - LH <i>not a</i>	\$ 322.00	+
24	DOOR CONTROL UNIT <i>not a</i>	\$ 685.00	+
25	UPPER DOOR HINGE - LH ?	\$ 96.00	?
26	LOWER DOOR HINGE - LH ?	\$ 94.00	?
27	LOWER PLATE ?	2 \$ 28.00	?
28	SIDE MEMBER TRIM - LH <i>not a</i>	\$ 783.00	✓
29	SIDE MEMBER TRIM ADHESIVE TAPE ? <i>not a</i>	NEC \$ 15.00	✓
30	SIDE MEMBER TRIM CLIP	NEC \$ 96.00	✓
31	FRONT ^{REAR} DOOR STONE GUARD FILM - LH <i>not a</i>	NEC \$ 108.00	✓
32	REAR SILL TRIM STRIP - LH ?	\$ 109.00	?
33	REAR FENDER - LH <i>not a</i>	\$ 3,162.00	+
34	INNER C-PILLAR PANEL - LH ? <i>not a</i>	\$ 754.00	+
35	QUARTER GLASS - LH	\$ 551.00	+
36	REAR SIDE WINDOW TRIM STRIPS - LH ?	\$ 235.00	+
37	ROOF MOLDING - LH <i>not a</i>	\$ 464.00	+
38	REAR BELT MOLDING - LH	\$ 256.00	+
39	LED TAIL LIGHT - LH <i>combined</i>	\$ 1,149.00	✓
40	TAIL LIGHT TRIM - LH <i>not a</i>	\$ 27.00	+
SUB TOTAL SPARE PARTS		\$ 9,378.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKF 528 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	ALUMINIUM RIM <i>at</i>	\$ 733.00	✓
42	RUBBER VALVE <i>new</i>	4 \$ 13.00	✓
43	WHEEL HOUSING LINER - LH	\$ 256.00	✓
44	WHEEL HOUSING LINER ATTACHMENT PARTS <i>2 new</i>	\$ 72.00	✓
45	ACRYLIC SEALANT <i>2</i>	S/N \$ 180.00	✓
46	CAVITY WAX	S/N \$ 140.00	✓
47	STONE CHIP	S/N \$ 180.00	✓
48	METAL FILLER POWDER <i>new</i>	S/N \$ 280.00	✓
49	1/4 GLASS SEALANT	S/N \$ 100.00	✓
50	SUNDRIES <i>?</i>	\$ 600.00	?
TOTAL SPARE PARTS		: \$ 21,549.00	
TOTAL LABOUR CHARGES		: \$ 27,512.00	
GRAND TOTAL		: \$ 49,061.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 07/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9825 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant