



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34548

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 03/08/2019

CLAIM NO. : 11401

POLICY NO. : 5065402007-05

FROM : SHIWEI

VEHICLE NO. : FBJ3974T
MAKE/MODEL : HON / CB400

*not Admin
ok
2/5/3
5/2/7
7/8/18 To be phd After rep*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$490.00	350 490.00
2	BALANCER HANDLE	REPLACE	2.00	\$27.00	54.00
3	BAR HANDLE P/N: 39463	REPLACE	1.00	\$192.00	34 192.00
4	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$202.00	202.00
5	BRACKET HEADLAMP RH P/N: 35203	REPLACE	1.00	\$85.00	85.00
6	BRACKET REAR BOX KAPPA P/N: 63122	REPLACE	1.00	\$170.00	170.00
7	BRACKET UNDER FORK P/N: 34927	REPLACE	1.00	\$490.00	490.00
8	BRIDGE, FORK TOP P/N: 47999	REPLACE	1.00	\$300.00	300.00
9	CABLE THROTTLE 1 P/N: 35073	REPLACE	1.00	\$77.00	77.00
10	CALIPER SUB ASSY., L. FR.	REPLACE	1.00	\$468.00	468.00
11	CALIPER SUB ASSY., R. FR.	REPLACE	1.00	\$468.00	468.00
12	CASE HEADLAMP P/N: 35215	REPLACE	1.00	\$224.00	224.00
13	CLAMP P/N: 39464	REPLACE	1.00	\$46.00	46.00
14	COOLANT (MOBIL) ANTIFREEZE P/N: 60213	REPLACE	2.00	\$17.00	34.00



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
15	COVER RADIATOR SIDE P/N: 45604	REPLACE	1.00	\$44.00	44.00 <i>nye</i>
16	COVER TAIL ASSY (BLACK) P/N: 59649	REPLACE	1.00	\$531.00	531.00 <i>11</i> X
17	CRASH BAR SET P/N: 59042	REPLACE	1.00	\$171.00	171.00 <i>3rd</i>
18	FOOTREST REAR LH P/N: 54786	REPLACE	1.00	\$64.00	64.00 <i>1/c 147</i> X
19	FOOTREST REAR RH P/N: 59023	REPLACE	1.00	\$70.00	70.00 <i>11</i> X
20	FORK FRONT ASSY LH P/N: 48335	REPLACE	1.00	\$1,485.00	1,485.00 <i>Tw1</i>
21	FORK FRONT ASSY RH P/N: 48333	REPLACE	1.00	\$1,485.00	1,485.00 <i>Tw1</i>
22	GASKET EXHAUST PIPE (FRONT) P/N: 28116	REPLACE	4.00	\$12.00	48.00 <i>m</i>
23	GRILL RADIATOR (PLASTIC MESH) P/N: 38904	REPLACE	1.00	\$105.00	105.00 <i>D.S</i>
24	HEADLAMP ASSY P/N: 29349	REPLACE	1.00	\$478.00	478.00 <i>500</i>
25	HOLDER STEP LH P/N: 60587	REPLACE	1.00	\$223.00	223.00 <i>Tw1</i>
26	HOLDER STEP RH P/N: 60590	REPLACE	1.00	\$223.00	223.00 <i>Tw1</i>
27	LABEL DRIVE P/N: 60798	REPLACE	1.00	\$31.00	31.00 ?
28	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$1,176.00	1,176.00 <i>400</i>
29	LEVER BRAKE P/N: 18930	REPLACE	1.00	\$65.00	65.00 <i>scr</i>
30	LEVER CLUTCH	REPLACE	1.00	\$27.00	27.00 <i>scr</i>
31	MARK P/N: 40930	REPLACE	1.00	\$18.00	18.00 ?
32	MASTER CYLINDER PUMP FRONT P/N: 46726	REPLACE	1.00	\$319.00	319.00 <i>147</i>
33	METER ASSY P/N: 45607	REPLACE	1.00	\$1,867.00	1,867.00 <i>320</i>
34	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$280.00	280.00 <i>175</i> <i>147</i>
35	MIRROR LH P/N: 43261	REPLACE	1.00	\$124.00	124.00 <i>320</i>



bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
36	MIRROR RH P/N: 40054	REPLACE	1.00	\$124.00	3rd 124.00 ✓
37	MUDGUARD FRONT (BLACK) P/N: 33882	REPLACE	1.00	\$241.00	241.00 ✓
38	MUFFLER (REAR) P/N: 34850	REPLACE	1.00	\$1,449.00	1,449.00? ✓
39	OIL BRAKE (KUTTEN KEULER) DOT 4 P/N: 39338	REPLACE	1.00	\$21.00	21.00 ✓
40	PACKING MUFFLER P/N: 57026	REPLACE	1.00	\$23.00	23.00 ✓
41	PIPE EXHAUST FRONT P/N: 41510	REPLACE	1.00	\$2,120.00	2,120.00 ✓
42	PLATE DIS FRONT LH ASSY	REPLACE	1.00	\$679.00	679.00 ✓
43	PLATE DIS FRONT RH ASSY	REPLACE	1.00	\$679.00	679.00 ✓
44	PLATE HEADLIGHT P/N: 45596	REPLACE	1.00	\$82.00	82.00 ✓
45	PLATE NUMBER FRONT (STRAIGHT) P/N: 26249	REPLACE	1.00	\$21.00	21.00 ✓
46	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$23.00	23.00 X
47	PROTECTOR EXHAUST PIPE FRONT P/N: 43475	REPLACE	1.00	\$96.00	96.00 ✓
48	RADIATOR ASSY P/N: 53469	REPLACE	1.00	\$980.00	980.00 ✓
49	RIM FRONT ASSY	REPLACE	1.00	\$1,189.00	1,189.00 ✓
50	SEAL DUST STEERING CONE P/N: 29262	REPLACE	1.00	\$17.00	17.00 ✓
51	SEAL DUST STEERING CONE 1 P/N: 29261	REPLACE	1.00	\$18.00	18.00 ✓
52	SHOCK ABSORBER REAR P/N: 39562	REPLACE	2.00	\$999.00	1,998.00 X
53	STAY HEADLAMP P/N: 35204	REPLACE	1.00	\$138.00	138.00 ✓
54	STEERING CONE LOWER P/N: 19467	REPLACE	1.00	\$42.00	42.00 ✓
55	STEERING CONE UPPER P/N: 19466	REPLACE	1.00	\$42.00	42.00 ✓
56	STICKER	REPLACE	1.00	\$54.00	54.00 ✓
57	STICKER FUEL TANK LH	REPLACE	1.00	\$48.00	48.00 ✓

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
58	STICKER FUEL TANK RH	REPLACE	1.00	\$48.00	48.00
59	SWITCH ASSY WINKER	REPLACE	1.00	\$181.00	181.00
60	SWITCH HANDLE LEVER CABLE 1	REPLACE	1.00	\$181.00	181.00
61	TANK FUEL ASSY	REPLACE	1.00	\$1,379.00	1,379.00
62	WINKER ASSY.	REPLACE	1.00	\$181.00	181.00

SUB TOTAL

\$24,188.00

GST @ 7 %

\$1,693.16

GRAND TOTAL

\$25,881.16

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃