

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722
Hp : 9183 3008 Fax : 6873 2017

Vehicle No : SLV7928U
Vehicle Model : Mazda 2

Estimate Repair Cost

No.	Qty	Parts List Items
1	1	Front bumper
2	2	Front bumper retainers
3	2	Front bumper brackets
4	1 set	Front bumper clips
5	1	Front fender LH
6	1	Front fender inner shield LH
7	1	Head lamp LH
8	1	Front support panel

Not Authorized
11 Day @ 1450/-
Resurvey After Painting
4 days

\$	894.00	X
\$	60.00	X
\$	46.00	X
\$	40.00	X
\$	380.10	✓
\$	100.10	✓
\$	678.00	✓
\$	414.00	X
Total	\$ 2,612.20	

208

Parts Special Nett Items

9	1	Front number plate
10	1	Stickers

\$	60.00	X
\$	600.00	2000
\$	660.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour

Total Parts \$ 3,272.20

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 800.00	350/-
2	To putty and respray painting on affected areas.	\$ 700.00	400/-
3	To remove, replace front fender fittings to facilitate repair.	\$ 300.00	X
4	To remove, replace front tyre and wheel rim.	\$ 150.00	X
5	To check wiring and lightings.	\$ 80.00	20/-

Total Labour \$ 2,030.00

Total Parts and Labour \$ 5,302.20