

T K MOTOR WORKSHOP

Adrian

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO : 53049097L

T/P ALG

DATE: 23/8/2019

VASHDEV PARSRAM CHANDIRAMANI
793A MOUNTBATTEN RD
SINGAPORE 437793

TP ALG
Shirley

US 5 day

By Hand: 15/10/19

DEAR SIR

ACCIDENT DATE: 04/08/2019

ESTIMATE COST OF REPAIRS BILL TO MERCEDES-BENZ C180 CAR NO: SMA795E

1	PC FRONT L/H FENDER	Repair	\$S	770.00	770.00	NETT	X
1	PC FRONT L/H HEADLAMP	cut		3,127.00	3,127.00	NETT	✓
1	PC FRONT BUMPER	Reformed		1,507.00	1,507.00	NETT	✓
2	PC FRONT BUMPER PARKING SENSOR	new		702.00	702.00	NETT	X
1	PC FRONT BUMPER R/H SIDE GARNISH			112.00	112.00	NETT	X
10	PC FRONT BUMPER CLIPS	new		50.00	50.00	NETT	✓
1	PC FRONT BUMPER SPONGE	cracked		255.00	255.00	NETT	✓
1	PC FRONT BUMPER REINFORCEMENT BEAM	Not new		675.00	675.00	NETT	X
1	PC FRONT BUMPER L/H INNER MEMBER GARNISH	cracked		375.00	375.00	NETT	✓
1	PC FRONT GRILLE			809.00	809.00	NETT	X
1	PC FRONT GRILLE EMBLEM	new		77.00	77.00	NETT	X
1	PC FRONT GRILLE INNER GARNISH	Not new		212.00	212.00	NETT	X
1	PC FRONT L/H HEADLAMP LOWER BRACKET	new		84.00	84.00	NETT	X
1	PC FRONT SPORT RIM "17" INCH	cut		1,650.00	1,650.00	NETT	1300 (N)
1	PC FRONT L/H LOWER ARM			693.00	693.00	NETT	X
1	PC FRONT L/H KNUCKLE ARM	Not new		596.00	596.00	NETT	X
1	PC FRONT L/H KNUCKLE HUP			451.00	451.00	NETT	X
1	PC FRONT L/H KNUCKLE HUP & BEARING	Not new		281.00	281.00	NETT	X
1	PC FRONT BUMPER CENTRE GRILLE	cracked		98.00	98.00	NETT	✓
1	PC FRONT BUMPER LOWER CHROME GARNISH	new		398.00	398.00	NETT	✓
1	PC FRONT BUMPER COVER GARNISH	Reformed		226.00	226.00	NETT	X
1	PC FRONT BUMPER TOP BRACKET BASE	cracked		112.00	112.00	NETT	X
1	PC FRONT GRILLE STAY BRACKET BASE	Not new		196.00	196.00	NETT	X
1	PC FRONT L/H FENDER INNER SHIELD	Not new		86.00	86.00	NETT	✓
1	PC FRONT L/H HORN	cracked		80.00	80.00	NETT	✓

5611

5049.80

5049.80

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO 53049097L

TO CHECK WIRING.	50.00	50.00 30
TO SPRAY PAINTING.	600	600 500
TO COMPUTER WHEEL ALIGHTMENT.	90.00	90.00 S/NETT ✓
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.	80.00	80.00 X
TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.	650.00	650.00 400
LABOUR CHARGE TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECKS.	80.00	80.00 ✓
TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & INSTALL PARKING SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING.	80.00	80.00 60
		<u>15,052.00</u> 15,652.00
TOTAL S\$		1160

total 7509.90
H/s GK
04 Days

GK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: