

97481150

WTS Automotive Services Pte Ltd
17 Kaki Bukit Road 4
#01-58/59/60/61/62
Singapore 417809
Main Line: 68449 449

Repair Quotation - SMK4457C

Client: AIG Asia Pacific Insurance Pte Ltd
Address:
Attention: LKK (Surveyor)
Contact No:
Fax No:
Email:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 5/8/2019
Veh No: SMK4457C
Veh Model: Honda Fit
Mileage:

Service Advisor		Payment Terms		Quotation Validity	
Name:	Muhammad Idarm	Credit Term		7 Days	
Contact No:	87489825 / 97481150				
Email:	muhammad.idram@pitstop.com.sg				
Fax No:	68449463				

S/No	Description	Qty	Price	Actions	Surveyor Remarks
1	REAR BUMPER CASING / CRA	1	After 135% \$490.00		520
2	SIDE BUMPER RETAINERS / 1pc. Snt.	2	\$38.00		40
3	REVERSED SENSOR / DM	1	\$120.00		
4	REAR DOOR / buc	1	\$680.00	120%	860
5	RIGHT REAR LIGHT CASING / CRA	1	\$225.00		350.5
6	REAR BUMPER SPOILER / re.	1	\$210.00		
7	PAINT - MATERIAL	3 PANELS	\$540.00	500	
8	LABOUR TO DISMANTLE AND REFIX		\$820.00	500 . 550	
** We will advise if further supplementary items are necessary					
Estimated Days of Repair Given :	4	Working Days			
			Sub-total	\$3,123.00	
			GST	\$218.61	
			Total	\$3,341.61	

*The above quotation is based on initial assessment. We will advise further if there is supplementary repair / additional items.
**Quotation for cash repair only, not for insurance claims purpose.

Gua Qiang - 82880282
part by part.

Surveyor Signature / Date / Time

(To accept this quotation, please sign & return)

before paint photos.

06/8/19. 4:45 pm

Gua Qiang @ lkk auto. com

Company Stamp