

Transcab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5973Z**AAD1908-030***Not Authorized*
11 Sep 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

06 AUG 2019

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5973Z

VF1ABL15AUC281228

RENAULT

LATITUDE

5.8.19

AXA

14/1/2015

PART**LIST**

1	BUMPER COVER FRT	\$	<i>Buc 120</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75	} X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68	
1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41	
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83	
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80	} X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21	
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08	
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43	✓
1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15	X
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83	✓
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84	} X
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79	
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84	
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22	
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75	} X
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79	
1	BONNET	\$	<i>N</i> 1,941.63	
1	BONNET INSULATOR	\$	<i>SL</i> 405.73	
1	BONNET STRUT LH	\$	<i>SL</i> 88.61	
1	BONNET STRUT RH	\$	<i>SL</i> 88.61	} X
1	BONNET HINGE LH	\$	<i>N</i> 348.31	
1	BONNET HINGE RH	\$	<i>N</i> 348.31	
1	BONNET LOCK	\$	<i>N</i> 305.48	
1	BONNET CABLE	\$	<i>SL</i> 119.19	

Trans-cab Auto Services Pte Ltd**AAD1908-030**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5973Z

1	BONNET CABLE COVER	\$	161.03
1	BONNET SEAL OUTER	\$	92.36
1	BONNET SEAL INNER	\$	157.28
1	AIR CLEANER BOX	\$	464.20
1	AIR CLEANER HOSE	\$	175.85
1	AIR CLEANER LOWER	\$	271.26
1	AUTO COMPUTER	\$	5,032.17
1	INJECTION COMPUTER	\$	4,706.30
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52
1	STEERING PUMP ELECTRIC L70Y	\$	2,306.90
1	STEERING PINION RACK L70Y	\$	4,413.11
1	LOWER ARM LH L70Y	\$	685.76
1	KNUCKLE ARM LH L70Y	\$	846.98
1	ABSORBER FRT LH L70Y	\$	360.54
1	DRIVESHAFT LH	\$	1,747.45
1	STABILIZER BAR FRT	\$	604.65
1	DOOR PANEL FRT LH	\$	2,844.66
1	DOOR MIRROR ASSY LH	\$	1,483.40

TOTAL \$ 45,842.02**10% \$ 4,584.20****\$ 41,257.81****Special Nett**

1	BUMPER CLIP FRT	\$	66.00
1	BUMPER BRACKET CLIP FRT LH	\$	12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50
1	BUMPER GRILLE LOWER CLIP	\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
1	WHEELARCH CLIP FRT LH	\$	30.50
1	FRONT LEFT TYRE	\$	300.00
1	FRONT LEFT TYRE RIM	\$	380.00
1SET	Front licence plate with holder	\$	80.00
1	WINDSCREEN SEALANT	\$	253.80
1	FRONT WINDSCREEN MOULDING	\$	120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00
6	BONNET INSULATOR CLIP L70Y	\$	7.30

Trans-cab Auto Services Pte Ltd**AAD1908-030**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5973Z

2	BONNET STRUT L70Y	\$	88.61	}	X
2	BONNET CABLE CLIP L70Y	\$	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	10.85		
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00		
1SET	RADIATOR GRILLE SCREW	\$	16.00		
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00		
1	FRONT DOOR STICKER 'Classic'	\$	80.00		
TOTAL		\$	1,882.88		
TOTAL PARTS		\$	43,140.69		

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 ⁴⁰⁰¹

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of front windscreen glass to facilitate bodywork repair.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ 380.00 X

To remove and renew power steering pump, oil cooler pipe and final checking and testing.

\$ 440.00 , X

Trans-cab Auto Services Pte Ltd**AAD1908-030**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5973Z

Putty and spray painting of the affected portion.	\$	6,000.00	4401
To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	301
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	nn X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	nn X
TOTAL	\$	16,000.00	
Over All Total	\$	59,140.69	

LUMP SUM (REPAIR DAY)**20 days****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: