

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-Aug-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8835 A

1 pc	Bonnet grille	— cr	\$	385.00 —
2 pcs	Front n/s & o/s head lamps @ \$1028.00	x su	\$	2,056.00
1 pc	Front bumper	— Repair	\$	531.00 —
1 pc	Front bumper emblem	— su	\$	44.00 —
1 pc	Front bumper centre grille	x su	\$	174.00
1 pc	Front bumper lower stiffer	x su	\$	134.00
1 pc	Front bumper tow hook cover	x su	\$	14.00
1 pc	Front bumper inner sponge	x su	\$	110.00
1 pc	Front bumper reinforcement	x su	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	x su	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	x su	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	x su	\$	32.00
1 pc	Boot lid	x repair	\$	1,119.00
1 pc	Boot lid lock	x su	\$	99.00
1 pc	Bootlid striker	x su	\$	21.00
1 pc	Bootlid emblem	— su	\$	27.00 —
1 pc	Bootlid CRDi	— su	\$	29.00 —
1 pc	Boot lid rubber weatherstrip	x su	\$	96.00
1 pc	Boot lid lower garnish	x repair	\$	290.00
2 pcs	Bootlid hinges @ \$66.00	x su	\$	132.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00	x su	\$	700.00
2 pcs	Rear n/s & o/s tail lamp @ \$421.00	x su	\$	842.00
1 pc	End panel	x repair	\$	250.00
1 pc	End panel inner garnish	x su	\$	74.00
1 pc	Rear bumper	— Repair	\$	696.00 —
1 pc	Rear bumper lower cover	— cut	\$	206.00 —
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	— cr	\$	58.00 —
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	x su	\$	92.00
1 pc	Rear bumper inner sponge	x su	\$	114.00 —
1 pc	Rear bumper reinforcement	x su	\$	607.00 —
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	x su	\$	36.00 —
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	x su	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	x su	\$	36.00
			\$	9,504.00
Less 10%			\$	950.40
			\$	8,553.60

6-Aug-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8835 A

S/NETT

1 set	Rear bumper clips	- <i>na</i>	\$	48.00 -
1 set	End panel inner garnish clips	X <i>na</i>	\$	30.00
1 set	Bootlid inner trim clips	X <i>na</i>	\$	52.00
1 set	Bootlid lower garnish clips	X <i>na</i>	\$	60.00
1 set	Bootlid stickers	- <i>na</i>	\$	100.00 -
1 set	Reverse sensor	- <i>sketch</i>	\$	280.00 <i>200 -</i>
1 pc	Rear no. plate with casing	X <i>na</i>	\$	50.00
1 pc	Front no. plate with casing	- <i>fit</i>	\$	50.00 <i>35 -</i>
1 pc	Front bumper clips	- <i>na</i>	\$	48.00 -

Sundry

\$ 50.00 *20*

Towing Fee

\$ 50.00 X *na*

To check for wiring and to focus head lamps

\$ 80.00 X *na*

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 120.00 *50*

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 *50*

To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut the panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc

\$ 800

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, floorboard compartment, front bumper

\$ 1,800.00

To apply rustproofing on the repaired and replaced panels.

\$ 900

\$ 1,200.00

\$ 120.00 X *na*

\$ 12,871.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to approval from Insurance Company

Signature:
Date:

15/8/19
calculated 4/5 \$3700 / 4 days

Ka (in 11/11/19)

M 6/8/19 1205h

4 Days

4/5

After Repair p Lda