

ASS. REC. BY:

REF: CS3/SPF19009505/4103-1 special instruction:

Senior:

ASSIGNMENT (Office)

From (Person): Hafizul Furhan of SPF Date/Time: 7/8/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGG1612 Insured: QX950E

at Workshop m/s STK AUTO Tel: 6386 0669

of Blk 8 kaki Bukit Ave 4 # 03-21 premier

Policy No: Claim No: AEMD/105/009/2019/068

Sum Insured: Excess:

Make of Veh: D.O.A. 24/5/19.  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:42pm @ 29/5/19 Person Contacted: Jing Jing Vehicle: IN/OUT

Date/Time	Action/Instruction	Fahmyl (x)
	SGG1612 - CS / MSG16014668 / 1clth3d1	
	DAR Report \$3350/-	

3000  
\$2850, 5 Days.  
(red: 3320; 52%)

Repair day 5  
weekend - 1 days  
total - 6 days

Repair Range - \$3000 - \$4000/-

3110 - File pass to typist.

RECEIVED 4 OCT 2019

Do Not Finalise

Do Not Finalise

0926H

## TOTAL

	
N/S	O/S

## Nivitha (LKK Auto)

---

**From:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Sent:** Wednesday, 7 August 2019 2:37 PM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Frankie THAY (SPF)  
**Subject:** Re-Survey for SGG161Z  
**Attachments:** Third party survey 2019-068.pdf

Our ref: AEMD/105/009/2019/068

Kindly re-survey SGG161Z.

The third party cost of repair is \$6,320.00 (pls refer to attached).

Thank you.

*Best Regards,*

*Hafizul Farhan Bin Rahmat*

*AEMD / PLD*

*Singapore Police Force*

*DID: (65) 6478 4840 / FAX: (65) 6478 4850*



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.

[www.avg.com](http://www.avg.com)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/05/2019 10:24
Date Of Accident	24/05/2019 18:55
Exact Location Of Accident	SHENTON WAY TOWARDS UNION STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG161Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GIAM MENG TUCK
NRIC No	S0080926H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97609963
Alternative Phone No	OFFICE-97609963
<b>Vehicle Particulars</b>	
Manufacturer	VOLKSWAGEN
Model	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	
	NO
If No, Please state action to be taken	
	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103789934 PREMIUM
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN BEE HONG
NRIC No	S1673586H
Date Of Birth	28/05/1964
Occupation	INDOOR
Date Of Driving Pass	24/02/1983
Driving Experience	36 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97995064
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 78 BAYSHORE ROAD #02-21 COSTA DEL SOL  
 Postcode 469991  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : GIAM MENG TUCK  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name MARINA BAY NPC  
 Police Station Address ROAD: 70 MARINA VIEW , POSTCODE: 018962 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: WITH OWNER  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX950E  
 Vehicle Make/Model/Colour TOYOTA LANDCRUISER 4.5 A  
 Details Of Properties  
 Vehicle Category GOVERNMENT  
 Name of Driver MOHAMMAD NAZARIE BIN ABDUL AZIZ  
 NRIC/Passport Number S9235848H  
 Contact Number 93364864  
 Address

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to  
Police Report

DECLARATION

I/We declare the foregoing particulars are correct to the best of my/our knowledge.

*[Signature]*

Policyholder's signature  
Date & time

27 MAY 2019

*[Signature]*

Police's signature  
Date and time of the police report

27 MAY 2019

EDAG KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492300

Email: yocko@singnet.com.sg

By the Motor Vehicle Insurance Corporation

Singapore



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0400519

Date of Report : 19/07/2019

To : Mr Giam Meng Tuck

C/o. 8 Kaki Bukit Avenue 4

#03-21 Premier @ Kaki Bukit

Singapore 415875

Date of Assignment : 27/05/2019

Report requested by : Mr Giam Meng Tuck

Date of Accident : 24/05/2019

Date of Inspection : 27/05/2019

Claim No. : Third Party Claim

Policy No. : -

### **PARTICULARS OF DAMAGED VEHICLE**

Vehicle Registration No. : SGG161Z  
Make & Model : Volkswagen Jetta  
Date of Registration : 30/09/2016  
Colour : Met. Silver

Engine Capacity (cc) : 1390cc  
Mileage (km) : 31550km  
Chassis / Frame No. : WVWZZZ16ZGM027099  
Engine No. : CAXF84240

### **TYRE CONDITION**

Front LH : 7 mm

Make : Pirelli

Front RH : 7 mm

Make : Pirelli

Rear LH : 7 mm

Make : Pirelli

Rear RH : 7 mm

Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### **PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)**

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### **PLACE OF REPAIRER OFFICE/WORKSHOP**

Location : M/s. STK Auto (S) Pte Ltd

8, Kaki Bukit Avenue 4, #03-21, Premier @ Kaki Bukit, Singapore 415875

### **ASSESSMENT**

Repairer's Estimate : \$ 9,485.50  
Revised Amount : \$ 7,901.10  
Less Excess : \$ -  
Recommended Reserve : \$ 6,320.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

*Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.*





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SGG161Z

Report No. : PAS/TP/0400519

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. STK Auto (S) Pte Ltd, 8, Kaki Bukit Avenue 4, #03-21, Premier @ Kaki Bukit, Singapore 415875.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the rear LH portion.

### DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, rear exhaust silencer, taillamps, rear reflectors, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$7,901.10.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$6,320.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
Prominent Appraiser Services Pte Ltd

  
Andrew How  
Automobile Appraiser  
MSAAA  
Licensed Appraiser





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SGG161Z

Report No. : PAS/TP/0400519

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Boot lid <i>X Repair</i>	Dented/Distorted		\$ 1,293.00	<del>\$ 1,293.00</del>
2	2 pcs	Boot reflector R/L <i>X SVC</i>	Cracked	\$ 223.00 ✓	\$ 446.00	<del>\$ 446.00</del>
3	1 pc	Boot center emblem	Necessary		\$ 56.00	<del>\$ 56.00</del>
4	1 pc	Boot emblem (JETTA)	Necessary		\$ 44.00	<del>\$ 44.00</del>
5	1 pc	Boot emblem (TSI)	Necessary		\$ 32.00	<del>\$ 32.00</del>
6	1 pc	Boot inner trim	Serviceable		\$ 112.00	\$ -
7	1 pc	Boot lock <i>X</i>	Bent/Damaged		\$ 124.00	<del>\$ 124.00</del>
8	1 pc	Boot lock catch <i>X SVC</i>	Bent		\$ 137.00	<del>\$ 137.00</del>
9	1 pc	Boot weatherstrip <i>X</i>	Torn/Necessary		\$ 241.00	<del>\$ 241.00</del>
10	2 pcs	Taillamp R/L <i>X SVC</i>	Broken/Cracked	\$ 382.00 ✓	\$ 764.00	<del>\$ 764.00</del>
11	1 pc	Rr bumper	Dented		\$ 983.00	<del>\$ 983.00</del>
12	1 pc	Rr bumper lower trim <i>X SVC</i>	Dented/Deformed		\$ 387.00	<del>\$ 387.00</del>
13	1 pc	Rr bumper reflector LH	Cracked		\$ 73.00	<del>\$ 73.00</del>
14	1 pc	Rr bumper center guide	Dented/Cracked		\$ 85.00	<del>\$ 85.00</del>
15	2 pcs	Rr bumper side guide R/L <i>X SVC</i>	Cracked/Necessary	\$ 63.00 ✓	\$ 126.00	<del>\$ 126.00</del>
16	2 pcs	Rr bumper bracket R/L <i>X SVC</i>	Necessary	\$ 38.00	\$ 76.00	<del>\$ 76.00</del>
17	1 pc	Rr bumper reinforcement	Dented		\$ 427.00	<del>\$ 427.00</del>
18	1 pc	Rr end panel <i>X Repair</i>	Dented/Distorted		\$ 685.00	<del>\$ 685.00</del>
19	1 pc	Rr end panel top garnish	Refit		\$ 98.00	\$ -
20	1 pc	Rr exhaust silencer	Dented/Repair	} <i>NN</i>	\$ 806.00	\$ -
21	2 pcs	Rr fender R/L	Dented/Repair		(Refer labour no. 3, 6 & 7)	
22	1 pc	Rr floor panel	Dented/Repair		(Refer labour no. 3, 6 & 7)	
23	1 pc	Rr exhaust silencer	Dented/Repair		(Refer labour no. 4)	
24	1 pc	Rr chassis member LH	Dented/Repair		(Refer labour no. 3, 6 & 7)	
					\$ 6,995.00	\$ 5,979.00
Less Discount : 10%					\$ 699.50	10% \$ 597.90
List Parts Sub-Total :					\$ 6,295.50	\$ 5,381.10
1	1 set	Reverse sensor	Dented/Damaged	S/N	\$ 250.00	<del>\$ 220.00</del>
2	1 pc	Rr end panel sealant <i>X SVC</i>	Necessary	S/N	\$ 50.00	<del>\$ 40.00</del>
Special Nett Sub-Total :					\$ 300.00	\$ 260.00
Parts Total :					\$ 6,595.50	\$ 5,641.10

2350.35  
10% : 215.32



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SGG161Z

Report No. : PAS/TP/0400519

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To transfer boot component parts to new boot.	\$ 100.00	\$ <del>X</del> 80.00
2	To check rear electrical wiring system.	\$ 80.00	\$ <del>30</del> 50.00
3	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 100.00	\$ <del>60</del> 80.00
4	To straighten, repair and realign rear exhaust silencer.	\$ 80.00	\$ <del>X</del> 60.00
5	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 50.00	\$ <del>40</del> 50.00
6	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,200.00	\$ <del>500</del> 880.00
7	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	\$ <del>800</del> 1,000.00
8	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ <del>X</del> 60.00
Labour Total :		\$ 2,890.00	\$ 2,260.00
Total (Parts & Labour) :		\$ 9,485.50	\$ 7,901.10

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 6,320.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **8 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

72 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

3745.32

20% 3000

5 Days.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS3/SPF19009505/Gtd3s2-1

ACCIDENT CLAIM SECTION (SPORE POLICE  
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD  
POLICE ACADEMY SINGAPORE 298333

Date : 07-10-2019



ATTN: HAFIZUL FARHAN

Code : SPF

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 950E	Veh. Inspected	SGG 161Z
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/068	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	07/08/2019

### 2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WVWZZZ16ZGM027099	Colour	SILVER
Odometer	31550	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	6 mm
L/H Front Tyre	205/55 R16	PIRELLI	6 mm
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	24/05/2019	Inspection Date	29/05/2019
Survey held at	STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 161Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOT LID	TO REPAIR SEE LABOUR	1,293.00	-
2	BOOT REFLECTOR R/L @ \$223.00	N/S CRACKED / O/S SERVICEABLE	446.00	223.00
1	BOOT CENTRE EMBLEM	NECESSARY	56.00	56.00
1	BOOT EMBLEM (JETTA)	NECESSARY	44.00	44.00
1	BOOT EMBLEM (TSI)	NECESSARY	32.00	32.00
1	BOOT INNER TRIM	SERVICEABLE	112.00	-
1	BOOT LOCK	SERVICEABLE	124.00	-
1	BOOT LOCK CATCH	SERVICEABLE	137.00	-
1	BOOT WEATHERSTRIP	SERVICEABLE	241.00	-
2	TAILLAMP R/L @ \$382.00	N/S CRACKED / O/S SERVICEABLE	764.00	382.00
1	RR BUMPER	DENTED	983.00	983.00
1	RR BUMPER LOWER TRIM	SERVICEABLE	387.00	-
1	RR BUMPER REFLECTOR LH	CRACKED	73.00	55.35
1	RR BUMPER CENTRE GUIDE	DENTED / CRACKED	85.00	85.00
2	RR BUMPER SIDE GUIDE R/L @ \$63.00	N/S DEFORMED / O/S SERVICEABLE	126.00	63.00
2	RR BUMPER BRACKET R/L @ \$38.00	SERVICEABLE	76.00	-
1	RR BUMPER REINFORCEMENT	DENTED	427.00	427.00
1	RR END PANEL	TO REPAIR SEE LABOUR	685.00	-
1	RR END PANEL TOP GARNISH	NOT NECESSARY	98.00	-
1	RR EXHAUST SILENCER	NOT NECESSARY	806.00	-
2	RR FENDER R/L (NPA)	NOT NECESSARY	-	-
1	RR FLOOR PANEL (NPA)	NOT NECESSARY	-	-
1	RR EXHAUST SILENCER (NPA)	NOT NECESSARY	-	-
1	RR CHASSIS MEMBER LH (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-699.50	-235.04
			6,295.50	2,115.31
<b>SPECIAL NETT ITEMS</b>				
1	SET REVERSE SENSOR (SN)	DENTED / DAMAGED	250.00	200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR END PANEL SEALANT (SN)	SERVICEABLE	50.00	-
			300.00	200.00
	<b>LABOUR</b>			
	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT.	NOT NECESSARY	100.00	-
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		80.00	30.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS.		100.00	60.00
	TO STRAIGHTEN, REPAIR AND REALIGN REAR EXHAUST SILENCER.	NOT NECESSARY	80.00	-
	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT.		50.00	40.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID AND RR END PANEL.		1,200.00	500.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,200.00	800.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	NOT NECESSARY	80.00	-
			2,890.00	1,430.00
<b>GRAND TOTAL</b>			<b>9,485.50</b>	<b>3,745.31</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,000.00</b>

Report Ref No. CS3/SPF19009505/Gtd3s2-1

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

RECOMMENDED REPAIR DAYS : 5

WEEKENDS : 1

TOTAL DAYS : 6

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.