

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : b1 52266
Date Estimated : 07/08/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chiong Chow Joo
53 Hillview Avenue
#09-05 Hillington Green

Singapore 669566

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD1663L	OR99898	21/04/2017	X3 sDrive20	0

DESCRIPTIONVALUE

Replacing rear bumper panel and attachments, rework bootlid

1700 ~~2,125.00~~

Spray rear bumper and bootlid

1805 ~~2,006.00~~

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 ~~271.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~177.00~~

Sundries

? 150.00

To replace front seat crash-active head restraint air bags including reset and conduct check for function.

457 ~~531.00~~Total Labour 1: **5,260.00**DESCRIPTIONQTYPRICVALUE

RR BUMPER CARRIER ECE ?

1

797.80

797.80

RR LH BUMPER MIDDLE MOUNTING ?

1

137.75

137.75

RR RH BUMPER MIDDLE MOUNTING ? X

1

137.75

137.75

RR BUMPER LH MOUNT ?

1

192.15

192.15

RR BUMPER RH MOUNT ? X

1

192.15

192.15

COVER MIDDLE BOTTOM ?

1

72.55

72.55

REAR BUMPER CLADDING (PDC/SCHWARZ) ?

1

211.45

211.45

REAR BUMPER PANEL PRIMED (XLINE/PDC) ?

1

1,510.10

1,510.10

UNDERRIDE GUARD PRIMED REAR (X LINE) ?

1

249.40

249.40

(DG) REP. KIT CRASH ACTIVE HEAD RES ?

2

115.35

230.70

DECOUPLING RING PDC TORQUE CONVERTE ?

4

5.05

20.20

BUMPER PDC SENSOR (A52 SPACEGRAU) ?

1

368.80

368.80

Total Parts : **4,120.80**

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 52266**
Date Estimated : **07/08/2019**
Prepared By : **Joseph Yaguel**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD1663L	0R99898	21/04/2017	X3 sDrive20	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 26/08/19 @ 1255 Excess S\$ _____

Surveyor's Name RAEUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	5,260.00
Parts	:	4,120.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	656.66
Grand Total	:	10,037.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **