

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 28 Aug 2020

## **Preliminary Advice**

Insured Vehicle No	: SKT3300D		
TP Vehicle No	: SMK9700S	Accident Date	: 05/08/2019
Make	: HONDA FREED	Assignment Date	: 08/08/2019
Date of Inspection	: 13/08/2019	Est. Duration of Repair	: 3
Inspection At	: ACE AUTOLUTION PTE LTD (KAKI BUKIT) 13 KAKI BUKIT ROAD 4, #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807		

## **Point of Impact / General Description of Damages**

The vehicle sustained damages at the rear o/s portion.

Repairer's Estimate (Gross)	:S\$	8,840.00
Revised Amount	:S\$	1,500.00 lump sum
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,500.00 lump sum
Lump Sum Repair	:S\$	

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

## **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on wp