



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP Sampo  
Denise

GBS1091054

Page No. 1

Vehicle No. SMK9700S HONDA FREED

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)		SURVEYOR ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>			<div>1235.00 X</div> <div>170.00 X</div> <div>850.00 X</div> <div>85.00 X</div> <div>1290.00 X 753</div> <div>90.00 X</div> <div>110.00 35</div> <div>350.00 X</div> <div>410.00 X</div> <div>710.00 X</div> <div>5300.00</div> <div>1060.00 20%</div> <div>4240.00</div> <div>100.00 30</div> <div>550.00 80</div> <div>410.00 X</div> <div>280.00 X</div> <div>80.00 X</div> <div>100.00 X</div> <div>80.00 X</div> <div>5840.00</div>			
1	REAR FENDER RH <i>Rep's</i>					
1	REAR FENDER INNER SHIELD RH <i>new</i>					
1	REAR FENDER DOOR SLIGHTLY GRILLE RH <i>new</i>					
1	REAR AIR VENT RH <i>new</i>					
1	REAR BUMPER <i>Deland</i>					
1	REAR BUMPER REFLECTOR LAMP RH <i>new</i>					
1	REAR BUMPER SIDE RETAINER RH <i>new</i>					
1	REAR BEARING HUB RH <i>new</i>					
1	REAR ABSORBER RH <i>new</i>					
1	REAR TAILLAMP RH <i>new</i>					
<i>Rear Bumper Bracket RH can'd.</i>						
<i>Rear Taillamp Bracket RH new</i>						
<u>SPECIAL NETT ITEMS</u>						
1 SET	REAR BUMPER CLIPS <i>new</i>					
1	REAR RIM COVER RH <i>new</i>					
1	REAR TYRE RH <i>new</i>					
1	REAR REVERSE SENSOR <i>new</i>					
1	REAR QUARTER GLASS SEALANT RH <i>2 new</i>					
1	REAR FENDER SEALANT					
1 SET	REAR FENDER INNER SHIELD CLIPS <i>new</i>					
Total Parts			5840.00			

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SMK9700S HONDA FREED

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	<del>1200.00</del>	400
2	To supply paint materials, expandable items & put respray paint on parts replaced	<del>1000.00</del>	500
3	To remove and refix wiring at damaged areas	<del>180.00</del>	30
4	To perform anti rust treatment on affected areas	<del>150.00</del>	30
5	To remove and replace undercarriage part	200.00	X
6	To conduct wheel alignment test	<del>150.00</del>	80
7	To remove & refix rear quarter glass rh	120.00	X
8	To remove reverse sensor	105.50	
	Labour Total :	3000.00	
	TOTAL (PARTS & LABOUR):	8840.00	

1110

Total 1896.80

2/3 1.5K  
03 Days

1.5K

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: